NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201			U.S. NUCLEAR REGULATORY COMMISSION		
SA	AFETY INSPE	CTION REPORT	AND COMPLIANC	E INSPECTION	
1. LICENSEE/LOCATION INSPECTED: SSM DePaul Health Center Department of Nuclear Medicine 12303 DePaul Drive, Bridgeton, Missouri 63044 REPORT NUMBER(S) 2009-001			2. NRC/REGIONAL OFFICE Region III U.S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, Illinois 60532-4351		
3. DOCKET NUMBER(S		4. LICENSEE NUM	RER(S)	5. DATE(S) OF INSPI	CTION
030-02308	"	24-02490-03	DLI ((O)	Sept. 24 , 2009	2011011
LICENSEE:					
to compliance with the N The inspection consisted and observations by the 1. Based on the insp 2. Previous violation(3. The violation(s), s identified, non-repetit 1600, to exercise disc	Juclear Regulator of selective exinspector. The ection findings, no vice closed. pecifically described ive, and corrective acretion, were satisfied. Non-Cited Violation of vour acretion certain of vour acretion.	ory Commission (NF aminations of proce inspection findings violations were identified. If to you by the inspector action was or is being taked. In (s) was/were discussed activities, as described by	RC) rules and regulatedures and represent are as follows: as non-cited violations, and the remaining critical involving the following recommendations.	e as they relate to radiations and the conditions of ative records, interviews to the not being cited because they reria in the NRC Enforcement Polyuirement(s) and Corrective Active in violation of NRC requiremente with 10 CFR 19.11.	with personnel, were self- olicy, NUREG- on(s):
corrective actions is made in	0 days, the actions of accordance with the will be achieved). I	described by me to the in	R 2.201 (corrective steps er written response to NR	4, above. orrect the violations identified. already taken, corrective steps v C will be required, unless specif Signature	which will be taken,
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Geoffr	rev M. Warren	9/11	/	9/24/00

NRC FORM 591M PART 3 (10-2003) 10 CFR 2.201		S. NUCLEAR REGULATORY				
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION						
1. LICENSEE SSM DePaul Health Center REPORT NUMBER(S) 2009-001	2, NRC/REGIONAL OFFICE NRC Region III 2443 Warrenville Ro Lisle, Illinois 60532-					
3, DOCKET NUMBER(S) 030-02308	4. LICENSE NUMBER(S) 24-02490-03	5. DATE(S) OF INSPECTION Sept. 24, 2009				
6. INSPECTION PROCEDURES USED 87131, 87132	7. INSPECTION FOCUS AREAS 03.01 - 03.08; 03.01 - 03.08					
SUPPLEMENTAL INSPECTION INFORMATION						
1. PROGRAM CODE(S) 2. PRIORITY 2	3. LICENSEE CONTACT Thomas Philip Bocchini, M.D., RSO	4. TELEPHONE NUMBER 314-344-6350				
X Main Office Inspection	Next Inspection Date: Sept. 2011					
Field Office		· · · · · · · · · · · · · · · · · · ·				
Temporary Job Site Inspection						

PROGRAM SCOPE

The licensee was a 300-bed hospital located in Bridgeton, Missouri, which performed activities using byproduct materials in Sections 35.100, 35.200, and 35.300, as well as a High Dose Rate remote afterloader (HDR) under 35.1000. While authorized to use materials in 35.400 and iodine-125 under 35.1000, the licensee had never used these materials. Licensed activities were conducted only at the address listed in the license.

The nuclear medicine service was staffed with four full-time technologists and one student who all rotated through nuclear medicine and nuclear cardiology. In both areas combined, licensee personnel typically administered 600 diagnostic doses and two iodine-131 doses monthly. The iodine-131 procedures included hyperthyroid treatments and whole body scans, with the iodine in capsule form. The diagnostic procedures were predominately technetium-99m cardiac, hepatobiliary, bone, and other scans, with doses received as unit doses or prepared from bulk technetium-99m. Doses for both areas were received in nuclear medicine from a licensed nuclear pharmacy. All waste was either stored for decay in storage or returned to the radiopharmacy.

The radiation oncology department was staffed with one radiation oncologist, one physicist, and one dosimetrist; the physicist and dosimetrist were part of a physics group. The department performed approximately 80 HDR fractions and seven thyroid ablations annually. The thyroid ablations were performed using iodine-131 capsules which had been received at the nuclear medicine area.

Performance Observations

The inspector observed four diagnostic administrations of licensed material, including dose preparation and disposal, one HDR fraction, and package receipt surveys and wipes. Licensee personnel demonstrated daily checks of the HDR unit, kit preparation, survey meter and wipe counter QC, dose calibrator constancy, and daily and weekly contamination surveys, and described iodine-131 therapy procedures, waste disposal procedures, and the training program. The inspector identified no concerns with the activities. The inspector reviewed written directives for HDR and radiopharmaceutical therapy treatments. Interviews with licensee personnel indicated adequate knowledge of radiation safety concepts and procedures. The inspector performed independent and confirmatory radiation measurements which indicated results consistent with licensee survey records and postings.

In the previous inspection, the licensee was cited for releasing patients following iodine-131 therapy treatments without determining that the TEDE to any other individual was not likely to exceed 0.5 rem as a result of releasing the patients as required by 10 CFR 35.75(a). The inspector determined that licensee personnel were following the procedures in NRC Reg Guide 8.39 and using the forms which the licensee had provided to NRC to determine whether the patients could be released. Based on this determination, the violation is considered closed.

