

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
St. Luke's Regional Medical Center
190 E. Bannock
Boise, Idaho 83712
Locations: 520 S. Eagle Rd. Suite 3104, Meridian, ID
300 E. Jefferson St. Boise, ID
100 E. Idaho St., Boise, ID
REPORT NO: 2009-001

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region IV, 612 East Lamar Blvd, Suite 400
Arlington, Texas 76011-4125

3. DOCKET NUMBER
030-32196

4. LICENSE NUMBER
11-27312-01

5. DATE OF INSPECTION
October 07-09, 2009

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

X 2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

X 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 35.61 requires in part, that survey instruments used to show compliance with this part and 10 CFR be calibrated annually.

Contrary to the above, the licensee used a Ludlum Model 1000 scaler, serial number 134612, to complete required transportation surveys and area wipe surveys to detect residual radioactive material contamination at the Idaho Cardiology Associates facility use location at 300 E. Jefferson Street. The instrument was last calibrated April 22, 1997, a period exceeding 12 months.

The licensee committed to use a calibrated survey instrument for the any required survey to show compliance, effective immediately. If the Ludlum 1000 instrument is to be used for any survey to show compliance, it will be appropriately calibrated within 30 days.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Jefferson Fairbanks		10/9/09
NRC INSPECTOR	R. Rick Muñoz		10/09/2009