November 5, 2009

ULNRC-05660

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555-0001

> 10CFR50.73(a)(2)(i)(B), 10CFR50.73(a)(2)(v)(B), 10CFR50.73(a)(2)(v)(D), and 10CFR50.73(a)(2)(vii)



Ladies and Gentlemen:

DOCKET NUMBER 50-483 CALLAWAY PLANT UNIT 1 UNION ELECTRIC CO. FACILITY OPERATING LICENSE NPF-30 LICENSEE EVENT REPORT 2008-002-01 VOID FOUND IN LINE EM-023-HCB – RESIDUAL HEAT REMOVAL <u>PUMP "A" TO SAFETY INJECTION PUMPS</u>

On December 23, 2008, Callaway plant submitted LER 2008-002-00 in accordance with 10CFR50.73(a)(2)(i)(B) and 10CFR50.73(a)(2)(vii) to report a void found in line EM-023-HCB (i.e., the line between residual heat removal pump "A" and the safety injection pumps).

The enclosed supplemental licensee event report, LER 2008-002-01, is submitted to include reporting in accordance with 10CFR50.73(a)(2)(v)(B) and 10CFR50.73(a)(2)(v)(D) for the same condition.

This letter does not contain new commitments.

Sincerely,

John T. Patterson Plant Director

EMF

Enclosure

ULNRC-05660 November 5, 2009 Page 2

cc: Mr. Elmo E. Collins, Jr. Regional Administrator
U.S. Nuclear Regulatory Commission Region IV
612 E . Lamar Blvd., Suite 400 Arlington, TX 76011-4125

> Senior Resident Inspector Callaway Resident Office U.S. Nuclear Regulatory Commission 8201 NRC Road Steedman, MO 65077

Mr. Mohan C. Thadani (2 copies) Senior Project Manager, Callaway Plant Office of Nuclear Reactor Regulation U. S. Nuclear Regulatory Commission Mail Stop O-8G14 Washington, DC 20555-2738 ULNRC-05660 November 5, 2009 Page 3

Index and send hardcopy to QA File A160.0761

Hardcopy:

Certrec Corporation 4200 South Hulen, Suite 422 Fort Worth, TX 76109 (Certrec receives ALL attachments as long as they are non-safeguards and may be publicly disclosed.)

LEREvents@inpo.org (must send the <u>WORD</u> version of the LER to this address)

Electronic distribution for the following can be made via LER ULNRC Distribution:

A. C. Heflin F. M. Diva D. W. Neterer L. S. Sandbothe S. A. Maglio S. L. Gallagher T. L. Woodward (NSRB) T. B. Elwood E. M. Fast C. S. Petzel D. E. Dumbacher (NRC) B. A. Brook (WCNOC) Ms. Diane M. Hooper (WCNOC) Mr. Dennis Buschbaum (Luminant) Mr. Ron Barnes (Palo Verde) Mr. Tom Baldwin (PG&E) Mr. Wayne Harrison (STPNOC) Mr. John O'Neill (Pillsbury Winthrop Shaw Pittman LLP) Missouri Public Service Commission Records Center (INPO)

NRC FOF (6-2004)	रM 366			U.S. NUCLE	AR RE	EGULATO	RY COMMI	ISSION	APPROVI Estimated request:	ED BY OMB I burden pe 50 hours. F	: NO. 3150-0 r response to Reported less	104 comply with t ons learned ar	EXPIRES: his mandato e incorporat	06/30/2007 ry collection ted into the
		LICEN	ISEE E	VENT REF	ORT	(LER)			licensing p estimate t Nuclear R e-mail to i and Regul	process and to the Record egulatory Co infocollects@ latory Affairs,	fed back to ind rds and FOIA ommission, Wa nrc.gov, and NEOB-10202	dustry. Send cor /Privacy Service ashington, DC 2 to the Desk Offi , (3150-0104), C	nments rega Branch (T- 0555-0001, c cer, Office o Office of Mana	rding burden 5 F52), U.S. or by internet f Information agement and
		(See r digit	everse ts/chara	for required	d nun ach b	nber of lock)			Budget, W collection not condu informatio	Vashington, does not disp uct or spons n collection.	DC 20503. If blay a currently sor, and a pe	a means used to valid OMB cont rson is not req	to impose ar rol number, t uired to resp	i information he NRC may pond to, the
1. FACIL Calla	. ITY NA way P	ME lant Unit	t 1						2. DOCK 05	ет NUMB 5000 483	ER	3. PAGE 1	OF 13	3
4. TITLE Void	Found	d in Line	EM-02	:3-HCB – R	esidı	ual Heat	Remova	al Pumj	o "A" to	Safety Ir	njection P	umps		
5. E	VENT D	ATE	6.	LER NUMBEF	2	7. R	EPORT D	ATE		8.	OTHER FA	CILITIES INV	OLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILIT	YNAME			DOCKET	NUMBER
05	21	2008	2008	- 002 -	01	11	05	2009	FACILIT	Y NAME			DOCKET	NUMBER
9. OPER	ATING	MODE	11	. THIS REPO	RTIS	SUBMITT		UANT T	O THE R	EQUIREM	ENTS OF 10	CFR§: (Che	ck all that a	apply)
	1		□ 20.22 □ 20.22 □ 20.22 □ 20.22 □ 20.22	201(b) 201(d) 203(a)(1) 203(a)(2)(i)			20.2203(a) 20.2203(a) 20.2203(a) 50.36(c)(1)	(3)(i) (3)(ii) (4) (i)(A)] 50.73(a)] 50.73(a)] 50.73(a)] 50.73(a)	(2)(i)(C) (2)(ii)(A) (2)(ii)(B) (2)(iii)	∑ 50.7 □ 50.7 □ 50.7 □ 50.7	′3(a)(2)(vii) ′3(a)(2)(viii) ′3(a)(2)(viii) ′3(a)(2)(ix)()(A))(B) (A)
10. POW	'er le\ 100	/EL	☐ 20.22 ☐ 20.22 ☐ 20.22 ☐ 20.22 ☐ 20.22 ☐ 20.22 ☐ 20.22	203(a)(2)(ii) 203(a)(2)(iii) 203(a)(2)(iv) 203(a)(2)(v) 203(a)(2)(vi)			i0.36(c)(1) i0.36(c)(2) i0.46(a)(3) i0.73(a)(2) i0.73(a)(2)	(ii)(A))(ii))(i)(A))(i)(B)		50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a)	(2)(iv)(A) (2)(v)(A) (2)(v)(B) (2)(v)(C) (2)(v)(D)	☐ 50.7 ☐ 73.7 ☐ 73.7 ☐ OTH Spee or in	'3(a)(2)(x) '1(a)(4) '1(a)(5) IER sify in Abstra N <u>RC Form 3</u>	ict below 366A
					1	2. LICENS	SEE CONT	TACT FO	OR THIS	LER				
FACILITY N T.B. EI'	^{IAME} wood,	Supervi	sing En	igineer, Reç	gulato	ory Affaiı	rs and Li	icensin	g		TEI 57	23-676-647	ER (Include Are 9	∋a Code)
			13. COM	PLETE ONE	LINE	FOR EACI	Н СОМРО	NENT F	AILURE	DESCRIB	ED IN THIS	REPORT	<u>. </u>	
CAU	SE	SYSTEM	COMPO	NENT FACTI	IU- JRER	REPOR TO I	RTABLE EPIX	CA	AUSE	SYSTEM	COMPONEN	IT MANU- FACTUREF	REPC)RTABLE) EPIX
		14	. SUPPL	EMENTAL RE	EPOR [®]	T EXPECT	ſED			15. E	XPECTED	MONTH	DAY	YEAR
□ YE	S (If yes	s, complet	e 15. EXI	PECTED SUB	MISSI	ION DATE	9		NO	SUB [
ABSTRA	CT (Lin	nit to 1400	spaces,	i.e., approxima	ately 1	5 single-s	paced type	ewritten	lines)					
On N	Aav 2	1.2008	. Calla	way plant	perse	onnel di	iscovere	ed a vo	oid in p	iping be	etween a	residual he	eat remo	val

On May 21, 2008, Callaway plant personnel discovered a void in piping between a residual heat removal heat exchanger and common suction header for the safety injection pumps (SIPs). The void had existed in the piping since restoration of maintenance on a relief valve on May 5, 2007. The void was found during ultrasonic testing of the piping to verify that the emergency core cooling system (ECCS) was full of water. Review of work history determined the cause of the void was improper filling and venting of the piping. The void was removed by venting the piping on May 21, 2008.

This piping where the void was located is used during the recirculation phase of a loss of coolant accident (LOCA), but not during the injection phase of a LOCA. A conservative evaluation of the potential effects of the void determined that the void could have degraded the performance of either both SIPs or both Centrifugal Charging Pumps during the recirculation phase. It was thus conservatively determined that the ECCS was inoperable with the presence of the void, thus constituting an operation or condition prohibited by the Technical Specifications, as well as a condition that could have prevented fulfillment of a safety function.

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	L	ER NUMBER (6)		PAGE (3)
Callaway Plant Unit 1		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
	05000483	2008	- 002 ·	• 01	2	OF	1
RATIVE (If more space is required, use addition	al copies of NRC Form 366	A) (17)					
I. DESCRIPTION OF THE REPO	ORTABLE EVENT						
A. REPORTABLE EVENT CL/	ASSIFICATION						
Evaluation of the condition	addressed by this L	FR determ	ined that the	condition	n is rei	ortable	ב
per the following criteria:				condition			0
10CFR50.73(a)(2)(i)(B)	– Operation or Con	dition Prol	nibited by Te	echnical S	pecifi	cations	
10CFR50.73(a)(2)(v)(B	B) - Event or Condition	on That C	ould Have P	revented	Fulfill	ment of	f a
Safety Function Needed	to Remove Residua	al Heat					
10CFR50.73(a)(2)(v)(D) – Event or Conditi	ion That C	ould Have F	revented	Fulfill	ment of	f a
Safety Function Needed	d to Mitigate the Cor	sequences	of an Accid	lent			
10CFR50.73(a)(2)(vii) -	- Common Cause In	operability	of Independ	dent Train	s or C	hannels	S
B. PLANT OPERATING CONI	DITIONS PRIOR TO	THE EVE	NT				
The plant was in MODE 1 a	at 100% power at the	e time the	condition wa	as discove	ered.		
C. STATUS OF STRUCTURE	S, SYSTEMS OR C	OMPONE	NTS THAT	WERE IN	OPER	ABLE	
AT THE START OF THE E	VENT AND THAT C	ONTRIBL	ITED TO TH	IE EVENT	-		
The event described in this	report is the discover	ry of a voi	d in a soctio	n of omor	aanau	ooro	
cooling system (ECCS) pin	ing that is required t	o be full o	f water for r	naintainin	geney a the I	ECCS	
in a standby operable status	during nlant operat	ion The a	ffected nine	section is	nart c	f the	
safety injection nump 'A/B	' common suction h	eader from	the "A" res	idual heat	remov	val hea	t
exchanger discharge As di	iscussed in the Narra	tive Sumn	nary of the F	Event sect	ion be	low the	e
void was introduced during	maintenance on the	safety inie	ection (SI)	EIIS syste	m: BC)]	C
system during Refuel Outag	pe 15 but was unkno	wingly not	t removed d	uring the f	ill and	l vent	
procedure completed prior	to restart from that o	utage. Th	e SI system	was not re	equire	to be	
operable at the time the voi	d was created and le	ft in place.			1		
		י רווחואים ד			/IN/AT	F	
TIMES						L	
NOTE: A listing of some of	f the terms used in th	is License	e Event Rep	ort (LER)	is pro	vided	
NOTE. A fisting of some of	t the terms used in th						
in section V, ADDITIONAL	L INFORMATION,	of this repo	ort.				
in section V, ADDITIONAL BACKGROUND:	L INFORMATION,	of this repo	ort.				
BACKGROUND:	INFORMATION,	of this repo	ort.	three core	roto		

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMISS (1-2001) LICENSEE EVENT REPORT (LER)	SION							
FACILITY NAME (1)	DOCKET (2) NUMBER (2)		LER N	IUMBER (6	5)		PAGE (3))
Callaway Plant Unit 1	05000483	YEAR 2008	SE -	EQUENTIAL NUMBER 002	REVISION NUMBER	4	OF	13
NARRATIVE (If more space is required, use additional copies	of NRC Form 366	A) (17)					01	
use of vent valve EMV0179. Altho OTN-EM-00001) was used and ide final filling and venting of the syst the outage.	ough an estab entified in the em was perfor	lished fill work doc rmed for	l-and cume syste	-vent pro ents, it ap em restor	ocedure (ppears that ration prio	lant pr an ina r to res	ocedur dequate tart fro	e e m
For restart from Refuel 15, the plan Subsequently, the plant entered MO 8, 2007 at 1010. The plant remain commenced October 10, 2008 at 22 the plant is in MODES 1, 2, or 3.	nt entered MC ODE 2 on Ma ed in MODE 300. As noted	DE 3 fro y 8, 2007 l until sh l above, b	om M ' at 04 utdov ooth 1	ODE 4 of 412, and wn for R trains of	on May 5, then MO lefuel 16 v ECCS are	2007 a DE 1 o vhich e requir	at 1805 on May red whe	en
During Operating Cycle 16, in resp Operating Experience, Callaway de Emergency Core Cooling System (implementing this plan, line EM-02 'A' During ECCS Recirculation (a exchanger to the SIPs), was found This exceeded the allowable void v documents for this section of pipin declared INOPERABLE pursuant entered into the Equipment Out of at valve EMV0179, SI Pump 'A' f at 2050 on May 21, 2008.	conse to NRC eveloped and (ECCS) was fr 23-HCB-6", S lso known as to contain a v volume of 2.10 g. At 1430, P to Technical S Service Log (rom RHR 'A'	Generic 1 implement ill of wat IP 'A/B' the "pigg oid appro 5 cubic f EM01A, pecificat EOSL) as HX Suct	Lette nted a cer. C Con cybac oxima feet a Safe ion 3 s EO cion V	er 2008-0 a plan to On May nmon Su k" line f ately 6.6 as specif ety Inject S.5.2.A. SL 1573 Vent, and	01 and Wo verify tha 21, 2008, action Hea from the '2 cubic fee ied in plan tion Pump This cond 31. The lin d declared	olf Cree at the while der fro A' RHI t in vol at engir 'A', w lition w he was OPER	m RHR R heat ume. neering vas vas vented ABLE	Ł
Based on a review of work history determined to be caused by inadeq work was done on that part of the s	performed on uate filling an system, which	the affec d venting was duri	cted s g of tl .ng R	system, t he system efuel 15	he discovo n followii	ered vo ng the l	oid was last time	e
NUREG 1022 requires clarification In this case, the event occurred on relief valve EM8858A. The void w the system was performed at that the 2008.	n of the event May 5, 2007, was introduced ime. The void	date if it when the l into the l was sub	is dif SI s pipin seque	fferent fr ystem w ng when ently dis	rom the di as restore the filling covered o	scover d from g and v n May	y date. work c enting 21,	on of
After discovery of the void, Amerer reportable. However, a notice of v report the event in accordance with Revision 0 of this LER for the con- condition constituted a condition p per 10CFR50.73(a)(2)(i)(B) as wel 0 of this LER, it was then identifie	enUE initially iolation was s 10CFR50.73 dition discove rohibited by t ll as 10CFR50 d that the even	determin ubsequer (a)(1). A red on M he Techn 0.73(a)(2) nt/conditi	and the ntly is Amero lay 2 ical S (vii). on ac	at the ev ssued to enUE the 1, 2008 of Specifica Follow ddressed	vent/condi Callaway erefore su on the bas ations and ving subm by this L	tion wa for fai bmitted is that was re ittal of ER sho	as not lure to d the portabl Revisio puld hav	le on ve

	FACILITY NAME (1)	NUMBER (2)	L	ER NU	JMBER (6)			PAGE (3)
	Callaway Plant Unit 1		YEAR	N	UMBER	NUMBER			
	-	05000483	2008	-	002 -	01	5	OF	13
ARR	ATIVE (If more space is required, use additional copie	es of NRC Form 366	4) (17)						
	 also been reported as one that country thus proposed a severity level 4 not the condition as a Safety System I submitted to additionally report the fulfillment of a safety function ne of an accident, pursuant to 10CFF E. METHOD OF DISCOVERY OF E PROCEDURAL ERROR The void was discovered while performed by the performance of the	Id have preven on-cited violati Functional Fail the subject even eded to remove S50.73(a)(2)(v) EACH COMPC erforming ultra	ted fulfillr on of 10C ure. Revis t/condition e residual l (B) and 10 NENT, SY	ment FR5(sion 1 n as c heat a)CFR (STE	of a saf 0.73(a)(1 of this one that and miti 350.73(a M FAIL check f	ety functi 2)(v) for LER is t could hav igate the c a)(2)(v)(D URE, OR	on. The not rep herefor ye prev consequent (), resp	ne NRC orting re ented uences ectivel EM-02	у. 23-
II.	The cause analysis of the event de EMV0179 to vent the associated I EVENT DRIVEN INFORMATION A. SAFETY SYSTEMS THAT RESP Not applicable for this issue.	etermined that a line, was the ro PONDED	a procedur ot cause o	e erro	or, i.e., void.	not using	valve		
	B. DURATION OF SAFETY SYSTE Although engineering judgment s System (ECCS) remained capable has been conservatively determine inoperable with respect to the requ condition could have prevented fu when the plant entered MODE 3 (time when the void was removed	EM INOPERAB upports a deter e of meeting the ed that the pres uirements of th ilfillment of a s (i.e., at 1805 or by venting at 2	ILITY mination t e ECCS ac ence of the e Technica afety func May 5, 20 050 on Ma	hat the tage of ta	he Emer ance cri d cause ecificat This c at the e 1, 2008.	rgency Co teria of 10 d the syst ions and t ondition e nd of Ref	ore Coo OCFR5 em to b hat the existed uel 15	oling 0.46, i be from until th	t ne
	C. SAFETY CONSEQUENCES AN A detailed risk assessment of the I corrective action system. The risk frequency (i.e. delta CDF) due to significance threshold of 1E-6 per	D IMPLICATIC EM-023-HCB- k assessment do this issue was f year. Therefo	ONS OF TH 6" void iss etermined 7E-8 per y re, this iss	HE E sue is that t rear, v sue w	VENT. s docum the incre which is vas deter	nented in t ease in co s well belo mined to	the plan re dam ow the be of y	nt's age risk- ⁄ery lo	W

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LE	ER NUMBER (6)		PAGE (3
Colloway Plant Unit 1		YEAR	SEQUENTIAL NUMBER	. REVISION NUMBER		
Canaway Plant Unit 1	05000483	2008	- 002	- 01	6	OF
(If more space is required, use addition	al copies of NRC Form 366,	4) (17)				
risk significance.						
With respect to a determinis of meeting the ECCS accept EM-023-HCB-6". At the sa conclusion that both trains o subsystem was inoperable. O requirements were not met a function. A complete evaluation	tic evaluation, it may tance criteria of 10Cl ame time, a conservat of one ECCS subsyste On this basis, it has b and that the condition ation, in which all the	be conclu FR50.46, d ive evalua em were po been deterr n could hav ree phases	ided that the espite the tion of the otentially a nined that of post-LC	the ECCS re voiding ide condition I ffected to t the associa d fulfillme DCA ECCS	emained entified leads to the extented TS ent of a S operat	d capal in line the ent that safety tion are
high-head injection function components must operate to refueling water storage tank required to deliver flow from RCS cold legs during the co piggyback alignment. In add via the RHR pumps to the R SIPs and CCPs are normally receipt of a safety injection (of the ECCS, respect provide borated wat (RWST) during the n the containment real ld leg recirculation n dition, the SIPs delive CS hot legs during the in standby operation (SI) signal.	ctively. Ther to the re ECCS injection circulation node of EC rer flow from the hot leg mand are re	tese pumps eactor coola sumps via CCS, common the contre- recirculatic equired to s	and their r ant system e. These p the RHR p nonly know tainment re on mode of start autom	respect (RCS) umps a pumps /n as th ecircula ECCS natically	ive sys from t re also to the e tion su tion su . The y upon
Injection Phase For the injection phase of an 023-HCB-6" would not be to are isolated by the EMHV88 downstream isolation valves	n accident, it has been ransported to any of 807A and B valves (1 8) which would prevent porce to transport the	n determine the ECCS residual he ent any sign	ed that the pump sucti at exchang nificant flo to the CCI	void identi ions. The j er 'A' to S w through Ps or SIPs of	ified in piggyba I pump this pij during ECCS to	line E ack lin suctio ping. the perfo
Therefore, with no motive for injection phase, the presence satisfactorily for the injectio	e of the void had no i on phase in response	impact on t to an accid	the capabilitent (LOCA	ity of the E A).		

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER	R NUMBER (6)			PAGE (3)
Callaway Plant Unit 1		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
	05000483	2008 -	002 -	01	7	OF	
(If more space is required, use additional	copies of NRC Form 366/	A) (17)					
(It more space is required, use additional transportation of the void wou the RHR pump/heat exchange the SIPs), to the SIP suction li HCB-6"), and then to the CCF performing their design safety The size of the void that could 5% void fraction, assuming the to each pump. The 5% void fraction for the second for the to each pump. The 5% void fraction for the to each pump. The 5% void fraction for the to each pump. The 5% void fraction for the to each pump. The 5% void fraction for the to each pump. The 5% void fraction for the to each pump. The 5% void fraction for the to each pump. The 5% void fraction for the to each pump. The 5% void fraction for the to each pump. The 5% void fraction for the to each pump. The size of the void that could be the to each pump. Th	copies of NRC Form 366 ald be established fr er, through EJHV88 ines, through the pi Ps. This flowpath c function because t l be swept into each the void was divided fraction is the current ect to what the pum the SIPs. (This is in a plant procedure ES	a) (17) rom the cont 304B (residu ggyback line could potent: the void cou h of the purch evenly enor nt acceptance p(s) can han COPs, the RH accordance v	tainment re ial heat ren es (EM-02 ially rende ild be trans up suctions ugh for tra- ce criterion ndle without HR 'A' pur with the sec	ecirculation noval train 2-HCB-6 r both CC ported int would be nsport of provided ut causing np may b quential a	on sum n 'B' s " and l CPs inc to both e in exe a large by the g the p e align	ap, thro supply to EM-02: capable a CCPs. cess of e fraction e pump ump(s) ned first ent of th	
and then to the SIPs. The start of a large fraction to a large fraction to the sign safety of the void that could be seen going into each SIP (a port of a large fraction to a long the adversely affect CPs by the discharge preduce of the 'A' RHR pumperains of RHR were align upps are aligned sequent to the CCPs and SIPs.)	pperate during the re ed from the contain n EJHV8804A, to the his flowpath could y function since the swept into the pum assuming, again, the both pumps). e noted that the void cted both CCPs and essure of the 'B' RH p. (The void would hed for the recircula tially and thus not a	-1.3.) In this ecirculation ment recircu- he CCP suct potentially r void could p suctions co at the void v d that was for l both SIPs. HR pump or d not be tran at the same t	s case, or i phase, a fl ulation sun tion lines, t render both be transpor ould be in was divided pund in the The void pushed to asported to at the same time for pro	n the even ow path f np, through through the SIPs inca- rted into be excess of d evenly e "piggy ba would eith the SIPs in any of the time, but oviding a	nt of a for tran the pigg apable both Sl a 5% enough ack" p her be by the e ECC t per th suctio	failure asportat RHR gyback of IPs. Th void a for iping pushed dischat S pump he EOP n flow	le le ltc ss s,
e 'B' RHR train to start or o the void could be established imp/heat exchanger, through hes, and then to the SIPs. The erforming their design safety ze of the void that could be se action going into each SIP (a ansport of a large fraction to ased on the above, it may be build not have adversely affect e CCPs by the discharge pre essure of the 'A' RHR pump oth trains of RHR were align e pumps are aligned sequent ath to the CCPs and SIPs.) espite the loss of an individu	perate during the re- ed from the contain n EJHV8804A, to the is flowpath could y function since the swept into the pum assuming, again, the both pumps). e noted that the void ceted both CCPs and essure of the 'B' RH p. (The void would need for the recircula tially and thus not a nal subsystem (i.e., its acceptance crite	-1.3.) In this ecirculation ment recircu- he CCP suct potentially r void could p suctions co- at the void v d that was for both SIPs. HR pump or d not be tran- at the same t the CCPs or eria, but not	s case, or i phase, a fl ulation sun tion lines, t render both be transpor ould be in was divided ound in the The void pushed to asported to at the same time for pro-	n the even ow path f np, through th SIPs inca- rted into t excess of d evenly e "piggy ba would eit the SIPs inca- any of the time, but oviding a , the ECC g its inten	nt of a for transformer the share pigg apable both SI a 5% enough ack" p her be by the e ECC t per the suction	failure sportat RHR gyback of IPs. Th void n for iping pushed dischar S pump n flow	ic o ic l l l l l l
the 'B' RHR train to start or o of the void could be established ump/heat exchanger, through nes, and then to the SIPs. The erforming their design safety ize of the void that could be se caction going into each SIP (a cansport of a large fraction to assed on the above, it may be ould not have adversely affect the CCPs by the discharge pre- ressure of the 'A' RHR pump oth trains of RHR were align the pumps are aligned sequent ath to the CCPs and SIPs.) Despite the loss of an individu- ave been capable of meeting afety function. The ECCS has cceptance criteria are met fol haximum fuel element claddi	perate during the re ed from the contain n EJHV8804A, to the his flowpath could y function since the swept into the pum assuming, again, the both pumps). e noted that the void cted both CCPs and essure of the 'B' RH p. (The void would hed for the recirculation tially and thus not a hall subsystem (i.e., its acceptance critica as a safety function llowing a postulated ng temperature is <	-1.3.) In this ecirculation ment recircu- he CCP suct potentially r void could p suctions co at the void v d that was for l both SIPs. HR pump or d not be tran at the same t the CCPs or eria, but not of ensuring d Loss of Co ≤ 2200 °F, 2	s case, or i phase, a fl ulation sun tion lines, t render both be transpor ould be in was divided bund in the The void pushed to asported to at the same time for pro- r the SIPs), performing the follow polant Acc.) maximum	n the even ow path f np, through through the SIPs inca- rted into be excess of d evenly of "piggy ba would eith the SIPs in any of the time, but oviding a , the ECC g its inten ving 10CF ident (LO n cladding	nt of a for transformer the share pigg apable both Sl a 5% enough ack" p her be by the e ECC t per th suction CS wounded de FR50.4 (CA): g oxida	failure asportat RHR gyback of IPs. Th void a for iping pushed dischar S pump e EOP a flow Ild still esign 6 1) ation is	e lt gsss,
the 'B' RHR train to start or o of the void could be established pump/heat exchanger, through lines, and then to the SIPs. The performing their design safety size of the void that could be so fraction going into each SIP (a transport of a large fraction to Based on the above, it may be could not have adversely affect the CCPs by the discharge pre- pressure of the 'A' RHR pump both trains of RHR were align the pumps are aligned sequent path to the CCPs and SIPs.) Despite the loss of an individu- have been capable of meeting safety function. The ECCS has acceptance criteria are met fol maximum fuel element cladding the a zirconium water reaction is <u>set</u>	perate during the re- ed from the contain n EJHV8804A, to the his flowpath could y function since the swept into the pum assuming, again, the both pumps). Is noted that the void ceted both CCPs and essure of the 'B' RH p. (The void would hed for the recirculation tially and thus not a hal subsystem (i.e., its acceptance crite as a safety function llowing a postulated ng temperature is \leq hickness before oxistical subsystem (i.e., its acceptance critericulation in the subsystem (i.e., its acceptance critericulation in the subsystem (i.e., its acceptance critericulation is a safety function in the subsystem (i.e., its acceptance critericulation is a safety function in the subsystem (i.e., its acceptance critericulation is a safety function in the subsystem (i.e., its acceptance critericulation is a safety function in the subsystem (i.e., its acceptance critericulation is a safety function in the subsystem (i.e., its acceptance critericulation is a safety function in the subsystem (i.e., its acceptance critericulation) is a safety function in the subsystem (i.e., its acceptance critericulation) is a safety function in the subsystem (i.e., its acceptance critericulation) is a safety function in the subsystem (i.e., its acceptance critericulation) is a safety function in the subsystem (i.e., its acceptance critericulation) is a safety function in the subsystem (i.e., its acceptance critericulation) is a safety function in the subsystem (i.e., its acceptance critericulation) is a safety function in the subsystem (i.e., its acceptance critericulation) is a safety function in the subsystem (i.e., its acceptance critericulation) is a safety function in the subsystem (i.e., its acceptance critericulation) is a safety function in the subsystem (i.e., its acceptance critericulation) is a safety function in the subsystem (i.e., its acceptance critericulation) is a safety function in the subsystem (i.e., its acceptance critericulation) is a safety function in the subsystem (i.e., its acceptance critericulation) is a safety	-1.3.) In this ecirculation ment recircu- he CCP suct potentially r void could p suctions co- at the void v d that was for l both SIPs. HR pump or d not be tran at the same t the CCPs of eria, but not of ensuring d Loss of Co- $\leq 2200 \ ^{\circ}F, 2$ idation, 3) n pothetical a	s case, or i phase, a fl ulation sun tion lines, t render both be transpor ould be in was divided bund in the The void pushed to asported to at the same time for pro- r the SIPs), performing the follow colant Acca) maximum h mount gen	n the even ow path f np, through the SIPs inca- rted into b excess of d evenly e "piggy ba- would eith the SIPs in any of the time, but oviding a , the ECC g its inten ving 10CF ident (LO n cladding ydrogen g erated if a	nt of a for transformer the share pigg apable both Sl a 5% enough ack" p her be by the e ECC t per th suction CS wounded de FR50.4 (CA): g oxida genera all of t	failure asportat RHR gyback of IPs. Th void a for iping pushed dischar S pump e EOP a flow Ild still esign 6 1) ation fro he meta	$\begin{array}{c} \text{ne} \\ 1 \text{ gs} \\ \text{s}, \\ \text{s}$

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMIS	SION							
FACILITY NAME (1)	DOCKET (2) NUMBER (2)				6)		PAGE (?	3)
		YEAR	SE		REVISION		<u></u>	-)
Callaway Plant Unit 1	05000483	2008	-	002	- 01	8	OF	13
NARRATIVE (If more space is required, use additional copie	s of NRC Form 366	A) (17)						
cooling capability is maintained.								
The potential impact of the void o	n the recircula	tion phase	e, i.e	., for th	e ECCS de	cay he	at rem	oval
function, was further evaluated, as	s supported by	Callaway	/ calc	culation	BN-16. T	he eva	luatior	n, as
summarized below, took into cons	ideration the l	arge brea	k LC	DCA and	d small bre	ak LO	CA .	
scenarios. For each case, the shor	test time possi	ble for en	try 1	nto the	recirculatio	on phas	se (pig	gу
required to be met by the ECCS at	t the onset of t	l represen	it the	n phase	um decay	neat to	ad	
required to be met by the LEES at	. the offset of th		nano	in phase	·•			
For a design basis large bre	ak LOCA (LB	LOCA).	the R	RCS wor	uld be at si	ich a lo	ow	
pressure that all three sets o	of pumps (RHF	R pumps,	SIPs	, and/or	CCPs) wo	ould be	capab	le of
supplying water to the RCS	. Assuming fu	ill flow fr	om a	all six E	CCS pump	os as w	ell as t	the
two Containment Spray pur	nps, (since the	RHR put	mps,	SIPs, C	CCPs, and	Contai	nment	
Spray pumps could all be op	perating during	g the injec	ction	phase of	of a LBLO	CA), tl	he	
approximate drain-down tir	ne of the RWS	T would	be 11	2.5 min	utes, or 75	0 seco	nds per	r
Case 1 of calculation BN-10	6, Rev. 1. Afte	er that, tir	ne w	ould be	required f	or oper	rators t	to
manually align the ECCS in	ito piggyback	alignment	t. Ba	ased on 40 scale	the timing	of sce	narios	
and SIPs into piggyback ali	annont At th	ia point in	ast Z	$40 \sec 0$	nus to tun	y angn		LPS nds
and SIFS into piggyback an	low demand fo	is point ii r providi	n uni n σ ac	le, I.e., a Jeanate	core decay	v heat r	emova	
would be no more than appr	roximately 72	5 gnm D	ing at	the rar	vid depress	urizati	on of t	he
RCS following a LBLOCA	this flowrate	is canable	e of l	being de	elivered by	one R	HR nu	mp
two CCPs, or two SIPs. Th	erefore. the re	auired flo	w ra	te to me	eet decav h	eat plu	110 pu 18 20%	imp,
(per the plant's design basis	s) would have	been prov	vided	l such th	at the ECO	CS rem	ained	
capable of satisfying the EC	CCS acceptanc	e criteria	of 10	OCFR50).46 for the	cold-l	leg	
recirculation phase following	ng a LBLOCA						U	
For a design basis small bre	eak LOCA (SB	SLOCA),	the F	RCS wo	uld remain	at an e	elevate	ed
pressure such that only the	SIPs and/or the	e CCPs w	ould	be cap	able of inje	ecting i	into the	e
RCS during the initial stage	s of the cold le	eg recircu	latio	n phase	of an acci	dent. ((The	
Containment Spray pumps	would not be r	unning si	nce t	the pres	sure in the	contai	nment	
building would not reach th	e Containmen	t Spray A	ctua	tion Sig	nal pressu	re setpo	oint of	27
psig following a SBLOCA.) Assuming th	at the SII	Ps an	d the C	CPs would	draw	down t	the
RWST water volume during	g the injection	phase, the	e mi	nimum	injection-p	hase ti	me bef	tore
switchover and piggyback a	ingnment wou	id be at le	east]	130 min	utes, or 78	UU sec	onds.	
Per calculation BN-16, the	RWST has a v	olume of	235,	597 gal	lons availa	ble for	r inject	ion
phase. The flowrates, noted	1 in BN-16, wi	th both C	CPs	and SIF	Ps running	would	be 962	2
gpm for the CCPs and 828	gpm for the SI	Ps. With	an a	vailable	e injection	volum	e of	
235,597 gallons and a drain	down flowrate	e of 1790	gpm	(CCPs	' flowrate j	plus SI	Ps'	

FACILITY NAME (1)	NUMBER (2)	LER	NUMBER (6)		Р	AGE (3)
Callaway Plant Unit 1	05000483	YEAR 2008 -	SEQUENTIAL NUMBER 002 -	REVISION NUMBER 01	9	OF
E (If more space is required, use additional c	opies of NRC Form 366	A) (17)				
minutes into the acciden before piggyback alignn alignment at 130 minute injection flow needed in gpm. (7000 seconds sub capable of being provide the gas void would bind configuration, adequate decay heat plus 20%. The acceptance criteria of 10	t. Additional time nent would be comes to the RCS to rem portical decay time d by either one C both SIPs or both flow would be pro- he ECCS would the OCFR50.46 for the	e (minimum ppleted. Con s) after onse ove decay h e requires 4 CP or one S CCPs upon ovided from herefore still cold-leg rec	240 second nservativel et of the acc eat plus 20 14.8 gpm.) IP. Thus, of alignment the unaffed be capable circulation	ds) would y assumin cident, the 0% would This amo even if it i in the pig cted pump e of satisfy phase foll	be require require be less bunt of s assun gyback os to rer ying the owing	uired yback ed than 4 flow i ned that move t e ECC a
Hot Leg Recirculation Phase Per the Callaway EOPs for bot cold leg recirculation, operator recirculation. Although hot leg RHR pumps providing suction switchover to cold leg recircula head so that the RHR pumps m supported by Callaway's emerg depressurizing the RCS. The H rapidly as possible following a support use of the RHR pumps	h small and large is s are required to p g recirculation can to the SIP), it can ation, the RCS is c hay be used for (or gency operating pu EOPs direct operat	LOCAs, this erform the a be establish be reasonable lepressurized to support) rocedures w	rteen hours actions nec- ned with or oly assume d to below hot leg rec hich provid lown and c	after the essary to s the SIP (wi d that at 1 the RHR circulation de guidance lepressuriz	switch switch t th one o 3 hours pump s . This ce for ze the F	over to to hot l or both after hutoff is RCS as
concluded that the presence of hot leg recirculation capability	to provide flow d the void in the EC following a LOC.	me hot leg r irectly to the CCS piggy b A.	ecirculatio e RCS hot ack piping	legs. It m would no	ed, the ay ther t have p	EOPs efore b preven
concluded that the presence of hot leg recirculation capability <u>Conclusion</u> In conclusion, despite the void meeting the ECCS acceptance the Technical Specifications for accommodate the various phas has been conservatively determ could have prevented fulfillme increase in core damage freque per year, thus confirming the v	LOCA. By the the to provide flow d the void in the EC following a LOCA identified in line I criteria of 10CFR: or having all three es of ECCS operanined that the present of a safety function for the true for the t	EM-023-HC 50.46. Neve of the noted tion for miti ence of the tion. Risk a F), due to the	ecirculatio e RCS hot ack piping CB-6", the l ertheless, a subsystem gation of a void consti assessment the identified is event.	ECCS was nd based on s availabl design-ba tuted a con determine d void cor	ed, the ay ther t have p s still ca on the i e to asis LO ndition ed that to adition	EOPs efore b preven apable ntent o CA, it that the was 71

Г

	DOCKET (2) NUMBER (2)	L			(6)		PAGE (3)
Callaway Plant Unit 1	-	YEAR	SE	EQUENTIA NUMBER	L REVISION NUMBER	-		
	05000483	2008	-	002	- 01	10	OF	1
If more space is required, use additional copie	of NRC Form 3664	A) (17)						
Limiting Condition for Operation 1, 2, and 3. With one train inopera Operable ECCS train available), O Action A.1 requires restoring the in Required Action and its associated Required Actions (B.1 and B.2) the within 6 hours and in Mode 4 with having two ECCS trains inoperable entered. Per LCO 3.0.3, action mo 7 hours, in Mode 4 within 13 hour As described earlier, LCO 3.5.2 re- corresponding to the high-head, in Based on how this LCO is structure inoperability of both trains of ECO discovered in the EM-023-HCB-6 if only for the recirculation phase to the determination that the prese Because the void was not known the removed prior to restart from Refu- requirements of LCO 3.5.2 and LO condition prohibited by the plant for Consistent with the above, the even 10CFR50.73(a)(2)(vii), i.e., as an independent trains to become inop- maintain it in a safe condition, rem- or mitigate consequences of an ac- void rendered both SIPs or both C inoperable.	of twe Form 3662 of TS 3.5.2 req ble (and at lea ondition A is r noperable train Completion T e plant must be in 12 hours. N e, so in the eve st be taken with and in Mode quires two train rermediate-heat ed, inoperabili S. Since it has d in operabili S. Since it has d in a ccident, nee of the void of an accident, nee of the void of exist for the t el 15 until it w CO 3.0.3 were to echnical Spect the is also requi- event where a se arable in a sing ove residual h ident. This is CPs inoperable	4) (17) quires both 1st 100% of required to 1 to Opera Time not r e placed in No Condit ent of such thin one h e 5 within as of each ad, and low ity of any s been con- l either bo a conserver l would have time from vas discovent ifications ired to be single care gle system heat, contre based on e, thus care	h EC of the co be able met, a a s tion h a c hour a 37 1 h of w-ho one onser oth S vative a ver the s reposed the s the cont the the the the the the the the the th	CCS tra le ECC entere status v Condit shutdow or Require condition to place hours. the three ead fun entire vativel IPs or b ve interp require en it w d on Ma condition pred put or condi- signed he relea conserving	ains to be C S flow equ d. Its asso- within 72 h tion B appl wn condition uired Actic on, LCO 3. the plant ee ECCS s actions to b subsystem y determin both CCPs pretation o d entry into as introduc as introduc as introduc as of radio value deter trains of or	perabl ivalent ciated i ours. ies, and on, i.e., on is sp 0.3 mu in Mo ubsyste e Oper is cons ed that inoper f LCO o LCO ced and 3, the re cons d at lea wn the active rminat	e in Mo to a sin Require With th d per its in Moc ecified st be de 3 wi ems able. sidered the voi able, ev 3.5.2 le 3.0.3. not stituted ast two reactor materia ion that ystem t	a an l, th

	FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LE	R NUMBER (6)		Р	AGE (3)
			YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		<u> </u>	<u> </u>
	Callaway Plant Unit 1	05000483	2008	- 002 -	01	11	OF	
RATI	IVE (If more space is required, use additional	l copies of NRC Form 366A	A) (17)					
	another subsystem.							
	Thus, although the ECCS ren 10CFR50.46 as described in S is also reportable under 10CF or condition that could have p heat and mitigate the consequ	nained capable of fu Section C of this LE (R50.73(a)(2)(v)(B) prevented fulfillmen pences of an acciden	lfilling the ER, it is con and 10CF t of a safet t, respectiv	ECCS acconservatively R50.73(a)(2 y function n yely.	eptance cr conclude 2)(v)(D), i needed to	iteria of d that th .e., as an remove	f his ev n ever resid	en nt ua
11.	CAUSE(S) OF THE EVENT	AND CORRECTIVE	<u>ACTION(</u>	<u>S)</u>				
	The investigation into why th procedure OTN-EM-00001, S point. This valve is needed to valve EMHV8807B, RHR H2 (Line EM-023-HCB-6").	e void was present of Safety Injection Sys o vent the section of X 'A' to SI PUMPS	determined tem, did no piping bet Suction D	that the fill of utilize values ween the 'A ownstream	l and vent lve EMV(A' SI Pum Isolation	section)179 as p suctio Valve V	of a ven on and /LV']	t 1 B'
	Revision 22 of procedure OT pipeline EM-023-HCB-6". C include EMV0179 as a vent l valve EMV0179 needed to be self-checking during the proc	N-EM-00001 did no consequently, all sub ocation. The procee included in OTN-F edure revision proce	ot include l osequent re dure writer EM-00001 ess.	EMV0179 a visions thro and review as a vent po	as a vent lo ough Revi vers did no oint due to	ocation sion 27 ot identi o inadeq	for did n fy tha uate	ot t
	The inadequate procedure is a and reviewed OTN-EM-0000 ensure the adequacy of proce- of OTN-EM-00001. OSP-SA and Venting, has been revised in removing voids.	considered to be a fl 1 have been coache dure reviews. The s A-00003, Emergency 1 to include EMV01	awed defe d on the ne subject ven y Core Coc 79 and oth	nse. The in eed to self-c t was incor oling System er valves as	dividuals heck their porated vi n Flow Pa s vent loca	that rev r work a a Revis th Verif ations to	vised and to ion 28 fication assis	3 on st
	Procedure APA-ZZ-00101, P revised in November 2007 (R change in the procedure revie Technical Review missing or	rocessing Procedure evision 045) to require w and approval pro overlooking an esse	es, Manual uire an add cess will h ential detai	s, And Desl itional Tecl elp minimiz l.	ktop Instru nnical Rev ze the pos	actions, view. T sibility o	was his of one	e

	FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LE	R NUMBER (6)		PAGE	(3)
	Callaway Plant Unit 1		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		05000483	2008 ·	- 002 -	01	12 OF	1
RA	TIVE (If more space is required, use additional co	opies of NRC Form 366	A) (17)				
	inadequate fill and vent instruct contain fill and vent instruction to add fill and vent sections to t Also, Preventative Maintenance susceptible system piping is wa in this LER have been added to	tions. At that tim is. The corrective the appropriate E0 e actions (PMs) w iter solid, on a reg these PMs.	e, the norm action to p CCS norma rere develop gular freque	al operating revent recur l system op ped to verify ncy. The se	g procedua rrence for erating pr y that void ections of	res did not this trend cocedures. ding- pipe discu	was ssed
/.	ADDITIONAL INFORMATION						
	DESCRIPTION OF ITEMS MENT	IONED ABOVE:					
	OSP-SA-00003, Emergency Core surveillance procedure for verifyin OTN-EM-00001, Safety Injection safety injection system. EJHV8804A, a motor-operated va and the charging pump supply [sy- EJHV8804B, a motor-operated va the safety injection pump supply [EMV0179, a valve for venting the exchanger and the "A" safety inject EMHV8807A, a motor-operated va heat exchanger and the safety inject the mainstream piping [system: B4 EMHV8807B, a motor-operated va heat exchanger and the safety inject the mainstream piping [system: B4 EMHV8807B, a relief valve in the 'A PRESS RLF TO RHT) [system: B4 EM-023-HCB-6 inch – designatio heat exchanger and the 'A' safety	Cooling System 1 ng and venting the System – the pro- live in the pipe be stem: BP, compo- live in the pipe be system: BP, compo- e section of piping ction pump [syster valve in the pipe be ction pump suction Q, component: He calve in the pipe be ction pump suction Q, component: He calve in the pipe be ction pump suction Q, component: He calve in the section of piping be calve in the pipe be ction pump suction Q, component: He calve in the section of piping be calve in the pipe be component: He calve in the section of piping be calve in the pipe be component: He calve in the pipe be calve in the pip	Flow Path V e emergency cedure for r tween the ' nent: HCV] tween the ' ponent: HC between the m: BQ, cor etween the on downstre CV]. etween the on downstre CV]. pump sucti V]. of piping be	Verification y core cooli normal line A' residual B' residual V]. he 'A' residual vam isolation 'A' residual cam isolation con piping (features)	and Vent ng systen up and op heat remo heat remo ual heat remo l heat rem n valve. ' I heat ren n valve. ' SI PMP A A' residu	ting – the n flow path peration of t oval system oval system emoval system This valve This valve This valve A SUCT al heat rem	the n and n and nt m is in m is in
		injection pump.				1	

FACILITY NAME (1) Callaway Plant Unit 1	DOCKET (2) NUMBER (2)	LER NUMBER (6)				PAGE (3)			
		YEAR NUMBER			NUMBER				
	05000483	2008	-	002	-	01	13	OF	1
TIVE (If more space is required, use additiona	l copies of NRC Form 3664) (17)							
RHR Heat Exchanger [system:]	BP, component: HX].							
RWST, Refueling Water Storage	e Tank [system: BP	compo	nent:	TK].					
SI pump, Safety Injection Pump	– intermediate head	pump. i	oart o	f the E	Emer	gency C	ore C	ooling	
System [system: BQ, componen	t: P]	P				Benej e		001112	

r