



**Entergy Nuclear South**  
Entergy Operations, Inc.  
17265 River Road  
Killona, LA 70057-3093  
Tel 504 739 6715  
Fax 504 739 6698  
rmurill@entergy.com

**Robert J. Murillo**  
Licensing Manager  
Waterford 3

W3F1-2009-0071

December 16, 2009

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555-0001

Subject: Licensee Event Report 09-005-00  
Waterford Steam Electric Station, Unit 3 (Waterford 3)  
Docket No. 50-382  
License No. NPF-38

Dear Sir or Madam:

Entergy is hereby submitting Licensee Event Report (LER) 09-005-00 for Waterford Steam Electric Station Unit 3. This report provides the details concerning a manual reactor trip and automatic engineered safety feature actuation of emergency feedwater subsequent to the spurious opening of a moisture separator heater relief valve. The condition is reported herein pursuant to 10CFR50.73(a)(2)(iv)(A).

This report contains no new commitments. Please contact Robert J. Murillo at (504) 739-6715 if you have questions regarding this information.

Sincerely,

 For R. Murillo

RJM/WJS

Attachment: Licensee Event Report 09-005-00

1E22  
NRR

(w/Attachment)  
cc: Mr. Elmo E. Collins, Jr.  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV  
612 E. Lamar Blvd., Suite 400  
Arlington, TX 76011-4125

NRC Senior Resident Inspector  
Waterford Steam Electric Station Unit 3  
P.O. Box 822  
Killona, LA 70066-0751

U. S. Nuclear Regulatory Commission  
Attn: Mr. N. Kalyanam  
Mail Stop O-07D1  
Washington, DC 20555-0001

Wise, Carter, Child & Caraway  
ATTN: J. Smith  
P.O. Box 651  
Jackson, MS 39205

Winston & Strawn  
ATTN: N.S. Reynolds  
1700 K Street, NW  
Washington, DC 20006-3817

Morgan, Lewis & Bockius LLP  
ATTN: T.C. Poindexter  
1111 Pennsylvania Avenue, NW  
Washington, DC 20004

Louisiana Department of Environmental Quality  
Office of Environmental Compliance  
Surveillance Division  
P. O. Box 4312  
Baton Rouge, LA 70821-4312

R.K. West, lerevents@inpo.org - INPO Records Center

**Attachment**

**W3F1-2009-0071**

**Licensee Event Report 09-005-00**

<b>NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION</b> (9-2007)				<b>APPROVED BY OMB NO. 3150-0104</b> Estimated burden per response to comply with this mandatory information collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to: bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.				<b>EXPIRES 8/31/2010</b>			
<b>LICENSEE EVENT REPORT (LER)</b> (See reverse for required number of digits/characters for each block)											
1. FACILITY NAME					2. DOCKET NUMBER			3. PAGE			
Waterford 3 Steam Electric Station, Unit 3					05000382			1 OF 4			
4. TITLE											
Spurious Moisture Separator Reheater Relief Valve Opening Resulting in a Manual Reactor Trip and an Engineering Safety Feature Actuation (Emergency Feedwater Actuation)											
5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER	
10	19	2009	2009	05	00	12	16	2009	NA	05000	
									FACILITY NAME	DOCKET NUMBER	
									NA	05000	
9. OPERATING MODE			11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)								
1			<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)					
			<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)					
			<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)					
			<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)					
			<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(x)					
			<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)					
			<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)					
			<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER					
10. POWER LEVEL			Specify in Abstract below or in NRC Form 366A								
100%			<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)						
12. LICENSEE CONTACT FOR THIS LER											
FACILITY NAME						TELEPHONE NUMBER (Include Area Code)					
Waterford 3 Steam Electric Station, Robert J. Murillo						(504) 739-6715					
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX		
B	SB	RV	Crosby Valves & Gage Co.	Y							
14. SUPPLEMENTAL REPORT EXPECTED					15. EXPECTED SUBMISSION DATE		MONTH	DAY	YEAR		
<input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO											
<b>ABSTRACT</b> (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)											
<p>On October 19, 2009, at approximately 09:44 with the plant operating at 100% power (Mode 1), Waterford 3 manually tripped the reactor due to lowering condenser hotwell level caused by a stuck open moisture separator reheater relief valve. The Plant Protection System (PPS) responded as designed, resulting in an uncomplicated reactor trip. Subsequently, Emergency Feedwater Actuation Signals (EFAS-1 and EFAS-2) were received due to low Steam Generator (SG) levels which is an anticipated response to the reactor trip with the plant at or near full power. The emergency feedwater system did not receive a signal to send water to the steam generators. The plant was then maintained in Mode 3 with both steam generators being fed from the main feedwater system with steam generator levels in the normal operational band for Mode 3. Failure Mode Analysis (FMA) identified a broken pilot valve spring on the stuck open moisture separator heater relief valve. The pilot valve spring was replaced on all six moisture separator heater relief valves prior to unit restart. Adequate water level was maintained in the steam generators to ensure decay heat removal from the Reactor Coolant System (RCS). The event is not considered a safety system functional failure. The event did not compromise the health and safety of the general public.</p>											

(9-2007)

# **LICENSEE EVENT REPORT (LER) CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Waterford 3 Steam Electric Station	05000382	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 4
		2009	- 005	- 00	

**NARRATIVE****REPORTABLE OCCURRENCE**

On October 19, 2009 at 09:44, Waterford 3 manually tripped the reactor due to lowering condenser hotwell level caused by a stuck open reheat system [SB] moisture separator reheater (MSR) relief valve [RV] (RS-203B). Subsequently, Emergency Feedwater Actuation Signals (EFAS-1 and EFAS-2) were received due to low Steam Generator (SG) levels actuating the Emergency Feedwater (EFW) System [BA]. The condition was reported to the NRC Operations Center within four hours. The event was reportable within four hours under criteria 10CFR50.72(b)(2)(iv)(B) for a manual reactor trip of the plant to preclude receiving an automatic Reactor Protection System (RPS) [JC] trip while the reactor was critical. Additionally, the event was reportable within eight hours under criteria 10CFR50.72(b)(3)(iv) for the automatic actuation of EFAS upon low Steam Generator levels. The manual reactor trip is reportable in writing (Licensee Event Report) within 60 days in accordance with 10CFR50.73(a)(2)(iv)(A) due to the manual actuation of the RPS and due to the automatic actuation of the Emergency Feedwater system.

**INITIAL CONDITIONS**

Just prior to the initiating events, the plant was operating in Mode 1 at 100% power. There were no procedures being implemented specific to this condition. There were no Technical Specification Limiting Conditions of Operation specific to this condition in effect.

**BACKGROUND**

Waterford 3 has two MSRs. The purpose of the MSRs are to remove the moisture and to reheat the steam from the high pressure turbine [TRB] exhaust to the low pressure turbine inlet. Each MSR is provided with overpressure protection by three pilot-operated relief valves mounted on top of the shell. These relief valves discharge to atmosphere at approximately 250 psig to prevent damage to the MSR shell. The design pressure of the shell is 265 psig.

With the stuck open moisture separator relief valve (RS-203B) open, the calculated flow rate based on hotwell level loss was 2500 GPM. The maximum makeup rate to the condenser hotwell through the makeup line is approximately 1250 gpm.

**EVENT DESCRIPTION**

On October 19, 2009 at 09:15, while operating at 100% power moisture separator reheater relief valve, RS-203B, spuriously opened causing reactor power to increase from 100% to 100.27% Rated Thermal Power (RTP). At 09:16, operations promptly reduced main turbine generator load to restore reactor power to less than 100% RTP. At 09:17 hotwell emergency makeup valve (CMU-715) opened. At approximately 09:42, operations commenced a rapid plant shutdown. At 09:44, operations manually tripped the reactor due to lowering condenser hotwell level and entered OP-902-000 (Standard Post Trip Actions). Emergency Feedwater actuation signals EFAS-1 and EFAS-2 automatically initiated due to low Steam Generator levels, an anticipated response to the reactor trip with the plant at or near full power. Steam was isolated to the MSRs. The inventory loss through the open relief valve stopped and hotwell level recovered. The plant was maintained in Mode 3 with both Steam Generators being fed from the non-safety main feedwater [SJ] system with steam generator levels in the normal operational band for Mode 3. The EFAS actuation signals were reset. Following the event, a post trip review was performed.

(9-2007)

# **LICENSEE EVENT REPORT (LER) CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Waterford 3 Steam Electric Station	05000382	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 4
		2009	- 005	- 00	

**NARRATIVE****CAUSAL FACTORS**

Results of condition investigations and failure modes analysis conclude that the most likely cause of the condition was a broken pilot valve spring in RS-203B. When the pilot valve spring fractured, the pressure load on the main valve disc was lost and the main valve spring opened RS-203B.

The pilot valve spring fracture appeared to be due to a high speed (single load) brittle fracture. Based on metallurgical analysis performed, the spring material became brittle while in service. This was caused by a problem during the manufacturing process. The failed spring was in service 3 years prior to failure.

**CORRECTIVE ACTIONS**

The carbon steel pilot springs in all six MSR relief valves were replaced with stainless steel springs during refueling outage 16.

**SAFETY SIGNIFICANCE**

The plant remained within safety limits throughout the event. The condition did not prevent the fulfillment of any safety function and did not result in a safety system functional failure (i.e. ability to shut down the reactor and maintain it in a safe shutdown condition, ability to remove residual heat, ability to control the release of radioactive material, and ability to mitigate the consequences of an accident) as defined by 10CFR50.73(a)(2)(v). The only engineered safety feature actuations were emergency feedwater actuation signals EFAS-1 and EFAS-2, which automatically initiated due to low steam generator levels. This is an anticipated response to the reactor trip with the plant at or near full power. Main feedwater maintained SG water level above the setpoint at which EFW control valves open; therefore, no injection of EFW occurred during the event.

Operations manually tripped the reactor which caused a turbine trip and steam to be isolated to the MSRs. There were no structures, systems, or components that were inoperable at the time of the event that contributed to this condition. Since engineered safety features actuated as required, and considering that primary system parameters were maintained within acceptable limits, the safety significance of this event is considered minimal.

(9-2007)

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Waterford 3 Steam Electric Station	05000382	2009	- 005	- 00	4 OF 4

**NARRATIVE****SIMILAR EVENTS**

A search was performed for other similar reported events at Waterford 3. No similar events were identified.

**ADDITIONAL INFORMATION**

Energy industry identification system (EIIIS) codes are identified in the text within brackets [ ].