


Carl L. Newman
Vice President

Regulatory Docket File

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N. Y. 10003
Telephone (212) 460-5133



August 26, 1975

RE: Indian Point Unit No. 2
Docket No. 50-247



Mr. Karl Goller
Assistant Director for Operating
Reactors
Division of Reactor Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Goller:

In accordance with the requirements of the Directorate of Licensing letter of November 8, 1973, Con Edison herewith submits the results of inspections of hydraulic snubbers installed in Indian Point Unit No. 2. The unit was shut down on July 28, 1975 and resumed power operation on August 10, 1975. Inspection of all snubbers was completed by July 31 1975.

Very truly yours,

Carl L. Newman
Vice President

mp

Copy to: Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
King of Prussia, PA 19406

8111110887 750826
PDR ADOCK 05000247
Q PDR

9161

Results of Inspection of Hydraulic Snubbers
Installed at Indian Point Unit No. 2
August 10, 1975

8-26-75

Bergen-Paterson Snubbers:

1. Located Inside Containment.

Date of Inspection: Completed July 31, 1975

Number of Snubbers Installed: 303

Seal Material: All ethylene-propylene

No. of Snubbers Inspected: All snubbers.

Results

Six snubbers had indications of significant leakage.
All units were in operable condition.

Corrective Action

Two of the leaking snubbers were replaced with refurbished units containing ethylene-propylene seals. Four snubbers were repaired by tightening fittings.

2. Located in PAB and Conventional Plant.

Date of Inspection: Completed July 31, 1975

Number of Snubbers Installed: 153

Seal Material: Millable gum - 88
(following
replacement) Ethylene-Propylene - 65

No. of Snubbers Inspected: All snubbers.

Results

One snubber had indications of significant leakage. All units were in operable condition.

Corrective Action:

Twenty-eight snubbers including the unit with indications of leakage were replaced with units employing ethylene-propylene seals.

Snubbers Supplied by Other Manufacturers (Grinnell):

1. Location Inside Containment (inaccessible during reactor operation).

Date of Inspection: Completed July 31, 1975

No. of Oil Reservoirs Installed: 8

No. of Oil Reservoirs Inspected: 8

Seal Material: Not applicable

Results:

Insignificant leakage was noted in several cases.

Corrective Action

Where necessary, oil reservoirs were filled to normal level.

2. Located Outside Containment.

No Grinnell snubbers are located outside the containment.