

Carl L. Newman  
Vice President

*Files*

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N. Y. 10003  
Telephone (212) 460-5133

August 6, 1976

RE: Indian Point Unit No. 2  
Docket No. 50-247  
Facility Operating License  
No. DPR-26

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement, Region 1  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following confirms the telephone notification to you on August 5, 1976 of Reportable Occurrence No. 76-2-13(A). The occurrence is the type defined by Regulatory Guide 1.16, Revision 4, Section C.2.a(8).

We have been advised by Westinghouse Electric Corporation that they have identified a generic error in the non-conservative direction in their Emergency Core Cooling System (ECCS) analyses for compliance with the Final Acceptance Criteria (FAC) of Appendix K to 10CFR Part 50. Westinghouse has determined that the analytical effect of error correction results in higher calculated peak clad temperatures for most Westinghouse plants. Initial review has demonstrated that for Indian Point Unit No. 2, sufficient margin to the maximum allowable peak clad temperature still exists even with the additional correction factor. At the present time, Westinghouse is performing a more detailed evaluation, and results of this review will be transmitted in the required 14-day report for this reportable occurrence.

Very truly yours,

*Carl L. Newman*

Carl L. Newman  
Vice President

mp

Copy to: Director of Nuclear Reactor Regulation  
ATTN: Mr. William G. McDonald, Director (2)  
Office of Management Information  
and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8111070632 760806  
PDR ADOCK 05000247  
S PDR

*T*