




Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003

July 26, 1974

Re: Indian Point Unit No. 2
AEC Docket No. 50-247
A.O. 4-2-22

Mr. James P. O'Reilly, Director
Directorate of Regulatory Operations
Region 1
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406



Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, we wish to inform you of an Abnormal Occurrence (A.O. 4-2-22), which was identified and reported to Mr. Anthony Fasano of your office on July 25, 1974.

The occurrence is the type defined by Technical Specification 1.8.a, where a protective instrumentation setting was found in excess of a limiting safety system setting established in the Technical Specifications.

The incident occurred during the performance of periodic test, PT-M11, "Steam Line Pressure Analog Channel Functional Test".

The "as found" setting on low pressure bistable PC-449A was found to be 581 psig instead of the required equal to or greater than 600 psig. The bistable, which is part of a two out of four logic associated with high steam flow safety injection actuation, was immediately reset and tested satisfactorily.

At the time of the occurrence, the reactor was operating at approximately 96% of rated power.

A followup report on this occurrence will be submitted within ten days.

*R. W. Van Wye
for W. Stein*

8110240561 740726
PDR ADOCK 05000247
S PDR

cc/ John R. O'Leary

REGULATORY DOCKET FILE COPY

8053