



ATTACHMENT I

Docket No. 50-247

Consolidated Edison Co. of N.Y., Inc.

LER-78-012/03L-0

Indian Point Unit No. 2

On April 19, 1978, while at cold shutdown for refueling, a review of surveillance testing conducted during the ongoing refueling outage revealed that the lift setting of one of the three pressurizer safety valves (PCV-468) was found to be approximately 0.8% below its minimum allowable setting, as specified in Section 3.1.A.3.c of the Technical Specifications. This review had been initiated following receipt of Inspection Report 50-247/78-03, dated March 30, 1978, which provided revised guidelines for judging the reportability of certain events as Licensee Event Reports.

This event was discovered upon bench testing of the valve in question. Its setpoint was subsequently reset to within limits prior to its reinstallation. This event was attributed to setting drift.

The pressurizer relief valve is a 6" Crosby valve, Mfg. Assy. Dwg. H-51250. A similar event was reported as TEIR-77-2-3, on August 12, 1977.