

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N.Y. 10003
Telephone (212) 460-3819

REGULATORY DOCKET FILE COPY

March 9, 1978
Re: Indian Point Unit No. 2
Docket No. 50-247
R.O.-77-2-14(A)
Update Report

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406



Dear Mr. Grier

Transmitted herewith is an update report for Reportable Occurrence R.O.-77-2-14(A). Three copies of this letter and the attachment are enclosed as required.

Very truly yours,

A handwritten signature in cursive script that reads "William J. Cahill, Jr." The signature is written in dark ink and is positioned above the typed name and title.

William J. Cahill, Jr.
Vice President

Attach.

Copy to Director of Nuclear Reactor Regulation
ATTN: Dr. Ernst Volgenau, Director (40 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director of Nuclear Reactor Regulation
ATTN: Mr. William G. McDonald, Director (3 copies)
Office of Management Information and
Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

A002
S
111

8110310781 780309
PDR ADOCK 05000247
S PDR

780740028

LICENSEE EVENT REPORT

R.O. 7-2-14(A)

CONTROL BLOCK: 1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: N Y I P S 2; LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0; LICENSE TYPE: 4 1 1 1 1; EVENT TYPE: 0 1; CATEGORY: CONT; REPORT TYPE: T; REPORT SOURCE: L; DOCKET NUMBER: 0 5 0 - 0 2 4 7; EVENT DATE: 0 7 0 2 7 7; REPORT DATE: 0 3 0 9 7 8

EVENT DESCRIPTION

02; 03; 04 SEE ATTACHED SHEET; 05; 06

SYSTEM CODE: CB; CAUSE CODE: E; COMPONENT CODE: P U M P X X; PRIME COMPONENT SUPPLIER: N; COMPONENT MANUFACTURER: W 1 2 0; VIOLATION: Y

CAUSE DESCRIPTION

08; 09 SEE ATTACHED SHEET; 10

FACILITY STATUS: C; % POWER: 0 0 2; OTHER STATUS: NA; METHOD OF DISCOVERY: A; DISCOVERY DESCRIPTION: Control Room Instrumentation

FORM OF ACTIVITY RELEASED: Z; CONTENT OF RELEASE: Z; AMOUNT OF ACTIVITY: NA; LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

13; NUMBER: 0 0 0; TYPE: Z; DESCRIPTION: NA

PERSONNEL INJURIES

14; NUMBER: 0 0 0; DESCRIPTION: NA

PROBABLE CONSEQUENCES

15; NA

LOSS OR DAMAGE TO FACILITY

16; TYPE: L; DESCRIPTION: Failure of No. 23 Controlled Leakage Reactor Coolant Pump Seals

PUBLICITY

17; Press Release - July 5, 1977

ADDITIONAL FACTORS

18; NA

19

EVENT DESCRIPTION

While critical at approximately 2 percent power, control room alarms and instrumentation indicated a failure of the seal package of No. 23 reactor coolant pump. A resultant decrease in pressurizer level was compensated for by placing a second charging pump in service. A concurrent decrease in pressurizer pressure was also observed. No. 23 reactor coolant pump was tripped, and the reactor was shut down. A plant cooldown was initiated, and a containment entry confirmed the seal package failure. Leakage from the seal package continued until the plant was depressurized and drained down. Total leakage to containment was calculated to be approximately 90,000 gallons, with a maximum leak rate of approximately 75 GPM. No requirement for the initiation of safeguards actuation existed at any time during the incident.

Due to the need for an expeditious cooldown following the seal failure, the Technical Specification cooldown rate of 100°F/Hr was marginally exceeded for a brief period of time. A maximum cooldown rate of 105°F/Hr was recorded between 4:00 A.M. and 5:20 A.M. while the RCS pressure dropped from 2150 psi to 700 psi during the same time interval.

An analysis was performed to assess the effect of this increased cooldown rate on the brittle fracture and fatigue life strength of the reactor vessel. This analysis indicated that there was no adverse effect on the integrity of the reactor vessel as a result of the slight variation from the cooldown rate limit.

[R.O.-77-2-14(A)]

CAUSE DESCRIPTION

The cause of this event was a failure of the seal package of No. 23 Reactor Coolant Pump. (Westinghouse, Controlled Leakage Pump, Model V11002-A1).

Investigation of the failure did not determine a definite cause of the seal failure. However, it was concluded, based on inspections of the failed parts and various thermal and stress analysis, that the No. 1 seal suddenly lost its lubricating film and rubbed as a result of: (1) a large quantity of foreign particles greater than 10 microns in size clogged the seal, or (2) one or more large chips spontaneously spalled from one of the seal faces thus leading to immediate failure. The reactor coolant pump rotating element, including the seal package, was replaced with a spare assembly.