

LICENSEE EVENT REPORT

TEIR-77-2-2

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME:

01	N	Y	I	P	S	2
----	---	---	---	---	---	---

 LICENSE NUMBER:

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE:

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE:

9	9
---	---

REPORT TYPE:

0

 REPORT SOURCE:

L

 DOCKET NUMBER:

0	5	0	-	0	2	4	7
---	---	---	---	---	---	---	---

 EVENT DATE:

0	5	0	7	7	7
---	---	---	---	---	---

 REPORT DATE:

0	8	1	2	7	7
---	---	---	---	---	---

EVENT DESCRIPTION

02

 | _____ 80

03

 | SEE ATTACHED SHEET 80

04

 | _____ 80

05

 | _____ 80

06

 | _____ 80

SYSTEM CODE:

S	B
---	---

 CAUSE CODE:

E

 COMPONENT CODE:

X	X	X	X	X	X
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER:

N

 COMPONENT MANUFACTURER:

X	9	9	9
---	---	---	---

 VIOLATION:

N

CAUSE DESCRIPTION

08

 | _____ 80

09

 | SEE ATTACHED SHEET 80

10

 | _____ 80

FACILITY STATUS:

G

 % POWER:

0	0	0
---	---	---

 OTHER STATUS:

NA

 METHOD OF DISCOVERY:

B

 DISCOVERY DESCRIPTION:

Surveillance Testing

FORM OF ACTIVITY RELEASED:

Z

 CONTENT OF RELEASE:

Z

 AMOUNT OF ACTIVITY:

NA

 LOCATION OF RELEASE:

NA

PERSONNEL EXPOSURES

NUMBER:

0	0	0
---	---	---

 TYPE:

Z

 DESCRIPTION:

NA

PERSONNEL INJURIES

NUMBER:

0	0	0
---	---	---

 DESCRIPTION:

NA

PROBABLE CONSEQUENCES

15

 | NA 80

LOSS OR DAMAGE TO FACILITY

TYPE:

Z

 DESCRIPTION:

NA

PUBLICITY

17

 | NA 80

ADDITIONAL FACTORS

18

 | NA 80

8111040018 770812
PDR ADOCK 05000247
S PDR

19

 | _____ 80

NAME: John M. Makepeace PHONE: 914-739-8823

EVENT DESCRIPTION

FOR INFORMATION ONLY. During the performance of surveillance testing of the Safety Injection System at cold shutdown, all components of the safety injection system functioned as required with the following exceptions:

- 1) Service Water Pump No. 24 did not start as required.
- 2) Auxiliary Component Cooling Pump No. 22 did not start as required.
- 3) Valves TCV-1104 and TCV-1105 did not open as required. These valves provide cooling water to the fan cooler units during an actuation of the engineered safeguards systems.
- 4) Valve 822B did not open as required. This valve provides component cooling to No. 22 RHR Heat Exchanger.

For items 1,2 and 4 above, the redundant components functioned as required and the associated systems would have been operable. For item 3, both redundant valves are located outside containment and could have been opened manually to provide the necessary flow path. The components which did not function properly were repaired as necessary and retested satisfactorily.

(TEIR-77-2-2)

CAUSE DESCRIPTION

- 1) Service Water Pump No. 24 would not start automatically because its breaker (Westinghouse Type DB-50) had not been fully racked in from the position required by periodic testing the preceding day. The breaker was reset and the pump functioned as required.
- 2) Auxiliary Component Cooling Pump No. 22 would not start automatically because the contacts on its SI-20X relay (Westinghouse Type BFD-66 Multi-Contact Relay) were dirty. The contacts were cleaned and the relay was tested satisfactorily.
- 3) Valves TCV-1104 and TCV-1105 (18 inch, Associated Control Equip, air operated, 150 psig) failed to open as a result of binding of the valves' internals, most likely caused by a buildup of foreign material in the valves. The valves were subsequently freed up and tested satisfactorily.
- 4) Valve 822B would not open as a result of a torque switch contact not functioning properly. The torque switch (Limitorque Corporation, Size SMB-00/SMB-000) was replaced and tested satisfactorily.