



July 5, 1977

Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement, Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following report of Reportable Occurrence No. 77-2-14(A), confirms a telephone report to Mr. Robert Carlson of your office on July 2, 1977.

The occurrence is the type defined in Regulatory Guide 1.16, Revision 4, Section C.2.a(3).

On July 2, 1977, during low power (approximately 2%) operation, control room alarms and instrumentation indicated a failure of the seal package of No. 23 Reactor Coolant Pump. The pump was tripped and the reactor shut down. A containment entry was made which confirmed the seal package failure. The reactor coolant system was brought to the cold shutdown condition and drained in preparation for the necessary repair effort.

Very truly yours,

Eugene R. McGrath
Manager, Nuclear Power
Generation
Indian Point Station
Buchanan, N.Y. 10511

Copy to: Director, Office of Management Information
and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8111040035 770705
PDR ADOCK 05000247
S PDR

70
A