


William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

March 16, 1977
Re: Indian Point Unit No. 2
Docket No. 50-247
R.O.-77-2-3(B)

Regulatory Docket File

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406



Dear Mr. O'Reilly

Transmitted herewith is Reportable Occurrence report R.O.-77-2-3(B). Three copies of this letter and the attachment are enclosed as required.

Very truly yours,

A handwritten signature in cursive script, appearing to read 'William J. Cahill, Jr.'.

William J. Cahill, Jr.
Vice President

Attach.

Copy to Director of Nuclear Reactor Regulation
ATTN: Dr. Ernst Volgenau, Director (30 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director of Nuclear Reactor Regulation
ATTN: Mr. William G. McDonald, Director (3 copies)
Office of Management Information and
Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8111040509 770316
PDR ADOCK 05000247
S PDR

770810309

LICENSEE EVENT REPORT

R.O.-77-2-3(B)

(PLEASE PRINT ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1 2 3 4 5 6

LICENSEE NAME 01 N Y I P S 2	LICENSE NUMBER 0 0 - 0 0 0 0 0 - 0 0	LICENSE TYPE 4 1 1 1 1	EVENT TYPE 0 3
CATEGORY 01 CON T	REPORT TYPE L	REPORT SOURCE L	DOCKET NUMBER 0 5 0 - 0 2 4 7
EVENT DATE 0 2 1 4 7 7	REPORT DATE 0 3 1 6 7 7		

EVENT DESCRIPTION

02 During normal operation, service water pump No. 22, which was one of
03 three pumps lined up to supply the essential header, tripped out of
04 service automatically. Upon restart, the pump was found to have exces-
05 sive vibration. The pump was removed from service and the essential
06 header was valved over to Pump Nos. 24, 25 and 26 within the Tech. Spec.

SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07 W A	E	P U M P X X	N	B 3 5 0	N

CAUSE DESCRIPTION

08 The Morse/Borg-Warner Corp. pump bearings (Code Name - Marlin, Part No.
09 EO 3600) exhibited excessive wear resulting in high vibration of the
10 pump.

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11 E	0 7 6	NA	A	Supervisory Panel Instrumenta- tion
FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE	
12 Z	Z	NA	NA	

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
13 0 0 0	Z	NA

PERSONNEL INJURIES

NUMBER	DESCRIPTION
14 0 0 0	NA

PROBABLE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
16 Z	NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 (Event Desc. Cont.) - allowable time period. [R.O.-77-2-3(B)].

19

NAME: C. Limoges

PHONE: 914-739-8823