



Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, NY 10003

December 13, 1976

Re: Indian Point Unit No. 2  
Docket No. 50-247

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement, Region 1  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following report of Reportable Occurrence No. 76-2-24(A) confirms a telephone report to Mr. John Streeter of your office, this date.

The occurrence is the type defined by Regulatory Guide 1.16, Revision 4, Section C.2.a(2).

On December 12, 1976, it was discovered that reactor power had been increased above 50% power, although the indicated axial flux difference was outside its target band for more than two hours cumulative in the preceding 24 hour period. Upon discovery, reactor power was immediately reduced from 68% to below 50%, and was held there until the requirements of Technical Specification 3.10.2.7.2 were satisfied.

Very truly yours,

*Edward P. Kessig*  
Edward P. Kessig  
Acting Manager  
Nuclear Power Generation  
Indian Point Station  
Buchanan, New York 10511

Copy to: Director, Office of Management Information  
and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

8111040644 761213  
PDR ADOCK 05000247  
S PDR