


William J. Cahill, Jr.
Vice President

Regulatory

File Cya

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819



Re: Indian Point Unit No. 2
Docket No. 50-247
R.O. -76-2-20(A)


Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
King of Prussia, Penn. 19406

Dear Mr. O'Reilly:

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-26, the attached report of Reportable Occurrence R.O. -76-2-20(A) is submitted. This report fulfills the requirement for a written report within 14 days of a Reportable Occurrence and is in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Three copies of this letter and the attachment are enclosed as required.

Very truly yours,


William J. Cahill, Jr.
Vice President


enc.

Copy to: Director of Nuclear Reactor Regulation
ATTN: Dr. Ernst Volgenau, Director (40 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director of Nuclear Reactor Regulation
ATTN: Mr. William G. McDonald, Director (3 copies)
Office of Management Information and
Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8111040668 761108
PDR ADOCK 05000247
S PDR

11463



LICENSEE EVENT REPORT

R.O.-76-2-20(A)

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE			EVENT TYPE											
01	N	Y	I	P	S	2	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1		
7	8	9				14	15											25	26				30	31	32	
CONT		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE			REPORT DATE													
01				T	L	0	5	0	-	0	2	4	7	1	0	2	5	7	6	1	1	0	8	7	6	
7	8			57	58	59	60							61												80

EVENT DESCRIPTION

012 During normal operation, upon completion of a filling operation of the
013 refueling water storage tank, it was discovered that the contents of the
014 tank had been approximately 800 gallons below the minimum technical spe-
015 cification of 350,000 gallons, prior to the filling operation. The pre-
016 ceding filling of the RWST had been completed on October 20, 1976.

[R.O.-76-2-20(A)]

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION				
S	F	F		A	C	C	U	M	U	N	Z	9	9	9	Y	
7	8	9	10	11	12					17	43	44			47	48

CAUSE DESCRIPTION

017 Subsequent investigation of this event indicated an overall system leak-
018 age of approximately 0.75 GPM. To insure against recurrence of this
019 event, the frequency of filling operations of this tank has been increased.

FACILITY STATUS	% POWER	OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
E	1	0	0	NA	A	NA				
7	8	9	10	11	12	13	44	45	46	
FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
Z	Z	NA			NA					
7	8	9	10	11	12	13	44	45		

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION			
0	Z	NA			
7	8	9	11	12	13

PERSONNEL INJURIES

NUMBER	DESCRIPTION			
0	NA			
7	8	9	11	12

PROBABLE CONSEQUENCES

015 NA

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION		
Z	NA		
7	8	9	10

PUBLICITY

017 NA

ADDITIONAL FACTORS

018 This event was incorrectly reported in the prompt report as having

019 occurred on October 24, 1976.

NAME: Austin J. Decker II

PHONE: 914-739-8922