

LICENSEE EVENT REPORT

R.O.-77-2-6(B)

[PLEASE PRINT ALL REQUIRED INFORMATION]

CONTROL BLOCK: 1 2 3 4 5 6

LICENSEE NAME: 01 N Y I P S 2 14

LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 25

LICENSE TYPE: 4 1 1 1 1 30

EVENT TYPE: 0 3 32

REPORT TYPE: L 59

REPORT SOURCE: L 60

DOCKET NUMBER: 0 5 0 - 0 2 4 7 68

EVENT DATE: 0 3 1 5 7 7 74

REPORT DATE: 0 4 0 8 7 7 80

EVENT DESCRIPTION

02 7 8 9 During routine startup operations, a visual inspection revealed a leak

03 7 8 9 at a weld on the drain valve connection for No. 23 Charging Pump.

04 7 8 9 (Plant Designation C-12). The pump was shutdown and isolated to effect

05 7 8 9 the necessary repair. Similar events occurred on July 29, 1975,

06 7 8 9 February 1, 1977 and March 11, 1977. [R.O.-77-2-6(B)]

SYSTEM CODE: P C 10

CAUSE CODE: E 11

COMPONENT CODE: P I P E X X 17

PRIME COMPONENT SUPPLIER: N 43

COMPONENT MANUFACTURER: Z 9 9 9 44 47

VIOLATION: N 48

CAUSE DESCRIPTION

08 7 8 9 The weld leak was attributed to excessive vibration in the charging sys-

09 7 8 9 tem. A study of this problem is being conducted to determine what modi-

10 7 8 9 fications can be made to reduce the probability of recurrence.

FACILITY STATUS: C 9

% POWER: 0 0 0 10 12

OTHER STATUS: NA 13

METHOD OF DISCOVERY: B 45

DISCOVERY DESCRIPTION: Routine Inspection 46 80

FORM OF ACTIVITY RELEASED: Z 9

CONTENT OF RELEASE: Z 10

AMOUNT OF ACTIVITY: NA 11 44

LOCATION OF RELEASE: NA 45 80

PERSONNEL EXPOSURES

NUMBER: 0 0 0 7 8 9

TYPE: Z 12

DESCRIPTION: NA 13 80

PERSONNEL INJURIES

NUMBER: 0 0 0 7 8 9

DESCRIPTION: NA 12 80

PROBABLE CONSEQUENCES

15 7 8 9 NA

LOSS OR DAMAGE TO FACILITY

TYPE: Z 7 8 9

DESCRIPTION: NA 10 80

PUBLICITY

17 7 8 9 NA

ADDITIONAL FACTORS

18 7 8 9 NA

19 7 8 9 8111040726 770408 PDR ADOCK 05000247 S PDR 80

NAME: Austin J. Decker II

PHONE: 914-739-8823

RECEIVED DOCUMENT
PROCESSING UNIT

1977 APR 11 PM 1 51