

LICENSEE EVENT REPORT

R.O. -76-2-16(B)

CONTROL BLOCK:

| | | | | | |
|--|--|--|--|--|--|
| | | | | | |
|--|--|--|--|--|--|

PLEASE PRINT ALL REQUIRED INFORMATION

| L | I | C | E | E | N | L | N | L | T | Y | P | S | E | L | N | L | T | Y | P | S | E | | | | |
|---|---|---|---|---|---|---|----|----|---|---|---|---|---|---|---|---|---|----|----|---|---|---|----|----|----|
| 0 | 1 | N | Y | I | P | S | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 0 | 3 |
| 7 | 8 | 9 | | | | | 14 | 15 | | | | | | | | | | 25 | 26 | | | | 30 | 31 | 32 |

| L | I | C | E | E | N | L | N | L | T | Y | P | S | E | L | N | L | T | Y | P | S | E | | | | | | | | | | |
|---|---|---|---|---|---|----|----|----|----|----|---|---|---|---|---|---|----|----|---|---|---|---|---|---|---|---|---|---|---|--|--|
| 0 | 1 | C | O | N | T | | | L | L | 0 | 5 | 0 | - | 0 | 2 | 4 | 7 | 0 | 9 | 2 | 2 | 7 | 6 | 1 | 0 | 2 | 2 | 7 | 6 | | |
| 7 | 8 | | | | | 57 | 58 | 59 | 60 | 61 | | | | | | | 68 | 69 | | | | | | | | | | | | | |

EVENT DESCRIPTION

| | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|
| 0 | 2 | During startup physics testing, the amount of water in the condensate storage tank was reduced approximately 60,000 gallons below the minimum of 360,000 gallons required when the reactor is heated above 350°F. The condensate storage tank was filled to above the minimum within the required time limit of Technical Specification 3.4.B. (R.O.-76-2-16(B)) | | | | | | | | | | | | | | | | | | | | | | | |
| 7 | 8 | 9 | | | | | | | | | | | | | | | | | | | | | | | |

| S | Y | S | T | E | M | C | O | D | E | S | C | O | D | E | S | C | O | D | E | S | C | O | D | E | S | C | O | D | E | |
|---|---|---|----|----|----|---|---|---|---|---|----|----|----|---|---|----|----|---|---|---|---|---|---|---|---|---|---|---|---|--|
| 0 | 7 | H | H | F | A | C | C | U | M | U | N | C | 3 | 1 | 0 | N | | | | | | | | | | | | | | |
| 7 | 8 | 9 | 10 | 11 | 12 | | | | | | 17 | 43 | 44 | | | 47 | 48 | | | | | | | | | | | | | |

CAUSE DESCRIPTION

| | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---|---------|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|
| 0 | 8 | The reduction in the amount of water in the condensate storage tank below the minimum Technical Specification requirement was the result of a bleed and feed operation to limit and control the chloride concentration in the | | | | | | | | | | | | | | | | | | | | | | | |
| 7 | 8 | 9 | (cont.) | | | | | | | | | | | | | | | | | | | | | | |

| F | A | C | I | L | I | T | Y | P | S | E | L | N | L | T | Y | P | S | E | L | N | L | T | Y | P | S | E | | | | | |
|---|---|---|----|----|----|----|----|------------------------------|----|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|--|--|--|--|--|
| 1 | 1 | B | 0 | 0 | 2 | NA | A | Control Room Instrumentation | | | | | | | | | | | | | | | | | | | | | | | |
| 7 | 8 | 9 | 10 | 11 | 12 | 13 | 44 | 45 | 46 | | | | | | | | | | | | | | | | | | | | | | |

| F | A | C | I | L | T | Y | P | S | E | L | N | L | T | Y | P | S | E | |
|---|---|---|----|----|----|----|---|---|---|---|---|---|---|---|---|---|---|--|
| 1 | 2 | Z | Z | NA | NA | | | | | | | | | | | | | |
| 7 | 8 | 9 | 10 | 11 | 44 | 45 | | | | | | | | | | | | |

PERSONNEL EXPOSURES

| N | U | M | B | E | R | T | Y | D | E | S | C | O | N |
|---|---|---|----|----|----|----|---|---|---|---|---|---|---|
| 1 | 3 | 0 | 0 | 0 | Z | NA | | | | | | | |
| 7 | 8 | 9 | 11 | 12 | 13 | | | | | | | | |

PERSONNEL INJURIES

| N | U | M | B | E | R | T | Y | D | E | S | C | O | N |
|---|---|---|----|----|----|---|---|---|---|---|---|---|---|
| 1 | 4 | 0 | 0 | 0 | NA | | | | | | | | |
| 7 | 8 | 9 | 11 | 12 | | | | | | | | | |

PROBABLE CONSEQUENCES

| | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|----|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|
| 1 | 5 | NA | | | | | | | | | | | | | | | | | | | | | | | |
| 7 | 8 | 9 | | | | | | | | | | | | | | | | | | | | | | | |

LOSS OR DAMAGE TO FACILITY

| T | Y | P | S | E | L | N | L | T | Y | P | S | E |
|---|---|---|----|---|---|---|---|---|---|---|---|---|
| 1 | 6 | Z | NA | | | | | | | | | |
| 7 | 8 | 9 | 10 | | | | | | | | | |

PUBLICITY

| | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|----|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|
| 1 | 7 | NA | | | | | | | | | | | | | | | | | | | | | | | |
| 7 | 8 | 9 | | | | | | | | | | | | | | | | | | | | | | | |

ADDITIONAL FACTORS (Cause Desc. Cont.):

| | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|
| 1 | 8 | secondary side of the steam generators. The excessive chloride experienced in the secondary water was due to main condenser tube leakage. | | | | | | | | | | | | | | | | | | | | | | | |
| 7 | 8 | 9 | | | | | | | | | | | | | | | | | | | | | | | |