



Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003

October 24, 1975

Re: Indian Point Unit No. 2
AEC Docket No. 50-247

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement, Region 1
U. S. Nuclear-Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following report of Abnormal Occurrence No. 75-2-24(A) confirms the telephone report to Mr. Paul Kellogg of your office on October 24, 1975.

The occurrence is the type defined by Regulatory Guide 1.16, Revision 3, Section C.2.a(9). 52

During the conduct of Periodic Surveillance Test PT-SA1 on October 23, 1975, it was found that the pressure drop across the demister and HEPA filter for one of four Fan Cooler Units tested (No. 24) was slightly higher (5.2 inches of water) than that allowed (5.0 inches of water) by Technical Specifications. On Monday, we will notify you of the results of the test for the one fan cooler unit which has not yet been tested. At the time of the occurrence, Unit No. 2 was in the cold shutdown condition for an outage which began on October 16, 1975.

Very truly yours,

Walter Stein

Walter Stein, Manager
Nuclear Power Generation
Indian Point Station
Buchanan, New York 10511

Copy to: Mr. Donald F. Knuth

8111090206 751024
PDR ADOCK 05000247
S PDR