



Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003

November 15, 1974

Regulatory

File Cy.

Re: Indian Point Unit No. 2
AEC Docket No. 50-247
A.O. 4-2-35

Mr. Edson G. Case, Acting Director
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D.C. 20545



Dear Mr. Case:

In accordance with the requirements of the Technical Specifications to Facility Operation License DPR-26, the attached report of an Abnormal Occurrence is submitted.

Walter Stein

Walter Stein, Manager
Nuclear Power Generation

Copy to: Mr. James P. O'Reilly
Regulatory Operations



8111090372 741115
PDR ADOCK 05000247
S PDR

11848

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 11848

FILE: _____

FROM: Consolidated Edison Co. Irving Place, N.y. Walter Stein		DATE OF DOC 11-15-74	DATE REC'D 11-20-74	LTR xxxxx	TWX	RPT	OTHER
TO: Mr. Edson G. Case		ORIG 1-signed	CC	OTHER	SENT AEC PDR <u>xxxxxxxxxx</u>		
					SENT LOCAL PDR <u>xxxxxxx</u>		
CLASS	UNCLASS xxxxxxx	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-247		

DESCRIPTION:

Ltr Trans the Following:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME:

Indian Point #2

ENCLOSURES:

Abnormal Occurrence #4-2-35 on 11-5-74 concerning the refueling water storage tank containing less than 350,000 gallons of water = as required by the Tech-Specs.....

93

FOR ACTION/INFORMATION

11-22-74

JGB

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u> AEC PDR OGC, ROOM P-506A MUNTZING/STAFF CASE GIAMBUSSO BOYD MOORE (L) (BWR) DEYOUNG (L) (PWR) SKOVHOLT (L) GOLLER (L) P. COLLINS DENISE REG OPR FILE & REGION (3) MORRIS STEELE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA VOLIMER	<u>DENTON</u> GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> DIGGS (L) GEARIN (L) GOULBOURNE (L) KREUTZER (E) LEE (L) MAIGRET (L) REED (E) SERVICE (L) SHEPPARD (L) SLATER (E) SMITH (L) TEETS (L) WILLIAMS (E) WILSON (L)	<u>A/T IND</u> BRAITMAN SALTZMAN B. HURT <u>PLANS</u> MCDONALD CHAPMAN DUBE w/input E. COUPE D. THOMPSON (2) KLECKER EISENHUT
---	--	--	---	--

EXTERNAL DISTRIBUTION

AD JK

1 - LOCAL PDR Montrose, NY	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - ASLB (E/W Bldg, Rm 529)	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - W. PENNINGTON, Rm E-201 GT	1 - G. ULRIKSON, ORNL
1 - ASLB	1 - B&M SWINEBROAD, Rm E-201 GT	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson	1 - CONSULTANTS	1 - R. D. MUELLER, Rm E-201 GT
1 - ACRS	NEWMARK/BLUME/AGBABIAN	

SENT to Lic Asst
T E E T

1. Report Number: 50-247/4-2-35
- 2a. Report Date: November 15, 1974
- 2b. Occurrence Date: November 5, 1974
3. Facility: Indian Point Unit No. 2
4. Identification of Occurrence:

This abnormal occurrence was the type identified by Technical Specification 1.8.b and relates to finding the refueling water storage tank containing less than 350,000 gallons of water as required by Specification 3.3.A.1.a.

5. Conditions Prior to Occurrence:

Prior to the occurrence, Unit No. 2 was operating at approximately 47% of rated power.

6. Description of Occurrence:

On November 5, 1974, following a filling operation of the refueling water storage tank, it was determined that the amount of water initially contained in the tank had been 3,600 gallons less than required.

7. Designation of Apparent Cause of Occurrence:

The refueling water storage tank is being filled routinely twice a week to make up for leakage and filling accumulators. These regular fillings have resulted in the addition of between approximately 1,400 and 2,200 gallons each time water was added. On November 5, 1974, however, 8,000 gallons was indicated to have been necessary to fill the refueling water storage tank.

8. Analysis of Occurrence:

Our review of this occurrence indicates that the safety implications are not significant.

Although the refueling water storage tank contained 3,600 gallons less than that required by the Technical Specifications, it did contain over 16,000 gallons more than indicated necessary by the accident analysis.

9. Corrective Action:

Upon completion of the filling operation, the refueling water storage tank level was at a point where the quantity of water was above the Technical Specification limit.

A review of the refueling water storage tank inventory requirements, usage, and level indication system has been completed. Based on the results of this review, a proposed Technical Specification change which would require a lower quantity of water in the tank, is presently being prepared for submittal to the AEC. This change would therefore increase the allowable operating band.

10. Failure Data:

Not Applicable

11. Notification:

An initial report of this occurrence was provided the Region 1 Regulatory Operations Office on November 6, 1974, followed by facsimile letter dated the same day.