

DEC 1 5 2009

10CFR50.73

LR-N09- 0287

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington DC 20555-001

> LER 311/09-002 Salem Nuclear Generating Station Unit 2 Facility Operating License No. DPR-75 NRC Docket No. 50-311

SUBJECT: 22 Component Cooling Heat Exchanger Inoperable for Greater Than Allowed Outage Time

This Licensee Event Report, "22 Component Cooling Heat Exchanger Inoperable for Greater Than Allowed Outage Time," is being submitted pursuant to the requirements of the Code of Federal Regulations 10CFR50.73 (a)(2)(i)(B), "any operation ... prohibited by the plant's Technical Specification."

The attached LER contains no commitments. Should you have any questions or comments regarding this submittal, please contact Mr. Brian Thomas at 856-339-2022.

Sincerely,

Robert Braun Site Vice President - Salem

Attachments (1)

IE22 NRR СС

Mr. S. Collins, Administrator, Region I, NRC

Mr. R. Ennis, Licensing Project Manager - Salem, NRC

Mr. D. Schroeder, USNRC Senior Resident Inspector, Salem (X24)

Mr. P. Mulligan, Manager IV, NJBNE

L. Marabella, Corporate Commitment Tracking Coordinator

H. Berrick, Salem Commitment Tracking Coordinator

NRC FOR	M 366			U.S	. NUCLE	AR RE	GULATOR	YCOMMI	SSION	APPROV	ED BY OMB:	NO. 3150	-0104		EXPIRES: (08/31/2010
LICENSEE EVENT REPORT (LER)							Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52). U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.									
1. FACIL	1. FACILITY NAME							2. DOCI		TNUMBER 3. PAGE						
Sal	em Ge	eneratir	ng Stat	ion	- Unit :	2				0	5000311				1 of 5	
4. TITLE 22 Component Cooling Heat Exchanger Inoperable for Greater Than Allowed Outage Time																
5. E	VENT D	ATE	6. LER NUMBER			7. REPORT DATE				8.	OTHER I	FACIL	ITIES INVO	LVED		
MONTH	DAY	YEAR	YEAR	SEQI NU	JENTIAL MBER	REV NO.	MONTH	DAY	YEA	FACILITY NAME			DOCKET N		UMBER	
10	17	2009	2009	0	0 2	0	12	15	200	9						UMBER
9. OPER	9. OPERATING MODE 11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)															
6 10. power level 0			□ 20.2201(b) □ 20.2201(d) □ 20.2203(a)(1) □ 20.2203(a)(2)(i) □ 20.2203(a)(2)(ii) □ 20.2203(a)(2)(iii) □ 20.2203(a)(2)(iii) □ 20.2203(a)(2)(iii) □ 20.2203(a)(2)(iv) □ 20.2203(a)(2)(v)			 20.2203(a)(3)(i) 20.2203(a)(3)(ii) 20.2203(a)(4) 50.36(c)(1)(i)(A) 50.36(c)(1)(ii)(A) 50.36(c)(2) 50.46(a)(3)(ii) 50.73(a)(2)(i)(A) 		 ☐ 50.73(a)(2)(i)(C) ☐ 50.73(a)(2)(ii)(A) ☐ 50.73(a)(2)(ii)(B) ☐ 50.73(a)(2)(iii) ☐ 50.73(a)(2)(iv)(A) ☐ 50.73(a)(2)(v)(A) ☐ 50.73(a)(2)(v)(B) ☐ 50.73(a)(2)(v)(C). 			 50.73(a)(2)(vii) 50.73(a)(2)(viii)(A) 50.73(a)(2)(viii)(B) 50.73(a)(2)(ix)(A) 50.73(a)(2)(ix)(A) 50.73(a)(2)(x) 73.71(a)(4) 73.71(a)(5) OTHER 		(A) (B) A)			
	□ 20.2203(a)(2)(vi)															
FACILITY N	AME		······			1	Z. LICENS	JEE CON	IACII				TELEF	HONE NUMBE	R (Include Are	a Code)
Brian Thomas													(856) 339 -2022			
			13. CON	IPLE	TE ONE	LINE	FOR EAC	НСОМРС	NENT	FAILUR	DESCRIB	ED IN TH	IIS RE	PORT		
CAUSE SYSTEM COMPONENT MANU- FACTURER TO EPIX								CAUSE	SYSTEM	SYSTEM COMPONENT MANU- FACTURER TO		RTABLE EPIX				
. 🗡	(BS	v	/	P3	40		Y								
	S (If ye	14 s, complet	I. SUPPL e 15. EX	PECT	NTAL R	EPOR BMISS	T EXPEC	TED	(15. E SUB	XPECTE MISSION DATE	D N	MONTH	DAY	YEAR
ABSTRA On sys MC res Ex clo Sp tha	ACT (Lin Octob Stem (F DDE O Sidual h change sed. A ecifica in 23 fe	nit to 1400 per 17, 2 RCS) ter PS TES neat rem er (HX) s At 0603, tion 3.9. eet abov	spaces, 009 at mperatu TING 2 toval (R service the CR 8.2 wa ye the r	i.e., a 0538 ure fa 2A V RHR) wate S en s en eact	approxim B hours ollowin ITAL B and co er outle ntered tered a or flang	ately 1 5, con g per US." ompo et valv the al t 060 ge. A	<i>ts single-s</i> trol roon formanc The co nent coo ve 22SW bnormal 3 hours At 0658 I	paced typ n operative of secontrol roo oling (CC /356 ges operatin for less hours, th	ewritter cors no ction 5 com su C) sys arbox ng pro than 2 che 228	n lines) oted an .3 of pro- perviso tem wh had rot becedure 2 trains SW356	abnormal ocedure S r (CRS) di ich identif ated caus for comp of RHR o valve was	increas 2.OP-S rected a ied that ing the onent c perable secure	se in ST.SS a wa t the valv oolin e and ed in	reactor co SP-0002, ' Ik down o 22 CC He e to go pa g. Techni I water lev position to	oolant 'SEC f the at rtially cal el less o preven	

the valve from going closed any further. At 0753 hours, operators verified the ability of the 22 CC HX to provide adequate core cooling by adjusting the RHR HX outlet control valve. RCS temperature reduced from 125.6 °F to 124.5 °F. At 0818 hours, 3000 gpm of service water flow was established to the 21 CC HX and a RCS temperature decrease was observed. At 1004 hours, 9000 gpm of flow was established to the 21 CC HX. At 1017 hours, TS 3.9.8.2 was exited.

The causes of this event were installation of the wrong material mounting bolts and incorrect torque values. Corrective actions consist of replacement of the valve and gearbox using proper mounting bolts, procedure changes, roll-outs to appropriate personnel, and generation of preventive maintenance tasks.

This report is being made in accordance with 10CFR50.73 (a)(2)(i)(B), "any operation ... prohibited by the plant's Technical Specification."

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET		6. LER NUMBEI	ર	3.	PAGI	E
Salem Generating Station Unit 2	05000311	YEAR			2	of	5

NARRATIVE

PLANT AND SYSTEM IDENTIFICATION

Westinghouse - Pressurized Water Reactor (PWR/4)

Component Cooling Water System {CC/-} Service Water System {BS/-}

* Energy Industry Identification System {EIIS} codes and component function identifier codes appear as {SS/CCC}

IDENTIFICATION OF OCCURRENCE

Event Date: October 17, 2009

Discovery Date: October 17, 2009

CONDITIONS PRIOR TO OCCURRENCE

Salem Unit 2 was in Operational Mode 6 during the seventeenth (2R17) refueling outage with both loops of Residual Heat Removal (RHR) being cooled by the 22 Component Cooling (CC) heat exchanger (HX). The 21 CCHX was removed from service as a result of planned maintenance activities.

DESCRIPTION OF OCCURRENCE

On October 17, 2009, at 0538 hours control room operators noted an abnormal increase in reactor coolant system (RCS) temperature following performance of section 5.3 of procedure S2.OP-ST.SSP-0002, "SEC MODE OPS TESTING 2A VITAL BUS." The control room supervisor (CRS) directed a walk down of the RHR and CC system for abnormalities. Salem Unit 2 was in Mode 6 with both loops of RHR being cooled by the 22 CC HX {CC/HX}. The field walk down identified that the 22 CC HX service water outlet valve 22SW356 {BS/V} gearbox had rotated causing the valve to go partially closed. At 0603, the CRS entered the abnormal operating procedure for component cooling. Technical Specification 3.9.8.2 was entered at 0603 hours for less than 2 trains of RHR operable and water level less than 23 feet above the reactor flange (the reactor head was de-tensioned). At 0615 hours, the CRS entered the abnormal procedure for RHR and directed restoration of the 21 CC HX. At 0658 hours, the 22SW356 valve was secured in position to prevent the valve from going closed any further. Service water flow through the 22 CC HX was approximately 3400 gpm. At 0747 hours, filling and venting of the 21 CC HX was complete. At 0753 hours, operators verified the ability of the 22 CC HX to provide adequate core cooling by adjusting the RHR HX outlet control valve. RCS temperature reduced from 125.6 °F to 124.5 °F. At 0818 hours, 3000 gpm of service water flow was established to the 21 CC HX and a RCS temperature decrease was observed. The abnormal operating procedures were exited at 0846 hours with the restoration of the 21 CC HX. At 1004 hours, 9000 gpm of flow was established to the 21 CC HX. At 1017 hours, TS 3.9.8.2 was exited.

NRC FORM 366A (9-2007)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET		6. LER NU	MBE	R	3. PAG	E
Salem Generating Station Unit 2	05000311	YEAR	SEQUEN NUMBE	rial R	REVISION NUMBER		
		2009	0 0	2	00	3 of	5

NARRATIVE

DESCRIPTION OF OCCURRENCE (cont'd)

It has been determined that since valve 22SW356 gear box mounting bolts failed after operation at 9500 gpm of service water flow during the outage, a similar failure could have occurred during post-LOCA conditions. Since the 22 CC HX was not able to perform its design basis post-LOCA heat removal function during the past operating cycle, the 22 CC HX was inoperable for greater than the allowed outage time of TS 3.7.3.

This report is being made in accordance with 10CFR50.73 (a)(2)(i)(B), "any operation ... prohibited by the plant's Technical Specification."

CAUSE OF OCCURRENCE

The gear box for the 22SW356 valve failed to the partially open position when all four (4) gear box-tovalve mounting bolts failed. Based on examination and lab analysis, the bolts failed due to lateral impact loads. The bolt failures are attributed to installing improper low strength bolts in April 2002 since the correct bolts were not specified in the work order. The lower strength bolts did not retain the preload allowing the bolts to loosen during high flow conditions when system vibration was elevated. In addition, the installation procedure that was created in 1996 did not include a torque value for the manual operator in use (MTD-4S). The procedure provided a torque value for a similar manual operator (MTD-4). This value was lower than the torque specified by the vendor for MTD-4S.

PREVIOUS OCCURRENCES

A review of LERs for Salem Units 1 and 2 for the previous three years did not identify any previous similar events.

NRC FORM 366A (9-2007)

(3-2007)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER	3. PAGE		
Salem Generating Station Unit 2	05000311	YEAR SEQUENTIAL REVISION NUMBER NUMBER			
		2009 0 0 2 00	4 of 5		

NARRATIVE

SAFETY CONSEQUENCES AND IMPLICATIONS

The 22 CC HX manual outlet valve 22SW356 failed to a partially open position on October 17, 2009. Salem Unit 2 was shutdown on October 13, 2009 to begin the seventeenth refueling outage (2R17) and Mode 5 was entered on October 14, 2009 at 0430 hours. At 0459 hours, the 22 CC HX was placed in service with 9500 gpm service water flow to support both trains of RHR and removal of the 21 CC HX to support outage maintenance activities. On October 16, 2009 at 1703 hours, Salem Unit 2 entered Mode 6 and the reactor head was fully de-tensioned at 2355 hours. On October 17, 2009 at 0603 hours, operators reported from the field that the gear box for valve 22SW356 had shifted and that flow through the 22 CC HX was reading approximately 3200 gpm. Operators entered Technical Specification (TS) 3.9.8.2 for two loops of RHR not being operable. At 0658 hours, the 22SW356 valve was secured in position to prevent the valve from going closed any further. Service water flow through the 22 CC HX was approximately 3400 gpm. At 0753 hours, operators verified the ability of the 22 CC HX to provide adequate core cooling by adjusting the RHR HX outlet control valves. RCS temperature reduced from 125.6 °F to 124.5 °F. At 0818 hours, service water flow was established to the 21 CC HX and a RCS temperature decrease was observed. Conservatively, the control room operators did not exit TS 3.9.8.2 until the 21 CC HX was configured to support both trains of RHR with one service water header out of service. Although there was a reduction in service water flow through the 22 CC HX, the capability to remove core decay heat during shutdown conditions was maintained as demonstrated by the ability to reduce RCS temperature through the manipulation of the RHR HX outlet control valves.

It has been determined that since valve 22SW356 gear box mounting bolts failed after 72 hours of operation at 9500 gpm during the outage, a similar failure could have occurred during post-LOCA conditions. For the majority of the previous operating cycle, the 21 CC HX was available and capable of providing post-LOCA heat removal. The 21 CC HX was inoperable for three periods during the previous operating cycle – December 2008 for ~ 25 hours; January 2009 for ~11.5 hours; February 2009 for ~ 44 hours. During these periods, the maximum calculated post-LOCA flow demand was approximately 6800 gpm and since the system vibration would have been considerably lower there is reasonable assurance that the 22SW356 valve gear box mounting bolts would not have failed. During these periods, the 22 CC HX was therefore capable of performing its design basis heat removal function.

A review of this event determined that a Safety System Functional Failure (SSFF) as defined in NEI 99-02, Regulatory Assessment Performance Indicator Guidelines, did not occur since the ability to remove residual heat and mitigate the consequences of an accident were maintained as described above. NRC FORM 366A (9-2007)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER	3. PAGE
Salem Generating Station Unit 2	05000311	YEAR SEQUENTIAL REVISION	•
		2009 0 0 2 00	5 of 5

NARRATIVE

CORRECTIVE ACTIONS

- 1. The 22SW356 valve and gearbox were replaced using the correct mounting bolts. The bolts were torqued to the correct values.
- 2. A roll-out of the work order deficiencies was conducted with the appropriate maintenance and planning personnel. This roll-out included a discussion on the use of proper bolts listed on the bill of materials.
- 3. The maintenance procedure for the manual valve operator has been placed on hold to prevent use of the procedure until revised to include the proper torque acceptance criteria for the mounting bolts.
- 4. New preventive maintenance items will be created for valves 11SW121 (11 CC HX inlet valve), 11SW355 (11 CC HX outlet valve), 21SW121 (21 CC HX inlet valve), 21SW355 (21 CC HX outlet valve), 22SW121 (22 CC HX inlet valve), and 22SW356 (22 CC HX outlet valve) to include removing the mounting bolts to inspect for damage, proper bolt material, inspection of bolt holes and reinstallation in accordance with procedure SC.MD-PM.ZZ-0167.

The above actions are being tracked in PSEG's corrective action program.

COMMITMENTS

No commitments are made in this LER.