

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | Y | I | P | S | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
0 1 | L | 0 | 5 | 0 | 0 | 0 | 2 | 4 | 7 | 0 | 2 | 0 | 6 | 7 | 9 | 0 | 3 | 0 | 5 | 7 | 9 |  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
0 2 | During normal operation, No. 22 Boric Acid Transfer Pump became inoper-  
0 3 | able as a result of a defective control transformer. Boric Acid Trans-  
0 4 | fer Pump No. 21 was operable at the time. Following repairs, the pump  
0 5 | was returned to service within the time limit specified in Technical  
0 6 | Specification 3.2.C.2.

0 7 | \_\_\_\_\_  
0 8 | \_\_\_\_\_  
7 8 9

0 9 | P | C | E | A | P | U | M | P | X | X | B | Z |  
7 8 9 10 11 12 13 18 19 20  
17 | LER/RO REPORT NUMBER | 7 | 9 | - | 0 | 0 | 6 | / | 0 | 3 | L | - | 0 |  
21 22 23 24 26 27 28 29 30 31 32  
A | Z | Z | Z | 0 | 0 | 0 | 0 | N | Y | N | G | 2 | 0 | 0 |  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
1 0 | A Goulds Pump, Model 3196-STD, became inoperable when its control trans-  
1 1 | former (Westinghouse Type MTW) failed. The control transformer was re-  
1 2 | placed, and the pump was returned to service.

1 3 | \_\_\_\_\_  
1 4 | \_\_\_\_\_  
7 8 9

1 5 | E | 1 | 0 | 0 | NA | A | Flight Panel Indication  
7 8 9 10 12 13 44 45 46

1 6 | Z | Z | NA | NA  
7 8 9 10 11 44 45

1 7 | 0 | 0 | 0 | Z | NA  
7 8 9 11 12 13

1 8 | 0 | 0 | 0 | NA  
7 8 9 11 12

LOSS OF OR DAMAGE TO FACILITY (12)  
\_\_\_\_\_

2 0 | N | NA  
7 8 9 10 11

7903090200