




Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N Y 10003

January 20, 1981

Re: Indian Point Unit No. 2  
Docket No. 50-247

Mr. Boyce H. Grier, Director  
Office of Inspection and Enforcement  
Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406



Dear Mr. Grier:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following confirms notification to Mr. Ted Rebelowski of your office, by Mr. John Makepeace of Consolidated Edison, of a potential Reportable Occurrence LER 81-005/01. This event is the type defined in Technical Specification, Section 6.9.1.7.1 (c).

During a review of video inspection tapes of fuel assembly No. E-42, it was determined that there was an apparent clad perforation on a fuel rod within the assembly. These video tapes were obtained as part of a visual fuel inspection program being performed during the current cycle 4/5 refueling and maintenance outage. The cause of this perforation and required corrective actions are under evaluation.

Consolidated Edison believes that this report also satisfies the requirements of 10 CFR Part 21.

Very truly yours,

*William A. Monti*  
William A. Monti, Manager  
Nuclear Power Generation Depart.  
Indian Point Station  
Buchanan, N.Y. 10511

JMM/sal

cc: See Attached Sheet

S

8101270664

A002  
S  
110

Mr. William McDonald, Director (2 copies)  
Office of Management Information and Program Control  
c/o Distribution Services Branch, DDC, ADM  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. T. Rebelowski, Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 38  
Buchanan, N.Y. 10511

