




Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003

March 13, 1981

Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406



Dear Mr. Grier:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following confirms notification to Mr. Ted Rebelowski of your office, by Mr. John Makepeace of Consolidated Edison, of a potential Reportable Occurrence LER 81-007/-1. This event is the type defined in Technical Specification, Section 6.9.1.7.1 (i).

In the course of our continuing evaluation of the performance of the Unit No. 2 fan cooler units, we have been advised by the vendor that the fiberglass pre-filters used in front of the cooling coils might degrade under postulated accident conditions and effect the heat removal capability of the coils. We are presently investigating the feasibility and availability of alternate prefilters which have been qualified at LOCA conditions. Until this investigation has been completed, we plan to remove the existing prefilters after final containment clean-up and prior to returning the unit to service.

Consolidated Edison believes that this report also satisfies the requirements of 10CFR Part 21.

very truly yours,

William A. Monti
William A. Monti
Nuclear Power Generation Dept
Indian Point Station
Buchanan, N.Y. 10511

JMM/sal

cc: See Attachment Sheet

A002
AS 11

S

8103190393

cc: Mr. William McDonald, Director (2 copies)
Office of Management Information and Program Control
c/o Distribution Services Branch, DDC, ADM
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. T. Rebelowski, Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 38
Buchanan, N.Y. 10511

