



ATTACHMENT

Docket No. 50-247

Consolidated Edison Co. of N.Y., Inc.

LER-81-007/01T-0

Indian Point Unit No. 2

In the course of our continuing evaluation of the performance of the Unit No. 2 containment fan cooler units, we have been advised by the vendor that the fiberglass prefilters used ahead of the cooling coils might degrade under postulated accident conditions and affect the heat removal capability of the coils. These pre-filters have been used to minimize potential coil fouling. After final containment clean-up following the conclusion of the ongoing refueling/maintenance outage, we plan to remove the prefilters prior to returning the unit to service. During power operation, periodic inspections of the condition of the cooling coils will be made to detect possible fouling which could affect the performance of the coils.

Additionally, we are investigating the feasibility and availability of alternate prefilters which have been qualified at LOCA conditions.