

SYSTEMS
-INTERACTION STUDY



**EBASCO** 

**VOLUME II** 

POWER AUTHORITY OF THE STATE OF NEW YORK

INDIAN POINT NO. 3 NUCLEAR POWER PLANT

SYSTEMS INTERACTION STUDY

VOLUME II



Prepared for the Power Authority of the State of New York

bv

EBASCO SERVICES, INCORPORATED

#### POWER AUTHORITY OF THE STATE OF NEW YORK

#### INDIAN POINT No. 3 NUCLEAR POWER PLANT

#### SYSTEMS INTERACTION STUDY

#### VOLUME II

#### CONTENTS

SECTION	<u>TITLE</u> <u>PAGE</u>
APPENDIX A	AUXILIARY FEEDWATER SYSTEM (AFS) SYSTEMS INTERACTION STUDY
A-1.1 A-1.2 A-2.1	Introduction A-1 Systems Interaction Study AFS Boundary A-2 Results on AFS of Interconnected A-3 Systems Interactions
A-2.2	Results on AFS of Non-connected  Systems Interactions  A-9
A-3.1 A-3.2 A-4.0 A-5.0	AFS Functional Description  AFS Operating Description  AFS Interaction Matrix/Documentation Sheets  AFS Non-connected Systems Interactions Study Photographs

# SYSTEMS INTERACTION STUDY APPENDIX A - AUXILIARY FEEDWATER SYSTEM (AFS)

#### APPENDIX A-1.1 INTRODUCTION

This chapter describes the work performed by Ebasco on the Indian Point No. 3 Nuclear Power Plant Auxiliary Feedwater System for systems interactions consistent with the criteria, methodology and guidelines presented in the Chapters 3 thru 6 of Volume I. Interconnected process coupled, and nonconnected spatially coupled systems interactions were investigated and the results presented in Sections A-2.1 and A-2.2 respectively.

#### APPENDIX A AUXILIARY FEEDWATER SYSTEM - (AFS) (Cont'd)

#### APPENDIX A-1.2 SYSTEM BOUNDARY CONDITIONS

The Indian Point No. 3 Nuclear Power Plant Auxiliary Feedwater System was reviewed for systems interactions based on current unit installations with credit taken for specific commitments to the NRC regarding hardware and procedural modifications.

The boundary of the systems interaction study for the Indian Point No. 3 Nuclear Power Plant, Auxiliary Feedwater System is shown in Figure A-6. The turbine steam supply from the steam generators and all of the Auxiliary Feedwater System components (see Table A-1) are included in the study. The water supplies to the extent of the piping systems and valves that deliver water to the Auxiliary Feedwater System are included. Electrical power and control supplies are included to the extent presented in Figure A-1 for three electrical states, full power, loss of one bus, and no AC electric power (onsite or offsite).

This evaluation is conducted assuming the presence of an AFS actuation signal, therefore the AFS actuation signal is outside the boundary of this study. As discussed in Chapter 5, latent and dynamic operator (Human) induced failures are also outside the boundary of this study. Consistent with this, the effects of control system failures on operator actions, i.e., those failures which deprive the operator of required information for normally controlling plant conditions, or which provide confusing or incorrect information to the operator, have been specifically omitted from this study.

The effects of non-safety-grade control system failures on plant safety is excluded from this study. Justification for this exclusion is provided in the Authority's response to IE Information Notice 79-22, via IPN-79-74, dated October 9, 1979.

# POWER AUTHORITY OF THE STATE OF NEW YORK INDIAN POINT NO. 3 NUCLEAR POWER PLANT SUMMARY OF COMPONENT TYPES TO BE REVIEWED FOR SYSTEMS INTERACTIONS

## TABLE A-1

MECHANICAL	ELECTRICAL	INSTRUMENTATION & CONTROL	HEATING, VENTIALTING & AIR CONDITIONING	ALL OTHERS
PUMP	MOTORS	TRANSMITTERS	FANS	
1) CENTRIFUGAL	CABLES	SWITCHES (PROCESS VARIABLE)	COOLERS	
2) RECIPROCATING	CONDUITS & TRAYS	POSITION OR LIMIT SWITCHES	DUCTWORK	
ALVE	BATTERIES & CHARGERS	PNEUMATIC CONTROLERS	LOUVERS	
1) Air Operated	DIESEL GENERATOR	PNEUMATIC CONTROL VALVES	CHILLERS	
2) Motor Operated	MOTOR CONTROL CENTER & SWITCHGEAR	PNEUMATIC SOLENOIDS		
3) Hydraulic Operator	CIRCUIT BREAKERS & CONTACTS	PNEUMATIC/ELECTRICAL CONVERTERS		
4) Check	SWITCHES	LOCAL INDICATORS		
5) Manual	INVERTERS	LOCAL CONTROL SWITCHES		
6) Safety/Relief	MOTOR OPERATORS FOR VALVES	INSTRUMENT RACKS	4.	
7) Solenoid		INSTRUMENT SENSING LINES	•	
FLOW ORIFICE		INSTRUMENT AIR LINES & SPECIALTIES		
RESTRICTION ORIFICE			The state of the s	
STEAM TURBINE				
COMPRESSORS			•	
PIPING			i	
	·	•	!	

GAS STORAGE TANKS
TANKS (FLUID)

#### SYSTEMS INTERACTION STUDY AUXILIARY FEEDWATER SYSTEM COMPONENT POWER SUPPLY SUMMARY (REF 1)

### TABLE A-3

Component	Power Supply	Primary Source (4)	Backup Source(5)	Function
A. STEAM SUPPLY TRAIN				
PCV-1139 (20-1/ABFP2) (1) PCV-1139 (20-2/ABFP2) (2) PCV-1310A (SOV-1310) (1) PCV-1310B (SOV-1311) (1)	125 Volt DC Pn1. 31 125 Volt DC Pn1. 31 125 Volt DC Pn1. 33 125 Volt DC Pn1. 34	Battery 31 Battery 31 Battery 31 Battery 32	Bus 3A Bus 3A Bus 3A Bus 3A	Stm. Supply to Aux. Blr. Fd. Pump 32 Turbine (N.C.) Stm. Supply to Aux. Blr. Fd. Pump 32 Turbine (N.C.) Stm. Supply Isolation Valve to Aux. BFP 32 Turbine (N.O.) Stm. Supply Isolation Valve to Aux. BFP 32 Turbine (N.O.)
B. TURBINE PUMP 32 TRAIN				
Aux. Blr. Fd. Pump 32	Steam Driven	Residual Heat Generated Steam		<del></del>
CT-10	Hand Operated			Valve on pump 32 Suction Heater from Condensate Storage Tank (L.O.)
PCV-1188 (SOV-1288) (3)	120 Volt AC Instrument Bus 31	Battery 31	Bus 3A	Valve on alt. path from City Wtr. Sys. for Aux. Fdwtr.
PCV-405A (1) PCV-405B (1) PCV-4050 (1) PCV-4050 (1)	120 Volt AC Instrument Bus 31 120 Volt AC Instrument Bus 31 120 Volt AC Instrument Bus 31 120 Volt AC Instrument Bus 31	Battery 31 Battery 32 Battery 33 Battery 34	Bus 5A Bus 3A Bus 3A Bus 3A	Pump 32 Suction (N.C.)  Aux. Blr. Fd. Pump 32 Discharge to Stm. Gen. 31 (N.C.)  Aux. Blr. Fd. Pump 32 Discharge to Stm. Gen. 32 (N.C.)  Aux. Blr. Fd. Pump 32 Discharge to Stm. Gen. 23 (N.C.)  Aux. Blr. Fd. Pump 32 Discharge to Stm. Gen. 24 (N.C.)
C. MOTOR-DRIVEN PUMP 31 TRAIN	ı		· .	
Aux. Blr. Fd. Pump 31 CT-27	480 Bolt Bus 3A Hand Operated	Bus 3A	Ds1. 31	Valve on Pump 31 Suction Header from Condensate Storage
PCV-1087 (SOV-1287) (3)	120 Volt AC Instrument Bus 33	Battery 33	Ds1. 31	Tank (L.O.) Valve on Alt. Path from City Wtr Sys. for Aux. Fd. Pump 31 Suction (N.C.)
PCV-406A (1) PCV-4068 (1)	120 Volt AC Instrument Bus 33 120 Volt AC Instrument Bus 33	Battery 33 Battery 33	Ds1. 31 Ds1. 31	Aux. Blr. Fd. Pump 31 Discharge to Stm. Gen. 31 (N.O.) Aux. Blr. Fd. Pump 31 Discharge to Stm. Gen. 32 (N.O.)
(4) AC Instrument Buses are p	of Air or Electric Power. of Air and cannot be Closed Withouss of Air or Electric Power owered off of corresponding DC pan to Bus 3A is manual. Backup to Bus	el.		(N.C.) = Normally Closed (N.O.) = Normally Open (L.O.) = Locked Open

# SYSTEMS INTERACTION STUDY AUXILIARY FEEDWATER SYSTEM COMPONENT POWER SUPPLY SUMMARY (REF 1)

### TABLE A-3 (Cont'd)

Component	Power Supply	Primary Source (4)	Backup Source(5)	Function
D. MOTOR-DRIVEN PUMP 33 TRAIN				
Aux. Blr. Fd. Pump 33	480 Volt Bus 6A	Bus 6A	Ds1. 32	
CT-33	Hand Operated	· •••		Valve on Pump 33 Suction Header from Condensate Storage Tank (L.O.)
PCV-1189 (SQV-1289) (3)	120 Volt AC Instrument Bus 32	Battery 32	Ds1. 32	Valve on Alt. path from City Water Sys. for Aux. Fd. Pump 33 Suction (N.C.)
PCV-406C (1)	120 Volt AC Instrument Bus 32	Battery 32	Ds1. 32	Aux. Blr. Fd. Pump 33 Discharge to Stm. Gen. 33 (N.O.)
PCV-406D (1)	120 Volt AC Instrument Bus 32	Battery 32	Ds1. 32	Aux. Blr. Fd. Pump 33 Discharge to Stm. Gen. 34 (N.O.)
E. MISCELLANEOUS				
LCV-1158 (SOV-1258) (3) CT-6 (4) CT-64 (4)	125 Volt DC Dist. Pnl. 31 Hand Operated Hand Operated	Battery 31  	Ds1. 32	Condensate Storage Tank low-level shutoff valve (N.O.) Condensate Storage Tank discharge valve (L.O.) Condensate Storage Tank discharge valve (L.O.)
(2) Valve Fails Open on Loss	of Air or Electric Power. of Air and cannot be Closed Withous s of Air or Electric Power	ıt Electric Power.		(N.C.) = Normally Closed (N.O.) = Normally Open (L.O.) = Locked Open

<sup>(4)</sup> AC Instrument Buses are powered off of corresponding DC panel.
(5) Transfer from Batteries to Bus 3A is manual. Backup to Bus 3A Diesel 31.

#### APPENDIX A AUXILIARY FEEDWATER SYSTEM (Cont'd)

APPENDIX A-2.1 Results on AFS of Interconnected Systems Interactions
(Cont'd)

Vent and drain lines and valves, and connected lines which are small in size were not evaluated since it was assessed that failure of these components would not significantly affect the system performance.

Other events that require operation of the Auxiliary Feedwater System are:

- Loss of main feedwater transient
- Loss of main feedwater with offsite power available
- Station blackout (loss of main feedwater without offsite power available)
- Rupture of a main steam line
- Loss of all AC Power
- Loss of coolant accident

#### APPENDIX A AUXILIARY FEEDWATER SYSTEM (Cont'd)

#### APPENDIX A-2.1.1 SUMMARY AND CONCLUSIONS

For the case presented, the acceptance criteria for evaluating component failures of the Auxiliary Feedwater System were as follows:

- 1 A flow rate of 400 gpm be delivered to at least two (2) steam generators
   (200 gpm to each)
- 2 The flow is delivered within 30 minutes of the initial demand.

Random component failures are categorized as recoverable or nonrecoverable. A recoverable random failure is defined as a failure that does not cause a system failure since the operator is assumed to have sufficient time to take successful action to recover from the failure. Recoverable failures are those that can be corrected before a specified time criteria is exceeded. Nonrecoverable random failures are failures that cause a system failure due to the inability of the operator to recover from the failure because of a time criteria.

The results presented in this section as described in Table A-2.1 show that the Auxiliary Feedwater System emergency operating mode for the loss of normal feedwater event resulting from a feedline break outside containment coincident with a loss of all offsite power is reliable. Component redundancy and recoverability of component failures made the system sound. These results are consistent with the PRA findings of the Pickard, Lowe and Garrick, Inc. Study.

## SYSTEMS INTERACTION STUDY APPENDIX A - AUXILIARY FEEDWATER SYSTEM

APPENDIX A-2.2 Results on the AFS of Nonconnected Systems Interactions

APPENDIX A-2.2.1 Systems Interactions Induced by the Effects of a Safe Shutdown Earthquake (SSE)

#### GENERAL DISCUSSION

General Design Criterior 2, "Design Bases for Protection Against Natural Phenomena", of Appendix A to 10CFR Part 50, "General Design Criteria for Nuclear Power Plants", require that structures, systems, and components important to safety be designed to withstand the effects of earthquakes without loss of capability to perform their intended safety functions.

NRC Regulatory Guide 1.29, "Seismic Design Classification", (formerly Safety Guide 29) describes an acceptable method of identifying and classifying those plant features that should be designed to withstand the effects of the SSE. Regulatory position C.1.g. of NRC 1.29 states that the Auxiliary Feedwater System including components, supports and foundations shall be designated as Seismic Category I and should be designed to withstand the effects of the SSE and remain functional. In addition, regulatory position C.2 of NRC RG 1.29 states that those portions of structures, systems, or components whose continued function is not required but those failure could reduce the functioning of any plant feature designated Seismic Category I, to an unacceptable safety level should be designed and constructed so that the SSE would not cause such failure.

Based upon the above, a review of the seismic design classification of the structures, systems and components associated with the safe operation of the Auxiliary Feedwater System was conducted. In addition a plant walkdown of the auxiliary feed pump building and associated structures was conducted to review the effects of nonseismic structures, systems and components whose failure during an SSE could reduce the functionability of any plant features important to safety to an unacceptable level.

APPENDIX A-2.2.1 Systems Interactions Induced by the Effects of a Safe Shutdown Earthquake (SSE) (Cont'd)

#### GENERAL DISCUSSION (Cont'd)

The plant walkdown activities were consistent with the methodology guidelines and evaluation criteria described in Chapters 5 and 6.

#### SUMMARY AND CONCLUSION

In general due to the lack of documentation, it was impossible to complete a comprehensive review of the seismic design classification. In those instances where documentation existed an appropriate reference was included.

Structures, systems and components that were not substantiated by seismic documentation consistent with the quality assurance requirements of Appendix B to 10CFR Part 50 were assumed to be nonseismic and were evaluated with respect to their effects on other Seismic Category I items.

Acceptable and unacceptable system interactions resulting from the failure of nonseismic structures, systems or components are presented in Appendix A-4.

From a review of the results of the seismic system interactions, the following items are considered to be the major contributors to the identification of adverse systems interactions,

- 1 Crane/monorail structure located directly above the two (2) motor driven and the turbine driven auxiliary feedwater pumps.
- 2 4" nonseismic floor drain pipe directly above the electrical cable trays containing essential safety related equipment.

- APPENDIX A-2.2 Results on the AFS of Nonconnected Systems Interactions
  (Cont'd)
- APPENDIX A-2.2.1 Systems Interactions Induced by the Effects of a Safe Shutdown Earthquake (SSE) (Cont'd)

#### SUMMARY AND CONCLUSION (Cont'd)

- 3 Space heaters and electrical lighting fixtures located directly above essential safety related equipment and structures.
- 4 Nonseismic electrical cable trays and conduit routed directly above essential safety related equipmenmt and structures.
- 5 Large nonseismic instrument rocks located within close proximity to essential safety related equipment and structures.
- 6 Large roll-up door located in the shieldwall whose structural failure could affect the flow control stations of the turbine driven auxiliary feedwater pumps.

Modifications including the possible use of guard structures, protective covers, and restraining devices are expected to prevent impairment of function due to the above concerns.

# SYSTEMS INTERACTION STUDY APPENDIX A AUXILIARY FEEDWATER SYSTEM

APPENDIX A-2.2 Results on the AFS of Nonconnected Systems Interactions
(Cont'd)

APPENDIX A-2.2.2 Pipe Failure Induced Systems Interactions

The Auxiliary Feedwater System was reviewed for potential systems interactions resulting from high energy line breaks. The Indian Point No. 3, Nuclear Power Plant, Safety Evaluation Report, Docket No. 50-286, dated September 21, 1973, Chapter 6 entitled Engineered Safety Features was used as the base document for pipe failure induced systems interactions.

Several modifications have been made to this system in order to give it additional protection in the unlikely event of high energy line breaks outside the containment. The auxiliary feedwater lines are directly connected into the feedwater system and experience the same pressure as the feedwater system. The Staff had a concern that a break in an auxiliary feedwater line within the room that houses the motor-driven and the steam turbine-driven auxiliary feedwater pumps might result in back flow from the feedwater system and could possibly flood these three pumps. Because of this concern, check valves were installed in the piping that connects the discharge side of these pumps with the normal feedwater system. These check valves are located outside of the auxiliary feedwater pump room and prevent backflow from the feedwater system into the Auxiliary Feedwater System.

Another modification made was additional protection of the electric motor-driven auxiliary feedwater pumps from a high temperature-high humidity environment. A postulated high-energy pipe break in the steam supply to the steam turbine-driven auxiliary feedwater pump might result in temperature and humidity conditions in the pump room for which the electric motor-driven pumps

APPENDIX A-2.2.2 Pipe Failure Induced Systems Interactions (Cont'd)

were untested. These motor-driven pumps are "drip-proof," but their operability at elevated temperatures and in a steam environment was not demonstrated. Consequently, two redundant valves in the steam supply line to the auxiliary feedwater turbine-dr ven pump were installed. These valves are outside of the room that houses the auxiliary feedwater pumps. Each valve is signaled to close automatically on high temperature in the pump room. Each valve has its own separate temperature sensor. There is control room indication of each valve's position, and an alarm will sound upon closure. Operation of these valves would limit the temperature and humidity rise in the pump room due to a break in the steam supply to the steam turbine auxiliary feedwater pump.

The consequences of pipe ruptures in the vicinity of the auxiliary feedwater pumps which might cause flooding in the pump room were also examined. The drainage capabilities of the pump room were modified to prevent water levels from reaching a depth of 14 in. off the floor from such postulated break. At the 14 in. level, water would begin to touch the bottom of the electric motor-driven auxiliary feedwater pumps. Pipe restraints on feedwater lines in the room above the auxiliary feedwater room were also installed. This was done to eliminate any concrete from the pump room roof falling onto the pumps as a result of whipping of the pipes after a postulated pipe rupture.

The Staff reviewed these modifications and found them acceptable.

In view of the design modifications that have been made to limit the consequences of pipe whip, flooding, and temperature and pressure transients in the pump room, and in view of the design criteria that were in effect at the time of the construction permit, it was concluded that the design of the Auxiliary Feedwater System, as modified, does not lead to any unacceptable systems interactions.

# SYSTEMS INTERACTION STUDY APPENDIX A AUXILIARY FEEDWATER SYSTEM

### •

APPENDIX A-2.2 Results on the AFS of Nonconnected Systems Interactions
(Cont'd)

APPENDIX A-2.2.3 Systems Interactions Induced by the Effects of Internally and Externally Generated Missiles

General Design Criterion 4, "Environmental and Missile Design Bases", requires that all structures, systems and components that are necessary for attaining and maintaining a safe snutdown of the reactor facility and whose failure could result in a significant release of radioactivity, be designed to withstand the effects of internally and externally generated missiles.

Internally generated missiles are components of pressurized systems such as valve bonnets and hardware retaining bolts, relief valve parts, and instrument wells: high speed rotati g machinery, such as impellers and fan blades resulting from component overspeed or failure (resulting from seisure) which are within a structure protecting systems and components necessary for safe shutdown.

Externally generated missiles are missiles generated by natural phenomena such as tornado and those components of pressurized systems and high speed rotating machinery located outside structures protecting systems and components necessary for safe plant shutdown.

APPENDIX A-2.2.3 Systems Interactions Induced by the Effects of Internally and Externally Generated Missiles (Cont'd)

A-2.2.3.1 Internally Generated Missile System Interactions

During the walkdown phase of the system interaction study, an observation was made relative to the potential for the generation of internal missiles from pressurized systems and high speed rotating machinery and the effects on safe shutdown capabilities. It was observed that adequate separation and system redundancy existed so as to preclude damaging effects from internally generated missiles such as valve bonnents and hardware retaining bolts, relief valve parts and instrument wells. In addition it was observed that high energy lines were provided with pipe whip restraints so as to prevent impact on safety related systems and components.

The auxiliary feedwater pumps located within the auxiliary feedpump building were evaluated for missiles assoicated with overspeed failure. The motor driven auxiliary feedwater pumps maximum no-load speed was assumed to be the synchronus speed of the motor which is no more than 2 percent above the rated operating speed. Consequently, no pipe break or single failure in the suction or discharge lines of the pump would increase the pump speed over that of the no-load condition. Therefore, the generation of missiles associated with the motor driven pumps is not a credible occurance. However, an evaluation of the turbine driven auxiliary feedwater pump showed that missiles could be generated due to turbine overspeed protection failure, and that several safety related systems and components in the auxiliary feed pump building were potential targets.

APPENDIX A-2.2.3 Systems Interactions Induced by the Effects of Internally and Externally Generated Missiles (Cont'd)

A-2.2.3.1 Internally Generated Missile System Interactions (Cont'd)

In November 1971, the NRC informed the Power Authority of the State of New York (PASNY) of the NRC's requirements for the Auxiliary Feedwater system at the Indian Point No. 3 Nuclear Power Plant. Among the long-term recommendations was the requirement to evaluate the potential for the generation of internal missiles in the Auxiliary Feedwater Pump Room and its effect on vital equipment and systems. On July 15, 1980 the NRC issued Interim Safety Evaluations of the auxiliary feedwater system. One of the open items in these reports was the stipulation that the "Licensee provide a description of the results of the (missile generation) evaluation prior to August 11, 1980 and prior to implementation of any corrective measures."

PASNY contracted EDS Nuclear Inc to evaluate the capability of the auxiliary feedwater system to withstand internally generated missiles. The evaluation has determined that the auxiliary feedwater pump turbine could be a source of a destructive missile and therefore, an analysis of auxiliary feedwater pump turbine missiles was undertaken.

The evaluation showed that missiles could be generated and that several safety related systems at different locations in the auxiliary feed pump building were potential targets. Because of these results, it was decided that protection at the missile source was the best approach.

APPENDIX A-2.2.3 Systems Interactions Induced by the Effects of Internally and Externally Generated Missiles (Cont'd)

A-2.2.3.1 Internally Generated Missile System Interactions (Cont'd)

From a systems interaction point of view, protection at the source designed for destructive overspeed missiles is an acceptable solution. This ensures that safe shutdown equipment will not interact with a missile source as a result of disk failure at any possible speed. Although the missile shield has not yet been installed it was assumed that near term modifications will be made. Therefore, based upon the commitment to install a missile shield system no credible interaction of a missile source with safety related targe equipment located in the auxiliary feed pump building were found.

#### A-2.2.3.2 Externally Generated Missile System Interactions

A review of the Indian Point 3 Facility Safety Analysis Report, Chapter 3.5 and the NRC (then AEC) Safety Evaluation Report, dated September 21, 1973 was conducted to determine if the structures systems and components associated with the auxiliary feedwater system were protected against the effects of externally generated missiles. A review of this type was conducted in order to preclude the evaluation of systems interactions resulting from externally generated missiles.

Our review concluded that various structures at the Indian Point 3 site have been designed and constructed to withstand the effects of tornado generated missiles. Among these structures are the primary auxiliary building, the control room, the containment building, the diesel generator building, the cable tunnels, and the waste hold-up tank pit. The shield wall of the auxiliary feedwater pump building has been designed considering the effects of externally generated missiles.

APPENDIX A-2.2.4 Systems Interactions Induced by the Effects of Flooding

Design Criterion 2, "Design Bases for Protection Against Natural Phenomena" require that all systems and components whose failure could prevent safe shutdown of the plant or result in uncontrolled release of significant radioactivity, be designed to withstand the effects of flooding due to natural phenomena.

A review of the Indian Point 3 Facility Safety Analysis Report, and the NRC (then AEC) Safety Evaluation Report, was conducted to determine to what extent the structures, systems and components associated with the Auxiliary Feedwater System were protected against the effects of flooding due to natural phenomena.

Our review concluded that it was established that the most severe flooding condition at the site, corresponds to a water elevation of 15 ft above mean sea level (MSL). As stated in the Facility SER, this elevation is lower by three inches than the critical elevation at which water would start seeping into the lowest of the plant buildings. The staff concluded in their report that under the most extreme conditions the flood level could reach a level of 15.0 ft MSL, exclusive of wind-generated wave action. Wind-generated wave action could raise the flooding level above plant grade in the vicinity of the service water pumps.

In the event of wind-generated wave action in conjunction with extreme flooding conditions, the plant will still be protected. In this unlikely event, the plant will be shutdown in accordance with the Techincal Specifications, and the service water pump areas will be protected. Other areas, such as the diesel generator area, will not require additional protection from the wind-generated waves in that these waves rapidly dissipate once they strike land.

- APPENDIX A-2.2 Results on the AFS of Nonconnected Systems Interactions
  (Cont'd)
- APPENDIX A-2.2.4 Systems Interactions Induced by the Effects of Flooding (Cont'd)

Consequently, the combination of the elevation of the plant structures, and the Technical Specification requirements on plant operation and service water pump protection, result in accetable conditions to protect the plant against flooding.

Based upon our review and the findings above, we concluded that no credible flooding conditions caused by natural phenomena will exist and therefore, no adverse system interactions were identified for the structures, systems and components of the Auxiliary Feedwater System.

- APPENDIX A-2.2 Results on the AFS of Nonconnected Systems Interactions
  (Cont'd)
- APPENDIX A-2.2.5 System Interactions Induced by Severe Environment (Other Than Flooding) Resulting From Natural Phenomena.

General Design Criterion 2, "Design Bases for Protection Against Natural Phenomena", require that all systems, components and structures whose failure could prevent safe shutdown of the plant or result in uncontrolled release of significant radioactivity, be designed to withstand the resulting effects of severe environment due to natural phenomena.

A review of the Indian Point 3 Facility Safety Analysis Report, and the NRC (then AEC) Safety Evaluation Report, was conducted to determine to what extent the structures, systems and components associated with the Auxiliary Feedwater System were protected against the effects of severe environment due to natural phenomena.

Our review concluded that the effects of tornado wind loadings and depressurization was considered in the design of all Category I structures. The auxiliary feed pump building is designated as a Category I structure. Therefore, no adverse system interactions were identified for the structures, systems and components of the Auxiliary Feedwater System contained within the auxiliary feed pump building.

APPENDIX A-2.2.6 Systems Interactions Induced by Fires

The Commission's basis criterion for fire protection is setforth in General Design Criterion 3, Appendix A to 10CRF Part 50, which states:

- 1 "Structures, systems, and componets important to safety shall be designed and located to minimize, consistent with other safety requirements, the probability and effect of fires and explosions."
- 2 "Noncombustible and heat resistant materials shall be used wherever pratical throughout the unit, particularly in locations such as the containment and the control room."
- 3 "Fire detection and protection systems of appropriate capacity and capability shall be provided and designed to minimize the adverse effects of fires on structures, systems, and components important to safety."
- 4 "Fire fighting systems shall be designed to assure that their rupture or inadvertent operation does not significantly impair the safety capability of these structures, systems, and components."

The Indian Point No. 3 Fire Protection Program Report, Revision 1, dated Ap-1 1977 was reviewed to determine to what extent the structures, systems and components associated with the Auxiliary Feedwater System were protected against the effects of fires.

It was concluded in the report that the results of the fire hazards evaluation had shown that there are no areas in the plant where a design basis fire would cause the loss of the primary as well as the redundant shutdown system. Therefore, no adverse system interactions were identified due to fire induced failures of systems, components and structures of the Auxiliary Feedwater System.

## SYSTEMS INTERACTION STUDY APPENDIX A - AUXILIARY FEEDWATER SYSTEM

#### APPENDIX A-3.0 Auxiliary Feedwater System Description

### APPENDIX A-3.1 System Functional Description (1)

The Auxiliary Feedwater System serves as a backup system for supplying feedwater to the secondary side of the steam generators at times when the feedwater system is not available, thereby maintaining the heat sink capabilities of the steam generator. The Auxiliary Feedwater System is an Engineered Safeguards System, and is directly relied upon to prevent core damage and primary system overpressurization in the event of transients such as a loss of normal feedwater or a secondary system pipe rupture, and to provide a means for plant cooldown following any plant transient.

Following a reactor trip, decay heat is dissipated by evaporating water in the steam generators and venting the generated steam either to the condensers through the steam dump or to the atmosphere through the steam generator safety valves or the power-operated relief valves. Steam generator water inventory must be maintained at a level sufficient to ensure adequate heat transfer and continuation of the decay heat removal process. The water level is maintained under these circumstances by the Auxiliary Feedwater System which delivers an emergency water supply to the steam generators. The Auxiliary Feedwater System is capable of functioning for extended periods, allowing time either to restore normal feedwater flow or to proceed with an orderly cooldown of the plant to the reactor coolant temperature where the Residual Heat Removal System can assume the burden of decay heat removal. The Auxiliary Feedwater System flow and the emergency water supply capacity must be sufficient to remove core decay heat, reactor coolant pump heat, and sensible heat during the plant cooldown.

APPENDIX A-3.1 System Functional Description (Cont'd)

#### **DESIGN CONDITIONS**

The reactor plant conditions which impose safety-r 1 ted performance requirements on the design of the Auxiliary Feedwater System are as follows for Indian Point Unit No. 3 Nuclear Power Plant.

- Loss of main feedwater transient
- Station blackout (i.e., loss of main feedwater without offsite power available)
- Rupture of a Main Steam Line
- Loss of all AC Power
- Loss of Coolant Accident (LOCA)
- Cooldown

#### Loss of Main Feedwater Transients

The design loss of main feedwater transients are those caused by:

- Interruptions of the Main Feedwater System flow due to malfunction in the feedwater or condensate system
- Loss of offsite power or blackout with the consequential shutdown of the main feedwater system pumps, auxiliaries, and controls

Loss of main feedwater transients are characterized by a rapid reduction in steam generator water levels which results in a reactor trip, a turbine trip, and auxiliary feedwater actuation by the protection system logic. Following reactor trip from high power, the power quickly falls to decay heat levels.

APPENDIX A-3.1 System Functional Description (Cont'd)

DESIGN CONDITIONS (Cont'd)

Loss of Main Feedwater Transients (Cont'd)

The water levels continue to decrease, progressively uncovering the steam generator tubes as decay heat is transferred and discharged in the form of steam either through the steam dump valves to the condenser or through the steam generator safety or power-o era ed relief valves to the atmosphere. The reactor coolant temperature increases as the residual heat in excess of that dissipated through the steam generators is absorbed. With increased temperature, the volume of reactor coolant expands and begins filling the pressurizer. Without the addition of sufficient auxiliary feedwater, further expansion will result in water being discharged through the pressurizer safety and relief valves. If the temperature rise and the resulting volumetric expansion of the primary coolant are permitted to continue, then (1) pressurizer safety valve capacities may be exceeded causing over-pressurization of the Reactor Coolant System and/or (2) the continuing loss of fluid from the primary coolant system may result in bulk boiling in the Reactor Coolant System and eventually in core uncovering, loss of natural circulation, and core damage. If such a situation were ever to occur, the Emergency Core Cooling System would be ineffectual because the primary coolant system pressure exceeds the shutoff head of the safety injection pumps, the nitrogen over-pressure in the accumulator tanks, and the design pressure of the Residual Heat Removal Loop. Hence, the timely introduction of sufficient auxiliary feedwater is necessary to arrest the decrease in the steam generator water levels, to reverse the rise in reactor coolant temperature, to prevent the pressurizer from filling to a water solid condition, and eventually to establish stable hot standby conditions. Subsequently, a decision may be made

APPENDIX A-3.1 System Functional Description (Cont'd)

DESIGN CONDITIONS (Cont'd)

Loss of Main Feedwater Transients (Cont'd)

to proceed with plant cooldown if the problem cannot be satisfactorily corrected. The blackout transient differs from a simple loss of main feedwater in that emergency power sources must be relied upon to operate vital equipment. The loss of power to the electric driven condenser circulating water pumps results in a loss of condenser vacuum and condenser dump valves. Hence, steam formed by decay heat is relieved through the steam generator safety valves or the power-operated relief valves. The calculated transient is similar for both the loss of main feedwater and the blackout, except that reactor coolant pump heat input is not a consideration in the blackout transient following loss of power to the reactor coolant pump bus.

The station blackout transient serves as the basis for the minimum flow (400 gpm) required for Indian Point No. 3 Nuclear Power Plant. The system is designed so that a minimum of 400 gpm is provided against the steam generator safety valve set pressure (with 3% accumulation) to prevent water relief from the pressurizer. This is accomplished, even considering the effect of the turbine driven pump throttling with an assumed single failure.

APPENDIX A-3.2 System Operating Description (2)

#### Auxiliary Feedwater Flow Path

The Auxiliary Feedwater System consists of two subsystems. One system utilizes a steam turbine-driven pump, with the steam capable of being supplied from No. 32 and No. 33 steam generators upstream of the isolation valves. A pressure reducing control valve reduces the pressure to the 600 psi design value of the turbine. This system is capable of supplying a total of 800 gpm to all four steam generators. The other system utilizes two motor-driven pumps each with a capacity of 400 gpm. The discharge piping is arranged so that each pump supplies two steam generators (see Figure A-2).

#### Water Supplies

Water supplies to the Auxiliary Feedwater System is redundant. The normal source is by gravity feed from the condensate storage tank which is sized to meet the normal operating and maintenance needs of the turbine cycle. Each auxiliary feedwater pump takes suction on the header through a check and normally open stop valve. Individual flow elements are provided on the suction to each of the two motor driven pum s (No. 31 and No. 33). Pump suction pressure is indicated in the control room by PI-1263-R, PI-1264-R and PI-1265-R for each pump. Availability of water from this source is guaranteed by LCV-1158 which closes when the quantity of water in the condensate storage tank drops to 360,000 gallons. When LCV-1158 closes, make-up to the main condensers is prevented and a sufficient quantity of water is assured to be available to remove the residual heat generated by the reactor for 24 hours at hot shutdown condition.

APPENDIX A-3.2 System Operating Description (Cont'd)

Water Supplies (Cont'd)

An alternate supply of water for the pumps is provided for emergency backup and long-term cooling from the city water system. Each pump is supplied from a header through a check and control valve which is normally closed. This valve is controlled by a switch located in the control room which will operate the solenoid, applying or removing air from the valve. Valve position is indicated in the control room.

#### Discharge Routing

Discharge from the pumps is routed to the steam generators. Steam generators No. 31 and No. 32 are supplied by No. 31 and No. 32 auxiliary boiler feed pumps. Steam generators No. 33 and No. 34 are supplied by No. 32 and No. 33 feed pumps. Each feedwater line is provided with a flow control valve for feedwater regulation. A common flow transmitter for each steam generator is used to indicate flow in the control room from the motor driven or turbine driven flow paths. Pump discharge pressure is provided both locally and in the control room. Recirculation lines, which are provided for pump protection are routed back to the condensate storage tank.

#### Motor Driven Auxiliary Feedwater Pumps

The motor driven pumps are Ingersoll-Rand Company No. 3HMTA, nine stage, horizontal split case centrifugal units, each of which supplies 400 gpm of water at a head of 1350 psi. The motor drives are furnished by Westinghouse Electric Corporation.

APPENDIX A-3.2 System Operating Description (Cont'd)

Motor Driven Auxiliary Feedwater Pumps (Cont'd)

#### a. Motor Driven Pump Control

Auxiliary feed pumps No. 31 and No. 33 are driven by motors supplied from 480V buses 3A and 6A respectively. Control switches exist both locally and in the control room on the Condensate and Feedwater Supervisory Panel. The local switches allow "Start and Stop" pushbutton operation of the pumps. The switches in the control room have three positions "On-Auto-Trip". The following conditions will automatically start the pumps as described.

- Automatic loss of either main boiler feed pump will start both No. 31 and No. 33.
- Low-Low steam generator level in any steam generator will start both No. 31 and No. 33.
- In the event of a unit trip which is initiated by a safety injection signal the following Auxiliary Feedwater System events will occur:
  - 1) Actuates the turbine driven AFW pump.
  - 2) The pumps will be provided with a start signal as the safeguards buses are reloaded.

#### APPENDIX A-3.2 System Operating Description (Cont'd)

#### Motor Driven Auxiliary Feedwater Pumps (Cont'd)

- a. Motor Driven Pump Control (Cont'd)
- Loss of outside power without safety injection will provide both pumps with a start signal after the diesels have tied into the 480V buses. A time delay is associated with starting the pumps to allow for loading of the diesels.

Undervoltage on either bus 3A or 6A will trip the pump fed by the bus. The following indication and alarms are provided in the CCR to monitor the pumps.

- Pump on-off-auto trip lights.
- Pump lock off alarm
- Pump auto trip alarm
- Pump on local control alarm

Each motor driven pump is provided with a pressure sustaining control system to prevent the pump from "running out" on its curve. As the discharge press re of the pump decreases below the set point of 1355, PT-406A for No. 31 pump and PT-406B f No. 33 pump will generate a signal that will override the signal from the flow controllers on the Condensate and Feedwater Supervisory Panel. The signal will operate to close the valves until the pressure is restored in the discharge line having low pressure.

APPENDIX A-3.2 System Operating Description (Cont'd)

#### Motor Driven Auxiliary Feedwater Pumps (Cont'd)

#### b. Turbine Driven Auxiliary Feedwater Pump

The full size turbine driven pump is a Worthington Corporation No. 4-WT-127, horizontal, multi-stage, centrifugal pump with a capacity of 800 gpm at 1350 psi.

#### Auxiliary Feedwater Turbine

#### a. Turbine Description

The turbine drive is a Worthington Corporation horizontal axial flow, non-condensing unit rated at 970 HP at 3570 RPM.

#### b. Auxiliary Turbine Steam Supply

Steam to drive the turbine is supplied from the main steam

#### shut ff

will close whenever the temperature in the Pump Room reaches 120°F preset valve. These valves have been added to protect motor driven pumps from being rendered inoperable in the unlikely event of the steam line rupturing within the building.

#### APPENDIX A-3.2 System Operating Description (Cont'd)

#### Auxiliary Feedwater Turbine (Cont'd)

#### b. Auxiliary Turbine Steam Supply (Cont'd)

During turbine operation the steam supply pressure is regulated by PCV-1139. This pressure control valve maintains a 600 psig steam pressure to the turbine. Pressure controller 1176-S senses the downstream pressure and generates a signal for use by the positioner. The control signal generated by the positioner is then applied to the diaphragm of PCV-1139 through the start solenoids (3 and 4). Pressure controller 1176-S will also alarm low pressure at 550 psig in the control room. Once the pressure has been reduced the steam enters the turbine steam chest which contains the governor and turbine trip valves.

To remove moisture in the main steam supply, traps have been provided where necessary. The discharge from the traps have been routed to the main steam trap system which is directed to the drains provided on the turbine casing, steam chest and exhaust piping. The exhaust from the turbine is directed to the atmosphere.

#### c. Auxiliary Turbine Cooling System

The thrust bearing and turbine inboard and outboard bearings are cooled by water from the discharge of the pump.

APPENDIX A-3.2 System Operating Description (Cont'd)

Auxiliary Feedwater Turbine (Cont'd)

#### c. Auxiliary Turbine Cooling System (Cont'd)

A pressure control valve PCV-1213 maintains the water supply to the bearing at 65 psig. The pressure control valve receives its signal from PC-1213 downstream of the control valve. The return water from each bearing is tied together and returned to the condensate storage tank. Flow through each bearing and the combined return temperature are indicated locally.

#### d. Turbine Driven Pump Control

The turbine driven pump is a variable speed device, and the two motor driven pumps are constant speed devices. The speed of the turbine driven pump is governed by a remote pneumatic speed changer (HC-1118) that is located on the Condensate and Feedwater Supervisory Panel in the control room. The speed changeris designed to operate over an entire speed range of 0 to 100%.

Pressure Reducing Valve PCV-1113 is used as the steam shutoff and start valve for the Auxiliary Feed Pump Turbine. The mode of operation of this valve is controlled by "Trip-Auto-On" switches; one located in the control room, and one in the Auxiliary Boiler Feed Pump Building. These switches control the position of f ur solenoid valves mounted on the air inlet

#### APPENDIX A-3.2 System Operating Description (Cont'd)

#### Auxiliary Feedwater Turbine (Cont'd)

#### d. Turbine Driven Pump Control (Cont'd)

to the valve actuator. These solenoid valves are in their de-energized state, which allows the positioner output to open the valve. Normally the valve is maintained in stand-by with the control switches in "Auto". In this position SOV's 1 and 3 are energized, this will cut off the positioner output (SOV-3 closed) and apply full instrument air pressure to the valve actuator (SOV-1 open) holding the valve closed. The SOV's will be de-energized and the pump started by any of the following:

- Low-Low water level in any two of the four steam generators (15% of span).
- Loss of outside power (provided a S.I. signal <u>DOES NOT</u> exist).
- Positioning the control switch to "START".

The turbine governor valve is controlled by a governor and speed changer. The speed changer can be operated locally or from the control room by HC-1118 as shown. A trip valve has been provided to immediately shutdown the turbine on an overspeed of approximately 4516 R.P.M. Turbine speed is indicated in the control room.

APPENDIX A-3.2 System Operating Description (Cont'd)

#### Recirculation Flow Path and Control

An automatic pump recirculation control system is provided on each motor driven pump to recirculate the pump discharge back to the condensate storage tank at low flow. A maintained contact "Close-Auto-Open" control switch and valve position indicating lights are located in the control room on the Condensate and Feedwater Supervisory Panel for each recirculation valve. A manual operator is provided on each valve for local operation. Suction flow is measured by flow switchs FC-1135-S, FC-1135SA-S and FC-1136-S, FC-1135SB-S for pumps No. 31 and No. 32 respectively. These swtiches are provided with contacts which are interlocked as follows:

- A decrease in flow to 100 gpm actuates a low flow annunciatorin the CCR.
- A further decrease in flow to 50 gpm will de-energize solenoid valve SOV 1321 SOV1323 on control valves FCV 1121 and FCV 1123 in the recirculation lines to initiate recirculation flow back to the condensate storage tank and also energize a time-delay relay.
- The time delay interlock functions to trip the pump in the event that the flow does not increase to 100 gpm in a preset amount of time. If the flow returns to above 100 gpm in less than the preset time, the recirculation valve will close, and the trip timer is reset.

If the pump is tripped by the low flow timer, the timer circuit must be reset by selecting the pump to the trip position prior to restarting. This will APPENDIX A-3.0 AUXILIARY FEEDWATER SYSTEM DESCRIPTION (Cont'd)

APPENDIX A-3.2 System Operating Description (Cont'd)

## Recirculation Flow Path and Control (Cont'd)

clear the trip circuit of the auxiliary feed pump circuit breaker and reset the common pump low flow alarm so that a low flow condition on the second pump, if operating, will still be alarmed. Pump control switch manual trip action, or automatic electrical stripping action will automatically perform the above trip timer and low flow alarm reset function. Selecting the recirculation valve control switch to the "Open" or "Close" position will defeat all automatic features (except the low flow alarm) and hold the valve in that position regardless of flow through the pump.

If during the winter a prolonged shutdown of the turbine generator is experienced a means has been provided to heat the condensate storage tank. The recirculation lines back to the condensate storage tank from the two motor driven pumps provides a source of both heat and flow in sufficient quantities to protect the tank from freezing. When using the pumps in this manner the recirculation flow must be adjusted to provide a flow of 125 gpm for each pump, using the special high pressure drop valves BFD-77 and 78. The flow to the tank is extremely important in order to provide the maximum BTU input to the tank with the minimum hazard to the pumps. Only one pump is required to protect the tank from temperatures above 15°F.

The turbine driven pump is provided with a continuous recirculation system back to the condensate storage tank. An additional feature provided on the turbine driven pump is that part of recirculated water is used to cool the thrust bearing and turbine bearings.

APPENDIX A-3.0 AUXILIARY FEEDWATER SYSTEM DESCRIPTION (Cont'd)

APPENDIX A-3.2 System Operating Description (Cont'd)

## Auxiliary Feedpump Flow Con rol

As previously described, two auxiliary feed systems exist which are independent of each other. Flow control to the steam generators is provided by eight controllers located on the Condensate and Feedwater Supervisory Panel in the control room. There are two controllers associated with each steam generator, one each for the feedwater supplies from the motor and turbine driven pumps. Which controller is used will be dependent on the operating conditions of the unit.

Flow indication is provided for each auxiliary feedwater line to each steam generator. The flow nozzle is located in the common terminal line from the steam driven and the motor driven pumps. The output from each of these transmitters is connected to flow indicators located on the Condensate and Feedwater Supervisory Panel and in the auxiliary feedwater pump building. The steam generator wide range level recorders have also been located on this panel.

Level in the steam generator is maintained by positioning the flow controller. All pneumatic instruments associated with the auxiliary pump flow controls are provided with nitrogen back-up. Three nitrogen bottles are located inside the auxiliary feed pump room which connect into the instrument air supply down stream of a check valve. A pressure regulator set at 50 psig will feed nitrogen into the instrument air supply system whenever the normal air supply pressure decreases below this setting. A pressure switch (PC-1355-S) located at the bottles will annunciate in the control room to warn the operator whenever the bottles require changing.

### SYSTEMS INTERACTION STUDY APPENDIX A NOTES TO TABLE A-2.1

#### NOTE:

- (1) Failure mode(s) for each type of component listed on Table 6-1 are summarized as follows:
  - A Complete loss of function due to instantaneous loss of electrical power
    - Loss of one redundant electrical division comcident with loss of all offsite power
    - 2) Loss of all AC power (onsite and offsite)
    - 3) Loss of DC power
    - 4) Other
  - B Complete loss of function due to instantaneous loss of power (other than electrical)
    - 1) Loss of pneumatic power (plant air, compressed gas, etc)
    - 2) Loss of hydraulic power
    - 3) Other (explain where necessary)
  - C Partial loss of function due to instantaneous loss of electrical power
    - 1) Loss of one redundant electrical division comcident with loss of all offsite power
    - 2) Loss of all AC power (onsite and offsite)
    - 3)
    - 4) Other
  - D Partial loss of function due to instantaneous loss of power (other than electrical)
    - Partial loss of pneumatic power (eg crimped air supply line)
    - 2) Partial loss of hydraulic power
    - 3) Other (explain where necessary)
  - E Complete loss of function due to instantaneous mechanical failure(s)
    - 1) plugged component
    - 2) component normally open and does not close
    - 3) component normally closed and does not open
    - 4) component does not start due to mechancial interference
    - 5) other (explain where necessary)

# SYSTEMS INTERACTION STUDY APPENDIX A NOTES TO TABLE A-2.1 (Cont'd)

#### NOTE:

- (1) Failure mode(s) for each type of component listed on Table 6-1 are summarized as follows: (Cont'd)
  - F Partial loss of function due to instantaneous mechanical failure(s)
    - 1) plugged component, partial
    - 2) component normally open and does not close completely
    - 3) component normally closed and does not open completely
    - 4) component does not reach full speed due to mechanical interference
    - 5) other (explain were necessary)
  - G Other failures not covered by A thru F. (describe where necessary)
- (2) It has been assumed that the loss of function, either completely or partially of pressure transmitters, pressure controllers, pneumatic/electrical converters, etc associated with the instrumentation and control components of the auxiliary feedwater system is less limiting than complete or partial loss of controlled component, eg pressure or flow control valves.

JTEM	COMPONENT	FAILURE MODE(S)		METHOD OF		_
No	DESCRIPTION	(SEE NOTE (II)	EFFECT ON SYSTEM	DETECTION	EVALUATION OF FAILURE	CONCLUSION
.*		ABCDEFG				
E-1	FLECTRIC MOTOR 31 FOR AFWPUMP 31,	0	Loss of auxiliary feedwater flow from pump no 31 to steam generators 31	OSTATUS Indication in control room that motor	If break is in sq 31 or 32, motor driven pump 33 will feed sqs 33434	SCCEPTABLE
	CONNECTED TO AC BUS		and 32	breaker is open 2 Pumpdischauge press	turbine driven pump 32 will feed unaffected SG 31 or 32. Operator	
• • •	<u> </u>	•		indication in CR	must terminate flaw from pump 32 to affected SG 31 or 32 by closing	
					If break is in SG 33 or 34, turbine	ACCEPTABLE
					driven pump 33 will feed unaffected SG3. Operator must terminate	
	*				flow to affected SGby closing FCV 405A,B,C ORD	
E-S	ELECTRIC MOTOR 33 FOR AFW PUMP 33, COURCIED TO AC	0	Loss of auxiliary feedwater flow from pump number 33 to steam generators 33 and 34	Same as item E-2	Similiar to Item E-2	A CCEPTABLE
- 2	Bus GA					
E-3	DC COUTROL POWER TO BUS 3A,		Loss of auxiliary feedwater flow from pump number 31 to steam generators 31 and 32	Dow pump discharge pressure indication in control room.	Similar to Item E-2	
E-4	DC BREAKER FOR BUS 34	2	pump number 31 to steam generators	Dstatus indication in control voous that		
			31 and 32	breaker is open		
	DC BREAKER FOR BUS 3A	<b>②</b>	Loss of auxiliary feedwater flow from pump 33 to steam generators 33 and 34	2 low pump discharge pressure indication in confrol room		
E-5	DC COUTROL POWER TO BUS GA	<b>2</b>	loss of auxiliary feedwater flow from pump 33 to Steam generators 33 and 34	Saur as Item E-3	SIMILIAR TO JEM E-3	
E-6	DC BREAKER FOR Bus 6A		Loss of auxiliary feedwater flow from pump 33 to steamgenerators 33 and 34	SAMES AS JIEM F-4	SIMILIAR TO JTEM E-4	<u>,</u>
						•

AUXILIARY FEEDWATER SYSTEM
FAILURE MODES & EFFECTS ANALYSIS
SHEET 1 OF 9
FIGURE A-2.1

JTEM No	COMPONENT DESCRIPTION	FAILURE MODE(S)	EFFECT ON SYSTEM	METHOD OF DETECTION	EVALUATION OF FAILURE	CONCLUSION
M-1		ABCDEFG	Loss of auxiliary feedwater flow from pump 31 to steam generators 31 and 32	1) lowpump discharge pressure indication in confrol voom. (PI-1260)	Similiar to evaluation of item E-1:	Loceptade
			Partial Loss of auxhay fedwater flow from pump 31 to steam generators 31 and 32	i) lowpump discharge pressure undication in control voom. (PI-1260)	Similar to evaluation of Item E-1	Acceptable
11-2	AFW PUMP33 (MOTOR DRIVEN)		{Similar to effects on item M-1	Similar to item M-1	Similar to evaluation of item E-1	Xcceptable
M-3	AFW PUMP 32 (TURBINE DRIVEN)		Lose auxiliary feedwater flow from pump 32 to steam generators 31,32,33 € 34	is low pump discharge pressure indication in confrol room. (PI-1261)	1) Mojor driven pumps 31 and 33 are available and are running. Operator must terminate auxiliary feedwater flow to affected steam generator.	Sceptable
M-4	TURBINE CONTROL SYSTEM FOR AFW PUMP 32-PCV-1139	3	PCV-1139 normally closed, fail closed, system receives automatic start signal and valve fails to open resulting in loss of steam flow to turbine and subsequent loss of feed flow from pump N°32 to SG 31, 32, 33, & 34	1) low pump discharge pressure undication in control room (PI-1261) 2) low Steam inlet press to steam turbine (PI-1126) 3) Valve PCV-1139 position indication (closed) in	Similar to evoluation of item M-3	Xcceptable
			PCV-1139 normally closed, fail closed, system veceives automatic start signal, control room operator begins to open valve, plant air is lost and valve goes fully closed resulting in loss of steam flow to turbine and subsequent loss of feed flow from pump 32 to 5G 31,32,33 & 34		Similar to evaluation of item M-3	Xcceptable

AUXILIARY FEEDWATER SYSTEM
FAILURE MODES & EFFECTS ANALYSIS
SHEET 2 OF 9
FIGURE A-2.1

JTEM	COMPONENT	FAILURE MODE(S)		METHOD OF		
No	DESCRIPTION	(SEE NOTE (11)	EFFECT ON SYSTEM	DETECTION	EVALUATION OF FAILURE	CONCLUSION
M-5	TURBINE TRIP CONTROL	ABCDEFG	Mechanical damage to steam turbine	i) turbine speed indica		200EPINBLE
	System For AFW PUMP 32		vesulting in turbine missile due to loss of overspeed protection - possible damage to turbine/pump couple system resulting in loss of feed flow from pump number 32.  If no mechanical damage, turbine will trip on overspeed		Motor driven pumps 31 and 33 are unaffected by turbine overspeed and ale running. Operator must terminate auxited by the affected affected.	
					steam generator. It nonechanical damage operator must veset system locally realigning valves and set points in Aux Feedwater Building	
M-6	CONDENSAJE STORAGE JANK-LOSS OF SUCTION TO PUMPS		Tank failure results in loss of suction to Xuxulary feedwater pumps number 31,33 and 32 from condensate storage tank	i) Level indication in control room (redunction to be installed) 2) loss pump suction pressure in confrol room (PI-1265, 1263, 1264)	Operator detects tank failure and opens city water backup supply valves PCV-1188, PCV-11187, PCV-1189	Acceptable
M-7	Manual Isolation Valves CT-6, CT-64		loss of suction flow to auxiliary feed water pumps number 31,33,32	vedundant position indicators provided in control voom  ioss of pump suction pressure in confrol room (PI-1265,1763, 1264)	Operator detects plugged valves and opens city water backup Supply Valves, PCV-1188, 1187, \$1189. Operator can also try to manually unplug c7-6 or C7-64	Acceptable
M-3	CITY WATER SUPPLY		City Water Tank failure, no effect on system since primary source of water is from condensate storage tank (short term)	1) low city water press indication in control room (PI-1205)	Not REQUIRED	ACCEPTABLE

AUXILIARY FEEDWATER SYSTEM FAILURE MODES & EFFECTS ANALYSIS SHEET 3 OF 9 FIGURE A-2.1

,	JTEM	COMPONENT	FAILURE MODE(S)	I .	METHOD OF	Evaluation Of Falling	Consulsion
	No	DESCRIPTION	ABCDEFG	EFFECT ON SYSTEM	DETECTION	EVALUATION OF FAILURE	CONCLUSION
	M-9 M-10	Manualisolation gate Valves CT-27, CT-		loss of suction fluid flow to corresponding auxiliary feed water pump		Alternate atywater supply available for operator to	Acceptable
	M-11	30 \$ CT-33		number 31, 32 or 33 and subsequent loss of feed flow to sais 31,32,33 & 34	in control voom,	remotely align the backup water supply to anxilioning feedwater	
	-	<b>t</b> .				pumps 31,32 and 33. Operator must also isolate affected	
		*				steam generator.	, , ,
.	M-12 M-13	Check valve CT-29	3	loss of suction fluid flow from either condensate storage tank or city	i) low pump suction pressure indication in	Since only one check valve is assumed to fail closed,	Acceptable
	M-14 M-15	Check valve c7-32 Check valve c7-25		corresponding auxiliary feedwater	control voom, PI-1263 PI-1264, PI-1265	operator is able to align the backup water supply to Sas 31,32	
-	M-16 M-17	(heek value c7-28 Check value c7-31		pump 31,32 or 33 and subsequent loss of feed flow to SG's 31,32,33 434		\$ 33 operator must also isolate affected steamgenerator	
		Check valve Ms-41	3	loss of steam flow to turbine drive for auxiliary feedwater pump number	SAME AS JEM M-4	SIMILIAR to evaluation	Acceptable
• .	M-19	Check valvems-42		32.	MI- 4	for Item M-4	4 4
	M-21	Check valve BFD-31 Check valve BFD-31 Check valve BFD-39	3	loss of auxiliary feedwater flow to corresponding steamgenerator 31, 32, 33 or 34	i) high pump discharge pressure indication in control room	Similiar to evaluations for Items E-1, E-2 and M-1	Acceptable
	M-23 M-24	Check valve BFD-35 check valve BFD-37	<b>3</b>	loss of auxiliary feedwater flow to SG 32 loss of auxiliary feedwater flow to SG 31	i) high pump discharge pressure indication	If the failure is on the same line as break, a flected SG	Acceptable
		#- 1 1 1			in control voom.	will be isolated by definition. Operator should assure isolation by closing appropriate FCV 406 ACOR 406 B	
		Check valve BFD-40 Check valve BFD-40		loss of auxiliary feedwater flow to 5433	i) high pump discharge pressure undication in control voom.	Similiar to the evaluation performed for Items M.23 & M.24	Acceptable
		Check valve BFD-47-31 Check volve BFD-47-32	1 1 1 1 1 1 1	loss of auxiliary feedwater flow to SG-31 loss of auxiliary feedwater flow to SG-32	i .	Similar to the evaluation performed for Items M-23,	Acceptable

AUXILIARY FEEDWATER SYSTEM
FAILURE MODES & EFFECTS ANALYSIS
SHEET 4 OF 9
FIGURE A-2.1

JTEM		FAILURE MODE(S)	EEEET ON SYSTEM	METHOD OF	Francis OF Faures	Consultan
No	DESCRIPTION	ABCDEFG	EFFECT ON SYSTEM	DETECTION	EVALUATION OF FAILURE	CONCLUSION
M-29 M-30	Check valve BFD-47-34 Check valve BFD-47-34	3	loss of auxiliar, feedwater than to SG-33 loss of auxiliar, feedwater flow to SG-34.	in control voom	M-24, M-25 & M-26.  Operator should assure Isolation of affected SG by clasing appropriate FCV 405 A, 405 B, 405 C OE 405 D.	
M-31 M-32 M-33 M-34 M-35 M-36 M-37 M-38	manual valve BFD-22 manual valve BFD-62-32 manual valve BFD-62-31 manual valve BFD-61-31 manual valve BFD-62-33 manual valve BFD-62-33 manual valve BFD-62-34	99999999	loss of auxhan feedwater flow to SG-32 loss of auxhan feedwater flow to SG-31 loss of auxhan feedwater flow to SG-33 DITTO loss of auxhan feedwater flow to SG-34 DITTO	i) high pump discharge pressure endication in control room - no indication of which volve is failed.	Similiar to the evaluation performed for items M-23 & M-24 and NN-25 & M-26	Acceptable
 M-39	manual valve Ms-54		loss of steam flow to turbine drive for auxiliary feedwater pump 32	i) low steam piess undication in confrol room-no direct undication in confrol roon of which valve has failed.	Similarito the evolution of Item M-4	acceptable
M-40	manual volve c7-49		loss of city water suction fluid flow to auxiliary feedwater pumps 31, 32 and 33	s low city water supply pressure undication in the control room.	Similar to the evolvation of Items M-15, M-16 and M-17	acceptable
M-41 M-42 M-43 M-44 M-45 M-46 M-48	Manual valveBFD-48-31  DITTO -31  DITTO -32  DITTO -32  DITTO -33  DITTO -33  DITTO -34  DITTO -34	000	loss of auxiliary fleidwafer flow from turbine driven pump no 32 to corresponding steam generator	NOUE	Similiar to the evoluation performed for Items M-27, M-28, M-29 4 M-30	acceptable

AUXILIARY FEEDWATER SYSTEM
FAILURE MODES & EFFECTS ANALYSIS
SHEET 5 OF 9
FIGURE A-2.1

JTEM	COMPONEUT DESCRIPTION	FAILURE MODE(S)	EFFECT ON SYSTEM	METHOD OF DETECTION	EVALUATION OF FAILURE	CONCLUSION
M- 49 M- 50 M- 51 M- 52 M- 54 M- 54 M- 56	PCV-1187 SOV-1287 PCV-1188 SOV-1288 PCV-1189 SOV-1189 LCV-1158 SOV-1258			i) Valve undication in control room for open/closed position. Partially open/close position not monitored. Local position indicator only  i) Valve undication in control room for open/closed position only Partially open/closed position not manifored.	backup nitrogen gas supply is available for operation of valve if necessary.  Manual operation will require jacking valve open or closed since no handwheel is provided  redundant level switches on the condensate storage tank provide reliability to the system in regard to alarming low water level in tank.  Mechanical failure of valve	Un acceptable
				Local position indicator only.	however will be independent of actuationsignal and as such, isolation of non- essential users is not assured Operator can take corrective action - close valve manually only after he/she defermines extent of damage - may not be possible	
M-59	Air Operated FCV-406A Air Operated FCV-406B Air Operated FCV 406 C Air Operated FCV 406 D		loss of auxiliary feedwater flow to corresponding steam generator from pump number 31 or 33.  partial loss of auxiliary feedwater flow to corresponding steam generator flow pump number 31 or 33	1) position molication in control room, for open/close only.	turbine driven auxiliary feedward pump and associated confrol volves and appartmences provide redundant auxiliary feedwater flow to una fected steam generator must isolate affected steam generator by clasing FCV 405A, B, COE DI and apparing FCV-1139 to admit steam to turbine. Turbine speed is confrolled by	

AUXILIARY FEEDWATER SYSTEM
FAILURE MODES & EFFECTS ANALYSIS
SHEET 6 OF 9
FIGURE A-2.1

JTEM	COMPONENT	FAILURE MODE	1	METHOD OF	6- F	
No	DESCRIPTION	ABCDEF	EFFECT ON SYSTEM	DETECTION	EVALUATION OF FAILURE	CONCLUSION
M-60 (CON'TD)	<b>.</b>				venote-manual operation from the control room.	
					If loss of functionisdue to complete loss of comprehed air to FCV-406 A,B, C & D. nitrogen backup is provided for volve operation.	
M-62 M-63	Airopenated FCV-405A Airopenated FCV-405B Airopenated FCV-405C Airopenated FCV-405D		Similar to items M-57, M-58, M-59, and M-60	i) position indication in confrol room, for open/close position only	Similar to the evaluation of items M.57, M.58, M.59, M.60	acceptable
	Airoperated automatic high temperature shut- off valve PCV-1310A		these valves are normally open and will automatically close open signal from sensing character and control circuit when temperature in aux feedpump	i) Control voom alarm for high temperature in aux feedpump building	There valves provide protection in the event of a high energy line break in the archang feedpunp building. Valves have 5e panale	acceptable
	Airoperated automatic Nigh temperature shut. of volve PCV-1310B		building reaches 120°F	2) volve position undication in confrol voom	Lenpeteture sensing conjonents and each volve is redundant to the other.	
M-65	PCV-1310A	0 000			For this case 1- an additional	
(Confinued) M-66	PCV-1310B				passive high energy pipe buck need not be costulated in the	
(Confinued)	<b>≠</b>				short term. In the long-term a passive pipe break in the steam Supply line to the Turbine is provided with adequate redundancy to isolate steam	
M-67 M-68	Air querated FCV-1121 SOV-1321		Not Enough INFORMATION		blaudaun into the reon	
	Auroperated FCV-1123 Sov - 1323	(H)	TO COMPLETELY EVALUATE			
M-71	Air operated PCV-1213		THESE FAILURES			

AUXILIARY FEEDWATER SYSTEM FAILURE MODES & EFFECTS ANALYSIS SHEET 7 OF 9 FIGURE A-2.1

	JTEM NO	COMPONEUT DESCRIPTION	FAILURE MODE(S)	EFFECT ON SYSTEM	METHOD OF DETECTION	EVALUATION OF FAILURE	CONCLUSION	
	I-I		ABCDEFG OOOO	Smiliar to mechanical component M-65 and M-66	Mone	Similiar to the evaluation of Item M-65 and M-66		
	I-2	Valve controller on valve PCY-13103	0000	Similar to mechanical component M-65 and M-66	None	- DITTO ABOVE-		
·	1-3	Temp sensor on valve PCV-1310 A		Ditto Xbove	Dirro	- Ditto-		
	<b>Z-4</b>	Temp sensor on volve PCV-1310 B	0 0 0 0 2 0	DITTO ÁBOVE	Ditto	- Ditto-		
	J-5 I-6	Flaw controller FC-1136 Flow confroller FC-1136 A	0000					-
	I-7 I-8	Flow confroller FC-1135 Flow confroller FC-1135	0 0 0 0 0 0 0 0					
. <del></del>	I-9	PT- 1265		SEE Noje 2	Noue	SEE NOIE 2		٠
	I-10	PT-1262		- DITTO	None	- D1770-		
	1-11	PT- 4068	0000	- DITTO-	None	- DITTO-		
-	I-12	PM- 406H HC- 406D		- Ditto-	None	- DITTO-		

AUXILIARY FEEDWATER SYSTEM
FAILURE MODES & EFFECTS ANALYSIS
SHEET 8 OF 9
FIGURE A-2.1

JTEM	COMPONENT DESCRIPTION	FAILURE MODE(S)	EFFECT ON SYSTEM	METHOD OF DETECTION	EVALUATION OF FAILURE	CONCLUSION
<u> </u>	DESCRIPTION	ABCDEFG	<u> </u>	DEJECTION	EVACUATION OF TAILURE	CONCLUSION
J-13	PM-406G HC-406C		- Ditto-	NOVE	- Ditto-	
7-14	PT-1263	000	- DITTO-	NOUE	- DITTO -	
I-15	PT-1260	0000	- DITTO-	Nove	- Di770-	
I-16	PT- 406 A	0000	-D1710 -	NOUE	- Ditto-	
1-17	PM- 406 E: HC- 406 A	000	- Ditto-	Nove	- Di770-	
1-18	PM-406F HC-406B	0000	- D1710 -	Noue	- 17:70-	
1-19	PT-1264	0000	- DITTO-	NOVE	- DITTO-	
T-20	F. 1213		SEE NOTE 2	None	SEE NOIE 2	
1-21	FT- 1261	0000	- D1770 ·	Noue	- D1710 -	
1-22	PT-1205	0000	- Di770-	None	- Driro-	
1-23	PC-1176	0000	- Di770-	Nove	- DITTO-	
1-24	PT- 1126	0000	- D1770-	Nove	- DiTTO-	
1-25	PC-1355		- Ditto-	None	-D1710-	

AUXILIARY FEEDWATER SYSTEM
FAILURE MODES & EFFECTS ANALYSIS
SHEET 9 OF 9
FIGURE A-2.1

### SYSTEMS INTERACTION STUDY APPENDIX A NOTES TO TABLE A-2.1


#### NOTE:


- Failure mode(s) for each type of component listed on Table 6-1 are summarized as follows:
  - A Complete loss of function due to instantaneous loss of . electrical power
    - 1) Loss of one redundant electrical division comcident with loss of all offsite power
    - 2) Loss of all AC power (onsite and offsite)
    - 3) Loss of DC power
    - 4) Other
  - B Complete loss of function due to instantaneous loss of power (other than electrical)
    - 1) Loss of pneumatic power (plant air, compressed gas, etc)
    - 2) Loss of hydraulic power
    - 3) Other (explain where necessary)
  - C Partial loss of function due to instantaneous loss of electrical power
    - 1) Loss of one redundant electrical division comcident with loss of all offsite power
    - Loss of all AC power (onsite and offsite)
    - 3) Loss of DC power
    - 4) Other
  - D Partial loss of function due to instantaneous loss of power (other than electrical)
    - Partial loss of pneumatic power (eg crimped air supply line) Partial loss of hydraulic power 1)
    - 2)
    - Other (explain where necessary)
  - E Complete loss of function due to instantaneous mechanical failure(s)
    - plugged component
    - 2) component normally open and does not close
    - 3) component normally closed and does not open
    - 4) component does not start due to mechancial interference
    - other (explain where necessary)

# SYSTEMS INTERACTION STUDY APPENDIX A NOTES TO TABLE A-2.1 (Cont'd)


#### NOTE:


- (1) Failure mode(s) for each type of component listed on Table 6-1 are summarized as follows: (Cont'd)
  - F Partial loss of function due to instantaneous mechanical failure(s)
    - 1) plugged component, partial
    - 2) component normally open and does not close completely
    - 3) component normally closed and does not open completely
    - 4) component does not reach full speed due to mechanical interference
    - 5) other (explain were necessary)
  - G Other failures not covered by A thru F. (describe where necessary)
- (2) It has been assumed that the loss of function, either completely or partially of pressure transmitters, pressure controllers, pneumatic/electrical converters, etc associated with the instrumentation and control components of the auxiliary feedwater system is less limiting than complete or partial loss of controlled component, eg pressure or flow control valves.







SHEET 2 OF 9







SLEET 4 OF 9






SHEET 6 OF 9









## SHEET 9 OF 9

Power Authority of the State of New York INDIAN POINT NO. 3 NUCLEAR POWER PLANT SYSTEMS INTERACTION STUDY AUXILIARY FEEDWATER SYSTEM

FAULT TREES FIGURE A-2.2








Power Authority of the State of New York INDIAN POINT NO. 3 NUCLEAR POWER PLANT SYSTEMS INTERACTION STUDY


ELECTRIC POWER SYSTEM DIAGRAM


FIGURE A-2.4


























SOURCE 01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 VALVES ELEC. BOX
SX-I
WALL BOX THEBLAL
321 (322 COUPLE SPACE HTREG SPACE HTR#4 4" DR. LINE FLEC. BOX SX-3 SPACE HTR# LIGHT #3 8"CT-1074 38 CT-83 (I"VENT) 6"CT-1074 39 CT-82(1" DR.) 26 30 40 CT-31 26 30 41 PCV-1189 26 30 42 SOV-1289 6"CT-1075 43 CT-8 (1" DR.) 17 17 17 18 19 19 44 CT-25 (CHECK) (18) (19) 17 17 17 45 PCV-1187 46 SOV-1287 8°CT-1076 47 CT-82 (1"DR.) **ÖB** 69 48 CT-28 BUILDING: AFW PUMP BLOG FIRE ZONE: \_\_ FOWER AUTHORITZ OF STATE OF NEW YORK INDIAN POINT NO B NUCLEAR FOWER PLANT MATRIX EBASCO SERVICES INCORPORATED No. VA NA LOCATION: DIV. MUE DR.MG. DATE JUISI CHI SCALE NOUS APPROVED WITHIN FIRE ZONE

SYSTEMS INTERACTION STUDY INTERACTION MATRIX

SHEET 9/39

BUILDING: AFW PUMP BLOG

FIRE ZONE:

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 09-02-48-09

INTERACTION SKETCH NO.

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Elect Box SX-2 (Target) CT-23, check volve

DESCRIPTION OF POSTULATED INTERACTION:

Elect best faits fum support and hets CT-28 check Valve.

EVALUATION & DISPOSITION OF INTERACTION:

Oceplable interaction - insufficient mass

BUILDING: AFW PUMP BLDG

FIRE ZONE:

23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 09-03-44-17, 09-03-45-17, 09-04-44-17, 09-04-45-17

INTERACTION SKETCH NO.: 09-05-44-17, 09-05-45-17

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) EUH # 311, ELECT BOX SX-1, ELECT BOX 321 & 322, SPACE HTR#3
LIGHT FIXTURE #3, SPACE HEATER#4

(Taiget) CT-25 checkVolve

DESCRIPTION OF POSTULATED INTERACTION:

Sources identified fail from support and hit CT-75 sheek volve

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction-check volve cannot be damaged by source items

Joquandi 2/9/8/ Interaction Engineer/Date

BUILDING: AFW PUMP BLOG

FIRE ZONE:

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 09-06-44-18, 09-06-45-18

INTERACTION SKETCH NO.:

45-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Spoce heater # 3 (2019-1) C7-25 che ex volve PCV-1187

DESCRIPTION OF POSTULATED INTERACTION

Space heater #3 fails from support and hets CT-25 and PCV-1182

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable interaction- PCV-118) contre damoged and lose functionability

BUILDING: KFW PUMP BLAG

FIRE ZONE:

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 59-07-41-19,09-07-45-19,09-08-44-19,

INTERACTION SKETCH NO.:

09-08-45-19

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) lighting fixture #3, Space heater #4 (Target) PCV-1187

lighting fixture and grace heaten # 4 fait from supports and hit PCV-1187

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable interoction - loss of function is credible.

BUILDING: KFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 09-09-40-26, 09-09-41-26, 09-09-42-26

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 4" plumbin, cham line (Targot) CT-31, PCV-1189 w SOV-1289

DESCRIPTION OF POSTULATED INTERACTION:

4" Humbing drain leve fails from Support and hits c7-31 and PCV-1189/w SOV-1289

EVALUATION & DISPOSITION OF INTERACTION:

29-09-40-26 is acceptable-noclamage Interaction with PCV-1189 W/50V-1289 is unacceptable-loss of function is cudible

Interaction Engineer/Date

Reviewer/Date 2/10/21

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 09-10-40-30, 09-10-41-30, 09-10-42-30

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Sour Ee) Electrical conduit box 5x-3 (target) CT-31, PCV-1189 W/SOV-1289

DESCRIPTION OF POSTULATED INTERACTION:

Electbox fails and hits CT-31, PCV-1189 W/80V-1289

EVALUATION & DISPOSITION OF INTERACTION:

and sov-129

Intéraction Engineer/Date

Reviewer/Date 210/81

BUILDING: AFW PUMP BLOG

FIRE ZONE:

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 09-11-38-38

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

DESCRIPTION OF POSTULATED INTERACTION:

EVALUATION & DESPOSITION OF INTERACTION:

Interaction Engineer/Date

								٠.					S	00	IR.	\	<u> </u>		· · · · · · · · · · · · · · · · · · ·				:					:			والجواحد		
		01	OS	03	04	05					,										:												
V	ALVES	Linds		SAIL	Finc	HTR# 5													-							,							
		ELEC. BOX	LIGHT #	Mono R	4"CONDUIT	SPACE H															•	-									•		
	6"CT-1073											-						1	!		.=				# # # #								-
56	CT-82 (1" DR.)																							-									1
27	CT-26	24			-																	. ,		-	ł								-
85	CT-27	24								·						-																	-
29	CT-35 (RELIEF	)																	VANDAGE 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1						į.								
30	CT-84 (INSTR.	<b>)</b>					-									-																	-
31	CT-84 (INSTR.	)												-								, ,		· .									
32	CT-59 (1/2 INSTR.)	<b>)</b>																		·													T
33	CT-83 (I"VENT	)					<u> </u>	-																	P.								1
34	ст-94	,	48	48	48	48																		-									1
	CT-94		48	48	48	48													-														1
36	CT-98(34" DR.)	<b>\</b>							<u> </u> -																		:						
	172°CT-1159									ļ										-					) i								
37	CT-85					1.													-									-	: -				1
			<u>                                     </u>																						-			·					T
	NG: AFW		IMP	> ₹	Li>	હ	· ·									· ·									1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	:		2 -					
CAT	· · · · · · · · · · · · · · · · · · ·	> \/ <i>H</i>	7												. · · · .	Annual Control		SER DR.			ORPC PPRO	_			1			•	NLYCE NT UDY	- 1	NO.	<b>V3</b>	

APPROVED

NUCLEAR FOWER PLANT SYSTEMS INTERACTION STUDY
INTERACTION MATRIX

INCHES !

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 08-01-27-24,08-01-28-24

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Elect Conduit Box #232 (Tanget) CT-26, CT-27

DESCRIPTION OF POSTULATED INTERACTION:

Concert box fails from support and hits

EVALUATION & DISPOSITION OF INTERACTION:

do cause loss of function. Insufficient wan

Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLOG

FIRE ZONE: 2

LOCATION WITHIN FIRE ZONE: WA

INTERACTION NO.: 08-02-34-48, 08-02-35-48

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

DESCRIPTION OF POSTULATED INTERACTION:

EVALUATION & DISPOSITION OF INTERACTION:

Interaction Engineer/Date

Reviewer/Date

BUILDING: XFW PUMPBLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: UA

INTERACTION NO.: 08-03-34-48, 08-03-35-48

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

DESCRIPTION OF POSTULATED INTERACTION:

EVALUATION & DISPOSITION OF INTERACTION:

Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMPBLOG

FIRE ZONE: 33

LOCATION WITHIN FIRE ZONE: MA

INTERACTION NO.: 08-04-34-48, 08-04-35-48

INTERACTION SKETCH NO .:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

DESCRIPTION OF POSTULATED INTERACTION:

EVALUATION & DISPOSITION OF INTERACTION:

Interaction Engineer/Date

Reviewer/Date

BUILDING: 🙏	FW PU	IMP 13	LDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 08-05-34-48,08-05-35-48

INTERACTION SKETCH NO.:

X5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

DESCRIPTION OF POSTULATED INTERACTION:

EVALUATION & DISPOSITION OF INTERACTION:

Interaction Engineer/Date

Reviewer/Date

SOURCE 01 02 03 04 05 VALVES 4'41% CONDUIT LIGHT #5 Mono RAIL 6°CT-1072 14 CT-82 (1" DR.) 15 CT-32 32 16 CT-33 32 CT-35 (RELIEF.) 18 CT-84 (INSTR.) 19 CT-84(INSTR) 20 CT-83 (1"VENT) 45 45 45 21 CT-94 5 45 45 45 X 22 CT-94 23 CT-98(3/4" DR.) 1/2"CT-1160 24 CT-85 6"CT-1072 45 45 45 25 CT-59 (1/2 INSTR

BUILDING :	AFW PUMP BLD	<u>G</u>
_	12	
FIRE ZONE:		
LOCATION:	NA	
WITHIN FIRE	ZONE	

EBASCO SERVICE	S INCORPORATED	
DIV. MUE DR. MG	APPROVED	
DATE 32481 CHIME		5
SCALE LONE		

INDIAN POINT NO B NUCLEAR POWER PLANT

NO.VE

SYSTEMS INTERACTION STUDY INTERACTION MATRIX

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 07-01-15-32,07-01-16-32

INTERACTION SKETCH NO.:

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Switch Box & conduit (Tanget) CT-32, CT-33

DESCRIPTION OF POSTULATED INTERACTION:

Switch box fails from support and hits C7-32 and CT-33

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable interaction - insufficient man to cause loss of function

Interaction Engineer/Date

BUILDING:	AFW	PUMP	BLDG
-----------	-----	------	------

FIRE ZONE:

23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 07-02-21-45,07-02-22-45,07-02-25-45

INTERACTION SKETCH NO.:

X5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

DESCRIPTION OF POSTULATED INTERACTION:

EVALUATION & DISPOSITION OF INTERACTION:

Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BIDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 07-03-21-45, 07-03-22-45, 07-03-25-45

INTERACTION SKETCH NO.:

X5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

DESCRIPTION OF POSTULATED INTERACTION:

EVALUATION & DISPOSITION OF INTERACTION:

Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLDG

FIRE ZONE:

23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 07-04-21-45, 07-04-22-45, 07-94-25-45

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

DESCRIPTION OF POSTULATED INTERACTION:

EVALUATION & DISPOSITION OF INTERACTION:

Interaction Engineer/Date

Reviewer/Date

SOURCE 01 02 03 04 05 06 07 08 09 VALVES EXIDE LTG. & Ba PSSW FOR HTR EUH 310 SPEAKER ELEC. BOX & MONO RAIL LIGHT # 2 4"COMDUIT 12"CT 1070 01 CT-6 1701 TO'S 39 39 02 CT-64 (HDR.) 03 CT-82 (1" DR) 13 13 13 04 CT-29 13 13 13 05 CT-30 06 CT-35 (RELIEF) 07 CT-84 (INSTR.) 08 CT-84 (INSTR) 09 CT-83 (1" VENT) 46 46 46 10 CT-94 11 CT-94 46 46 46 12 CT-98(34" DR) 13 CT-83 (1" VENT)

BUILDING :	LFW PUMP	BUILDING	
FIRE ZONE:	0.3		
LOCATION:	NX		
WITHIN FIRE	ZONE	•	

EBASCO	SERVICES	INCORPORATED	;
DIV. LIVE	DR.146	APPROVED	
2475 3 11/16	1/au M_1		

CALCARTA CREM CECTATE OF NEW YORK
INDICATED THE PONT TO BE
INDICATED FONER PLANT

No. VI

DATE 3 MB CH M STITEMS INTERFACTION ISTUE SCALE NOVE MATRIX

BUILDING: AFW PUMP BIDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 06-01-04-13, 06-01-05-13

INTERACTION SKETCH NO.:

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Electricol Wall Box

(Tanget) CT-29, CT-30

DESCRIPTION OF POSTULATED INTERACTION:

Wallbox fails from support and hits C7-29 & C7-30

EVALUATION & DISPOSITION OF INTERACTION:

acceptable interaction. Fisufficient meass

BUILDING: AFW PUMP BLDG

FIRE ZONE:

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 06-02-04-13, 06-02-05-13

INTERACTION SKETCH NO.:

45-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Exide lighting Box (Target) CT-29, CT-30

DESCRIPTION OF POSTULATED INTERACTION:

lighten box fails fromwall support and hits C1-29 and C7-30

EVALUATION & DISPOSITION OF INTERACTION:

acceptable interaction-insufficient mass

SHEET 3 OF &

POWER AUTHORITY OF THE STATE OF NEW YORK INDIAN POINT 3 NUCLEAR POWER PLANT SYSTEMS INTERACTION STUDY EXTERNALLY INDUCED SYSTEMS INTERACTION INTERACTION DOCUMENTATION SHEET

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 06-03-04-13, 06-03-05-13

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Unit Deater #300

(Tanget) CT-29, CT-30

DESCRIPTION OF POSTULATED INTERACTION:

Enit heater #310 fails from supports and buts 07.29 =7-30

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable interoction - nodamage possible

Interaction Engineer/Date

Reviewer/Date(

2/10/81

BUILDING: AFW PUMPBLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 06-04-02-39

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Paging Speaker (Target) CT-64 w/ limit switches

DESCRIPTION OF POSTULATED INTERACTION:

Paging 5 pearson fails from support and hits CT-64 w/lemit switches

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable interaction-speaker candanage lemit switches which are required for status industion.

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: 14

INTERACTION NO.: 06-05-02-39

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Electrical Box Q-27 (Target) CT-64 w/lemit switches

DESCRIPTION OF POSTULATED INTERACTION:

electrical lox Q-77 fails from support and hets C7-64/w lemit switches

EVALUATION & DISPOSITION OF INTERACTION:

Charceptable interection. Volve Status andication is necessary for sofe plant operation.

Maghar 6 2/9/8/ Interaction Engineer/Date

Reviewer/Date/

2/10/81

BUILDING: AFW DUMP BLDG

FIRE ZONE:

23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 06-06-10-46, 06-06-11-46

INTERACTION SKETCH NO.:

45-1

IDENTIFICATION OF INTERACTION COMPONENTS:

Source Monovaid

(Target)

DESCRIPTION OF POSTULATED INTERACTION:

EVALUATION & DISPOSITION OF INTERACTION:

Interaction Engineer/Date

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: WA

INTERACTION NO.: 06-07-10-46, 06-07-11-46

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

DESCRIPTION OF POSTULATED INTERACTION:

EVALUATION & DISPOSITION OF INTERACTION:

Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 06-07-10-46,06-07-11-46

INTERACTION SKETCH NO.:

Á5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

DESCRIPTION OF POSTULATED INTERACTION:

EVALUATION & DISPOSITION OF INTERACTION:

Interaction Engineer/Date

Reviewer/Date

			•												S		R												٠		•			
		•		01	OS	60	04	05	06	07	80	09	Ø													,								·
	11	1E			20	12		HTR*20	TR 21	ଏହରେ <b>24</b>																								
-	· .			ELEC. BOX	LIGHT #	LIGHT #	LEC.	SPACE	SPACE	22,23 4 24																				·				
0	1	4 BFD 4 BFD 4 BFD 4 BFD	-1001	80/	81		84	83	85	85										<u> </u>	<u>                                     </u>													
0	2	4 BFD	-1002	80/	81	1	84	83	85	85	-				1																			<u> </u>
10	3	4 BFD	- 1003	80/	81	82		<u></u>		85											<del> </del>					li i								
10	4	4 BFD	-1004	80	81	82	1		<del>                                     </del>	85		-,	·								<del>                                     </del>						·							
10	5 .	4" MS- 10"MS 12" MS	1027	80/		82	<u> </u>	L 				-							<u> </u> 		<u> </u>		<del> </del>											
10	6	IO"MS	- 1016	80/		82	4								-			-				ļ		· · · · · · · · · · · · · · · · · · ·				<del> </del>						-
10	7	12" MS	. 1017	80/	91			<u> </u>		·												<del> </del>		,		<u>-</u>								-
	•	<u> </u>	.0.,	/83	01			ļ						 <del>                                     </del>		-			<u> </u>			1				!								-
	+			<del> </del>		<u>                                     </u>										<u> </u>										<del></del> -								-
-	$\dashv$	, ,				·								-	159							<u> </u> -		-								· .	-	<del> </del>
_	+				<u> </u>										-				·			-				 			ļ					<u> </u>
	_			<u></u> ,		ļ	ļ							ļ	ļ							<u> </u>				 	ļ							
_				<u> </u>		ļ																<u> </u>												
																					<u> </u>					),   	·		,					
	T	· · · · · · · · · · · · · · · · · · ·		.]																					:	·		·						

BUILDING: KUXILL	ary FEEDPU	MP BUILDI	૭૯
FIRE ZONE:	52A		:
LOCATION:	NA		
WITHIN FIRE ZONE	·		

	EBASCO SERVICE	S INCORPORATED	(	7.
	DIV MUE DR. MG	APPROVED		
- 1	DATE 3 RUBICH M		1 5	,

FOWER AUTHORITY OF STATE OF NEW YORK INDIAN POINT NO 3 NUCLEAR FOWER PLANT

IVIATRIX No.LS

SYSTEMS INTERACTION STUDY
INTERACTION MATRIX

SHEET5/29

BUILDING: AFW PUMP BLDG

FIRE ZONE: 52A

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 05-01-101-80/82, 05-01-102-80/82, 05-01-103-80/82 INTERACTION SKETCH NO.: 05-01-104-80/82, 05-01-105-80/82, 05-01-106-89/82

54 A5-2 05-01-107-80/82

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Electrical Concuit Box 57-6

(Tangots) 4"BFD-1001,1002,1003,1004

4" MS-1027

10"115-1016

121115-1017

DESCRIPTION OF POSTULATED INTERACTION:

Conduit box fails from surport and his Vienuous pipes.

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable interaction - ensufficient size and mais Lo damage Largets

BUILDING: A FW PUMP BLDG

FIRE ZONE: 52A

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 05-02-101,05-02-102,05-02-103,05-02-104,

INTERACTION SKETCH NO.: 05-02-107-81

A5-2

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) leghting fixture #20 (Tanget) 4# BFD-1001,1002,1003,1004 12" MS-1017

DESCRIPTION OF POSTULATED INTERACTION:

light fixture fails from Support and hits 4"BFD-1001,1002,1003,1004 and 12"MS-1017

EVALUATION & DISPOSITION OF INTERACTION:

acceptable interaction - ensufficient mess

Interaction Engineer/Date

Reviewer/Date 0

BUILDING: AFW PUMP BLDG

FIRE ZONE: 52A

LOCATION WITHIN FIRE ZONE: MA

INTERACTION NO.: 05-03-103-82, 05-03-104-82, 05-03-105-82, 05-03-106-82

INTERACTION SKETCH NO.:

A5-2

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) leghteny fixture #21 (7aigct) 4"BFD-1003,1004 4" MS-1007,10"MS-1016

DESCRIPTION OF POSTULATED INTERACTION:

Leghting fixture fails from support and hits 4"8FD-1003 and 4"BFD-1004, and 4"MS-1017, 10"MS-1016

EVALUATION & DISPOSITION OF INTERACTION:

acceptable interoction insufficientmess

Manual 2/9/8/
Interaction Engineer/Date

Neviewer/Date

BUILDING: AFW PUMP BLDG

FIRE ZONE:

52A

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 05-04-101-84, 05-04-102-84

INTERACTION SKETCH NO.:

15-2

IDENTIFICATION OF INTERACTION COMPON

(Sour a) Electrical Populing Ponel ( Target) 4"BFD-1001

4BFD-1002

DESCRIPTION OF POSTULATED INTERACTION:

lighter panel fail from sepport and hits 4"BFD-1001 and 4"BFD-1002

EVALUATION & DISPOSITION OF INTERACTION:

acceptable interaction-insufficient mess

BUILDING: AFW PUMP BLDG

FIRE ZONE:

52A

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 05-05-101-83, 05-05-102-83

INTERACTION SKETCH NO.:

A5-2

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Space Heater #20 (nget) 4"3FD-1001 4"3FD-1002

DESCRIPTION OF POSTULATED INTERACTION:

Space heater # 20 fails from support and bits 4"BFD-1001 and 4"BFD-1002

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable interoction - Space heater # 20 con couse loss of function of lines.

Interaction Engineer/Date

Reviewer/Date 2/10/81

BUILDING: AFW DUMP BLDG

FIRE ZONE:

52A

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 05-06-101-85, 05-06-102-85

INTERACTION SKETCH NO.:

A5-2

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Space Heater #21 (Target) 4"BFD-1001 4" BFD-1002

DESCRIPTION OF POSTULATED INTERACTION:

Space heater#21 fails from support onl hits 4"BFD -1001 & 1003

EVALUATION & DISPOSITION OF INTERACTION:

Unouptable Meroction-loss of function credible

BUILDING: AFW PUMP BIDG

FIRE ZONE:

52A

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 05-07-101-85,05-07-102-85, 05-07-103-85

INTERACTION SKETCH NO.: 05-07-104-85

X5-2

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) lighting fixtures 20,23,24 (Targets) 4"BFD-1001, 1002, 1003, 1004

DESCRIPTION OF POSTULATED INTERACTION:

light fixtures fail from supports and Ents 4"BFD-1001, 1002, 1003, 1004

EVALUATION & DISPOSITION OF INTERACTION:

acceptable interoctions-consufficient

SOURCE 05 00 07 08 U5 04 LINE LIGHT # 14 4" CONDUIT LIGHT #15 LIGHT # LIGHT # 06 6"CT-1073 13 3 BFD - 1001 49/50 49/ 14 3 BFD-1002 15 4"BFD - 1003 16 3"BFD-1003 61 61 63 17 3"BFD-1004 6161 ď 0 BUILDING: XXXLIARY FEED PUMP BUILDING FIRE ZONE: 23 INDIAN POINTING 3 NUCLEAR FOWER PLANT MATRIX No.L 4 EBASCO SERVICES INCORPORATED LOCATION: WITHIN FIRE ZONE DIV. MUE DR 36 DATE 3248L CHINE SCALE NOVE APPROVED SYSTEMS INTERACTION STUDY SHEET4/39

.

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 04-01-06-48

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 4" Electrical conduit

(Tanget) 6" CT-1073

DESCRIPTION OF POSTULATED INTERACTION:

4"electrical conduit fails from support and hits 6"c7-1073

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable interaction, elect conduct is of insufficient signandmens bodamage 6"c7-1073

Maghardi 2/9/8/ Interaction Engineer/Date

Reviewer/Date 0

BUILDING: AFW PUMP BLDG

FIRE ZONE:

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 04-02-06-48

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) lighting fixture #4 (Target) 6"CT-1073

DESCRIPTION OF POSTULATED INTERACTION:

lighting fixture # 4 fails from support and hits 6"07-1073

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable Interaction-lighting fixture is if on sufficient size and was to damage 6"107-1073

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 04-03-13-49/50, 04-03-14-49/50

INTERACTION SKETCH NO .:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) lighting fixture# 15 Tauget) 3"BFD-1001 3" BFD- 1002

lighting fixture #15 fails fum support and hets 3"BFD-1001 and 3"BFD-1002

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable interoction- Insufficient moss to damage 3"BFD-1001 & 1002

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 04-04-15-54/59

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) lighting fextere 48 (Tanget) 4"BFD-1003

DESCRIPTION OF POSTULATED INTERACTION:

leght fixture #8 fails from Support and huts 413FD 1003

EVALUATION & DISPOSITION OF INTERACTION:

acceptable interoctions - insufficient mass

SHEET 5 OF 9

POWER AUTHORITY OF THE STATE OF NEW YORK INDIAN POINT 3 NUCLEAR POWER PLANT SYSTEMS INTERACTION STUDY EXTERNALLY INDUCED SYSTEMS INTERACTION INTERACTION DOCUMENTATION SHEET

BUILDING: AFW PUMP BLDG

FIRE ZONE:  $\lambda$ 3

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 04-05-15-54/59

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 5" Elect Conduit (Target) 4" BFD-1003

5" electrical conduit fails from supports and hits 4" BFD-1003

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable interaction, 5" conduit con cause loss of function of 4"13FD-1003

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 04-06-15-54/59

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 3" electrical conduit

(Target) 4" BFD-1003

DESCRIPTION OF POSTULATED INTERACTION:

3" electrial conduct fails from syport and buts 4"BFD-1003

EVALUATION & DISPOSITION OF INTERACTION:

Coceptable entertation insufficient size and moss Le damage 4"3FD-1003

Mograndi 49/8/ Interagtion Engineer/Date

Reviewer/Date 10/8

BUILDING: AFW PUMP BUILDING

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 04-07-16-61, 04-07-17-61

INTERACTION SKETCH NO.

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Lighting fixture # 14 (Target) 3"BFD-1003 3" BFD-1004

DESCRIPTION OF POSTULATED INTERACTION:

light fixture fails from syports and hits 3"BFD-1003 and 3"BFD-1004

EVALUATION & DISPOSITION OF INTERACTION:

Ecceptable interaction-insufficient. Sincan mais

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: //

INTERACTION NO.: 04-08-16-61, 04-08-17-61

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Wall lighting Pisterie and conduit
(Target) 3" BFD-1003
3" BFD-1004

DESCRIPTION OF POSTULATED INTERACTION:

Wall lighting fixture fails from support and hits 3"BFD-1003 and 3"BFD-1004

EVALUATION & DISPOSITION OF INTERACTION:

acceptable interaction- insufficient mass

Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW DUMP BLG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: WA

INTERACTION NO.: 04-09-16-63

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Souvie) Electrical Conduits, Small 12" (Target) 3" 8FD-1003

Electrical conduct fails from Export and heto 3"BFD-1003

EVALUATION & DISPOSITION OF INTERACTION:

acceptable interoction - insufficient muss

Interaction Engineer/Date

Reviewer/Date

					*C#*C #1550**\$620##	annos politicas.									S	0									A run etch	. 1									
		•	01	OS	03	04	05	06	70	80	09	10								7		777			!						·				<u>:</u>
	LII	NE		CATION	TINONO	SECURITY ALARM BOX & CONDUIT	NO RAIL	LIGHT #2										-											•						
	31	2"CD-1031																																	<u></u> :
	32	4"M5-1027			62		63 65	165	CA/ 65																										
	33	1" M5-1120													ļ. -			-																	
,		1" M5-1121										ļ														ļ					:			·	
	35	10"MS- 1016		ļ <u></u>											ļ	<u> </u>	-																		:
	36	12"MS-1017				-			·			<u> </u>			ļ					<u> </u>															
	37	2" LA (LINE)	36	40		ļ		ļ														•									· .				· · · · · · · · · · · · · · · · · · ·
	38	S. FC(rine)		4	42	42						-	-		-		_																		<u>.</u> <u>!</u>
G.F.		12"M5- 1016 12"M5- 1017 2" LA(LINE) 2" LC(LINE)		-								-		-		-									<u> </u>				•.	·			 		. ! !
AR	-			<u> </u>		-		<u> </u>				-			<u> </u>	-							-		1							ļ. 			
1	-			-								-			-	+							-	-		i									
				<u> </u>		·		-			-		<u> </u>			-			ļ				<del>                                     </del>												
	-		-	<u>  ·                                     </u>			-	<u> </u>			-	-	-			-										i									
					-	-		-	ļ			<del> </del>														1									
					<u> </u>		<u>                                     </u>			<u> </u>	1	<u> </u>		<u> </u>	1			1		<u> </u>	<u></u>		<u></u>	1 .	<u> </u>			]			<u> </u>				
BL	IILDI	NG: AUXILLA	ey Fe	ED	Pum	p B	JILD	wę		· ·	<del></del>								•		÷														/
i	EBASCO SERVICES INCORPORATED FOWER AUTHORITY OF STATE OF NEW YORK NATRIX NO.L3  OCATION: NATRIX NO.L3																																		
LC WI	OCATION: NA SHEET 3/39  OTHER ZONE  OTHER ACTION STUDY  SCALE NOVE INTERACTION MATRIX														DIV. DAT SCA	W T		APPRO	DVED		SYS	TEM	UDY	. 1											

HICHES PHONE

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 03-01-37-36

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Electrical box 5x-7 (Tanget) 2"LA pump recirc line

DESCRIPTION OF POSTULATED INTERACTION:

electrical box 5x-7 fails from support and hits 2"LA pump recire line.

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable intercetion - elect box cannot domage 2"LA purp recinc line

Interaction Engineer/Date

Reviewer/Date 7/10/2

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 03-02-37-40, 03-02-38-40

INTERACTION SKETCH NO.:

15-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Ventilation Lawres (Target) 2"LA Recive Line 2" LC Recive Line

DESCRIPTION OF POSTULATED INTERACTION:

Ventlation louvers fail from support structure and hets 2" LA &LC recirculation lines.

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable interaction, adequate isolation provisions

BUILDING: A FW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: A/A

INTERACTION NO.: 03-03-32-62, 03-03-38-42

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

Source 3" Electrical Conduit

(Targel) 4"M5-1027

2" LC recirculation line

DESCRIPTION OF POSTULATED INTERACTION:

3" electrical conduit fails from support and hits 4"M3-1027 line and 2" Le recirulation line.

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable interaction, conchit is yensufficient size and mass to dange tanget

Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 03-04-38-42

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Electrical conduit box (Target) 2" LC Recirculation line

DESCRIPTION OF POSTULATED INTERACTION:

Electrical conduit box fails from support and buts 2"10 Recirculation line.

EVALUATION & DISPOSITION OF INTERACTION:

Receptable enterorion conduit box às of insufficient moss to dange d'un recirculation lene

My Manual d/1/
Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 03-05-32-62/64/65

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Monorail

(Target) 4" MS-1027

DESCRIPTION OF POSTULATED INTERACTION:

Mono rail fails from support and hits

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable interoclier - loss of steam Supply to turbine

Interaction Engineer/Date

Reviewer/Date 191

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 03-06-32-64/65

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) lighting firture #2 (Target) 4" M5-1027

DESCRIPTION OF POSTULATED INTERACTION:

Lighting fixture #2 fails from support and hito

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable interoction. lighting fixture connot damage 4" M5 1007 8 team Syngdue to insufficent

Interaction Engineer/Date

Reviewer/Date O

BUILDING: A FW PUMP BLDG

FIRE ZONE: Z3

LOCATION WITHIN FIRE ZONE:

03-07-32-64/65 INTERACTION NO.:

INTERACTION SKETCH NO.

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 4" Elect Conduit Target) 411 M5-1007

DESCRIPTION OF POSTULATED INTERACTION:

electrical concruit fails from support and hits 4" MS-1027 Steam Supply line.

EVALUATION & DISPOSITION OF INTERACTION:

acceptable interaction-conduit is of insufficient mass to damage steam sypty las

			01	02	03	04	05	06	07	08	09	10	11	12	13	14	15			18	19	50			23	24	25		ļ				 
IN	E		2 CONDUIT	Mono RAIL	LIGHT #6	12" CONDUIT	ELEC. BOX	VENTILATION LOUVERS	LIGHT # 7	3 CONDUIT	Mone RAIL	LCHT #0	4"DR. LINE	ELEC. BOX <b>SX-G</b>	LIGHT # 11	LIGHT# 12	3"CONDUIT	CONDUITS (SMALL)	SPEAKER	CONDUIT BOX	NITROGEN Bottles	SPACE HTR"	Rock-Up Door	TELEPHONE STA	4"DR. LINE	RACK 9 & 26		·	-				-
6	3"BF1	0-1003																								-							
7	3 BFC	-1004																								63 <sup>°</sup>						<u> </u>	 
3	6 BFD	- 1005						1							70	70	70/ /71	71				<b>/</b>					,					ļ	 
9	3"8FD	-1005													·		<u> </u>		72	73	74	75	76	(ख			,						 <b> </b> -
0	"BFD	-1006																	72)	73	74	75	76	(1)									ļ
1	3 BFC	0-1007																							(18)		·				.		_
2	3 BFD	)- 100B	1						1																78			~					L
3	2"BFI	0-1009	1	1				40		(52	<b>52</b>	52	(53	53							4 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -						į						
4	2 BFS	0-1010 0-1009	29	(31	31	33	36	40	44	44	44						·																<u> </u>
25	3"BF1	2-1011																									,						
		D. 1012				37																	-										L
-		D- 1013				35/	7																										
		0-1014																														•	
		-1015																												<u>.</u>			
		-1030			1:	1	1					1						1.															

BUILDING :	AUXILIARY FEED PUMP BUILDING
FIRE ZONE:	17
-	
LOCATION: WITHIN FIRE	

EBASCO SERVICES INCORPORATED FOWER ADMINISTRATION OF THE OF MG APPROVED NUCLEAR FOWER FLANT APPROVED DATE 324 BICH MG

SYSTEMS INTERACTION STUDY INTERACTION MATRIX

SHEET 2/39

MATRIX No.**L Z** 

INCHE!

BUILDING: AFW PUMP BUILDING

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 02-01-24-29

INTERACTION SKETCH NO.:

5-1, Photo 29

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 2" ELECTRICAL COUDUIT (Target) 2" BFD-1010

DESCRIPTION OF POSTULATED INTERACTION:

2" ELECT CONDUIT FAILS From Support AND 1175 2" BFD-1010

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Inferaction Criteria

A Gogliadi
Interaction Engineer/Date

Reviewer/Date No 181

BUILDING: XFWPUMPBUILD

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: 1)A

INTERACTION NO.: 02-02-24-31

INTERACTION SKETCH NO.:

5-1. Photo 31

IDENTIFICATION OF INTERACTION COMPONENTS:

Source - Monorail Target - 2" BFD-1010

DESCRIPTION OF POSTULATED INTERACTION:

Monorail fails from support and hits 2"BFD-1010

Causing replace of the time,

Monorail also hits 2"BFD 1009 causing repture of the line (see L-2 sheef 9)

EVALUATION & DISPOSITION OF INTERACTION: Unaceptable

Monovail failure and Subsequent repluse flines 2BFD-1010 and 100% results in loss of function of motor devenpunes Nº2 31 and 33. Councident with a single failure of the turbine drivenpunp, results in complete loss of auxiliary feedwater sopply to all steam generators.

BUILDING: AFW Dump Building

FIRE ZONE: 27

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 02-03-24-31

INTERACTION SKETCH NO.:

5-1, photo 31

IDENTIFICATION OF INTERACTION COMPONENTS:

(Sauce) lighting fixture #6

Cigntine fixture fails from support and hits 2"3FD-1010

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable interaction-lighting fixture not capable of damaging 2"3FD-1010 line

Interaction Engineer/Date

Reviewer/Date ~12 17.

BUILDING: AFW PUMP Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: UA

INTERACTION NO.: 02-04-24-33, 02-04-26-37, 02-04-27-35/37

INTERACTION SKETCH NO.:

5-1, photo 33

IDENTIFICATION OF INTERACTION COMPONENTS:

(Sauce) 1/2" Electrical Conduit

Tanget) 2"BFD-1010 (Tanget) 2"BFD-1012 (Tanget) 2"BFD-1013

DESCRIPTION OF POSTULATED INTERACTION:

1/2" Electrical conduit fails from support and hits 2"BFD-1010,

2"BFD-1012, and 2"BFD-1013

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable interactions-conduit connot damage pipe due to insufficient mass of conduit.

M. Joghandi 2/9/81 Interaction Engineer/Date

Reviewer/Date

Viol81

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 02-05-24-36

INTERACTION SKETCH NO.

5-1, Photo 36

IDENTIFICATION OF INTERACTION COMPONENTS:

(Sance) Electrical Box SX-7

( Jarget) 2"BFD-1010

DESCRIPTION OF POSTULATED INTERACTION:

Electrical BOX SX-7 fails from support and hits 2"8FD-1010.

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable unteraction-sectrical box is ofensufficient size and wass todamoge 2"8FD-1010

Mariandi 2/9/8/
Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLOG

FIRE ZONE:  $\angle 3$ 

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 02-06-23-40, 02-06-24-40

INTERACTION SKETCH NO.:

5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Ventilation housers (Target) 2"OFD-1009 (Target 2"BFD-1010

Ventilation Louver fails from support and his

2"8FD-1009 and 2"8FD-1010

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable interaction. See L-2 sheet 2 for evoluation.

M Doquark 2/9/8/ Interaction Engineer/Date

Revi

evilewer/Date

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: 1/A

INTERACTION NO.: 02-07-24-44

INTERACTION SKETCH NO.:

5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) lighting fixture #7 (Jange 1) 2"BFD-1010

DESCRIPTION OF POSTULATED INTERACTION:

Lighting fexture #7 fails from support and hits 2"8FD-1010

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable interaction
See 1-2 sheet 3 for evoluation

Woodeard 1/9/81
Interaction Engineer/Date

Reviewer/Date 2/10/2.

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: ,02-08-23-52,02-08-24-44

INTERACTION SKETCH NO.:

5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 3" Conduit (Target) 2" BFD-1009 2" BFD-1010

DESCRIPTION OF POSTULATED INTERACTION:

3" electrical conduit fails from support and hits 2"BFD-1009 and 2"BFD-1010

EVALUATION & DISPOSITION OF INTERACTION: Unacceptable Interaction

3" Conduit hits BFD-1009, and BFD-1010 causing a

reptere in both lines, vesultin, in loss of flow from

pumps 31 and 33. Councident single failures furbine

chover pump results in total hoss of aux feed flow to

steam generators violating acceptance critoria.

Myoguarch 1/9/8/
Interaction Engineer/Date

BUILDING: AFW PUMP Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: DA

INTERACTION NO.: 02-09-23-52, 02-09-24-44

INTERACTION SKETCH NO.:

5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Monorail (Target) 2"BFD-1009 2"BFD-1010

DESCRIPTION OF POSTULATED INTERACTION:

Monovail fails from support and hets 2"3FD-1009 and 2"BFD-1010

Tentraction results in total loss of aixiliary
feedwater flow to steam generators when
assumed coincident single failure is Turbine driven
pump failure to start.

M Sogliash 2/9/8/
Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLDG

FIRE ZONE:

LOCATION WITHIN FIRE ZONE: WA

INTERACTION NO.:

02-10-23-52

INTERACTION SKETCH NO.:

5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Jarget) 2"BFD-1009

DESCRIPTION OF POSTULATED INTERACTION:

Leghting fexture fails from support and hits

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable interaction. See L-2 Sheet 7

Mogliardi 2/9/8/ Interaction/Engineer/Date

Reviewer/Date 17)

BUILDING: AFW PUMP BLDG

FIRE ZONE:

23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 02-11-23-53

INTERACTION SKETCH NO.:

5-/

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 4" plumbing drain line (Target) 2"BFD-1009

DESCRIPTION OF POSTULATED INTERACTION:

duain line fails and hits 2"BFD -1009

EVALUATION & DISPOSITION OF INTERACTION: Laceptable interaction drain lone failure causes supteme of line 2"BFD-1009 resulting in loss of function of motor duvenpung No. 31. purps 32 and 33 are avoilable for greation.

M Log ward 2/9 8)
Interaction Engineer Date

Reviewer/Date 21,3181

BUILDING: AFW PUMP BLOG

FIRE ZONE:

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 02-12-23-53

INTERACTION SKETCH NO.:

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Electrical Box 5x-6 (Tanget) 2"BFD - 1009

DESCRIPTION OF POSTULATED INTERACTION: electrical box # 5x-6 fails from support and hits

2"BFD-1009

Acceptable interaction-elect box is of insufficient size and mass to damage 2"3FD-1009

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 01-/3-/8-70

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) lighting fixture # 11 (Target) 6"BFD-1005

DESCRIPTION OF POSTULATED INTERACTION:

leghting fixture # 14 alls and hits 6"3FD-1005

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable interaction. lighting fixture is of insufficient 513e and wass to damage 60BFD 1005

Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLOG

FIRE ZONE:

23

LOCATION WITHIN FIRE ZONE: WA

INTERACTION NO.: 02-14-18-70

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) lighting fixture # 12 Target) 6"BFD-1005

DESCRIPTION OF POSTULATED INTERACTION:

lighting fixture #12 fails from its support and hotes 6"BFD-1005

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable interaction
See evoluation sheet 13

Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: LA

INTERACTION NO.: 02-15-18-70/71

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 3" Electrical conduit (7 angel) 6" BFD-1005

DESCRIPTION OF POSTULATED INTERACTION:

3" Mechical conduit fails from support and hits

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable interoction-electricolconduit is of inoufficient size and was to damage 6"BFD-1005

Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 02-16-18-71

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Small(22") électricel conduits (Target) 6"BFD-1005

DESCRIPTION OF POSTULATED INTERACTION:

Small electrical conduits fail from support one hits

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable interoction-conducts are of insufficient size and mass to damage 6"8FD-1005

M JOGUAN (L. 2/9/8/ Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 02-17-19-72, 02-17-20-72

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Paging Speake Target) 3"8FD-1005 3"8FD-1006

DESCRIPTION OF POSTULATED INTERACTION:

Maging greater fails and hits 3"BFD-1005 and 3"BFD-1006

EVALUATION & DISPOSITION OF INTERACTION:

acceptable Intraction Pagar greaxer con cause loss of function of aix feed pump 32. Coincident with the single failuse of one motor duren pump, the other motor driven pump is available for feel flow to 2 steam generators.

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 02-18-19-73, 02-18-20-73

INTERACTION SKETCH NO.:

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Conduit BOX (Target) 3"8FD-1005 3" BFD-1006

DESCRIPTION OF POSTULATED INTERACTION

Conduit Box fails from support and histo 3" 8FD-1005 and 3"BFD-1006

EVALUATION & DISPOSITION OF INTERACTION:

acceptable Interaction-andust box is of insufficient size and mass to damage 3"BFD-1005 and 3"BFD-1006

BUILDING: AFW PUMP BLOG

FIRE ZONE:

23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 02-19-19-74, 02-19-20-74

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Hitrogen Gas Bottles (Target) 3"BFD-1005 3"BFD-1006

DESCRIPTION OF POSTULATED INTERACTION:

Nitrogen bas bottles Sail from Supports and hets 3"BFD-1005 and 3"BFD-1006

EVALUATION & DISPOSITION OF INTERACTION:

acceptable interaction- no damage credible

Interaction Engineer/Date

Reviewer/Date 212 K

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 02-20-19-75, 02-20-20-75

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

Source) Space Heater#/ (Tanget) 3"BFD-1005 3"BFD-1006

DESCRIPTION OF POSTULATED INTERACTION:

Space thater # 1 faits from support and hits 3"BFD-1005 and 3"BFD-1006

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable interoction- beater con caul 1055 of four two of 3"BFD-1005 and 3"BFD-1006

Mogliandi 2/9/8/ Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLOG

FIRE ZONE: 2

LOCATION WITHIN FIRE ZONE: UA

INTERACTION NO.: 02-22-19-77, 02-22-20-77

INTERACTION SKETCH NO.:

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Communication Center

(Target) 3"BFD-1005 3"BFD-1006

DESCRIPTION OF POSTULATED INTERACTION:

Communication Center fails from support structure and hits 3"BFD-1005 and 3"BFD-1006

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable interoction-Communication conter can cause loss of function of 3118FD 1005 and 1006

Interaction Engineer/Date

Reviewer/Date

A10131

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: X/A

INTERACTION NO.: 02-23-21-78, 02-23-22-78

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 4" plumbing drain line (Tanget) 3"BFD-1007 3"BFD-1008

DESCRIPTION OF POSTULATED INTERACTION:

4" plumbing line fails from support and hits 3"BFD-1007 and 3"BFD-100B

EVALUATION & DISPOSITION OF INTERACTION:

Anaceptable interaction, 4" lare candomage 3" BFD-1007 and 3"BFD-1008 cousing loss of function.

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: WA

INTERACTION NO.: 02-24-17-63

INTERACTION SKETCH NO.:

A5-1

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Small electrical conduits from pack 9226 (Target) 3"3FD-1004

Electrical conduit fails from Support and luits 3"3FD-1004

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable enterection-conduits are of insufficient size and was to cause damage.

Interaction Engineer/Date

Reviewer/Date

7,0%

	AND THE PROPERTY OF THE PROPER	•				,								S																				
		C	63	03	04	05	06	07	08	09	10	11	12	13	14		16	17	18	19	20	51	52	23	24	25	56	27	28	29	30	31	32	33
L	LINE No.		ELEC. BOX FM - 279	ELEC. BOX	SPACE HTR#2	LIGHT #2	WALL SW BOX	Exide LTG. & Box	PESW FOR MTR EUM 310	Mono RAIL	2" STA. AIR	EUH 311	ELEC. BOX	WALL BOX (TWERUAL 321 ( 322 COUPLE)	SPACE HTR#3	*	SPACE HTR 4	750	2"STA. AIR	ELEC. BOX	4" DR. LINE	SPACE HTR#5	2"CONDUIT	SWITCH BOKES	SPACE HTR. #G	SPEAKER	ELEC. BOX &	PUMP # 33 DOWER	ELEC. Box & SX.5 CONDUIT	LIGHT # 7	3 CONDUIT	MONO RAIL	LIGHT # 5	1/2 & 4" CONDUIT
01	12"CT- 1070								,																		, ,	41/42	41/43	þ				
02	8 CT- 1071 (HOR						,				16				18	19	19	34	34			28			38	39								
03	8°CT-1071					46	13	13	13	46																1							i	46
04	6"CT-1072																							32		1						45	45	45
05	1/2°CT-1160																	·																
06	6°CT-1073									48		17	17	17	18	19	19			24	27	48												
70	1/2"CT- 1159					<del>                                     </del>					1																							
08	8"CT-1074(HDR	101	1		ĬO					14/15	10	1			18	19	19	22	SS	1		28												
																				<del>i</del>	26	1			38									
10	6"CT-1074										16	16/	16/17	17	18	19	19												1					
[ 11	8'CT-1076	2	ŏ8	09									,					l v	23															
12	4"BFD-1001									47													-							44/	44	44	)	47
13	3"BFD-1001																			1														
14	3 BFD-1002																			<b> </b>														
<b>}</b>	4'BFD-1003			1						59	1			1									29		· .						59	54	)	

BUILDING: XUXILIARY FEEDWATER PUMP BUILDING

FIRE ZONE: 23 ELEVATION 18'-6

LOCATION: NOT XPPLICATURE - SEE KEY PLAN WITHIN FIRE ZONE

EBASCO SERVICES INCORPORATED DATE 32481 CHILL SCALE NONE APPROVED

FOWER AUTHOR TY OF STATE OF NEW YORK INDIAN POINT NOTS NUCLEAR FOWER PLANT

SYSTEMS INTERACTION STUDY

MATRIX No. L

BUILDING: AFW PUMP Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: UA

01-33-03-46,01-33-04-45,01-33-12-47

INTERACTION SKETCH NO.

5-1, Photo 46,45 \$47

IDENTIFICATION OF INTERACTION

(Source) 11/2" & 4" (onduit

(Target) 8"CT-1071 6"CT-1072 4"BFD-1001

DESCRIPTION OF POSTULATED INTERACTION:

Conduits fail from Supports and hets 8"07-1071, 6"07-1072 and 4"BFD-1001

EVALUATION & DISPOSITION OF INTERACTION:

acceptable Interaction - Criteria

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: 114

INTERACTION NO.: 01-32-04-45

INTERACTION SKETCH NO.:

5-1, Photo 45

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Lighting Fixture #5 (Target) 6"CT-1072

DESCRIPTION OF POSTULATED INTERACTION:

Lighting Fixture #5 fails from support and hits 6"C7-1078 Supply to pump #33

EVALUATION & DISPOSITION OF INTERACTION:

Receptable infersetion-insufficient was to

M/Goglandi 2/9/8/ Interaction Engineer/Date

Reviewer/Date O

BUILDING: AFW PUMP Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: UA

INTERACTION NO.: 01-31-04-45, 01-31-12-44, 01-31-15-54

INTERACTION SKETCH NO.:

5-1, PHOTO 45, 44 \$54

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Mono Rail

(Target) 6"CT-1072

4"BFD-1003

DESCRIPTION OF POSTULATED INTERACTION:

Mono Roil fails from Supports and hets 6"CT-1072, 4"BFD 1001, 4"BFD 1003

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable Interaction - Lose Suction and discharge flow.

M Gogiardi 2/9/8/
Interaction Engineer/Bate

Reviewer/Date V 10 181

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 01-30-12-44, 01-30-15-59

INTERACTION SKETCH NO.:

5-1, Photo 44 \$ 59

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 3" Electrical Conduit

(Targets) 4" BFD-1001

A" BFD-1003

DESCRIPTION OF POSTULATED INTERACTION:

3" electrical conduit hits 4"BFD-1001 and 4"BFD-1003

EVALUATION & DISPOSITION OF INTERACTION:

Reseptable interaction. Cuteria \_\_\_\_

MGag/iardi 2/9/8/
Interaction Engineer/Date

Reviewer/Date 10 10 10 1

BUILDING: AFW PUMP Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 01-29-12-44/47

INTERACTION SKETCH NO.:

5-1. PHOTO 44 \$ 47

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Electrical Lighting Fixture (Target) 4"BFD-1001

DESCRIPTION OF POSTULATED INTERACTION:

Electrical light for true fails and hits 4"BFD-100)

Acceptable interaction - insufficient mass to damage piping

BUILDING: AFW PUMP BUILDING

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: 11A

INTERACTION NO.: 0/-27-0/-41/43, 0/-28-0/-41/43

INTERACTION SKETCH NO.:

5-1, PHOTO 41 443

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 4" Conduit to Pump # 33 & ELECTRICAL BOX SX-5 W/conduct (Tanget) 12" CT-1070

DESCRIPTION OF POSTULATED INTERACTION: 4" Conduit fails alongwith electrical box 5x-5 and hits 12"07-1070

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable interaction- insufficient mons to damage the piping.

BUILDING: AFW PUMP Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 01-25-02-39

INTERACTION SKETCH NO.:

5-1, PHO7039

IDENTIFICATION OF INTERACTION COMPONENTS:

(Sance) Large Paging Speaker (Target) 8°CT-1071 (402)

DESCRIPTION OF POSTULATED INTERACTION:

Speaker fails from its supportant hits 807-1071

EVALUATION & DISPOSITION OF INTERACTION:

deceptable interaction - ensufficient mass to domage the pipung.

Maghardi 2/9/81
Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BUILDING

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 01-24-09-38, 01-24-09-38

INTERACTION SKETCH NO.

5-1, PHOTO 38

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source ) Space Heater #38

(Target) 8"CT-1071 (HOR) 6"CT-1074

DESCRIPTION OF POSTULATED INTERACTION:

Space heater # 38 fails from its support and hits 8"CT-1071 and 6"CT-1074

EVALUATION & DISPOSITION OF INTERACTION:

Receptable interaction, Trisufficient blass to damage the piping.

M Gag lardi 2/9/8

㈜.

POWER AUTHORITY OF THE STATE OF NEW YORK INDIAN POINT 3 NUCLEAR POWER PLANT SYSTEMS INTERACTION STUDY EXTERNALLY INDUCED SYSTEMS INTERACTION INTERACTION DOCUMENTATION SHEET

BUILDING: AFW PUMP BUILDING

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: 1)1

INTERACTION NO.: 01-22-15-29

INTERACTION SKETCH NO.:

5-1, PHOTO #29

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 2" ELECTRICAL CONDUT

(TARGET) 4" BFD-1003, DISCHARGE LINE FROM Pump# 31 to Steam Generators 31 \$32

DESCRIPTION OF POSTULATED INTERACTION:

2" Electrical Conduit fails from Support and hels 4"BFD-1003 discharge line from Pump #31

EVALUATION & DISPOSITION OF INTERACTION:

Race plable Interation, Cuteria

BUILDING: A FW PUMP BUILDING

FIRE ZONE: Z3

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 0/-23-04-32

INTERACTION SKETCH NO.:

5-1, PHOTO 32

IDENTIFICATION OF INTERACTION COMPONENTS:

(SOURCE) ELECTRICAL SWITCH BOX & CONDUIT (WALL MOUNTED) (TARGET) 6"CT- 1072, SUPPLY LINE TO PUMP #33

Electrical Box Fails Lion its was support and hets 6"c7-10/2 Supply line to Jump #33

EVALUATION & DISPOSITION OF INTERACTION:

acestable Interaction- Wall Box has insufficient mans to damage piping.

BUILDING: A FW PUMP BUILDING

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 01-21-02-28, 01-21-06-48, 01-21-08-28,

INTERACTION SKETCH NO.:

5-1, PHOTO 28,48,

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) SPACE HEATER#5

(TARGET) 8"CT-1071 (HDR) 6"CT-1073 8"CT-1074 (HDR)

DESCRIPTION OF POSTULATED INTERACTION:

SPACE HEATER# 5 FAILS FROM SUPPORTS AND HITS 8"CT-1071, 6"CT-1073, 8CT-1074

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction, Insufficient Woss to damage piping

MGAGLIARDI 49/8/ Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: WA

INTERACTION NO.: 0/-20-06-27, 01-20-09-26

INTERACTION SKETCH NO.:

5-1, PHOTO 27 \$26

IDENTIFICATION OF INTERACTION COMPONENTS:

Source) 4" FLOOR DRAIN LINE

(Tanget) 6" CT-1073,

DESCRIPTION OF POSTULATED INTERACTION:

4" FLOOR Drain Line Fails and hits 6" CT-1073

EVALUATION & DISPOSITION OF INTERACTION:

acceptable Interaction, By Criteria\_

M Goglandi 2/9/8/
Interaction Engineer/Date

Reviewer/Date Viol81

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 01-19-06-24

INTERACTION SKETCH NO.:

5-1, PHOTO 24

IDENTIFICATION OF INTERACTION COMPONENTS:

(SOUVCE) ELECT BOX 232 & CONDUIT (Tanget) 6"CT-1073

DESCRIPTION OF POSTULATED INTERACTION:

Elect 30x fails from wall support and his 6"1-1073

EVALUATION & DISPOSITION OF INTERACTION:

Sceptable Interestion, insificient mass

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 01-18-02-34, 01-18-08-22, 01-18-11-23

INTERACTION SKETCH NO.:

5-1, PHOTO

IDENTIFICATION OF INTERACTION COMPONENTS:

(SOURCE) 2" STATION AIR

(TARGET) 6"CT-1071, 8"CT-1074 8"C7-1076

DESCRIPTION OF POSTULATED INTERACTION:

2" STATION AIR LINE FAILS AND HITS 8"CT-1071, 8"CT-1074, 8"CT-1076

EVALUATION & DISPOSITION OF INTERACTION:

ACCEPTABLE INTERACTION - BY CHTERIA

MGAGLIARDI 2/9/80 Interaction Engineer/Date

Reviewer/Date
110 |31

BUILDING: AFW PUMP BLDG

FIRE ZONE: 33

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 01-17-02-34, 01-17-08-22,01-17-11-23

INTERACTION SKETCH NO.:

5-1, PHOTO 34, 22, 23

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 2" ELECT CONDUIT

(TARGET) 8"CT-1071

B"CT-1074

8"07-1076

DESCRIPTION OF POSTULATED INTERACTION:

2" Elect Conduit Fails from Support and hets 8"27-1071, 8" CT-1074, 8"CT-1076

EVALUATION & DISPOSITION OF INTERACTION:

acceptable Interaction-By Cutena \_

WGAGLIARDI 2/9/81
Interaction Engineer/Date

Heviewer/Date 10 181

BUILDING: AFW PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 01-16-02-19,01-16-06-19,01-16-08-19,01-16-10-19

INTERACTION SKETCH NO.:

5-1, PHOTO 19

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) SPACE HEATER# 4

(TARGET) 8"CT-1071 6"CT-1075 6"CT-1073 8"CT-1074

DESCRIPTION OF POSTULATED INTERACTION:

Space Heater Foul's from Support and hits 8cT-1071, 6cT-1073, 8cT-1074, 6cT-1075

EVALUATION & DISPOSITION OF INTERACTION:

aceptable Interaction, Insufficient Mass.

MGaglandi 2/9/81
Interaction Engineer/Date

Reviewer/Date 710 181

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.:01-15-02-19, 01-15-06-19, 01-15-08-19, 01-15-10-19

INTERACTION SKETCH NO.:

5-1, PHOTO 19

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) LIGHTING FIXTURE#3

(TARGET) 8"CT-1071, 6"CT-1075 6"CT-1073, 8"CT-1074,

DESCRIPTION OF POSTULATED INTERACTION:

Lighting fixture fails from supportant hits lines 8 CT-1071, 6CT-1073, 8CT-1074, 6CT-1075

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable interaction, insufficient Mais

Mbogleach 2/9/81
Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: A

INTERACTION NO.: 01-14-10-18

INTERACTION SKETCH NO.:

5-1, PHOTO 18

IDENTIFICATION OF INTERACTION COMPONENTS:

(Earce) Space Heater #3 Joseph 6"CT-1075

DESCRIPTION OF POSTULATED INTERACTION:

Space Heate #3 fal's and hits line 6" c7-1075

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable Interaction - Trafficient was

MGaguardi 2(9)

BUILDING: AFW PUMP BLOG

FIRE ZONE: 2ろ

LOCATION WITHIN FIRE ZONE: DA

INTERACTION NO.: 01-14-08-18

INTERACTION SKETCH NO.:

5-1, Photo 18

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Space Hearen #3

(72911) 8"c7-1074

DESCRIPTION OF POSTULATED INTERACTION:

Space Heater # 3 fails and pits Cine 8"CT-1074

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable Interaction, Insufficient Mass

BUILDING: AFW PUMP BLOG

FIRE ZONE:

23

LOCATION WITHIN FIRE ZONE: //A

INTERACTION NO.: 0/-14-06-18

INTERACTION SKETCH NO.:

5-1, PHOTO 18

IDENTIFICATION OF INTERACTION COMPONENTS:

Source) SPACE HEATER# 3

(torget) 6" CT-1073

DESCRIPTION OF POSTULATED INTERACTION:

Space Heater fails and hits line 6" c7-1073

EVALUATION & DISPOSITION OF INTERACTION:

acceptable Interaction: Insufficient whom

M Gapliard 2/9/81
Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLOG

FIRE ZONE:

23

LOCATION WITHIN FIRE ZONE: UA

INTERACTION NO.: 01-14-02-18

INTERACTION SKETCH NO.:

5-1, Photo 18

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) SPACE HTR# 3

(Torget) 8"G-1071 (header)

DESCRIPTION OF POSTULATED INTERACTION:

Space Heater fails from support and hits 8°C-1071

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable Interaction, Linguest wass

MGOglanti a/4/8/ Interaction Engineer/Date

Reviewer/Date 12 14

BUILDING: AFW PUMP BLDE

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: A

INTERACTION NO.:01-13-10-17

INTERACTION SKETCH NO.:

5-1, Photo 17

IDENTIFICATION OF INTERACTION COMPONENTS:

(Sance) Wall Boxes #321 \$ 322

(Tanget) 6" CT-1075, City Water Supply to Pump Nº31

DESCRIPTION OF POSTULATED INTERACTION:

Wall Boxes fail and hit 6" CT-1075

EVALUATION & DISPOSITION OF INTERACTION:

Oup table Interaction, insufficient mass

M Gagliardi 2/9/8/
Interaction Engineer/Date

Reviewer/Date 110 181

BUILDING: AFW PUMPBLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 01-13-06-17

INTERACTION SKETCH NO.:

FIG 5-1, PHOTO 17

IDENTIFICATION OF INTERACTION COMPONENTS:

(SOURCE) THERMAL COUPLE WALLBOX 321 & 322

(target) 6" CT-1073, Normal Supply to AFW Pump Nº31

DESCRIPTION OF POSTULATED INTERACTION:

wall Boxos failant hit 6"CT-1073 line

EVALUATION & DISPOSITION OF INTERACTION:

Receptable Interaction- insufficient mass

M Goghad 3/9/8/
Interaction Engineer/Date

Reviewer/Date O

BUILDING: AFW PUMP 13LOS

FIRE ZONE:

LOCATION WITHIN FIRE ZONE: WA

INTERACTION NO.: 01-12-10-16/17

INTERACTION SKETCH NO.

FIG 5-1, Photo 16 \$17

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) ELECT BOX #5x-1

(Toget) 6"CI-1075, SUPPLY FROM CITY WATER SUPPLY TO PUMP Nº31

DESCRIPTION OF POSTULATED INTERACTION:

Elet Box foils from 5 yport and het's 6 "c7-10)5

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interoction, Insufficient mass.

M Gogliard 2/9/8/
Interaction Engineer/Date

BUILDING: AFW BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: A

INTERACTION NO.: 01-12-06-17

INTERACTION SKETCH NO.:

FIGURE 5-1, Photo1)

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) ELECTRICAL BOX # SX-1

(Target) 6" c7-1073, Normal Water Supply to AFW Pump NO31

DESCRIPTION OF POSTULATED INTERACTION:

Electrical BOX# SX-1 fails from supports and hits 6"CT-1073 Line

EVALUATION & DISPOSITION OF INTERACTION:

acceptable Intersetion- Insuffrent Mass

V Gogleach Interaction Engineer/Date

Reviewer/Date

110 13

BUILDING: AFW PUMP BUDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: A

INTERACTION NO.: 01-11-10-16/17

INTERACTION SKETCH NO.

FIGURE 5-1, PHOTOS 16 &17

IDENTIFICATION OF INTERACTION COMPONENTS:

(Fource) Elect Unit Heater #311 (Target) 6"CT-1075, Supply line from City Water Backup Service

DESCRIPTION OF POSTULATED INTERACTION:

Unit heaten# 311 his 6"c7-1075 line

EVALUATION & DISPOSITION OF INTERACTION:

acceptable interaction Cuterio - Insufficient was

M Gagiandi 2/9/81
Interaction Engineer/Date

Reviewer/Date 2/10/21

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: ///

INTERACTION NO.: 01-11-06-17

INTERACTION SKETCH NO.:

F165-1, PHOO 17

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) ELECT UNIT HEATER #311 (Torget) 6"CT-1073, NORMAL WATER SUPPLY TO AVMPNO31

DESCRIPTION OF POSTULATED INTERACTION:

Ecectrical Unit Heater #311 fails and Hits 6" CT-1073, Normal Water Supply to Pimp Nº31

EVALUATION & DISPOSITION OF INTERACTION:

Occeptable interaction-INSUFFICIENT WASS OF UNIT Heater to damage 6" c7-1073

M Goglia ch' 2/9/8/ Interaction Engineer/Date

Reviewer/Date His Mi

BUILDING: AFW DUMP BLDG

FIRE ZONE: 3

LOCATION WITHIN FIRE ZONE: //

INTERACTION NO.: 0/-/0-/6

INTERACTION SKETCH NO.:

F16 5-1, PHOTO 16

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) : 2" STATION AIR LIVE

Tanget) 6" CT-1075, CITY WATER SUPPLY LINE TO PUMP Nº31

DESCRIPTION OF POSTULATED INTERACTION:

2" STATION AIR LINE HITS 6" CT-1075, CITY Water Sopply line to Pump Nº31

EVALUATION & DISPOSITION OF INTERACTION:

acceptable Interaction

MGOghandi 9/9/6/ Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLDG

FIRE ZONE: 33

LOCATION WITHIN FIRE ZONE: 1)A

INTERACTION NO.: 0/-/0-08-16

INTERACTION SKETCH NO.:

FIGURE 5-1, PHOTO 16

IDENTIFICATION OF INTERACTION COMPONENTS:

(SOURCE) 2"STATION AIR LIVE

(TARGET) B"CT-1074, CITY WATER SUPPLY HEADER

DESCRIPTION OF POSTULATED INTERACTION:

2" STATION AR LINE HITS 8"CT-1074 CITYWATER SUPPLY HEADER.

EVALUATION & DISPOSITION OF INTERACTION:

ACCEPTABLE JUTERACTION -CRITERIA-

Mbughadi 2/9/8/ Interaction Engineer/Date

Reviewer/Date 2/10/21

BUILDING: AFW PUMPBLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: A

INTERACTION NO.: 01-10-02-16

INTERACTION SKETCH NO.:

FIG 5-1, PHOTO16

IDENTIFICATION OF INTERACTION COMPONENTS:

(SOURCE) Z"STATION AIR LINE

(Target) 8" CT-1071, SUPPLY LINE FROM COND STORAGE TANK

DESCRIPTION OF POSTULATED INTERACTION:

2" STATION AIR LIVE HITS 8" CT+071 SUPPLY LIVE

EVALUATION & DISPOSITION OF INTERACTION:

ACCEPTABLE INTERACTION

CRITERIA

MGcghach 2/9/8/
Interaction Engineer/Date

Reviewer/Date 210/8

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: A/A

INTERACTION NO.: 01-09-15-59

INTERACTION SKETCH NO.:

FIGURE 5-1, PHOTO 59

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) Mono Rail

(Tangel) 4"BFID-1003, Feed Supply from Pump 31 to Steam Generators Nº 31 & 32

DESCRIPTION OF POSTULATED INTERACTION:

Mono Rail fails and damages 4"BFD-1003 feed SUPPLY from pump Nº 31 to Steam generators Nº 31 \$32

EVALUATION & DISPOSITION OF INTERACTION:

Unaugstable Interaction-Similar to Interaction 01-09-12-47, sheet 13. SEE FOR DETAILS

MGogliach' 49/9/
Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMPBLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 01-09-12-47

INTERACTION SKETCH NO.:

F165-1, PHOTO47

IDENTIFICATION OF INTERACTION COMPONENTS:

(SOLELE) AFW PUMP MONO RAIL

(Target) 4"BFD-1001 Feed supply from Pump NO 33 to Steam Generators Nº 33 & 34

DESCRIPTION OF POSTULATED INTERACTION:

Mono Rail fails and clamages 4" BFD-1001 feed Supply from Pump Nº 33 to Steam Generators Nº 33 & 34.

EVALUATION & DISPOSITION OF INTERACTION:

Conscriptable Interaction-Lose flow to SG's # 33 & 34 and with common made failure of loss of suction to Turb Driven Pump & Motor Driven Amp 31, NO AFW to Stm1 generators

Magliad: 2/9/8/ Interaction Engineer/Date Reviewer/Date 7 1071

BUILDING: AFW PUMP BLOCK

FIRE ZONE:

23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 01-09-08-14/15

INTERACTION SKETCH NO.:

FIGURE 5-1, PHOTO 14 \$15

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) AFW PUMP MONO PAIL

(TARGET) 8"CT-1074 SUPPLY HEADER FROM CITY WATER SUPPLY

DESCRIPTION OF POSTULATED INTERACTION:

Mono voil fails during seismic event and damages 8"CT-1074 Supply hooler from City Water Epply.

EVALUATION & DISPOSITION OF INTERACTION:

Inacceptable interaction - see sheet is for reasons

M Goglandi d/9/8/ Interaction Engineer/Date

Reviewer/Date 10 0

BUILDING: AFW PUMP BLOG

FIRE ZONE: 2

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 01-09-06-48

INTERACTION SKETCH NO.:

FIGURE 5-1, PHOTO 48

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) MONO RAIL

(Target) 6" CT-1073 - SUPPLY LINE FROM COND STORAGETAUX HEADER TO AFW PUMP Nº 31

DESCRIPTION OF POSTULATED INTERACTION:

Mono Rail fails during seismicevent and damages 6" c7-1073 Supply line to AFW Pump Nº31

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable interaction, - Loss of Scretion flow to
AFW Aurp Nº31 - Common made failure - also damages
8"CT-1074 Header causing loss of scretion flow to
AFW Pumps Nº 32 & 33

MGaglianch 2/9/8/
Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 01-09-03-46

INTERACTION SKETCH NO.:

FIGURE 5-1, PHOTO 46

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) AFW Pump Mono Roil

(Target) 8"CT-1071 AFW PUMP SUPPLY LINE FROM HEADER

DESCRIPTION OF POSTULATED INTERACTION:

Mono Roil fails during rismic Ever out hits 8"c7-1071 Supply line from header

EVALUATION & DISPOSITION OF INTERACTION:

Mossphable Interaction - Mono rail is of sufficient mass to damage the supply line CI-1071. Assuming a concurrent single failure of per 1188, No Suction flow to the turbine derven AFW pump is afforded.

Magharan 2/9/8/ Interaction Engineer/Vate

Reviewer/Date 210/2,

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 01-08-03-13

INTERACTION SKETCH NO.:

FIGURE 5-1 PHOTO 13

IDENTIFICATION OF INTERACTION COMPONENTS:

(Sauce) Puni Switch BOX FOR ELECT UNIT HEATER # EUH 310 (Tanget) 8"CT-1071 AFW PUMP SUPPLY LINE FROM HEADER

DESCRIPTION OF POSTULATED INTERACTION:

PULL SWITCH BOX FAILS FROM 175 SUPPORT AND HITS 8"CT-1071 AFW PUMP SUPPLY LIVE

EVALUATION & DISPOSITION OF INTERACTION:

acceptable interaction, pull switch box does not have Sufficient mass to damage the pipe line CT-1071

M Gagliandi 0/9/8/ Interaction Engineer/Date

Reviewer/Date 7/0/8/

BUILDING: AFW PUMP BLOG

FIRE ZONE: 23

1. 1. 1 m Z

LOCATION WITHIN FIRE ZONE: 1/4

INTERACTION NO.: 01-07-03-13

INTERACTION SKETCH NO.:

FIGURE 5-1, PHOTO 13

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) EXIDE EMERGLIGHT FIXTURE (TARGET) 8" AFW PUMP SUMPLY FROM HEADER CT-1071

DESCRIPTION OF POSTULATED INTERACTION:

Exide emergency lighting fixture fails from it's wall support and hit's 8" AFW Pump Supply line from header c7-1071

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable interaction; Exide emerging lighting fexture does not have sufficient mass to damage the pipe line CT-1071

M GAGUARDI 2/9/81 Interaction Engineer/Bate

Reviewer/Date

713/81

BUILDING: AUX FEED PUMP BLIDG

FIRE ZONE: 23

the part of the party

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 01-07-07-01

INTERACTION SKETCH NO.:

FIGURE 5-1, PHOTO# 01

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) EXIDE EMERG LIGHT FIXTURE (TARGET) 8" AFW PUMP SUPPLY HEADER FROM CONDENSATE STORAGE TANK, LINE # CT-1071

DESCRIPTION OF POSTULATED INTERACTION:

Exide emergence; lighting fixture fails from it's wall support and his gu AFW Pring Supply header #CT-1071

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable interaction, Exicle emergency lighting fixture does not have sufficient mans to damage the line.

CT-1071

M Goguardi 2/9/6/ Interaction Engineer/Date

Reviewer/Date
V10/81

BUILDING: LUX FEED PUMP BLDG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 01-06-03-13

INTERACTION SKETCH NO.:

F16 5-1, P40TO #13

IDENTIFICATION OF INTERACTION COMPONENTS:

(SOURCE) ELECT SWITCH BOX WALL MOUNTED

(TARGET) 8"SUPPLY TO TURB DRIVE AFW PUMP Nº32

LINE# CT-1071

DESCRIPTION OF POSTULATED INTERACTION:

ELECT SWITCH BOX FAILS AND HITS LINE CT-1071

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable interoction, Insufficient mass of wall mounted Switch Box to damage line # c7-1071

M Goglonch 2/9/81 Interaction Engineer/Date

Reviewer/Date

7/10/7.

BUILDING: AUXILIARY FEED RIMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: WA

INTERACTION NO.: 01-05-03-46

INTERACTION SKETCH NO.:

FIGURE 5-1, PHOTO &6

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) LIGHTING FIXTURE # 2

(TARGET) B"CT-1071 LINE-CONDENSATE STORAGE TANK SURPLY TO AFW PUMP SUCTION

DESCRIPTION OF POSTULATED INTERACTION:

LIGHT FIX #2 HITS 8" LINE CT-1071

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Intersection-Light furture # 2 has insufficient mass to damage Line 27-1071

MGAGLIARIDI 2/9/81
Interaction Engineer/Date

Reviewer/Date

VIO 18.

BUILDING: DOX FEED PUMP BLOG

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 0/-04-08-10

INTERACTION SKETCH NO.:

FIGURE 5-1, PHOTO#10

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) SPACE HEATER# 2 (TARGET) 8 CITY WATER SUPPLY HEADER# CT-1074

DESCRIPTION OF POSTULATED INTERACTION:

SPACE HEATER#Z FAILS OFF 17'S SUPPORT AND HITS CITY WATER SUPPLY HEADER # CT-1074

EVALUATION & DISPOSITION OF INTERACTION:

ACCEPTABLE JUTERACTIONS MASS OF SPACE HEATER # 2
15 INSUFFICIENT TO DAMAGE CITY WATER SUAPLY
HEADER # C7-1074

M GAGLIAROI 2/9/81
Interaction Engineer/Date

Réviewer/Date 181

BUILDING: AUXILIARY FEED DUMP BUILDING

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 01-03-11-09

INTERACTION SKETCH NO.:

FIG 5-1, PHOTO # 09

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) ELECTRICAL BOX SX-2

(TARGET) 8" CITY WATER SUPPLY LINE # CT-1076

DESCRIPTION OF POSTULATED INTERACTION:

ELECTRICAL BOX SX-2 FAILS & LITS 8" CITY WATER
SUPPLY LINE # CT-1076

EVALUATION & DISPOSITION OF INTERACTION:

ECCEPTABLE INTERACTION, MASS OF ELECTIBOX SX-Z NOT SUFFICIENT TO DAMAGE GTY WATER LINE # CT-1076

MGAGLIARDI 2981
Interaction Engineer/Date

Reviewer/Date / 10 /81

BUILDING: XUX FEED PUMP BUILDING

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: N

INTERACTION NO.: 01-02-11-08

INTERACTION SKETCH NO.:

FIGURE 5-1, PHOTO # 08

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) FLECTRICAL BOX FM-279 SUPPORTED OFF WALL

(TARGET) 8" LINE CT-1076 CITYWATER SUPRY LINE TO VALVE PCY1188

DESCRIPTION OF POSTULATED INTERACTION:

ELECT BOX FM-279 FAILS & HITS 8" CT-1076 CITY
WATER SUPPLY LINE

EVALUATION & DISPOSITION OF INTERACTION:

LCCEPTABLE JUTERACTION,
MASS OF ELECT BOX NOT SUFFIENT TO
DAMAGE CITY WATER SUPPLY LINE

MGAGLIARDI 2981
Interaction Engineer/Date

Reviewer/Date 7/10/81

BUILDING: XUXILIARY FEED PUMP BUILDING

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: N &

INTERACTION NO.: 01-01-08-01

INTERACTION SKETCH NO.:

FIGURE 5-1, PHOTO # 01

IDENTIFICATION OF INTERACTION COMPONENTS:

Non-Seismic 4" FLOOR DRAIN PIPE (SOURCE)
8" LINE CT-1074 CITYWAJER SUPPLY-HEADER (TARGET)

DESCRIPTION OF POSTULATED INTERACTION:

4" DRAIN PIPE FAILS AND HITS 8" CT-1074 CITY WAJER SUPPLY HEADER

EVALUATION & DISPOSITION OF INTERACTION:

SCCEPTABLE JUJERACTION- CRITERIA 4.

MGAGLIAROI 2 9 81
Interaction Engineer/Date

Réviewer/Date
VIO A.

SOURCE 01 02 03 04 05 VALVE LIGHT#20 2 3/4" 80 82 INSTR 82 101 BFD-64 102 BFD-64 GEN. 31 103 BFD-68 3/4" 80/82 82 INSTR. 82 104 BFD-64 3/4" 80/82 82 INSTR 82 105 BFD-64 106 BFD-67 3/4" 80/ INSTR. 82 81 8 108 BFD-G4 GEN 34 109 BFD-70 110 BFD-G4 3/4" 80/82 81 111 BFD-64 14" 80/82 81 112 BFD-69 GEN. BUILDING : FIRE ZONE: EBASCO SERVICES INCORPORATED POVER AUTHORITY OF STATE LETTER MORAL POINTING B. NUCLEAR FOWER PLANT No.VIS DIV. MUE DR. MG DATE 224 BICH IV SCALE NOUE APPROVED LOCATION: WITHIN FIRE ZONE SYSTEMS INTERACTION STUDY INTERACTION MATRIX

INCHES TOTAL

SOURCE 01 02 03 04 05 VALVES Bokes 4"MS-1027 143 MS-54 144 M5-33(34" DR.) 67/67/68 145 PCV-1139 146 MS-33 (34 DR.) 147 MS-52 148 M5-44 (1" (NSTE.) 149 MS-SI (34" INSTE) 1"MS-1120 150 MS- 93 151 MST-65 69 1" MS - 1121 152 MS-93 153 MST- 64 BUILDING : FIRE ZONE: \_ INDIAN POINT NO.3

NUCLEAR POWER PLANT MATRIX No. VI3 EBASCO SERVICES INCORPORATED LOCATION: \_\_\_\_\_\_ ZONE DIV. MUE DR. MG. DATE 3 2 BL CH IV SCALE NOUE SYSTEMS INTERACTION STUDY
INTERACTION MATRIX SHEET 18/3

, B

SOURJE VALVES 3" BFD-1011 133 BFD-50 134 BFD-51 1"BFD-1014 135 BFD . 73 136 BFD - 74 (BY-PASS) 137 PCV-1213 138 BFD-73 139 BFD-75(5/4" INSTR.) 140 CD-123 < 2"CD-1031 141 CD-122 142 CD-125 BUILDING : FIRE ZONE: POWER AUTORITION OF THE OFFICE MORK INDIANT POINT INSIG NUCLEAR POWER FLANT No.VIZ NA EBASCO SERVICES INCORPORATED LOCATION: WITHIN FIRE ZONE DIV. MUE DR. MG DATE 3 WBI CH M SCALE LONE APPROVED SYSTEMSIMIERACTION STUDY INTERACTION MATRIX SHEET 17/39

SOURCE 01 02 03 04 05 VALVES 2"BFD-1009 121 BFD-77 53 53 122 BFO-65 (34 DR.) 53 53 53 53 123 FCV- 1121 53 53 124 SOV- 1321 125 BFO- 52 126 BFD. 53 2" BFD-1010 127 BFD-78 35 128 BFD-65 (3/4" DR.)  $\triangleleft$ 37 36 40 129 FCV-1123 37 36 40 130 SOV - 1323 131 BFD. 54 40 132 BFD - 55 40 BUILDING : FIRE ZONE: MATRIX No. VII EBASCO SERVICES INCORPORATED DIV. MUE DR. MA DATE 3 24/BL CH W SCALE LOUG APPROYED SHEET 16/39 PATERIATION STUDY CONDUMNTRIX

			MACHELLO REPUBLICA	r on feel feel selfender)	AN AN MEMBER 2	A TOTAL CO					Marie Construir (* )	Politic Harm Grand	FREE FOR VALUE	S	ÖU	R			-											APRILITA APRIL				
		01	02	03	04	٥5																		·										
V	VALVES	W																																
		LINE					·.																			4								
,		Oa			-							•																		·				8
		,4	·									ļ.	-																					
	3"BFD-100"	1		ļ				<u>                                     </u>	<u> </u>		-			-	ļ						· ·					!		·						
	09 BFD-49(3/4"v	1	<u> </u>								· 		<u> </u>											-								·		
· .	0 BFD- 47	78										· .		ļ														·						
11	11 BFD-G5(%)		ļ																					. ;										
	3"BFD-1008	·	<u> </u>																							,								
·	2 BFD-48	78				·																				,								* * * * * * * * * * * * * * * * * * *
	13 BFD-65 (3/4"D	R) 78																	-		•													:
	4 FCV-405C	78								عتبداءه													,						·			j.		
7 11	15 BFD-47	78																																•
A T T	6 BFD-49 (3/4" V.	78																									·		·				•	
_ [11	17 BFD-48	78	1																															
111	8 BFD- G5 (3/4"DI	2) 78													•						•													•
	6"BFD-100	5					·																					<del></del>						
11	9 BFD-GI(34 INS	(R)																		·						· · ·		·				•		
1	BFD-GI(% INSTR																																	
	DING:		S								- <del></del>					·		· · · · · · · · · · · · · · · · · · ·				1		<u></u>										!
	ZONE:	23	}							- -							<del></del>			المرتب والمحرور	un indian	- <del> </del>		and the same of th	सा रागांकाकृतस्य स							manage-1	***************************************	
_OCA	ATION: IN FIRE ZONE	N,	A														DIV.I DATE SCAL	AUE AUE	SER'	VICES	INC A	PPRO	PED	D		4					V YOR UDY	•	MAT No. N	/10

INCHES TO A STATE OF THE STATE

	ŧ			1	<u> </u>		<del></del>	· 1	T	Т		1		7	UU	R	<u> </u>	1	1 <del></del>	· .	<del></del>	<del></del>	 · · · · · ·		···	•	γ · · · ·	1	<del></del>		 <b>,</b>
		01			04	05	06	07	08	09	10	:								ļ							-		•		L
<b>V</b> A	LVES	SPEAKER	CONDUIT BOX	SPACE HTR# 1	Rou-UP DooR	TELEPHONE STA.	4" DR. LINE	erandelle millete enderste sterre enderste sterre enderste millete millete millete enderste enderste enderste											Angerer and Angels for Spring the Control of the Co												
	3 BFD-1005		·																	1				j							
75	BFD-65 (3/4" DR.)	72	73	75	76												<del> </del>			<del> </del>	<del> </del>				· •						
	3".BFD- 1006										•				ļ							. 1,1, ~ 1,4			i						
	<del></del>	72	73	75	76	77			<b></b>					-		<del> </del>	<del> </del>								•				· ·		
	BFD- G5(1/4 DR.)	<del> </del>										<del> </del>					<u> </u>								·						
	FCV- 405 B		1		1	1				<del> </del>				<u> </u>																	,
	<del></del>	<del> </del>	<del></del>	75	<del> </del>				<u> </u>	ļ					· ·	} 		 		<del> </del>		-									_
	BFD- 49(3/4° V)	<del> </del>	<del> </del>	<del>}</del>	<del> </del>	<del>                                     </del>			<u> </u>		•		<u> </u>		<u> </u>		-	ļ			-									-	
		1		75	1	1	-					<u> </u>				-			<u>                                     </u>	<u>                                      </u>					-	<u> </u>		· .	 		 
104	<del></del>	<del></del>	<del></del>		<u> </u>	<u> </u>	<del>                                     </del>		<u>  ·                                   </u>				-	ļ	-	<u> </u>		ļ	ļ		ļ	•			-;						 -
107	BFD- G5(3/4" DR.)	16	13	13	16	67	<u> </u>	ļ	<u> </u>			<u></u>	<u> </u>	<del> </del>			<u> </u>												 		 -
	3"BFD - 1007		ļ .						<u> </u>				-	<u> </u> .	. 		ļ			ļ	ļ										 -
	8FD-48		ļ	-			78		ļ					ļ		<u> </u>	ļ	<u> </u>			<u> </u>				<del></del> -		<u> </u>				
106	BFD-65 (34"DR)						78						<u> </u>			ļ									!						
701	FCV-405 D		<u> </u>				78																		1 .						
801	BFD-47		1				78																								

BUILDING : _	AFW BL	<del>)</del>		
FIRE ZONE: _	23	· · · · · · · · · · · · · · · · · · ·	· : ·	
LOCATION: _	NA			
WITHIN FIRE Z	ONE			

DIV LUE DR. UG DATE ZEHELCH NOWE APPROVED

EBASCO SERVICES INCORPORATED FOWER AUTHORITY OF STATE OF NEW YORK
DIV UNE DRUG APPROVED NUCLEAR FOWER PLANT

SYSTEMS INTERACTION STUDY INTERACTION MATRIX

MATRIX No. V9

		elitaliandAntavalegui			ACTION OF BYTHE STATE OF				Magazza de La Caractería (n. 1822).		S	DÙ	RC						- Land Control of the							
		01	20	03	04	05																				
V	ALVES	LIGHT #14	SPEAKER	CONDUIT BOX	SPACE HTR"1	Roll-UP DooR															,					
	3"BFD-1004	<b>.</b>		,										-												
8	5 FCV- 406 B	61												 												
8	6 BFD-35	GI														·						,				
8	7 BFD-36	GI													*					·				İ		
8	BFD-65 (3/4)	e.)G1				ļ.														1.						
	6 BFD-1005																									
8	9 BFD-32(3/4"V	)					·	·							·											
9	3 BFD-1005 BFD-48					- (																				
H.	3"BFD-1005											6														
¥9	BFD-48		72	73	75	76				1, 3										e.						
19	2 BFD-65(3/4° DI	<b>?</b> )	37	73	75	76														1				· .		
9	3 FCV- 405B		ST	73	75	76											·				 					
9	4 BFO-47		72	73	75	76																				
q	5 BFD-49 (¾" v.	)	72	73	75	76								·												
	6 BFD-48		72	73	75	76														1						
BUIL	DING: AF	WI	3LE	K																1				-	MAT	

FIRE ZONE: LOCATION: \_\_\_\_\_ WITHIN FIRE ZONE

EBASCO SERVICES INCORPORATED FOWER ANTHORITY OF STATE OF NEW YORK
INDIAN POINT NO. 3
DIV MUE DR MG APPROVED NUCLEAR POWER PLANT APPROVED

MATRIX No. V8 SHEET 13/39

DIV. MUE DR. MG. DATE 3 DUB! CH. M. SCALE LOUE SYSTEMS INTERACTION STUDY
INTERACTION MATRIX

	•					. =								R					T	 		1	·T		i	· i			-
		01	90	03	04	i	i	07	09	10	 									 	\{				<b></b>		 		,
	LVES	2"Conduit	LIGHT #8	MONO RAIL	S"CONDUIT	3"CONDUIT	LIGHT # 14	WALL LIGHTING CONDUIT																					
	4"BFD-1003								 															. • • • •		;			
3	BFD-34	29	59	59	59	59					 																		
4	BFD.GG(INSTR.)	29	59	59	59	59	<u> </u>		 		 er van her <del>gegeer</del> er.																		<del></del>
	3"BFD-1003																						-						
5	BFD-G2						GI	GI												 									- <i></i>
6	BFD-44 (3/4" v.)			,			61	61																·					
7	BFD-65 (34"ng)						61	GI					ļ- <b>-</b>					·	-										
8	FCV-406A						GI	GI								-													
9	BFD-37						61	GI																					
0	BFD-37 BFD-38						GI	61																					
1	BFD-G5(3/4"DR.)			·			GI	61																					
	3"BFD-1004																					,			.			,	
32	BFD-G2						61																						
3	BFD-44(%"V.)						GI					:				·													
34	BFD-GS(%TOR						61																						

BUILDING:	AFW BLOG	
FIRE ZONE:	23	
LOCATION:	<b>UA</b>	

DIV MUE DR ME APPROVED TOWER ADDITION TO STATE OF NEW YORK DIV. MUE DR. NG DATE 3 14 81 CH SCALE NOUE

SYSTEMS INTERACTION STUDY INTERACTION LIMATERS

MATRIX No. V7 SHEET/2/

01 02 03 04 05 VALVES MONO RAIL S"CONDUIT LIGHT #8 LIGHT # 15 3-BFD-1001 GI BFD-43 62 BFD-G5(3/4"DR) 49 3"BFD-1002 63 BFD-G2 64 BFD-44 (34"v) 49 65 BFD-65 (34" DE) 49 66 FCV-406C 49 67 BFD-40 68 BFD-41 49 69 BFD-65 (3/4 DR) 49 4"BFD-1003 70 BFD-GI (INSTR.) 59 59 59 59 71 BFD-GI(INSTE) 59 59 59 59 72 BFD-32(34"V) 59 59 59 59 BUILDING: KFW PUMP BLOG FIRE ZONE: 23 EBASCO SERVICES INCORPORATED ! NA LOCATION: \_ DIV. MUE, DR. MG APPROVED WITHIN FIRE ZONE DATE 3 WOLE

Q


SOURCE 01 02 03 04 05 06 07 08 09 10 **VALVES** INSTR. TUBING LIGHT #15 LIGHT #2 Mono RAIL LIGHT# 7 8"CT-1076 08 09 11 49 PCV- 1188 10 50 SOV-1288 0809 11 10 4 BFD-1001 47 47 47 47 51 BFD-32(3/4" DR.) 52 BFD-39 44 44 44 53 BFD-GG (INSTR.) 54 BFD-GI (INSTR.) 55 BFD-GI(INSTR) 3"BFD-1001 56 BFD-G2 57 BFD-44 (34"V) 58 BFD- 65 (34" DK) 49 59 FCV-406D 60 BFD-42 BUILDING: AFW PUMP BLOG FIRE ZONE: 23 EBASCO SERVICES INCORPORATED ADVICE AUTHORITY OF STATE OF NEW YORK INDIANT POINT NO B

DIV. NUE DR. NG | APPROVED | HUCLEAR POWER PLANT MATRIX No. **V5** LOCATION: \_ DATE JUNE DE NA I

WITHIN FIRE ZONE

5 (CTEMSINTERACTION STUDY IN TERACTION MATRIX

SHEET 10/39



SOURCE 13 14 15 01 02 03 04 05 06 07 08 09 10 11 12 INSTR. 4 th Couburt 4" DR. LINE SWITCH BOKE CONDUIT FOR BOX 321 4 522 2" STA. AIR 3 Mono RAL S SPACE HTR 2 CONDUIT LIGHT # LIGHT LIGHT" 8 CT-1071 SENSING LINE OF PT-1264 8,9,8,9,46 8,9, 8,9, 8,9, 46 46 8,9 02 PI-1264 G"CT-1072 03 FE-1123 04 FC-1136-S 34 34 32 05 FC-1136A-S 34 34 32 45 45 45 06 PT - 1265 07 PI-1265 45 45 45 Ĭ 6'CT-1073 0 25 25 08 **LE-1151** 24 25 25 27 FC-1135-S 26 FC-1135A-S SENSING LINE OF PT-1263 PI- 1263 AFW BUILDING : 23 FIRE ZONE:

HCM3 9

NA

LOCATION:

WITHIN FIRE ZONE

SYSTEMS INTERACTION STUDY INTERACTION MATRIX

FOWER AUTHORITY OF STATE OF NEW YORK INDIANT FOINT INS 3 NUCLEAR POWER PLANT

No.II

EBASCO SERVICES INCORPORATED

APPROVED

DIV. JEC DR. DK. DATE 3.2481 CH. VIII SCALE NONE

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: N. A.

INTERACTION NO.: 01-09-11-12, 02-09-11-12, Matrix No I-1

INTERACTION SKETCH NO .: 5-3, Photo 46 for sources, Photo 8 \$ 9 for targets

IDENTIFICATION OF INTERACTION COMPONENTS:

Targets: PT-1264 sensing line & PI-1264
Sources: Mono Rail, 4" 4 1/2" Conduits, Light # 2

DESCRIPTION OF POSTULATED INTERACTION:

Seismically included failures of the sources can cause damages to PT-1264 and its instrument tubing thereby resulting in water spillage and a loss of AFW pump 32 suction pressure indication in the control room (for NPSH protection)

EVALUATION & DISPOSITION OF INTERACTION:

Interaction is unacceptable
Review seismic decumentation. If the sources are not seismically supported, provide seismic supports

Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: N.A.

INTERACTION NO .: 04-02-03-08,05-02-03-08, Matrix No I-1

INTERACTION SKETCH NO.: 5-3, Photo No. 32, 34

IDENTIFICATION OF INTERACTION COMPONENTS:

Targets: Fe-1136-S & FC-1136A-S(Flow switches to monitor AFW Sources: 2" conduit, 2" station air pipe, switch boxes and conduite

Seismically induced failures of the sources can eause damages to the targets and their sensing lines thereby resulting in water spillage and a loss of Pump 33 suction flow alarm in the control room.

EVALUATION & DISPOSITION OF INTERACTION:

The loss of suction flow alarm is not critical. However, the water spillage can cause damages to other compenents in the area. Therefore, the sources should be seismically supported.

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:  $\mathcal{N}$ .  $\mathcal{A}$ 

INTERACTION NO.: 06-09-010-011, 07-09-010-11, Matrix No. I-1

INTERACTION SKETCH NO.: 5-3, Photo 45

IDENTIFICATION OF INTERACTION COMPONENTS:

Targets: PT-1265 sensing line & PI-1265 ( for measurement of Punjo 33 suction pressure)

Sources: Monorail, Light #5, 4" and 1/2" conduits

# DESCRIPTION OF POSTULATED INTERACTION:

Seismically induced failures of the sources can cause damages to PT-1265 and its instrument tubing thereby resulting in water spillage and aloss of AFW Pump 33 suction pressure indication in the control room.

### EVALUATION & DISPOSITION OF INTERACTION:

Interaction is unacceptable

Review seismic documentation. If the sources are
not seismically supported, provide seismic supports.

Interaction Engineer/Date 2/11/8/

Reviewer/Date

AFW Pump Building

FIRE ZONE:

LOCATION WITHIN FIRE ZONE: N.A.

INTERACTION NO.: 09-04-05-06-07, 10-07 Matrix No I-1

INTERACTION SKETCH, NO.: 5-3, Photo No. 24, 25, 26, 27

#### IDENTIFICATION OF INTERACTION COMPONENTS:

Targets: FC-1135-5, FC-1135A-S ( Flow switches to menitor AFW Pump 31 suction flow)

Sources: Elec. box 232 and conduit, Light #3, space heater #4,

### DESCRIPTION OF POSTULATED INTERACTION:

Scismically induced failures of the sources can cause damages to the targets and their sensing lines thereby resulting in water spillage and a loss of Pump 31 suction flow alarm in the control room.

EVALUATION & DISPOSITION OF INTERACTION:

The loss of suction flow alarm is not critical, However, the water spillage can eause damages to other components in the area. Therefore, seismic documentation review should be conducted. If the sources are not seismically supported, provide seismic supports

D Kanchanas 2/11/8/ Aghardi d/so/8, Interaction Engineer/Date

BUILDING:

AFN Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: N.A.

INTERACTION NO.: 15-01-02-03-04-05-07-08, 16-01-02-03-04-05-06-07Matrix No. I-2 INTERACTION SKETCH NO.: 5-3, Photo No. 17, 18, 19, 22

IDENTIFICATION OF INTERACTION COMPONENTS

PCV-1187 Valve Station (including valve, solenoid, instrument air lines, electrical wires and terminal bex)

Sources: Electrical box SX-1, space heater #3, Light = 2, space heater #4, 2" conduit, 2" station air pipe.

Description of postulated interaction:

Scientically included failures of the sources can cause:

Da loss of function of city water supply valve pov-1187

of AFIV Fump 31 and 2) instrument air piping rupture.

EVALUATION & DISPOSITION OF INTERACTION:

The rupture of instrument air piping is a common mode failure in the entire enstrument air piping in the pump room. Such failure will cause pneumatically operated valves in the room to be inoperable.

The loss of function of PCV-1187 will require manual operation to open the valve. However, PCV-1187 does not have a hand operation. Interaction is unacceptable. Review seismic elocumentation and provide seismic supports for the sources if they are not be Kamphanae 2/11/2. I halo. 1. 3/11/2 Interaction Engineer/Date 2/1/8/

BUILDING: AFW Pump Building

FIRE ZONE:

LOCATION WITHIN FIRE ZONE: N.A.

INTERACTION NO.: 17-07-08-13, 18-07-08-13, Matrix No. I2

INTERACTION SKETCH NO.: 5-3, Photo No. 12 \$23

IDENTIFICATION OF INTERACTION COMPONENTS:

Targets: PCV-1188 Valve Station (including valve, solenoid, instrument air lines, electrical wires and terminal box)

Sources: 2" conduit, 2" station air pipe, Light # 2.

DESCRIPTION OF POSTULATED INTERACTION:

Scismically induced failures of the sources can cause: 1) a loss of function of the city supply valve Pev-1128 of AFIV Pump 32 and 2) instrument air piping rupture.

EVALUATION & DISPOSITION OF INTERACTION:

The rupture of instrument air piping is a common mode failure in the entire instrument air piping in the pump room. Such failure will cause pneumatically operated valves in the room to be inogentle. The loss of function of PCV-1188 will require manual operation to gen the valve. However, PCV-1188 does not have a hand operator, Interaction is unacceptable. Review seismic documentation and provide seismic supports for the sources if they are not so supported.

D. Vandon 20 2/11/01 D Karchanage 2/11/8/ Interaction Engineer/Date

BUILDING:

AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: N.A.

INTERACTION NO.: 19-09-10-11-12, 20-09-10-11-12, 21-09-10-11-12, 22-09-10-11-12, Matrix No I-2 INTERACTION SKETCH NO.: 5-3, Photo No 44, 47

IDENTIFICATION OF INTERACTION COMPONENTS:

Targets: PT-406B, PI-1262, PT-1262R

Sources: Light # 7, 3" conduit, Monorail, instrument tubings between Rack #28 & Rack #5

DESCRIPTION OF POSTULATED INTERACTION:

Seismically induced failures of the sources can cause damages to the targets thereby resulting in water spillage and loss of functions the pressure transmitters which sense outlet pressure Cf AFW Pump 31. Scismically induced failure of instrument lines between Rack # 28 and Rack # 5 is aggravated by the fact that Rack # 28 is not anchored EVALUATION & DISPOSITION OF INTERACTION:

Interaction is unacceptable.

Review seismic documentation and provide seismic supports for the scurces if they are not so supported.

BUILDING: AFW Pump Building

FIRE ZONE:

LOCATION WITHIN FIRE ZONE: N.A.

INTERACTION NO.: generic.

INTERACTION SKETCH NO.: 5-3, Photo No. 53 Event Analysis Figure No. EA-1

IDENTIFICATION OF INTERACTION COMPONENTS:

Instrument Rack #28 contains flow transmitter's which share the same sensing tubings as those of flow transmitters that generate signals for the control room indication of main feedwater flow and for the steam-feedwater flow mismatch plant protection function.

# DESCRIPTION OF POSTULATED INTERACTION:

Rack # 28 is not secured. It is not supported from the floor or wall. Therefore, a seismically induced movement of this rack will eause sensing line ruptures, damages to Fev-1121 and FeV-406D resulting in the losses of valve functions, steam-feedwater flow mismatch protection and important information evaluation & DISPOSITION OF INTERACTION:

Interactions are unacceptable. Corrective actions:

· Review seismic qualification of Rack # 28. If not qualified, modify the rack.

· Provide anchor bolts for the rack

· Perform seismic review for the sensing tubings and supports. Seismically support the tubings if required.

D Kanchanasan 2-9-81 Deglach d/b/
Interaction Engineer/Date

Reviewer/Date

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: N.A.

INTERACTION NO.: generic

INTERACTION SKETCH NO .: Composite Piping and Instrument Air Tubing Flow Diagram No. (Kater), Event Analysis Diagram No EA-2

IDENTIFICATION OF INTERACTION COMPONENTS:

Instrument tubings and N2 Backup cylinders.

DESCRIPTION OF POSTULATED INTERACTION:

A rupture in instrument air tubing circuit can cause the AFW flow central / shutoff valves, steam pressure central valve and turbine central valve to be inoperable because of a loss of instrument air or N2 backup pressure in the tubing circuit.

EVALUATION & DISPOSITION OF INTERACTION:

Interaction can prevent a timely termination of AFW to a faulted steam generator. It can cause all three trains of the AFW system to be inoperable from the control room. Independence of the tubing circuit contradicts the separation civiteria of the electrical circuits that operate instrument air sclenoids etc.

Instrument air piping should be modified to three train circuit, cosh of which is provided with a N2 backup, cylinder

Interaction Engineer/Date

Manchana 2-11-81

Interaction Engineer/Date

BUILDING: AFW Pump Building

FIRE ZONE: . 23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: generic

INTERACTION SKETCH NO.:

Photo No. (Later)

IDENTIFICATION OF INTERACTION COMPONENTS:

Volume tanks of the AFW turbine steam supply pressure control valve, PCV-1139.

DESCRIPTION OF POSTULATED INTERACTION:

These tanks must be seismically supported. The existing supports are questionable.

EVALUATION & DISPOSITION OF INTERACTION:

Review seismic documentation of the tanks and their If found unacceptable, provide new supports.

D Kauchanas 2/9/8/ Interaction Engineer/Date

SOURCE 01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 INSTR. INSTR. TUBING SPACE HTR#4 MONO RAIL 3"CONDUIT 2" CONDUIT 2" STA. AIR LIGHT #7 ELEC. BOX SX-1 WALL BOX T LIGHT # LIGHT 6"CT-1074 13 PCV - 1189 14 SOV - 1289 6 CT-1075 15 PCV-1187 17 17 18 19 19 55 55 17 16 SOV-1287 17 17 17 18 19 19 55 55 8°CT-1076 PCV- 1188 51 23 23 18 SOV-1288 23 23 12 4"BFD-1001 19 PT- 406B 20 PI-1262 21 PT- 1262 22 PT- 1262R

BUILDING :		AFW		
FIRE ZONE:		23		
LOCATION:		NA		
WITHIN FIRE	ZONE			

EBASCO	SERVICES	INCORPORATED	F
DIV TEC	DR <b>DK</b>	APPROVED	1

POWER AUTHORITY OF STATE OF NEW YORK INDIAN POINT NO 3 NUCLEAR POWER PLANT

NO.IZ SHEETO2/39

SYSTEMS INTERACTION STUDY INTERACTION MATRIX

SOURCE 01 02 03 04 05 06 07 08 09 10 INSTR. 3"COMBUIT LIGHT #8 CONDUIT MONS RAIL LIGHT 3"BFD-1001 23 FCV- 406D 49 24 PM-40GH 49 25 HC-406 D 49 3"BFD-1002 26 FCV-406C 49 27 PM-40GG 49 28 HC-406C 49 4"BFD-1003 29 PI-1260 30 PT-1260 31 PI-1260 R 32 PT-406A AFW BUILDING : 23 FIRE ZONE: MATRIX No.13 NA DIV. I.C. DR. DY DATE 3 HO CHANT SCALE LONE LOCATION: WITHIN FIRE ZONE SHEET 23/39 STREESUNTERACTION STUDY

Canal S

SOURCE 03 04 05 06 07 08 09 10 INSTR WALL LIGHTING CONDUIT SPACE HTR#1 Rou-Up Door CONDUIT BOX STA SPEAKER TELEPHONE 3"BFD-1003 33 FCV-406A 61 61 34 PM-406E 35 HC-406 A 61 61 3"BFD-1004 36 FCV-406 B 37 PM-40GF 38 HC-406B 3 BFD- 1005 AR 39 FCV- 405 A 72 73 75 76 77 40 PM - 405 A 72 73 75 76 77 41 HC-405 A 72 73 75 76 77 3" BFD-1006 72 73 75 76 77 42 FCV - 405 B 43 PM-405 B 72 73 75 76 77

BUILDING:	AFW	
FIRE ZONE:	23	_
LOCATION:	NA	_
WITHIN FIRE ZONE		<del>-</del> .

EBASCO SERVICE	S INCORPORATED
DIV. LEC DR. DW	APPROVED
DATE 3246 CHILL	
SCALE DOVE	

FOWER AUTHORITY OF STATE OF NEW YORK
INDIAN POINT NO 3
NUCLEAR FOWER PLANT

SYSTEMSTINTERACTION STUDY INTERACTION MATRIX

MATRIX No. 14

SHEET24/39

SOURCE 01 02 03 04 05 06 07 08 09 10 INSTR. CONDUIT BOX Rou-UP DooR SPACE HTRE TELEPHONE STA LINE SPEAKER 4" DR. 8"BFD-1006 44 HC-405B 72 73 75 76 17 3"BFD - 1007 45 FCV-405 D 78 46 PM-405 D 78 47 HC - 405 D 78 3"BFD - 1008 48 FCY-405 C 78 49 PM-405C 18 50 HC-405C 78  $\triangleleft$ G"BFD-1005 51 PI- 1261 52 PT- 1261 53 PI- 1261 R 54 PI-GAGE F AFW BUILDING : FIRE ZONE: \_\_\_\_ EBASCO SERVICES INCORPORATED FOWER AUTHORITY OF NEW YORK INDIAN POINT, NO. 3 MATRIX No.15 DIVENCE DR. DK.
DATE 3 401 CHMM.
SCALE LONE LOCATION: APPROVED WITHIN FIRE ZONE

HOCHES CHARLES

SYSTEMS INTERACTION STUDY

INTERACTION\_MATRIX

SHEET 25/39

SOURCE 01 02 03 04 05 06 07 08 09 10 INSTR. 4" DR. LIN
ELEC. BOX
SX-G
WALL BOX &
CONDUITS
LIGHT # I
ELEC. BOX
YGT
ELEC. BOX 2"BFD- 1009 55 FCV-1121 53 53 53 53 56 SOV - 1321 2" BFD-1010 57 FCY- 1123 36 36 58 SOV - 1323 1" BFD- 1014 PEV-1213 60 PC - 1213 2 CD-1031 ď GI T1-1324 4"MS-1027 1/68/68 58 62 PCV-1139 66 63 PC-1176 66 64 PT - 1126 BUILDING : NUCLEARIPOWER PLANT No.16 EBASCO SERVICES INCORPORATED FIRE ZONE: \_\_ DIV. TEC DR. DK. DATE 340 CHALL SCALE NOUE APPROVED LOCATION: \_\_\_\_\_ SHEET 26/39 SYSTEMS INTERACTION STUDY INTER ACTION DE TRIN

HOCHES &

4 6 1		01	20	03	04	05	06	07	08																				ļ					-
INSTR.		PUMP #33 POWER	SX-5 CONDUIT	Nitrogen Bottles	SPACE HTR# 1	Roll-Up Doog	Doog & CONDUIT	MONO RAIL	LIGHT # 2	4" CONDUIT	RACK # 5																							
	12"CT- 1070	0. 1	m 41	<b></b>	•	u.	- A																											-
<b>5</b> 5	LCY-1158	41/43	41/43								·																·							-
36	504-1258	41/43	41 43 41 43																·															
•				4										-	ļ.														<u> </u>	-				
57	PANEL			74	75	76	79								ļ.																			+
	TIOR COUTDO							c4/	(A )	c4 /	14/			ļ											·				ļ					1
8	TURB. CONTROL PANEL	<del> </del>	-				·	64/ 65	<b>/c</b> 5	65	/65	·			<u> </u>					·				÷					:					+
													ļ	-	-														ļ					+
						*		<b>a</b> .						<u> </u>	-																	-		+
															-					-					•				<u> </u>					+
														-										·							· ·			+
															<del> </del>																			$\frac{1}{1}$
•			<del>                                     </del>		ļ																													+
																																		Ť
				Λ	FL	, )										٠					,	,				1	- <del> </del>			:				
	NG:				70	3	<del></del>						· · ·			:					·	·	·						<u>.</u>		·			
ΑΤΙ	ONE: ION: FIRE ZONE				VE	2								÷.			DIV	361	SER _ DR. _ CH_	VICE:		CORPO		1		8					w yof nt	1	No.	. ]
,, · ¥											•		-				DATE	John	T CH	¥1		Ī			2X2,	TEM	TOA	reka Ionl	CTIO	N.ST TRIX	TUDY		SHEE	

SOURCE 01 02 03 04 05 INSTR. 7 = LIGHT LIGHT 69 PT-419C GEN. 70 PT-429C GEN. 71 PT-439C GEN 33 72 PT-449C GEN 34 55 58 73 RACK 5 FT-418A FT-428A FT-438A RGE FT-448A FT- 418B  $\overline{\triangleleft}$ FT- 428B FT-438B FT-448B BUILDING : FIRE ZONE: EBASCO SERVICES INCORPORATED FOWER AUTHORITY OF STATE OF NEW YORK
DIV. TEC. DR. DE APPROVED NUCLEAR POWER PLANT MATRIX No.18 DIV. I C DR. DY DATE 3 HOLCH 1/2 SCALE LOUE SHEET 28/39 SYSTEMS INTERACTION STUDY INTERACTION MATRIX

INCIRS PARAMETERS

SOURCE 01 02 03 04 05 INSTR. SPACE HTR." 4" DR. LINE 2"CONDUIT LIGHT 02 03 06 07 110 74 RACK 8 PT-1126 PT- 1163 PT- 1164 PT-1165 PT- 1166 PT- 1205 PT- 1260 PT-1261 AR PT- 1262 PT-1263 PT- 1264 PT - 1265 BUILDING: \_\_\_ FIRE ZONE: FOWER AUTHORITY OF STATE OF NEW YORK INDIAN POINT NO.3 NUCLEAR POWER PLANT MATRIX No. 19 EBASCO SERVICES INCORPORATED LOCATION: DIV. ICC DR. DK DATE 3240 CH141 SCALE DOVE APPROVED WITHIN FIRE ZONE SYSTEMS INTERACTION STUDY INTERACTION MATRIX SHEET 39/34

SOURCE 01 02 03 04 05 INSTR. ന LIGHT 75 RACK 9 PT-419A PT-429A PT-439A PT-449A PT-419B PT-429B PT-439B ARGE PT- 449B PT- 419C PT-429C PT-439C PT - 449C BUILDING : FIRE ZONE: EBASCO SERVICES INCORPORATED FOWER AUTHORITY OF STATE OF NEW YORK
DIV 16C DR 15K APPROVED NUCLEAR FOWER PLANT MATRIX No. IIO DIVILOC DRIM DATE 3 DUBL CHANGE SCALE LOUE LOCATION: APPROVED WITHIN FIRE ZONE SHEET 30/39 SYSTEMS INTERACTION STUDY INTERACTION MATRIX

SOURCE 01 02 03 04 05 INSTR. LIGHT 76 RACK 26 FT- 1200 FT- 1201 FT-1202 FT- 1203 PT- 1181 PT-1182 PT- 1183 PT-1184 77 RACK 28 FT-418L FT-428L FT- 438L FT-448L BUILDING : FIRE ZONE: EBASCO SERVICES INCORPORATED FOWER AUTHORITY OF STATE OF NEW YORK INDIANT POINT NOTS

RIVING OF DROME APPROVED RUCLEAR FOWER FLANT MATRIX No.III

DATE 3048 CHULL SCALE DOUG

APPROVED

SYSTEMS INTERACTION STUDY.


SHEET 31/39

Inches !

LOCATION: WITHIN FIRE ZONE

01 02 03 04 05 INSTR. LIGHT #21 101 FE - 1200 GEN. 102 FT- 1200 103 F1-1200 104 FE-1201 GEN. 105 FT-1201 106 FI- 1201 107 FE-1203 GEN 108 FT- 1203 109 FI - 1203 110 FE -1202 GEN 111 FT-1202 112 F1-1202 4" MS- 1027 113 PCV-1310B 80 82 80 82 114 504. 1311 BUILDING : FIRE ZONE: \_\_\_\_ EBASCO SERVICES INCORPORATED INDIAN POINT NO BE NUCLEAR POWER PLANT SIZ ON LOCATION: ZONE DIV. IC DR. DY DATE IVB/ CHILD SCALE LOVE APPROVED SYSTEMS INTERACTION STUDY SHEET 32/39

. .



SOURCE 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 01 02 03 04 05 06 07 08 09 10 11 12 ELECTRICAL ELEC BOX

G. 26

From G-26

From G-26

From G-26

Z. Conduit

From G-26

3 Conduit

From G-26

1/2 Conduit From

1/2 Conduit From SPACE HTR#5 SPACE HTR#4 2" STA. AIR CONDUCT 7551 DISC SWITCH LIGHT #4 MONO RAIL 4" DR. LINE SPACE HTR S S CONDUIT 1"CONDUIT INSTR. AIR ConDuit 3"CONDUIT LIGHT # SPEAKER LIGHT LIGHT. TRAY- I 112 117 115 116 116 117 118 M3/ 202 112 113 / 113 / 113 / 115 / 115 / 116 / 201 | 115 / 116 OZ TRAY- II 118 115 116 117 118 03 TRAY- III 114 114 113 113 113 115 116 V 04 TRAY- IV LCV-5 ¢ 100 100 100 05 SX-5 06 CONDUIT 755 101/101/101/101/101/101 101 101 101 101 101 101 101 OT CONDUIT 7551 08 Meron # 33 102 102 102 102 102 103 103 103 103/103 103. 104 104 104 104 10 SX-3 & COUDUIT 104 104 JUNCTION 105 11 X232 BOX 105 105 105 12 CONDUIT FC-1135 105 105 105 105 105 105 105 13 CONDUIT 105 14 CONDUIT FC-113C 106 106 106 15 CONDUIT FC-113GA 106 104 X 15A MOTOR # 31 BUILDING: KUXILIARY FEEDWAYER PUMP BLOG FIRE ZONE: 23 AUTHOR TX OF CHARLES CHARLANDER INDIAM FORMT NO B NUCLEAR FOWER FLANT MATRIX EBASCO SERVICES INCORPORATED

APPROVED

SYSTENSTINTERACTION STUDY

No.El SHEET33/39

DIV. ELEC DRGVI DATE 32481 CH 42 SCALE DOVE

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:

INTERACTION NO.: 33-01-05-100, 33-02-05-100

INTERACTION SKETCH NO. 100 photo 100

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 4"Conduits 755 & 7551 for AFW pump motor #33
(Target) Conduit box #5x-5

DESCRIPTION OF POSTULATED INTERACTION:

Conduits fail from supports and hit Box 5x-5 which are required for the operation of LCV-5

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable interaction

G c Fan 2-10-8/ Interaction Engineer/Date Maghardi 2/23/81
Reviewer/Date

BUILDING: AFW pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 33-03-01-117, 33-03-05-100, 33-03-06-101

INTERACTION SKETCH NO.: 33-03-07-101 \$ 33-03-08-102

Fig 5-4, Photo # 117, 100, 101 \$ 102

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 2"Conduit near ceiling (Targets) Tray I, Conduit box "SX-5, power conduits 755 & 755/ and AFW pump motor # 33

DESCRIPTION OF POSTULATED INTERACTION:

2"conduit fails from supports and hits targets

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction - 2" conduit described does not have sufficient mass to damage any target identified

G C Pan 2-10-8/
Interaction Engineer/Date

Agharh 2/23/8/
Reviewer/Date

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 33-03-09-103, 33-03-10-104

INTERACTION SKETCH NO. Fg5-4, photo 103, 104

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 2" conduit near ceiling (Targets) Conduit for CT-64 Conduit box 5x-3 for PCV-1189

DESCRIPTION OF POSTULATED INTERACTION:

2"Conduit fails from supports and hits targets

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction - 2" conduit does not have sufficient mass to damage the targets

Interaction Engineer/Date

Maylandi 2/23/81
Reflewer/Date

AFW Pump Building

FIRE ZONE:

LOCATION WITHIN FIRE ZONE: A/A

INTERACTION NO.: 33-04-06-101, 33-04-09-101

INTERACTION SKETCH NO. 195-4, photo 101

IDENTIFICATION OF INTERACTION COMPONENTS:

( Source): Flu LTG FIX #5

(Targets): AFW pump moter # 33 Feeder Conduits #155 & 755/

DESCRIPTION OF POSTULATED INTERACTION:

Lighting Fixture #5 fails from supports and hits Conduits 755 \$ 7551

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction - lighting fixture does not have sufficient mass to damage the 4" conduits identified.

Marliani 2/23/81

Reviewer/Date

BUILDING: AFW PUMP Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: A

INTERACTION NO.: 33-04-09-103

INTERACTION SKETCH NO. 45-4, Photo 103

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source): Lighting Fix #5

(Target): Conduit for CT-64

DESCRIPTION OF POSTULATED INTERACTION:

Lighting Fixture = 5 fails from supports and hits Conduit feeding CT-64

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction - lighting fixture does not have sufficient mass to cause any unacceptable damage to the Conduit.

Maylar 2/23/8/

Deliawar/Date

BUILDING: AFW Fump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:  $\mathcal{NA}$ 

INTERACTION NO.: 33-05-06-101, 33-05-07-101, 33-05-08-102

INTERACTION SKETCH NO. 5 -4, photo 101, 10 2

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source): 5" conduit over the targets

(Targets): 4"conduct 155

2" Conduit 755/

Terminal box for AFW motor #33

DESCRIPTION OF POSTULATED INTERACTION:

5" Conduit fails from supports and hits targets directly below

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable Interaction - AFW pump motor #33 feeder Conduits 755 \$ 7551 and motor

#33 terminal box may be

damaged

nteraction Engineer/Date

Mayland 2/23/81

Revlewer/Date

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 33-06-06-101, 33-06-09-101, 33-06-08-101

INTERACTION SKETCH NOTINGS-4, Photo 101, 102

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source): Overhead Mono Rail

(Target): Motor #31

Feeder Conduits # 155 & 1551 for motor # 33

DESCRIPTION OF POSTULATED INTERACTION:

Mono rail- folls from supports and hits motor #33 ) its feeder conduits 155 & 1551 and motor #31 Both motors are 400 MP, 440 volt with open dripproof enclasure.

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable Interaction - Targets may be damaged by the failure of the mono rail support. Motor terminal boxes which are made of fabricated steel plates, are deemed to be the most suseptibles.

1 Jaylanli 2/33/8/

BUILDING: AFOU pump Building

FIRE ZONE: 2.3

LOCATION WITHIN FIRE ZONE: 1/ 4

INTERACTION NO.: 33-07-06-101, 33-07-07-101, 33-07-08-102
INTERACTION SKETCH NO.: 33-07-09-103, 33-07-104

INTERACTION SKETCH NO.:

Fig 5-4, photo 101, 102, 103, 104

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source): 1" Overhead conduit

(Targets) Motor #31, Motor #33

Conduits 755 & 7651 Conduit to CT-64

BOX SX-3

DESCRIPTION OF POSTULATED INTERACTION:

Conduits folk from supports and hits targets

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction - 1"conduit does not have

Sufficient mass to cause

damage

Maylandi 2/23/8/
Reviewer/Date

BUILDING: AFW pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 33-08-06-101, 33-08-07-101, 33-08-08-102

33-09-06-101, 33-09-07-101, 33-09-08-102

INTERACTION SKETCH N Fig 5-4, photo 101,102

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source): Lighting Fixture #6, 3" over head conduits

(Targets): Motor #31 Motor #33

Feeder Conducts 255 87551

DESCRIPTION OF POSTULATED INTERACTION:

Conduits or lighting fixture falls from their supports and hit tanget

EVALUATION & DISPOSITION OF INTERACTION:

a. lighting fixture does not have sufficient mass Acceptable Interactions . b. Conduits is located behind

seismically supported heavy Piping

Interaction Regineer/Date

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 33-10-09-103, 33-11-09-103, 33-12-10-103

INTERACTION SKETCH NO .: Fig 5-4, photo 103

IDENTIFICATION OF INTERACTION COMPONENTS:

(Sources); paging speaker Instrument Air Tubing Space heater Unit NO.6

Target: Conduit to CT-64

DESCRIPTION OF POSTULATED INTERACTION: Speaker, Instrument Tubing and Space heater Unit fall from their support and hit the conduit.

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction - a. Speaker and Tubing do not have Sufficent mass to cause unacceptable clamage to the tanget. b. Space heaten is located approx 4'-0" from the wall and is unlikely to damage the conduit putich is supported 1" off the wall. Maphaeli 2/2/81

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 33-/3-/0-/04, 33-/3-/1-/05, 33-/3-/2-/05

INTERACTION SKETCH NO.: 33-/3-/2-/06, 33-/3-/5-/06

Fig 5-4, Photo 104, 105, 106

IDENTIFICATION OF INTERACTION COMPONENTS:

Source: 4" Drain Line

Targets: Box # sx-3, Box # x282,

Conduits for FC-1135, FC-1135A, FC-1136 & FC-1136A

DESCRIPTION OF POSTULATED INTERACTION:

Drain line fail from its supports and hit target identified,

EVALUATION & DISPOSITION OF INTERACTION:

Interaction is deemed "not credible" due to the locations of the targets which are all mounted against the wall. The Source, however, may cause unacceptable damage to the Instrument which are identified separately,

G c fan 2-11-8 | Interaction Engineer/Date

BUILDING: AFW PUMP

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: MA

INTERACTION NO.: 33-14-10-104, 33-15-10-104, 33-15-10-104INTERACTION SKETCH NO.: Fig 5-4, Photo 104, 106

IDENTIFICATION OF INTERACTION COMPONENTS:

Sources: 2" station Air line Space Heaten #5 Cighting Fixture #4

Target: Box SX-3 and associated Conduits to FC-1136 and FC-1136A

DESCRIPTION OF POSTULATED INTERACTION:

Sources fail from support and hit the target.

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction: Conduit and box are located no more than I" from the wall. No unacceptable damage is deemed likely,

Maylow 2/27/8,

BUILDING: AFW fump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE:  $\wedge A$ 

INTERACTION NO.: 33-17-11-105, 33-17-12-105, 33-17-13-105 33-18-11-105, 33-18-12-105, 33-18-13-105 INTERACTION SKETCH NO.:

Fig. 5-4, photo 105

IDENTIFICATION OF INTERACTION COMPONENTS:

(Sources): Electric Unit Heater Disconnect Switch Clanting Fixture #3

(Targets): Box # x 23 z Conduits To FC-1135 & FC1135A

DESCRIPTION OF POSTULATED INTERACTION:

Sources fall from support and hit tangets

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction - Sources identified do not have sufficient mass to cauch any unacceptable damage to the tanget.

Interaction Engineer/Date

Myalasti 2/27/81

BUILDING: AFW pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: A/A

INTERACTION NO.: 33-19-14-106, 33-19-15-106

INTERACTION SKETCH NO.: Fig 5-4, photo 106

IDENTIFICATION OF INTERACTION COMPONENTS:

Source: Box # sx-3

Targets: Conduits to FC-1136 & FC-1136A

DESCRIPTION OF POSTULATED INTERACTION:

BOX falls from its support and hits conduits

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction - SX-3 box does not have sufficient to cause any unacceptable damage

Interaction Engineer/Date

Maghardo 1/27/8/
Reviewer/Date

Building: AFW pump Building

FIRE ZONE: 2.3

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 33-20-11-105, 33-20-12-105, 33-20-13-105

INTERACTION SKETCH NO.: 7-9 5-4, Photo 105

IDENTIFICATION OF INTERACTION COMPONENTS:

Source: Space Heater \$4

Target: Box # x 232 and conduits to trays
Conduits to FC-1135 & FC-1135A

DESCRIPTION OF POSTULATED INTERACTION:

Space Heater#4 falls from its support and hits target

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable Interaction - Damage to box x232 and conduits will disable the operation of FC-1135 and FC-1135A

Gc Pan 2-11-6/ Interaction Engineer/Date Maliadi 2/23/8/
Reviewer/Date

BUILDING: AFW pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

33-25-02-113/201, 33-27-02-113/201, 33-27-02-113/wi INTERACTION NO.:

33-28-02-113/201, 33-26-04-113/201, 33-27-04-113/201

INTERACTION SKETCH NO.: 33-28-04-113/201

IDENTIFICATION OF INTERACTION COMPONENTS:

Sources: Conduix Box Q-26 and 3-associated conduits 1/2", 21/2" 834 Target · Cable Trays I & II.

DESCRIPTION OF POSTULATED INTERACTION:

Conduits and Box fail from their support and bit adjacent Trays I FIT.

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction - Conduits and box do not have sufficient mass to cause eny unacceptable damage

Moliado 2/23/8/ Reviewer/Date

BUILDING: AFW pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: VA

INTERACTION NO.: 33-29-01-115, 33-29-02-115, 33-29-03-115 33-29-04-115INTERACTION SKETCH NO.: Fig 5-4, photo 115

IDENTIFICATION OF INTERACTION COMPONENTS:

Source: 11/2" Conduits from Instrument Racks 9 \$26 Targets: Cable Tray I, II, II & IV

DESCRIPTION OF POSTULATED INTERACTION:

Conduits fail from their support and bit cable Trays

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction - 1/2" conduits running mostly perpendicular to the trays with conduit length ranging from approx. 8'0" to 150" will not have sufficient mass to cause any unacceptable damage to the trays.

Reviewer/Date

BUILDING: AFW pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 33-30-01-116, 33-30-02-116, 33-30-03-116
INTERACTION SKETCH NO.:

Fig 5-4, Photo 116

IDENTIFICATION OF INTERACTION COMPONENTS:

Source: 1/2" conduit from 5x-1

Targets: Trays I, II, II & II

DESCRIPTION OF POSTULATED INTERACTION:

Conduit fails from support and hits trays

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction-1/2 Conduit does not have sufficient mess to cause any unacceptable damage.

Interaction Engineer/Date

Maliante Jaz fo,

BUILDING: AFW pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 33-31-01-116, 33-31-03 -116

INTERACTION SKETCH NO.: Fig 5-4, Photo 116

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source) 21/2" conduit from X-32 (Target): Cable Tray I & III

DESCRIPTION OF POSTULATED INTERACTION:

Zik" Conduit fails from its support and hits cable Tray I & II

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable Interaction

G Com 2-11-8/ Interaction Engineer/Date Whelesh Hazfe/
Reviewer/Date

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 33-32-01-117, 33-32-03-117

INTERACTION SKETCH NO .: Fy 5-4, photo 117

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source): power feeder conduit for space Heater #3 & 4 (Tanget): Tray I & II.

DESCRIPTION OF POSTULATED INTERACTION:

Conduit fail from their support and hit tray

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable Interaction: Simutaneous failure of mony small conduits from their support is deem likely to damage the cable trails below.

Interaction Engineer/Date

Maleodi 2/33/8/ Reviewer/Date/

BUILDING: AFW pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 33-33-01-118, 33-33-02-118, 33-33-03-118

INTERACTION SKETCH NO .: Fig 5-4, Photo 118

IDENTIFICATION OF INTERACTION COMPONENTS:

(Source): 2" conduit from Sx-2 (Target): Tray I, II, II

DESCRIPTION OF POSTULATED INTERACTION:

Conduit fails from its support and nit cable Tray

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction - 2" conduit does not have sufficient mass to cause any unacceptable damage to the tray support or cable.

Interaction Engineer/Date

Medicarli 2/23/8/ Reviewer/Date

BUILDING: AFW pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 33-23-01-114, 33-23-03-114 33-24-01-114, 33-24-03-114INTERACTION SKETCH NO.: Fig. 5-4, Photo 114

IDENTIFICATION OF INTERACTION COMPONENTS:

Source: Electric Unit Space Heater (EUH) Power Supply 3" conduit and associated pull box

Target: Tray I & Th

DESCRIPTION OF POSTULATED INTERACTION:

3" Conduit and box fail from supports and hit cable tray

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable Interaction: This is a case where, in our judgement, an unacceptable interaction is unlikely, due to the short length of the exposed conduit, but possible. More precise evaluation is required to classify the interaction as "acceptable"

BUILDING: AFW pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 33-21-02-1/3/202 , 33-22-02-1/3/202

INTERACTION SKETCH NO.: Fig 5-4, photo 113, 202

IDENTIFICATION OF INTERACTION COMPONENTS:

Source: pull box and other small conduit (1/2", 1" etc)
4" Conduit parallel to cable Tray

Target: Tray I

DESCRIPTION OF POSTULATED INTERACTION:

Simultaneous failure of conduit and Box support to enable many conduits and box to hit Cable Tray II

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable Interaction: Sufficient numbers of conduit and box may fail and hit Tray I to cause an unacceptable damage.

G C Pan 2-12-8 | Interaction Engineer/Date M. Jerliaudi 3/23/8/
Refviewer/Date

BUILDING: AFW pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 33-/3-01-//2, 33-/3-02-//3/202, 33-/3-03-//2

INTERACTION SKETCH NO.: Fig 5-4, Photo 1/2, 1/3, 202

IDENTIFICATION OF INTERACTION COMPONENTS:

Source: 4" Drain Line

Target: Tray I, II, III.

DESCRIPTION OF POSTULATED INTERACTION:

4" Drain line fails from Supports and hit Cable Tray I, II directly below;

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable Interaction

G C Fan 2-/2-8/ Interaction Engineer/Date Maliasli Haz/81
Revijewer/Date

01 02 03 04 05 06 07 08 09 10 11 12 ELECTRICAL Rose-UP Doog HANGING INCAN. I" INSTR. AIR 4" DR. LINE 1"CONDUIT 2"CONDUIT SPACE HIE Rottles EUH-311 DS N2 AABE 16 Box 321 107 107 107 107 17 Box 322 AABF 107 107 107 107 18 SX-1 + CONDUIT (07 107 107 107 19 SX-2 + CONDUIT 108 108 108 108 108 (m) m 20 VENTILATION FARS AFW PUMPS 203 X 203 203 74 LOCAL CONT PNL  $\overline{\triangleleft}$ BUILDING: <u>AUXILIARY FEEDWATER PUMP BUILDING</u> FIRE ZONE: 3 FOWER AUTHORITY OF STATE OF MEALICEA INDIAN POINT NO B NUCLEAR POWER PLANT MATRIX No. E2 EBASCO SERVICES INCORPORATED LOCATION: \_ DIV FLEC DREST.

DATE 324 BI CH 44 SCALE LOUE APPROVED WITHIN FIRE ZONE SYSTEMS INTERACTION STUDY INTERACTION MADERIA

· Liminghaman parkagan parkagan p

BUILDING: AFW pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 34-01-16-107, 34-01-17-107

INTERACTION SKETCH NO.:

Fig 5-4, Photo 107,

IDENTIFICATION OF INTERACTION COMPONENTS:

Source: 2" station Air line

Target : Box 321 (AABE), Box 322(AABF)

DESCRIPTION OF POSTULATED INTERACTION:

2" Station Air fails from its support and hits the targets

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction - Boxes are mounted against the wall, unacceptable clamage is deemed unlikely.

G C Pan 2-12-8/

Mediewer/Date

Reviewer/Date

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: AA

INTERACTION NO.: 34-0/-18-107, 34-0/-19-108

INTERACTION SKETCH NO.: Fig 5-4, Photo 107, 108

IDENTIFICATION OF INTERACTION COMPONENTS:

Source: 2" station Air line

Target: 5x-1 and conduit to pav-1187

5x-2 and conduit to PEV-1188

DESCRIPTION OF POSTULATED INTERACTION:

2" Station Air fails from its support and hits the torgets

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable Interaction: a. Damage to wall mounted boxes 5x-1 or 5x-2 is unlikely

> b. Flexible conduits to PCV-1187 and pov-1,88 are very susepectible

to most palling objects

Maladi 2/23/8/

BUILDING: AFW pump Building

FIRE ZONE:

LOCATION WITHIN FIRE ZONE: NA

34-02-16-107, 34-02-17-107, 34-03-16-107

34-03-17-107,34-04-16-107,34-04-17-101

INTERACTION SKETCH NO.: Fig 5-4, Photo 107

IDENTIFICATION OF INTERACTION COMPONENTS:

Source: 1" Instrument Air

2" and 1" conduit

Target: Conduit Box 321 (AARE) & 322 (AARE)

DESCRIPTION OF POSTULATED INTERACTION:

Instrument Air piping and conduits fail from their supports and hit the Targets

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction - a. Air piping and conduits described do not appear to have sufficient moss to cause any unacceptable elamage b. Boxes are of steel plates tupe and mounted directly against the wall

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: A

34-02-18-107, 34-02-19-108, 34-03-18-107, 34-03-19-108

INTERACTION NO.: 34-04-18-107, 34-05-18-107

INTERACTION SKETCH NO.: Fig 5-4, Photo 107, 108

IDENTIFICATION OF INTERACTION COMPONENTS:

Sources: 1" Instrument Air, 2" conduit, 1" conduit, space Heater DS

Targets: Box SX-1 and conduit to Pev-1187 Box SX-2 and Conduit to Pev-1188

and Heaten Disconnect Switch

DESCRIPTION OF POSTULATED INTERACTION:

Instrument Air piping, electrical conduits fail from their support and hit thetargets identified.

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable Interaction - a. Boxes 5x-1 and 5x-2 are unlikely to be damaged. Boxes are wall mounted. b. Flexible conduits for PCV-1189 & PCV-1188 are very suseptible to any falling objects

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: MA

INTERACTION NO.: 34-06-19-108

INTERACTION SKETCH NO.: Fig 5-4, Photo 108

IDENTIFICATION OF INTERACTION COMPONENTS:

Source: conduit box FM-279

Target: Box 5x-z and associated conduits including 1-1/2" rigid and 3-3/4" flexible conduits

DESCRIPTION OF POSTULATED INTERACTION: Conduit box FM-279 fails from its support and hits 5x-2 and its associated conduits

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable Intraction - a. Wall mounded rigid conduit and box is unlikely to be domaged

b. Flexible conduit may be damaged

when struck by box FM-279

Interaction Engineer/Date

Majuardi 2/03/8/
Repriewer/Date

BUILDING: AFW Pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 34-07-19-108

INTERACTION SKETCH NO.: Fig 5-4, Photo 108

IDENTIFICATION OF INTERACTION COMPONENTS:

Source: Electrical Unit Space Heater# 2

Target: Box 5x-2 and its associated conduits

DESCRIPTION OF POSTULATED INTERACTION:

Space Heaten #2 fails from its support and hit

EVALUATION & DISPOSITION OF INTERACTION:

Unacceptable Interaction: Unit heaten with a motor driven fan has sufficient mass to cause an unacceptable damage,

Interaction Engineer/Date

BUILDING: AFW pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 34-08-20-111

INTERACTION SKETCH NO.: Fig 5-4, Photo 111

IDENTIFICATION OF INTERACTION COMPONENTS:

Source: 4" Drain Line

Target: Ventilation Fon

DESCRIPTION OF POSTULATED INTERACTION:

4" Drain line fails from its support and hit Ventilation fan directly below

EVALUATION & DISPOSITION OF INTERACTION:

Un acceptable Interaction

BUILDING: AFW pump Building

FIRE ZONE: 2**3** 

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 34-09-20-111

INTERACTION SKETCH NO .: Fig 5-4, Photo 111

IDENTIFICATION OF INTERACTION COMPONENTS:

Source : Poll-up Door

Target: Ventilation Fans

DESCRIPTION OF POSTULATED INTERACTION:

Roller-up door damaged due to external missile and hit ventilation fans

EVALUATION & DISPOSITION OF INTERACTION:

Acceptable Interaction - The location of the ventilation for Units makes the domage very unlikely. However, the failure of the Roller-up door will cause excessive damage to other indoor equipment which shall be evalyated separately.

Majuarli 2/2/8/
Reviewer/Date

BUILDING: AFW pump Building

FIRE ZONE: 23

LOCATION WITHIN FIRE ZONE: NA

INTERACTION NO.: 34-09-2/-X, 34-10-21-203, 34-11-2/-203, 34-13-2/-203 INTERACTION SKETCH NO.:

Fig 5-4, photo 203

IDENTIFICATION OF INTERACTION COMPONENTS:

Sources: Roll-up door, Honging INCANDECENT LTG, TRAY I, TRAY III, No Bottles Target: AFW Pump Local control panel

DESCRIPTION OF POSTULATED INTERACTION:

Failure of the support or restraint for the sources will enable one or more of the sources to hit the target.

EVALUATION & DISPOSITION OF INTERACTION: Unacceptable Interaction - Control panel can not withstand force Caused by any flying or falling objects, Unacceptable Control wiring short circuit, instrument false indication are very possible when struck by the sources identified

G C Pan 2-11-8 Interaction Engineer/Date

SOURCE 01 02 03 04 05 ELECTRICAL LIGHT LIGHT 22 RACK # 5 55 58 FROM TRAY I FT-418A FT- 428A FT-438A FT-448A FROM TRAY II FT-418B ARGE FT-428B FT-438B FT-448B XFW PUMP BLOG BUILDING : 23 FIRE ZONE: EBASCO SERVICES INCORPORATED FOWER AUTHORITION TO BE INCORPORATED INDIAN POINT NO B NUCLEAR FOWER PLANT MATRIX No. E3 LOCATION: DIV. ELEC DR. GP DATE 324/8/ CH. 1/1/1 SCALE NOUE APPROVED WITHIN FIRE ZONE SYSTEMS INTERACTION STUDY INTERACTION MATRIX SHEET35/39

4

SOURCE 01 02 03 04 05 ELECTRICAL 4" DR. LINE 2"CONDUIT SPACE HTR 7.7 LIGHT 04 07 02 03 110 23 RACK B FROM TRAY I PT-1262 . PT-1163 PT-1265 FROM TRAY II PT-12G1, PT-112G PT-12G4, PT-11G4 FROM TRAY III PT-1260, PT-1165 PT-1263, PT-1205 FROM TRAYIV PT-1166 RGI  $\triangleleft$ BUILDING: AFW Pump Bldg

FIRE ZONE: 23 FOWER AUTHORITY OF STATE OF NEW YORK INDIAN POINT NO 3 NUCLEAR POWER PLANT

EBASCO SERVICES INCORPORATED

AFFROVED

DIV. ELEC DR.GPL DATE JUNE CHALL SCALE NOVE

MATRIX No. E4

SHEET36/39

SYSTEMS INTERACTION STUDY INTERACTION\_MATRIX

INCMES PROPERTY

्राच्या च्या १ व्याप्त । १ व्याप्त १ व्य १ व्याप्त 
LOCATION: \_

WITHIN FIRE ZONE

ELECTRICAL	01	1									 		ノレハ							٠.	1.							
ELECTRICAL		OS	03	04	05																1							
	8				·						·						·											
	LIGHT #																											
24 RACK # 9	51										-							<del>!</del> -										
FROM TRAY I						,											-				•		ļ 					·
PT-419A ,PT-429	4					·																						
PT-439A,PT-449	A									-									· · ·			<u> </u>						<u> </u>
FROM TRAY II				·	·									İ														
PT-419B, PT-429B								·																				· .
PT-439B,PT-449B												-			<del></del>		•	<u> </u>										<del></del>
FROM TRAY III	-					·											·											
PT-429C															۰								<b> </b>					
PT-429C PT-439C																							·			*		
FROM TRAY IV																												
PT-419C																												i
PT-449C									·										·					4-2-0-1-0				
			,					·													1							<u>-                                    </u>
							·														र्ग र				·			
UILDING:	A	Fω	) Pu	mp i	Bld	<b>1</b>			-															<u> </u>		<u> </u>	L	

ne erministraturus araba araba araba araba araba araba araba araba araba araba araba araba araba araba araba a Bara araba |                       |      |                           |        |    |          |          |      |   |         |                                       |     |                                     |  | · | S | 0U       | R | <br>- i | ·            |             |       | -     |       |   |     |       |            |                      |             |      |                     |             |     |     |          |
|-----------------------|------|---------------------------|--------|----|----------|----------|------|---|---------|---------------------------------------|-----|-------------------------------------|--|---|---|----------|---|---------|--------------|-------------|-------|-------|-------|---|-----|-------|------------|----------------------|-------------|------|---------------------|-------------|-----|-----|----------|
|                       |      |                           | 01     | OZ | 03       | 04       | 05   |   |         |                                       |     |                                     |  |   |   |          |   |         |              |             |       |       |       |   | -   |       | !          |                      |             |      |                     |             |     |     |          |
|                       | Eu   | ECTRICAL                  | ZI # J |    |          |          | -    | - |         |                                       |     |                                     | versettlandativette: saatpivativetes saanse  |   |   |          |   |         |              | -           |       |       |       |   | -   |       |            |                      |             |      |                     |             |     |     |          |
| :                     |      |                           | LIGH   |    |          | -        |      |   |         |                                       |     |                                     | Andrew Comments of the Comment |   |   |          |   |         |              |             |       |       |       | - |     |       | 1          |                      |             |      |                     | -           |     |     |          |
|                       |      | RACK # 26                 | 57     |    |          |          | -    |   | ·       |                                       |     |                                     |  |   |   |          |   |         |              |             | : :   |       | -     |   |     |       |            |                      |             |      |                     |             |     |     |          |
| ·<br>. ·              |      | FROM TRAY I<br>TO BOX 4   |        |    |          |          |      |   |         |                                       |     |                                     |  |   |   |          |   |         |              |             |       |       |       |   |     |       | :          | ·                    |             | -    |                     |             |     |     |          |
|                       |      | FT-1200                   |        |    |          |          |      |   |         |                                       |     |                                     |  |   |   |          |   |         |              |             | Í     |       |       |   |     |       |            |                      |             |      |                     |             |     |     |          |
|                       | 1 .  | PT- 1181                  |        |    |          |          |      |   |         |                                       |     |                                     |  |   |   |          |   |         |              |             |       |       |       |   |     |       |            |                      |             |      |                     |             |     |     |          |
|                       |      | FROM TRAY IL<br>To Box 3  |        |    |          |          |      |   |         |                                       | -   |                                     |  |   |   |          |   |         |              | į           |       |       |       |   |     |       |            |                      |             | _    |                     |             |     |     |          |
|                       | 1    | FT- 1201                  |        |    |          |          |      |   |         |                                       |     |                                     |  |   |   |          |   |         |              |             |       |       |       |   |     |       |            |                      |             |      |                     |             |     |     |          |
|                       | 1 1  | PT- 1182                  |        |    |          | 1        |      |   |         |                                       |     |                                     | :  |   |   |          |   |         |              | 1           | I     |       |       | - |     |       |            |                      |             |      |                     |             |     |     |          |
| SH                    | 1 1  | FROM TRAY III. TO BOX 2   |        |    |          |          |      |   |         |                                       |     |                                     |  |   |   | ·        |   |         |              |             |       |       | -     |   |     |       |            |                      |             |      |                     |             |     |     |          |
| <b>IRGET</b>          |      | FT- 1202                  |        |    |          |          |      |   | ·       |                                       |     |                                     |  |   |   |          |   |         |              |             |       |       |       |   |     | •     | ı          |                      |             |      |                     |             |     |     |          |
| X                     | ,    | PT- 1183                  |        |    |          | •        |      |   |         |                                       |     |                                     |  |   |   |          |   |         |              |             |       |       |       |   |     |       |            |                      |             |      |                     |             |     |     |          |
| Z<br>T                |      | FROM TEAY IV.<br>TO BOX I |        |    |          |          |      | · |         |                                       |     |                                     |  |   |   |          |   |         |              |             |       |       |       |   |     |       |            | ·                    | -           |      |                     |             |     |     |          |
|                       |      | FT-1203                   |        |    |          |          |      |   |         |                                       |     | -                                   |  |   |   |          |   |         |              |             |       |       |       |   |     | ·     |            |                      |             |      |                     |             |     |     |          |
|                       |      | PT-1184                   |        |    |          |          |      |   |         | ļ                                     |     |                                     |  |   |   | ļ.       | ļ | ļ       |              |             |       |       |       |   |     |       |            |                      | -           | -    |                     |             |     |     |          |
|                       |      |                           |        |    | <u> </u> |          |      |   |         |                                       |     |                                     |  |   |   |          |   |         |              |             |       | ļ.    |       |   |     |       |            |                      |             |      |                     |             |     |     |          |
|                       |      |                           |        |    | <u></u>  | <u> </u> |      |   | <u></u> |                                       |     |                                     |  |   |   | <u> </u> |   |         |              |             |       |       |       |   |     |       |            |                      |             |      |                     |             |     |     |          |
|                       | •    | NG:                       | A      | FW |          | mp t     | olda |   |         | · · · · · · · · · · · · · · · · · · · | · · |                                     |  | - |   |          |   |         | -            |             |       |       |       | · |     |       |            |                      |             |      |                     |             |     |     |          |
| LO                    | CATI | ONE:                      |        |    | <u>2</u> | UA_      |      |   |         |                                       |     | · ·                                 |  |   |   |          |   | EB.     | 45(0<br>ELEC | SEC<br>Lore |       | S 12' | CORP( |   | D P | Û:VÊR | INC<br>NUC | DARTE<br>MAN<br>LEAF | POIN<br>FOV | NER. | F. NEW<br>B<br>FLAN | i Yor<br>Ni | -50 | MO. | ŘíX<br>G |
| WITHIN FIRE TOUR TOUR |      |                           |        |    |          |          |      |   |         |                                       |     | SYSTEMS INTERACTION STUDY SHEET38/3 |  |   |   |          |   |         |              |             | 38,39 |       |       |   |     |       |            |                      |             |      |                     |             |     |     |          |

MC 153 (

SOURGE 01 02 03 04 05 ELECTRICAL 26 RACK # 28 FROM TRAY FT- 418L FT- 428L FT-438L FT-448L RGE 0 AFW Pump BIDG BUILDING : \_ FIRE ZONE: \_\_\_\_\_ EBASCO SERVICES INCORPORATED NOTICE OF NEW YORK


DIV. ELECT DR. GILL APPROVED NUCLEAR POWER PLANT MATRIX No. ET APPROVED DIV. ELECT DR.G.M., DATE JUNE CHART SCAVE LOVE LOCATION: ZONE SHEET 39/39

incomplemental A


SYSTEMSUNTERACTION STUDY




PICTURE 1




PICTURE 2




PICTURE 3




PICTURE 4




PICTURE 6



PICTURE 7



PICTURE 8



PICTURE 9




PICTURE 10



PICTURE 11




PICTURE 12



PICTURE 13




PICTURE 14



PICTURE 15



PICTURE 16




PICTURE 17




PICTURE 18




PICTURE 19



PICTURE 20




PICTURE 21




PICTURE 22




PICTURE 23




PICTURE 24




PICTURE 25




PICTURE 26




PICTURE 27




PICTURE 28




PICTURE 29




PICTURE 30




PICTURE 31




PICTURE 32




PICTURE 33




PICTURE 34




PICTURE 35




PICTURE 36




PICTURE 37




PICTURE 38




PICTURE 39




PICTURE 40




PICTURE 41








PICTURE 43



PICTURE 44




PICTURE 45



PICTURE 46



PICTURE 47



PICTURE 48



PICTURE 49




PICTURE 50



PICTURE 51




PICTURE 52




PICTURE 53



PICTURE 54



PICTURE 55



PICTURE 57



PICTURE 58



PICTURE 59




PICTURE 61




PICTURE 62




PICTURE 63




PICTURE 64



PICTURE 65




PICTURE 66




PICTURE 67




PICTURE 68




PICTURE 69




PICTURE 70




PICTURE 71



PICTURE 72



PICTURE 74




PICTURE 73




PICTURE 75



PICTURE 76




PICTURE 77




PICTURE 78




PICTURE 79



PICTURE 80




PICTURE 81




PICTURE 82




PICTURE 83







PICTURE 85




PICTURE 100




PICTURE 101




PICTURE 102




PICTURE 103



PICTURE 104




PICTURE 105




PICTURE 106




PICTURE 107




PICTURE 108




PICTURE 109




PICTURE 110



PICTURE 111




PICTURE 112




PICTURE 113




PICTURE 114




PICTURE 115




PICTURE 116



PICTURE 117



PICTURE 118




PICTURE 201




PICTURE 202




PICTURE 203




**INSTRUMENT RACK NO. 5** 






**INSTRUMENT RACK NO. 9** 



**INSTRUMENT RACK NO. 28** 



VOLUME TANKS OF PCV-1139