

LAW OFFICES OF  
LEBOEUF, LAMB, LEIBY & MACRAE

1757 N STREET, N.W.  
WASHINGTON, D.C. 20036

ARVIN E. UPTON  
EUGENE B. THOMAS, JR.  
LEONARD M. TROSTEN  
HARRY H. VOIGT  
LEX K. LARSON  
WASHINGTON PARTNERS

March 25, 1974

NET NUMBER  
REGD. & UTIL. F. 1...

*Del Cases*  
*50297*

ONE CHASE MANHATTAN PLAZA  
NEW YORK, N.Y. 10005

WASHINGTON TELEPHONE  
202-872-8668

CABLE ADDRESS  
LALALU, WASHINGTON D.C.

Anthony Z. Roisman, Esq.  
Berlin, Roisman & Kessler  
Fourth Floor  
1712 N Street, N.W.  
Washington, D.C. 20036

Re: Indian Point 2

Dear Mr. Roisman:

Enclosed is a copy of a letter from Mr. Stein  
to Mr. O'Reilly dated March 19, 1974.

Very truly yours,


LEBOEUF, LAMB, LEIBY & MACRAE  
Attorneys for Consolidated Edison  
Company of New York, Inc.

By *Edward L. Cohen*  
Edward L. Cohen

BY HAND



Enclosure

cc w/enc: William C. Parler, Esq.  
Dr. John A. Buck  
Dr. Lawrence R. Quarles  
Samuel W. Jensch, Esq.  
Mr. R. B. Briggs  
Dr. John C. Geyer  
Myron Karman, Esq.  
Angus Macbeth, Esq.  
J. Bruce MacDonald, Esq.  
Hon. Louis J. Lefkowitz  
Secretary, U.S. Atomic Energy Commission  
Atomic Safety and Licensing Board Panel



8110240171 740325  
PDR ADDCK 05000247  
G PDR

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, NY 10003



March 19, 1974

Re: Indian Point Unit No. 2  
A.E.C. Docket No. 50-247  
Operating License DPR-26  
A.O. 4-2-11

Mr. James P. O'Reilly, Director  
Regulatory Operations, Region I  
U. S. Atomic Energy Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the requirements of Section 6.12.2(a) of the Technical Specifications of Facility Operating License No. DPR-26, the following report is submitted:

On March 15, 1974, the failure of valves 876A and 876B to operate was reported to your office as A.O. 4-2-10. These valves failed to operate as required during the performance of periodic surveillance test PT-R13 "Safety Injection System Test".

Upon completing the above test the results were reviewed and two additional deficiencies were identified. These deficiencies were No. 22 diesel generator coming up to speed and then tripping on loss of field, and No. 21 service water pump failing to start. Even with the above two failures the required two out of three essential service water pumps operated following actuation of the safeguards logic.

The above deficiencies in themselves did not constitute an abnormal occurrence. However, the system would not have been able to perform its intended safety function if there had been a concurrent loss of outside power.

Mr. James P. O'Reilly

- 2 -

March 19, 1974

Re: Indian Point Unit No. 2  
A.E.C. Docket No. 50-247  
Operating License DPR-26  
A.O. 4-2-11

As stated in our report on A.O. 4-2-10 the reactor was in the cold shutdown condition at the time of the occurrence. Both diesel No. 22 and service water pump No. 21 were started successfully several times following the test.

Mr. Anthony Fasano of your office was informed of this occurrence by Mr. John M. Makepeace on March 15, 1974.

Very truly yours,

*Walter Stein*

Walter Stein, Manager  
Nuclear Power Generation  
Department

cc: Mr. John F. O'Leary