

LAW OFFICES OF
LEBOEUF, LAMB, LEIBY & MACRAE
1757 N STREET, N.W.
WASHINGTON, D.C. 20036

NET NUMBER
REG. & UTIL. F. No.

Rel Cases
50297

ARVIN E. UPTON
EUGENE B. THOMAS, JR.
LEONARD M. TROSTEN
HARRY H. VOIGT
LEX K. LARSON
WASHINGTON PARTNERS

March 25, 1974

ONE CHASE MANHATTAN PLAZA
NEW YORK, N.Y. 10005

WASHINGTON TELEPHONE
202-872-8668

CABLE ADDRESS
LALALU, WASHINGTON D.C.

Anthony Z. Roisman, Esq.
Berlin, Roisman & Kessler
Fourth Floor
1712 N Street, N.W.
Washington, D.C. 20036

Re: Indian Point 2

Dear Mr. Roisman:

Enclosed is a copy of a letter from Mr. Stein
to Mr. O'Reilly dated March 19, 1974.

Very truly yours,


LEBOEUF, LAMB, LEIBY & MACRAE
Attorneys for Consolidated Edison
Company of New York, Inc.

By *Edward L. Cohen*
Edward L. Cohen

BY HAND

Enclosure


cc w/enc: William C. Parler, Esq.
Dr. John A. Buck
Dr. Lawrence R. Quarles
Samuel W. Jensch, Esq.
Mr. R. B. Briggs
Dr. John C. Geyer
Myron Karman, Esq.
Angus Macbeth, Esq.
J. Bruce MacDonald, Esq.
Hon. Louis J. Lefkowitz
Secretary, U.S. Atomic Energy Commission
Atomic Safety and Licensing Board Panel



8110240171 740325
PDR ADDCK 05000247
G PDR

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003

L. J. Crawford, Lamb, Leiby & MacDae
RECEIVED
MAR 22 1974
RECEIVED
Per *fm*



March 19, 1974

Re: Indian Point Unit No. 2
A.E.C. Docket No. 50-247
Operating License DPR-26
A.O. 4-2-11

Mr. James P. O'Reilly, Director
Regulatory Operations, Region I
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the requirements of Section 6.12.2(a) of the Technical Specifications of Facility Operating License No. DPR-26, the following report is submitted:

On March 15, 1974, the failure of valves 876A and 876B to operate was reported to your office as A.O. 4-2-10. These valves failed to operate as required during the performance of periodic surveillance test PT-R13 "Safety Injection System Test".

Upon completing the above test the results were reviewed and two additional deficiencies were identified. These deficiencies were No. 22 diesel generator coming up to speed and then tripping on loss of field, and No. 21 service water pump failing to start. Even with the above two failures the required two out of three essential service water pumps operated following actuation of the safeguards logic.

The above deficiencies in themselves did not constitute an abnormal occurrence. However, the system would not have been able to perform its intended safety function if there had been a concurrent loss of outside power.

Mr. James P. O'Reilly

- 2 -

March 19, 1974

Re: Indian Point Unit No. 2
A.E.C. Docket No. 50-247
Operating License DPR-26
A.O. 4-2-11

As stated in our report on A.O. 4-2-10 the reactor was in the cold shutdown condition at the time of the occurrence. Both diesel No. 22 and service water pump No. 21 were started successfully several times following the test.

Mr. Anthony Fasano of your office was informed of this occurrence by Mr. John M. Makepeace on March 15, 1974.

Very truly yours,

Walter Stein

Walter Stein, Manager
Nuclear Power Generation
Department

cc: Mr. John F. O'Leary