

50-247

LAW OFFICES OF
LEBOEUF, LAMB, LEIBY & MACRAE
1757 N STREET, N.W.
WASHINGTON, D.C. 20036

ARVIN E. UPTON
EUGENE B. THOMAS, JR.
LEONARD M. TROSTEN
HARRY H. VOIHT
LEX K. LARSON
WASHINGTON PARTNERS

January 25, 1974

ONE CHASE MANHATTAN PLAZA
NEW YORK, N.Y. 10005

WASHINGTON TELEPHONE
202-872-8688

CABLE ADDRESS
LALALU, WASHINGTON D.C.

Anthony Z. Roisman, Esq.
Berlin, Roisman & Kessler
Fourth Floor
1712 N Street, NW
Washington, D.C. 20036

Re: Indian Point 2

Dear Mr. Roisman:

Enclosed are copies of two (2) letters from Mr. Cobean to Mr. O'Reilly dated January 21, 1974.



Very truly yours,

LEBOEUF, LAMB, LEIBY & MACRAE
Attorneys for Consolidated
Edison Company of New York, Inc.

By Edward L. Cohen

Edward L. Cohen

BY HAND

Enclosures.

cc w/ encs: William C. Parler, Esq.
Dr. John A. Buck
Dr. Lawrence R. Quarles
Samuel W. Jensch, Esq.
Mr. R. B. Briggs
Dr. John C. Geyer
Myron Karman, Esq.
Angus Macbeth, Esq.
J. Bruce MacDonald, Esq.
Hon. Louis J. Lefkowitz
Secretary, U.S. Atomic Energy Commission

B110240238 740125
PDR ADDCK 05000247
G PDR

RECEIVED
JAN 24 1974
RECEIVED

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003

Per *pm*

January 21, 1974

Re: Indian Point Unit No. 2
AEC Docket No. 50-247
Operating License DPR-26
A.O.-4-2-3

Mr. James P. O'Reilly, Director
Regulatory Operations, Region I
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

DOCKETED
AEC
JAN 29 1974
Office of the Secretary
Public Proceedings
Branch
CS

Dear Mr. O'Reilly,

In accordance with the requirements of Section 6.12.2a of the Technical Specifications of Facility Operating License No. DPR-26, the following report is submitted.

Following completion of repairs associated with the November 13, 1973 feedwater line break incident, an inspection of all Bergen-Paterson hydraulic shock and sway arrestors (snubbers) located in the vapor containment was performed. This inspection was completed on January 18, 1974 and of the approximately 350 snubbers in the containment two (2) did not meet the established criterion for operability; that is, the accumulator oil level plunger was more than one inch below the "EXT" mark.

One of the above two snubbers (SR-1040) is located on the component cooling return line (Line No. 14) from upper bearing cooler of No. 23 reactor coolant pump and the other (SR-48-SR3) is located on the secondary blowdown line (Line No. 48) from No. 24 steam generator. Both snubbers have been replaced with spares. The two defective snubbers will be disassembled for inspection in an effort to determine the cause of failure.


Mr. Don Capton of your office was notified of this occurrence by Mr. John Makepeace on January 18, 1974.

Very truly yours,

Warren R. Cobean, Jr.

Warren R. Cobean, Jr., Manager
Nuclear Power Generation

cc: Mr. John F. O'Leary




Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003

LaBow, Lamb, Luby & MacRae
RECEIVED
JAN 25 1974
RECEIVED

January 21, 1974

Re: Indian Point Unit No. 2
AEC Docket No. 50-247
Operating License DPR-26
A.O.-4-2-4



Mr. James P. O'Reilly, Director
Regulatory Operations, Region I
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly,

In accordance with the requirements of Section 6.12.2a of the Technical Specifications of Facility Operating License No. DPR-26, the following report is submitted.

During the course of a routine plant inspection on January 21, 1974 a small leak was observed at the upstream orifice flange connection for flow transmitter 946B in the six inch residual heat removal system return line (line No. 355) to No. 21 reactor coolant loop. At the time of this observation, the reactor was in the cold shutdown condition with the residual heat removal system in service and pressurized to about 400 psig.

The leak is at the base of the fillet weld attaching a 3/4" pipe nipple to the orifice flange and is on the pipe side of the weld. Preparations for repair of the leak are underway; however, before repairs are initiated, a dye penetrant inspection of the weld will be made to determine the nature and extent of the defect. In addition our Engineering Department is investigating the occurrence in an effort to determine the cause.

Mr. Anthony Fasano of your office was notified on January 21, 1974 of the circumstances relating to this occurrence.

Very truly yours, ¹

Warren R. Cobean, Jr.
Warren R. Cobean, Jr., Manager
Nuclear Power Generation

cc: Mr. John E. O'Leary