

# LICENSEE EVENT REPORT

R.O.-77-3-3(B)

[PLEASE PRINT ALL REQUIRED INFORMATION]

CONTROL BLOCK: 

--	--	--	--	--	--	--	--

LICENSEE NAME				LICENSE NUMBER						LICENSE TYPE				EVENT TYPE											
01	N	Y	I	P	S	3	15	0	0	-	0	0	0	0	-	0	0	4	1	1	1	1	1	0	3
7	8	9	14	15	25	26	30	31	32																

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE											
01	CONT		L	0	5	0	-	0	2	8	6	0	1	2	7	7	7	0	2	2	5	7	7
7	8	57	58	59	60	61	68	69	74	75	80												

### EVENT DESCRIPTION

02 During normal operation, the rod position indicator for rod B-10, Control Bank D, indicated greater than 235 steps, with the bank demand position at approximately 222 steps. A quadrant power tilt calculation verified rod B-10 in alignment with its group. The IRPI for rod B-10 was subsequently realigned. [R.O.-77-3-3(B)].

SYSTEM CODE	CAUSE CODE	COMPONENT CODE				PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION					
07	R	B	E	I	N	S	T	R	U	N	M	0	3	5	N
7	8	9	10	11	12	17	43	44	47	48					

### CAUSE DESCRIPTION

08 A Magnetics, Inc. operational isolation amplifier in the signal conditioning circuitry for indication of rod B-10 required retuning. Voltage signal from the coil stack to the signal conditioner was checked

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION					
11	E	0	9	0	NA	A	Flight Panel Indicator		
7	8	9	10	12	13	44	45	46	80

  

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE				
12	Z	Z	NA	NA			
7	8	9	10	11	44	45	80

### PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION				
13	0	0	0	Z	NA	
7	8	9	11	12	13	80

### PERSONNEL INJURIES

NUMBER	DESCRIPTION				
14	0	0	0	NA	
7	8	9	11	12	80

### PROBABLE CONSEQUENCES

15 NA

### LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION			
16	Z	NA		
7	8	9	10	80

### PUBLICITY

17 NA

### ADDITIONAL FACTORS

18 (Cause Desc. Cont.) - and verified to be correct.

19 8111070280 770225  
PDR ADOCK 05000286  
S PDR

NAME: Austin J. Decker II PHONE: 914-739-8823