

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819


February 2, 1977
Re: Indian Point Unit No. 3
Docket No. 50-286
R.O.-77-3-1(B)

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly,

We transmit herewith Reportable Occurrence report R.O. -77-3-1(B).
Three copies of this letter and the attachment are enclosed as
required.

Very truly yours,





William J. Cahill, Jr.
Vice President

attach.
nvg

Copy to Director of Nuclear Reactor Regulation
ATTN: Dr. Ernst Volgenau, Director (30 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director of Nuclear Reactor Regulation
ATTN: Mr. William G. McDonald, Director (3 copies)
Office of Management Information and
Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, N.Y. 10019



8111070296 770202
PDR ADOCK 05000286
S PDR

LICENSEE EVENT REPORT

R.O.-77-3-1(B)

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME 01 N Y I P S 3	LICENSE NUMBER 0 0 - 0 0 0 0 0 - 0 0	LICENSE TYPE 4 1 1 1 1	EVENT TYPE 0 3
---	---	---	---

CATEGORY 01 CONT	REPORT TYPE L	REPORT SOURCE L	DOCKET NUMBER 0 5 0 - 0 2 8 6	EVENT DATE 0 1 1 2 7 7	REPORT DATE 0 2 0 2 7 7
---	--	--	--	---	--

EVENT DESCRIPTION

02 Following an inadvertent plant trip from 100% power, an automatic safety
03 injection signal was initiated. No. 33 safety injection pump failed to
04 start as required by the safety injection sequence. After replacement
05 of a time delay relay in the starting circuit of the pump, the pump was
06 satisfactorily tested and returned to service. [R.O.-77-3-1(B)].

SYSTEM CODE S F	CAUSE CODE E	COMPONENT CODE R E L A Y X	PRIME COMPONENT SUPPLIER N	COMPONENT MANUFACTURER A 1 0 9	VIOLATION N
--	---	---	---	---	--

CAUSE DESCRIPTION

08 An agastat time delay relay, Model 2412 PC, 125 VDC, in the starting
09 circuit of No. 33 safety injection pump, failed. The relay was re-
10 placed and the pump was tested satisfactorily before the unit was re-
 turned to service.

FACILITY STATUS G	% POWER 0 0 0	OTHER STATUS NA	METHOD OF DISCOVERY A	DISCOVERY DESCRIPTION Supervisory Instrumentation
--	--	--	--	--

FORM OF ACTIVITY RELEASED Z	CONTENT OF RELEASE Z	AMOUNT OF ACTIVITY NA	LOCATION OF RELEASE NA
--	---	--	---

PERSONNEL EXPOSURES

NUMBER 0 0 0	TYPE Z	DESCRIPTION NA
---	---	-------------------

PERSONNEL INJURIES

NUMBER 0 0 0	DESCRIPTION NA
---	-------------------

PROBABLE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE Z	DESCRIPTION NA
---	-------------------

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

19

NAME: Austin J. Decker II

PHONE: 914-739-8823