William J, Cahill,¹ Vice President

Regulatory Docket File

Consolidated Edison Company of New York, Inc. 4 Irving Place, New York, N Y Horry



January 28, 1977

Indian Point Unit No. 3 Docket No. 50-286

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement Region I U.S. Nuclear Regulatory Commission 631 Park Avenue

King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

We transmit herewith Reportable Occurrence Report R.O. -77-3-2(A). Three copies of this letter and the attachment are enclosed as required.

Very truly yours,

William J. Cahill, Jr. Vice President


Attach. 1b

Copy to:

Director of Nuclear Reactor Regulation Att: Dr. Ernst Volgenau, Director (40 copies) Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D. C. 20555

Director of Nuclear Reactor Regulation Att: Mr. William G. McDonald, Director (3 copies) Office of Management Information and Program Control U.S. Nuclear Regulatory Commission Washington, D. C. 20555

Mr. George T. Berry General Manager and Chief Engineer Power Authority of the State of New York 10 Columbus Circle New York, N.Y. 10019 Bill1070318 770128 PDR ADUCK 0500028



4 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	an a	
		R.O77-3-2 (A) (PLEASE PRINT ALL REQUIRED INFORMATION)
0 7	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	LICENSE EVENT TYPE TYPE 4 1 1 1 1 1 0 1 26 30 31 32
	CON'T $\begin{bmatrix} AEPORT & REPORT \\ TYPE & SOURCE & DOCKET NUMBER \\ \hline T & T & T & 0 5 0 - 0 2 8 6 0 \\ 57 58 59 60 61 61 68 69 \\ \hline T & 70 69 \\ \hline T & 70$	EVENT DATE REPORT DATE 1 5 7 7 0 1 2 8 7 7 74 75 80
02	EVENT DESCRIPTION During normal operation, control room instrum	entation indicated a leak-
7 I 03	age of reactor coolant to containment. The r	80 ate of leakage was deter-
7	mined to be approximately 15 GPM, and the sou	rce of leakage was identi-
7	e fied as the packing gland of pressurizer spra	y control valve PCV-455B.
2 []6 7	9 The reactor was brought to the cold shutdown	
	SYSTEM CAUSE COMPONENT COMPONENT COMPONENT CODE CODE COMPONENT COMPONENT COMPONENT C J E V A L V E X N C 6 3 10 11 12 17 43 44	
08	CAUSE DESCRIPTION The valve stem packing for a 3" air operated	Copes Vulcan Valve, assem-
7 E 09	bly drawing No. B130260, failed, causing reac	. 80
7 E 10	excess of the limits of Technical Specificati	on 3.1.F.5.
7 E	FACILITY METHOD OF STATUS % POWER OTHER STATUS DISCOVERY [E] [0] 9 1 [NA [A] [Sup 9 10 12 13 44 45 46	DISCOVERY DESCRIPTION ervisory Panel Alarm 80
12	FORM OF ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY Z Z Z NA NA NA 9 10 11 44 45	LOCATION OF RELEASE
, c	9 10 11 44 45 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION	80
[1]3 7 ε	0 0 0 7 NA 11 12 13	
14	PERSONNEL INJURIES NUMBER DESCRIPTION 0 0 0 NA]
15	PROBABLE CONSEQUENCES	80
78	OSS OR DAMAGE TO FACILITY YPE DESCRIPTION	80
16 7 8	<u>Z</u> <u>NA</u> 10	
	NA	
· – • • •	DDITIONAL FACTORS	80
18 7 8	(Event Desc. Cont.) - vere accomplished.	[R.O77-3-2(A)]. BO
19		1
78	NAME:Austin J. Decker TT	PHONE 914-739-8833