

William J. Cahill,
Vice President

Regulatory Docket File

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N.Y. 10003
Telephone (212) 460-3331

January 28, 1977



RE: Indian Point Unit No. 3
Docket No. 50-286
R.O. -77-3-2(A)




Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

We transmit herewith Reportable Occurrence Report R.O.
-77-3-2(A). Three copies of this letter and the
attachment are enclosed as required.

Very truly yours,


William J. Cahill, Jr.
Vice President

Attach.
1b

Copy to:

Director of Nuclear Reactor Regulation
Att: Dr. Ernst Volgenau, Director (40 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Director of Nuclear Reactor Regulation
Att: Mr. William G. McDonald, Director (3 copies)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, N.Y. 10019

8111070318 770128
PDR ADDCK 05000286
6 PDR

1057

LICENSEE EVENT REPORT

R.O.-77-3-2(A)

CONTROL BLOCK:

--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME			LICENSE NUMBER						LICENSE TYPE			EVENT TYPE												
01	N	Y	I	P	S	3	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1
7	8	9	14	15	25	26	30	31	32															
CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE			REPORT DATE													
01	CONT	T	I	0	5	0	-	0	2	8	6	0	1	1	5	7	7	0	1	2	8	7	7	
7	8	57	58	59	60	61	68	69	74	75	80													

EVENT DESCRIPTION

02	During normal operation, control room instrumentation indicated a leak-																							80
03	age of reactor coolant to containment. The rate of leakage was deter-																							80
04	mined to be approximately 15 GPM, and the source of leakage was identi-																							80
05	fied as the packing gland of pressurizer spray control valve PCV-455B.																							80
06	The reactor was brought to the cold shutdown condition, and repairs																							80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION		
07	C	J	E	V	A	L	V	E	X	N	C	6	3	5	N
7	8	9	10	11	12	17	43	44	47	48					

CAUSE DESCRIPTION

08	The valve stem packing for a 3" air operated Copes Vulcan Valve, assem-																							80
09	bly drawing No. B130260, failed, causing reactor coolant leakage in																							80
10	excess of the limits of Technical Specification 3.1.F.5.																							80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
11	E	0	9	1	NA	A	Supervisory Panel Alarm						
7	8	9	10	12	13	44	45	46	80				
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE					
12	Z	Z	NA	NA				NA					
7	8	9	10	11	44	45	80						

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION						
13	0	0	0	Z	NA					
7	8	9	11	12	13	80				

PERSONNEL INJURIES

NUMBER		DESCRIPTION							
14	0	0	0	NA					
7	8	9	11	12	80				

PROBABLE CONSEQUENCES

15	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION										
16	Z	NA										
7	8	9	10	80								

PUBLICITY

17	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	(Event Desc. Cont.) - were accomplished. [R.O.-77-3-2(A)].																							80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----