

LICENSEE EVENT REPORT

R.O.-76-3-38(B)

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER												LICENSE TYPE						EVENT TYPE	
01	N	Y	I	P	S	3	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3									
7	8	9	14	15	25	26	30	31	32																								
01		CONT		CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE						REPORT DATE											
01	CONT			L	L	0	5	0	-	0	2	8	6	1	1	0	8	7	6	1	2	0	6	7	6								
7	8	57	58	59	60	61	68	69	74	75	80																						

EVENT DESCRIPTION

02	While at steady state operation, Shutdown Bank "A" rod G-5 dropped, ac-																																																																															
03	tuating rod bottom and dropped rod alarms and initiating a turbine run-																																																																															
04	back to 640 MW. Maximum indicated tilt was calculated to be 9.9%. Reac-																																																																															
05	tor power was reduced to 65% as a result of the turbine runback. The																																																																															
06	rod was realigned within two hours, to satisfy the requirements of Tech-																																																																															

SYSTEM CODE				CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	R	B	E	C	K	T	B	R	K	N	X	9	9	9	N		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22		

CAUSE DESCRIPTION

08	The fuse (Sawmut, a 25x10, 10 Amp, 250 Volt) for the stationary gripper																																																																															
09	coil of Rod G-5 blew, causing the rod to drop. The fuse was replaced																																																																															
10	and the rod retrieved using standard plant procedures.																																																																															

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	0	9	1	NA	A	NA		
7	8	9	10	11	12	13	14	15	16
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
12	Z	Z	NA			NA			
7	8	9	10	11	12	13	14	15	16

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION	
13	0	0	0	Z	NA
7	8	9	11	12	13

PERSONNEL INJURIES

NUMBER		DESCRIPTION		
14	0	0	0	NA
7	8	9	11	12

PROBABLE CONSEQUENCES

15	NA																																																																															
7	8	9																																																																														

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION	
16	Z	NA	
7	8	9	10

PUBLICITY

17	NA																																																																															
7	8	9																																																																														

ADDITIONAL FACTORS (Event Desc. Cont.) - nical Specification 3.10.3.2. Power

18	range overpower trip setpoints were then reduced to 98%. A similar																																																																															
7	8	9																																																																														

19	event occurred on June 8, 1976. [R.O.-76-3-38(B)]																																																																															
7	8	9																																																																														

NAME: Austin J. Decker II

PHONE: 914-739-8823