

William J. Cahill, Jr.
Vice President


Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

October 22, 1976

REGULATORY DOCKET FILE COPY

Re: Indian Point Unit No. 3
Docket No. 50-286
R.O. -76-3-35(B)

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
King of Prussia, PA 19406



Dear Mr. O'Reilly:

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-64 the attached report of Reportable Occurrence R.O.-76-3-35(B) is submitted. This report fulfills the requirement for a written report within 30 days of a Reportable Occurrence and is in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Three copies of this letter and the attachment are enclosed as required.



Very truly yours,

A handwritten signature in cursive script, appearing to read "William J. Cahill, Jr.".

William J. Cahill, Jr.
Vice President

Enc:
PK/mmg

Copy to: Director of Nuclear Reactor Regulation
ATTN: Dr. Ernst Volgenau, Director (30 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director of Nuclear Reactor Regulation
ATTN: Mr. William G. McDonald, Director (3 copies)
Office of Management Information and
Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, N.Y. 10019

10831

8111070432 761022
PDR ADOCK 05000286
S PDR

LICENSEE EVENT REPORT

R.O.-76-3-35(B)

(PLEASE PRINT ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1 2 3 4 5 6

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	I	P	S	3	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3		
7	8	9				14	15											25	26				30	31	32	

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE										
01	CONT		L	L	0	5	0	-	0	2	8	6	0	9	2	4	7	6	1	0	2	2	7	6
7	8		57	58	59	60	61				68	69				74	75			80				

EVENT DESCRIPTION

02	During the performance of a monthly operational test of emergency diesel																								80
03	generators, the frequency of No. 31 diesel generator increased to 62																								80
04	Hertz. The speed control switch was ineffective in attempts to reduce																								80
05	speed. Thus, the operator took manual control of the governor, reduced																								80
06	speed, and removed the unit from service. A similar event occurred on																								80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER					VIOLATION	
07	E	E	E	M	E	C	F	U	N	N	W	2	9	0	N		
7	8	9	10	11	12				17	43	44			47	48		

CAUSE DESCRIPTION

08	The cause of the event was attributed to air in the oil lines to the																								80
09	Woodward Governor, which caused it to malfunction. This air pocket																								80
10	apparently resulted from the previous repair. The lines were purged,																								80

FACILITY STATUS		% POWER		OTHER STATUS					METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
11	G	0	0	0	NA				B	Surveillance Testing						
7	8	9	10	12	13				44	45	46				80	

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY					LOCATION OF RELEASE					
12	Z	Z	NA						NA					
7	8	9	10	11					44	45				80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION	
13	0	0	0	Z	NA
7	8	9	11	12	13

PERSONNEL INJURIES

NUMBER		DESCRIPTION	
14	0	0	0
7	8	9	11

PROBABLE CONSEQUENCES

15	NA																								80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY																										
TYPE		DESCRIPTION																								
16	Z	NA																								
7	8	9	10																							

PUBLICITY																									
17	NA																								80

ADDITIONAL FACTORS (Event Description Cont.) -

18	August 30, 1976. [R.O.-76-3-35(B)]																								80
(Cause Description Cont.) -																									
19	refilled, and the diesel returned to service.																								80

NAME: Austin J. Dacker II

PHONE: 914-739-8823