


William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

Regulatory Docket File

March 30, 1976
Re Indian Point Unit No. 3
Docket No. 50-286
R.O. -76-3-1(B)

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
King of Prussia, PA 19406



Dear Mr. O'Reilly

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-64 the attached report of Reportable Occurrence R.O.-76-3-1(B) is submitted. This report fulfills the requirement for a written report within 30 days of a Reportable Occurrence and is in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Three copies of this letter and the attachment are enclosed as required.



Very truly yours

William J. Cahill, Jr.
Vice President

Copy to Director of Nuclear Reactor Regulation
ATTN: Mr. Donald F. Knuth, Director (30 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director of Nuclear Reactor Regulation
ATTN: Mr. William F. McDonald, Director (3 copies)
Office of Management Information and
Program Control

U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8111070649 760330
PDR ADOCK 05000286
S PDR

3282

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 N Y I P S 3						LICENSE NUMBER: 00-00000-00						LICENSE TYPE: 41111			EVENT TYPE: 03	
CATEGORY: 01 CONT		REPORT TYPE: L	REPORT SOURCE: L	DOCKET NUMBER: 050-0286				EVENT DATE: 030876			REPORT DATE: 033076					

EVENT DESCRIPTION

02 During precritical hot shutdown operation, No. 31 steam generator blow-
03 down isolation valve 1214 failed to close upon operation of its control
04 room switch. Series Valve 1214A did close, and the isolation valves at
05 the steam generator were manually closed. The valve was repaired with-
06 in the required time specified in Technical Specification 3.6.a.(3),(cont'd)

SYSTEM CODE: 07 H I	CAUSE CODE: E	COMPONENT CODE: V A L V E X	PRIME COMPONENT SUPPLIER: N	COMPONENT MANUFACTURER: W 3 1 5	VIOLATION: N
----------------------------	----------------------	------------------------------------	------------------------------------	--	---------------------

CAUSE DESCRIPTION

08 A Worthington Controls Company, 2", 20,000 series control valve, plant
09 designation 1214, failed to operate due to a scored plug and guide
10 bushing.

FACILITY STATUS: 11 B	% POWER: 000	OTHER STATUS: NA	METHOD OF DISCOVERY: A	DISCOVERY DESCRIPTION: NA
FORM OF ACTIVITY RELEASED: 12 Z	CONTENT OF RELEASE: Z	AMOUNT OF ACTIVITY: NA	LOCATION OF RELEASE: NA	

PERSONNEL EXPOSURES

NUMBER: 13 000	TYPE: Z	DESCRIPTION: NA
-----------------------	----------------	------------------------

PERSONNEL INJURIES

NUMBER: 14 000	DESCRIPTION: NA
-----------------------	------------------------

PROBABLE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE: 16 Z	DESCRIPTION: NA
-------------------	------------------------

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 (Event Cont.) - Subsequent operational test of valve 1214 was success-
ful. (R.O. - 76-3-1 (B)).

19

NAME: **MICHAEL SHATKOUSKI**

PHONE: **(914) 739-8823**