Docket No. 50-286

Power Authority of the State of New York Indian Point 3 Nuclear Power Plant ATTN: Mr. Joseph Russell Resident Manager P.O. Box 215 Buchanan, New York 10511

Gentlemen:

Subject: Inspection No. 50-286/89-20

This refers to your letter dated January 19, 1990, in response to our letter dated December 29, 1989.

Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By:

Marvin W. Hodges, Director Division of Reactor Safety

cc w/encl:

- J. Bayne, President
- J. Brons, Executive Vice President Nuclear Generation
- G. Goldstein, Assistant General Counsel
- A. Klausmann, Senior Vice President, Appraisal and Compliance Services
- G. Wilverding, Manager, Nuclear Safety Evaluation
- C. Jackson, Manager, Regulatory Affairs
- R. Beedle, Vice President Nuclear Support
- W. Josiger, Vice President Nuclear Operations and Maintenance
- S. Zulla, Vice President Nuclear Engineering
- P. Kokolakis, Director Nuclear Licensing PWR
- D. Halama, Quality Assurance Superintendent
- M. Peckham, Assistant to Resident Manager

Dept. of Public Service, State of New York

State of New York, Department of Law

Public Document Room (PDR)

Local Public Document Room (LPDR)

Nuclear Safety Information Center (NSIC)


NRC Resident Inspector

State of New York, SLO Designee

OFFICIAL RECORD COPY

PRELL/IP3 REPLY/2/21/90 - 0001.0.0

02/21/90



bcc w/encl:

Region I Docket Room (with concurrences) Management Assistant, DRMA (w/o encl)

- P. Eselgroth, DRS
- J. Prell, DRS
- W. Schmidt, SRI Fitzpatrick
- F. Crescenzo, SRI Indian Point 2
- J. Neighbors, NRR
- J. Dyer, EDO

DRS Files (2)

DAS:RI Gallo

DRS:RI

Hodges

Indian Point 3 Nuclear Power Plant P.O. Box 215 Buchanan, New York 10511 914 736.8001



Joseph E. Russell Resident Manager

January 19, 1990 IP3-90-003 JC-90-002B

Docket No. 50-286 License No. DPR-64

Mr. Marvin W. Hodges, Director Division of Reactor Safety U.S. Nuclear Regulatory Commission Region 1 475 Allendale Road King of Prussia, PA 19406

SUBJECT: Inspection No. 50-286/89-20 and Associated Notice of Violation (89-20-01)

Dear Mr. Hodges:

This letter and Attachment I, provide the Authority's response to the notice of violation (89-20-01) identified in Inspection Report No. 50-286/89-20 and to the unresolved item (89-20-02) on the requalification program.

Should you or your staff have any questions concerning this matter, please contact Mr. M. Peckham of my staff.

Is Cum

Incerely

Joséph E. Russell Resident Manager Indian Point Unit 3 Nuclear Power Plant

JER:JC/rl

Attachment

CC: Document Control Desk (original)
U.S. Nuclear Regulatory Commission
Mail Station P1-137

Washington, D.C. 20555

Resident Inspector's Office

Indian Point 3

U.S. Nuclear Regulatory Commission

P.O. Box 337

Buchanan, NY 10511

904266201

ATTACHMENT I RESPONSE TO NOTICE OF VIOLATION 89-20-01

VIOLATION:

10 CFR 50.54 paragraph (i-1) requires, in part, that the licensee have an operator requalification program which must as a minimum meet the requirements of 10 CFR 55.59 paragraph (c) and that the scope of the requalification program may not be reduced except as authorized by the NRC.

10 CFR 55.59 paragraph (a) (1) requires, in part, that licensed operators successfully complete a licensee developed requalification program.

10 CFR 55.59 paragraph (c) (2) requires, in part, that the licensee have preplanned lectures on a regular and continuing basis throughout the license period.

Contrary to the above, during requalification training week 89.3 the Operations Superintendent was waived by the Resident Manager from attending classes identified in the licensee's requalification training program. This is contrary to 10 CFR 55.59 which requires licensed operators to complete the license developed requalification program preplanned lectures.

This is a Severity Level IV Violation (10 CFR 2, Appendix C, Supplement I).

RESPONSE:

The Authority has reviewed in detail the notice of violation outlined in Attachment A of NRC Inspection Report 89-20 and agrees that the event occurred as discussed. The Authority believes that this event was not a safety significant concern. This was an isolated case of oversight in not recognizing that we could not waive licensed requalification topics. A review of training records reveals that no licensed operator currently holding an active license has been waived from any training.

The following corrective actions have been implemented:

- 1. The Operations Superintendent made up the classroom portion of week 89.3 by 3 days of directed self study.
- 2. The Operations Superintendent is scheduled to make up the simulator portion of week 89.3 upon completion of a scheduled simulator upgrade outage. This is currently scheduled for February 1990.

ATTACHMENT I RESPONSE TO NOTICE OF VIOLATION 89-20-01

3. The IP-3 Training Department has implemented a written training policy which prohibits waiver of licensed operator training.

The Authority believes that these corrective actions will be effective in preventing similar occurrences in the future.

UNRESOLVED ITEM (89-20-02):

Although the licensee has not committed to industry standard ANSI/ANS-3.1-1987 or ANSI/ANS-3.1-1981, both the NRC and industry endorse the inclusion of Applicable Industry Operating Events, discussed in these standards, in the licensee's specified requalification training program. Indian Point 3 has not specified this topic as part of their formal requalification training program. This is an unresolved item (50-286/89-20-02).

RESPONSE:

After detailed review of unresolved item (50-286/89-20-02) the Authority concludes that the licensed operator requalification program does specify that applicable industry operating events be included in the curriculum. In the past these modules did not require mandatory attendance. Effective immediately these topics will require mandatory attendance by licensed operators.

The Authority believes this resolves Unresolved Item 50-286/89-20-02.