

Stephen B. Bram  
Vice President

Consolidated Edison Company of New York, Inc.  
Indian Point Station  
Broadway & Bleakley Avenue  
Buchanan, NY 10511  
Telephone (914) 737-8116


April 10, 1992

Re: Indian Point Unit No. 2  
Docket No. 50-247  
LER 92-05-00

Document Control Desk  
US Nuclear Regulatory Commission  
Mail Station P1-137  
Washington, DC 20555

The attached Licensee Event Report LER 92-05-00 is hereby  
submitted in accordance with the requirements of 10 CFR 50.73.

Very truly yours,



Attachment

cc: Mr. Thomas T. Martin  
Regional Administrator - Region I  
US Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Mr. Francis J. Williams, Jr., Project Manager  
Project Directorate I-1  
Division of Reactor Projects I/II  
US Nuclear Regulatory Commission  
Mail Stop 14B-2  
Washington, DC 20555

Senior Resident Inspector  
US Nuclear Regulatory Commission  
PO Box 38  
Buchanan, NY 10511

9204200224 920410  
PDR ADDCK 05000247  
S PDR

IF22  
111

**LICENSEE EVENT REPORT (LER)**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) <b>Indian Point Unit No. 2</b>	DOCKET NUMBER (2) <b>0 5 0 0 0 2 4 7</b>	PAGE (3) <b>1 OF 0 3</b>
---	---	-----------------------------

TITLE (4)  
**Missed Surveillance, Test for Instrument Channel Checks**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)
0 3	1 1	9 2	9 2	0 0 5	0 0	0 4	1 0	9 2		0 5 0 0 0

OPERATING MODE (9) **N**

POWER LEVEL (10) **1 0 0**

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.405(c)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.405(a)(1)(i)	<input type="checkbox"/> 50.38(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)
<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 50.38(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 366A)
<input type="checkbox"/> 20.405(a)(1)(iii)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	
<input type="checkbox"/> 20.405(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME <b>George Dahl, Engineer</b>	TELEPHONE NUMBER
	AREA CODE: <b>9 1 4</b> NUMBER: <b>5 2 6 - 5 1 8 6</b>

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)     NO

EXPECTED SUBMISSION DATE (15)

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On March 11, 1992, while the plant was at 100% power, it was determined that the surveillance interval for channel check of the instruments that monitor containment pressure, subcooling margin, PORV position, PORV block valve position, pressurizer safety valve position, and auxiliary feedwater flow rate had been exceeded by four days due to personnel error. These checks are required by Technical Specification Table 4.1-1 and are performed in one common surveillance test, PT-M64. Upon discovery, the test was promptly performed and all instrument readings were found to be satisfactory. Changes will be made to the scheduling database to indicate if a test procedure has actually been issued to the group responsible for performing the test. The health and safety of the public were not affected during the period of the missed test.

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 600 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Indian Point Unit No. 2	DOCKET NUMBER (2)  0   5   0   0   0   2   4   7 9   2	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
			- 0   0   5	- 0   0	0   2	OF	0   3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

**PLANT AND SYSTEM IDENTIFICATION:**

Westinghouse 4-Loop Pressurized Water Reactor

**IDENTIFICATION OF OCCURRENCE:**

Surveillance intervals for instrument channels exceeded.

**EVENT DATE:**

March 11, 1992

**REPORT DUE DATE:**

April 10, 1992

**REFERENCES:**

Significant Occurrence Report (SOR) 92-137

**PAST SIMILAR OCCURRENCE:**

None

**DESCRIPTION OF OCCURRENCE:**

On March 11, 1992, with reactor power at 100%, it was determined that PT-M64, the monthly channel check of a number of instruments, had not been performed at its required frequency but was four days beyond the allowed time period. These surveillance tests are required by Technical Specification Table 4.1-1. The instruments involved monitor high range containment pressure, reactor coolant system subcooling margin, PORV position, PORV block valve position, pressurizer safety valve position, and auxiliary feedwater flow rate. The common surveillance test procedure for these instruments was issued and the test was performed immediately.

**ANALYSIS OF OCCURRENCE:**

Although the instruments were not checked at the required frequency, all readings were found to be acceptable when the test was performed. No adjustments, calibrations or repairs were required. Therefore, there were no impacts on the operability of any of the instruments during the period of the missed test.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-830), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Indian Point Unit No. 2	DOCKET NUMBER (2)  0   5   0   0   0   2   4   7	LER NUMBER (6)			PAGE (3)		
		YEAR 9   2	SEQUENTIAL NUMBER -   0   0   5	REVISION NUMBER -   0   0	0   3	OF	0   3

TEXT (If more space is required, use additional NRC Form 386A's) (17)

ANALYSIS OF OCCURRENCE: (continued)

The Test and Performance (T&P) section develops, revises and issues surveillance test procedures to various groups in the station who then conduct the test. Operations, Instrumentation and Controls, and the Test Group are some of the groups that actually perform the required tests. To aid these groups in scheduling of the tests, T&P issues a weekly scheduling report that lists the tests needed to be performed for the next two weeks and indicates an issue date for each test. The test procedures are also issued at this time. To alert the various groups to tests that are nearing their regulatory required date, T&P issues a delayed test report twice a week. This affords each group the opportunity to verify that they received a copy of the test and that the test was in fact completed, or, to perform the test prior to its due date. Once a test nears its due date and T&P has not received notification of its completion, a call is made to the responsible group to check on the status.

In this particular instance involving PT-M64, circumstances combined such that the normal process described above did not ensure the test was completed within the required frequency. Coincidentally with the issuance of the PT-M64 schedule, the PT-M64 test procedure was undergoing a change review cycle. An error in communication occurred which mistakenly led to the belief that the test had been performed, when in actuality only the approval of changes to the test procedure had been completed.

CAUSE OF OCCURRENCE:

Although several factors combined to cause the missed surveillance, personnel error, in particular miscommunication, was the principal cause.

CORRECTIVE ACTIONS:

Although the normal process for test issuance, scheduling and performance has been effective in the past, revisions will be made to the scheduling database to avoid, in the future, any potential confusion between surveillance test performance scheduling and the status of test procedure change reviews.

The need for formality in communication between station groups concerning nuclear safety matters will be stressed with the individuals involved.