DOCKET FILES



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

JUN 0 5 1990

See Rpt.

Docket No. 50-247

9006110210 900605 PDR ADOCK 05000247

ø

LICENSEE: Consolidated Edison Company of New York, Inc.

FACILITY: Indian Point Nuclear Generating Unit No. 2

SUBJECT: MEETING MINUTES REGARDING MAY 21, 1990 MEETING TO DISCUSS RESULTS OF MID-CYCLE INSPECTION OF INDIAN POINT 2 STEAM GENERATORS

A meeting was held in the NRC One White Flint Office in Rockville, Maryland on May 21, 1990, with Consolidated Edison and NRC staff representatives to discuss the results of the recently completed mid-cycle inspection of the Indian Point 2 steam generators. This meeting was requested by the NRC staff as a followup to the March 14, 1990 meeting during which the initial results of the mid-cycle inspection were discussed. The purpose of the meeting was for the licensee to brief the staff on the results of the mid-cycle inspection of the Indian Point 2 steam generators and to review the results of the licensee's analysis supporting continued operation of Indian Point 2. Enclosure 1 is a list of

Prior to the meeting, the staff had received and reviewed copies of proprietary WCAP 12573 and non-proprietary WCAP 12574 "Indian Point Unit 2 Steam Generator Inspection, Repair, and Restoration Program."

The licensee's presentation consisted of a non-proprietary discussion of inspection results, repairs, metallurgical analyses, root cause and mitigating actions and a proprietary discussion of industry experience and steam generator integrity evaluations. Enclosure 2 is a copy of the licensee's non-proprietary handout. The material used during the proprietary discussion was attached to Enclosure 3; however, the proprietary material has been removed and is being withheld from public disclosure.

During the meeting, the licensee reported that analyses had determined that the cracking in the girth welds, base material of the transition cones and in the feedwater ring supporting brackets was caused by corrosion fatigue and/or stress corrosion depending on the loads, environment and location. These analyses also determined that the crack initiation occurred at locations with (residual or applied). The cracking in the feedwater piping and nozzles was caused by corrosion fatigue.

The licensee has removed and repaired all identified cracks in accordance with ASME Code requirements. The feedwater piping and nozzles have been returned to the original design configuration. The licensee is also making modifications to the plant to reduce the level of oxygen in the water that contributes to

pitting and crack initiation. In addition, the licensee has a program to replace all copper bearing materials in the condensate and feedwater system during the next two refueling outages. In response to NRC's concern that pitting in other parts of the steam generator shells could lead to cracking, the licensee stated that although they had not performed detailed inspections of the lower internal surfaces of the steam generator shells, they had noted that the surface pitting appeared concentrated in the areas near the girth welds.

At the conclusion of the meeting, the NRC staff reiterated its position that the steam generators, including internal brackets and feedwater nozzles, must meet the requirements of the ASME Boiler and Pressure Vessel Code for restart and for the duration of the subsequent operating period. The licensee's analyses for restart and continued operation must include consideration of the maximum additional cracking considered credible during the next period of operation.

Based on the information presented at the meeting and the staff's preliminary review of the licensee's analyses, the NRC staff made the following requests:

- 1. The licensee should perform appropriate visual inspections of one steam generator to confirm that the lower interior surface of the steam generator shell is acceptably free of surface pitting. The results of these inspections should be recorded. The licensee committed to perform these visual inspections.
- 2. The NRC should be informed of the inspection plan and engineering acceptance criteria for these visual inspections prior to initiating these visual inspections.
- 3. If the acceptance criteria for surface pitting is exceeded, the results should be reported to the NRC and the licensee should determine the extent of additional volumetric inspections required.
- 4. Prior to restart, the licensee should provide the NRC with a summary of inspections performed during the current outage. This summary should include the results of additional UT inspections currently being performed.

2 -

\*\*\* \*!...... The licensee should provide a comprehensive final report within approximately 30 days of restart. This report should include:

- a. inspection results
- b. definition of loads considered
- c. stress analyses
- d. fracture mechanics
- e. metallurgical analyses
- f. repair methods

## ORIGINAL SIGNED BY

Donald S. Brinkman, Senior Project Manager Project Directorate I-1 Division of Reactor Projects - I/II Office of Nuclear Reactor Regulation

Enclosures: As stated

5.

cc w/enclosures: See next page

## **Distribution:**

Docket File NRC/Local PDRs FMiraglia JPartlow PDI-1 Reading RACapra DBrinkman OGC EJordan NRC Participants ACRS(10) JLinville

PDI-1 *DH* DBrinkman:rsc 5/31/90

PDI-1 Poe RACapra 6/5/90

DOCUMENT NAME: MEETING MINUTES 5/21/90

Mr. Stephen B. Bram Consolidated Edison Company of New York, Inc.

cc:

Mayor, Village of Buchanan 236 Tate Avenue Buchanan, New York 10511

Ms. Donna Ross New York State Energy Office 2 Empire State Plaza 16th Floor Albany, New York 12223

Mr. Charles W. Jackson Manager of Nuclear Safety and Licensing Consolidated Edison Company of New York, Inc. Broadway and Bleakley Avenue Buchanan, New York 10511

Senior Resident Inspector U.S. Nuclear Regulatory Commission Post Office Box 38 Buchanan, New York 10511

Mr. Brent L. Brandenburg Assistant General Counsel Consolidated Edison Company of New York, Inc. 4 Irving Place - 1822 New York, New York 10003 Indian Point Nuclear Generating Station 1/2

Mr. Charlie Donaldson, Esquire Assistant Attorney General New York Department of Law 120 Broadway New York, New York 10271

Mr. Peter Kokolakis, Director Nuclear Licensing Power Authority of the State of New York 123 Main Street White Plains, New York 10601

Mr. Walter Stein Secretary - NFSC Consolidated Edison Company of New York, Inc. 4 Irving Place - 1822 New York, New York 10003

Regional Administrator, Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406