

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | Y | I | P | S | 3 | (2) | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | (3) | 4 | 1 | 1 | 1 | 1 | (4) | \_\_\_\_\_ | (5)

CON'T  
01 | REPORT SOURCE | L | (6) | 0 | 5 | 0 | 0 | 0 | 2 | B | 6 | (7) | 0 | 6 | 1 | 4 | 8 | 0 | (8) | 0 | 6 | 2 | 7 | 8 | 0 | (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | WHILE OPERATING AT FULL POWER, TESTING WAS PERFORMED TO VERIFY THE AIR  
03 | FLOW IN THE CONTROL ROOM AIR FILTRATION SYSTEM. THE TEST INDICATED A  
04 | TOTAL FILTER FLOW OF 1833 CUBIC FEET PER MINUTE. THIS IS GREATER THAN  
05 | THE EXTRAPOLATED MAXIMUM FLOW OF 1333 CUBIC FEET PER MINUTE AT WHICH THE  
06 | CHARCOAL HAS A METHYL IODINE REMOVAL EFFICIENCY OF 90 PERCENT, AS IS  
07 | REQUIRED BY TECHNICAL SPECIFICATION 4.5.A.5.D.(1). PLANT PERFORMANCE WAS  
08 | NOT AFFECTED BY THIS INCIDENT. NO SIMILAR EVENTS HAVE BEEN REPORTED. (8)

09 | SYSTEM CODE | A | A | (11) | CAUSE CODE | E | (12) | CAUSE SUBCODE | B | (13) | COMPONENT CODE | V | A | L | V | E | X | (14) | COMP. SUBCODE | X | (15) | VALVE SUBCODE | X | (16)

(17) LER/RO REPORT NUMBER | 8 | 0 | (21) | EVENT YEAR | 8 | 0 | (22) | SHUTDOWN METHOD | Z | (21) | HOURS | 0 | 0 | 0 | 0 | (22) | ATTACHMENT SUBMITTED | N | (23) | NPRD-4 FORM SUB. | N | (24) | PRIME COMP. SUPPLIER | N | (25) | REVISION NO. | 0 | (32) | COMPONENT MANUFACTURER | A | I | 6 | 0 | (26)

ACTION TAKEN | E | (18) | FUTURE ACTION | X | (19) | EFFECT ON PLANT | Z | (20) | SHUTDOWN METHOD | Z | (21) | HOURS | 0 | 0 | 0 | 0 | (22) | ATTACHMENT SUBMITTED | N | (23) | NPRD-4 FORM SUB. | N | (24) | PRIME COMP. SUPPLIER | N | (25) | COMPONENT MANUFACTURER | A | I | 6 | 0 | (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | THE DRIFTING OF AN ALLEN-BRADLEY 802T-A DAMPER WAS FOUND TO BE  
11 | RESPONSIBLE FOR THE HIGH FLOW. THIS CONDITION WAS IMMEDIATELY RECTIFIED  
12 | BY BALANCING THE SYSTEM, AFTER WHICH THE FLOW WAS REDUCED TO 905 CUBIC  
13 | FEET PER MINUTE. TO PRECLUDE RECURRENCE OF THIS SITUATION, THE CONTROL  
14 | ROOM AIR FILTRATION CHARCOAL HAS BEEN UPGRADED AND TESTED TO HIGH FLOWS. (8)

15 | FACILITY STATUS | E | (28) | % POWER | 1 | 0 | 0 | (29) | OTHER STATUS | NA | (30) | METHOD OF DISCOVERY | B | (31) | DISCOVERY DESCRIPTION | ROUTINE SURVEILLANCE | (32)

16 | ACTIVITY CONTENT | Z | (33) | RELEASED OF RELEASE | Z | (34) | AMOUNT OF ACTIVITY | NA | (35) | LOCATION OF RELEASE | NA | (36)

17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | (37) | TYPE | Z | (38) | DESCRIPTION | NA | (39)

18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | (40) | DESCRIPTION | NA | (41)

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | (42) | DESCRIPTION | NA | (43)

20 | PUBLICITY ISSUED | N | (44) | DESCRIPTION | NA | (45)