

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	I	P	S	3	2	0	0	-	0	0	0	0	0	0	0	0	3	4	1	1	1	4	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33
LICENSEE CODE								LICENSE NUMBER								LICENSE TYPE 57 CAT 58										

0	1	L	0	5	0	0	0	2	8	6	7	1	0	2	5	8	0	8	1	1	2	4	8	0	9
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83
REPORT SOURCE								DOCKET NUMBER								EVENT DATE REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 WHILE AT COLD SHUTDOWN, ACCUMULATOR LEVEL TRANSMITTER CALIBRATION TEST

0 3 (3PC-R16A) INDICATED THAT TWO OF THE EIGHT LEVEL TRANSMITTERS WERE

0 4 OUTSIDE OF THE PROCEDURAL LIMITS IN THE NONCONSERVATIVE DIRECTION:

0 5 TRANSMITTERS LT934B AND LT935B INDICATED HIGH ON A LOW LEVEL TEST SIGNAL

0 6 BY 9.5 AND 2.5 PERCENT, RESPECTIVELY. UNDER THESE CONDITIONS THE

0 7 POTENTIALITY EXISTS FOR OPERATING WITH THE ACCUMULATOR WATER VOLUME

0 8 OUTSIDE THE LIMITS SET BY TECHNICAL SPECIFICATION 3.3.A.3.C.

0	9	C	J	11	E	12	E	13	I	N	S	T	R	U	14	T	15	Z	16																										
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26																										
SYSTEM CODE			CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE								COMP. SUBCODE		VALVE SUBCODE																												
17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47															
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																			
8		0		0		1		4		/		0		3		L		0		E		Z		Z		0		0		Y		N		R			3			6			9		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE ACCUMULATOR LEVEL TRANSMITTERS (ROSEMOUNT, MODEL 1151 DP ) WERE

1 1 IMMEDIATELY RESET TO WITHIN TECHNICAL SPECIFICATION REQUIREMENTS AND

1 2 RETURNED TO SERVICE. THE CAUSE OF THIS INCIDENT WAS DETERMINED TO BE

1 3 INSTRUMENT DRIFT. SIMILAR EVENTS OCCURRED ON JULY 5, 1978 (LER 78-

1 4 015/03L-0) AND NOVEMBER 27, 1979 (LER 79-015/01T-0).

1	5	G	28	0	0	0	29	NA	30	B	31	SURVEILLANCE TEST	32
7	8	9	10	11	12	13	14	15	16	17	18	19	20
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
1	6	Z	33	Z	34	NA	35	NA	36	LOCATION OF RELEASE			
7	8	9	10	11	12	13	14	15	16	17	18	19	20
ACTIVITY		CONTENT		AMOUNT OF ACTIVITY		PERSONNEL EXPOSURES		DESCRIPTION					
1	7	0	0	0	37	Z	38	NA	39	PERSONNEL INJURIES			
7	8	9	10	11	12	13	14	15	16	17	18	19	20
RELEASED OF RELEASE		AMOUNT OF ACTIVITY		PERSONNEL EXPOSURES		PERSONNEL INJURIES		LOSS OF OR DAMAGE TO FACILITY					
1	8	0	0	0	40	NA	41	NA	42	PUBLICITY			
7	8	9	10	11	12	13	14	15	16	17	18	19	20
LOSS OF OR DAMAGE TO FACILITY		PUBLICITY		ISSUED		DESCRIPTION		NRC USE ONLY					
1	9	Z	43	NA	44	8012010	45	415	8012010				
7	8	9	10	11	12	13	14	15	16	17	18	19	20
ISSUED		DESCRIPTION		PUBLICITY		ISSUED		NRC USE ONLY					
2	0	N	44	NA	45	8012010	46	415	8012010				
7	8	9	10	11	12	13	14	15	16	17	18	19	20

ATTACHMENT 1

Docket No. 50-286  
LER 80-014/03L-0

Power Authority of the  
State of New York

The plant was in the cold shutdown condition.

On October 25, 1980, performance of the Accumulator Level Transmitter Calibration Test (3PC-R16A) indicated that two of the eight level transmitters were indicating non-conservative values on a trip signal.

Technical Specification 3.3.A.3.c. requires a minimum of 800 and a maximum of 815 cubic feet of water in each accumulator. These limits, when converted to percent of span are read as 33.5 and 51.1 percent, respectively. The level transmitters, which have a tolerance of  $\pm 2\%$ , are tested by submitting them to input signals at the low and high trip setpoints and observing the resultant indications.

The following results were observed:

<u>Transmitter</u>	<u>Input Signal</u>	<u>Indication</u>		<u>Difference</u>	
		<u>Percent</u>	<u>Cu.Ft.</u>	<u>Percent</u>	<u>Cu.Ft.</u>
LT934B	33.5% (Low)	43.0	808	9.5	8.0
LT935B	33.5% (Low)	36.0	802	2.5	2.0

In order to be conservative, the transmitters must read less than or equal to 33.5 percent for a low level signal. It can be seen from the above table that the transmitters were out of specification by 9.5 and 2.5 percent.

The accumulator level transmitters (Rosemount, Model 1151 DP) were immediately reset to within Technical Specification requirements and returned to service. The cause of the incident was determined to be instrument drift.

Similar events occurred on July 5, 1978 (LER 78-015/03L-0) and November 27, 1979 (LER 79015/01T0).