

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	I	P	S	B	2	0	0	-	0	0	0	0	0	0	0	3	4	1	1	1	1	4	5	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34

CON'T

0	1	L	6	0	5	0	0	0	2	8	6	7	1	2	0	5	8	0	8	1	2	1	7	8	0	9	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 WHILE AT COLD SHUTDOWN, DURING A ROUTINE CHECK, A LEAK OF 0.25 PINTS PER

0 3 MINUTE WAS IDENTIFIED IN FAN COOLER UNIT NO. 35. THIS EVENT FALLS UNDER

0 4 THE JURISDICTION OF IE BULLETIN 80-24, WHICH REQUIRES NOTIFICATION OF

0 5 ANY SERVICE WATER SYSTEM LEAKS WITHIN CONTAINMENT. AS THE PLANT WAS IN

0 6 THE COLD SHUTDOWN CONDITION, NO IMMEDIATE ACTION WAS NECESSARY UNDER THE

0 7 TECHNICAL SPECIFICATIONS.

0	9	S	B	11	E	12	B	13	B	L	O	W	E	R	14	Z	15	Z	16	17	8	0	18	0	19	0	20	21	1	22	0	1	23	1	24	0	1	25	0	26	0	27	0	28	1	29	0	30	1	31	0	32	0	33	34	0	35	Z	36	Z	37	0	38	0	39	0	40	N	41	Y	42	N	43	W	44	1	45	2	46	0	47	26
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80									

1	0	B	18	Z	19	Z	20	Z	21	0	22	0	0	0	0	N	23	Y	24	N	25	W	26	1	27	0	28
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE UNIT WAS ISOLATED FOR REPAIRS. A LEAK WAS OBSERVED TO EXIST IN A

1 1 TUBE OF THE MAIN COOLING COILS (WESTINGHOUSE, SPEC. 677119) FOR FAN

1 2 COOLER UNIT NO. 35. THE LEAKING TUBE WAS REPAIRED, AFTER WHICH THE UNIT

1 3 WAS TESTED AND RETURNED TO SERVICE. A SIMILAR EVENT OCCURRED ON JULY 16,

1 4 1980(LER 80-011/03L-0).

1	5	G	28	0	0	0	29	NA	30	B	31	ROUTINE CHECK	32	NA	36
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22

1	6	Z	33	Z	34	NA	35	NA	39
7	8	9	10	11	12	13	14	15	16

1	7	0	0	0	37	Z	38	NA	41
7	8	9	10	11	12	13	14	15	16