

FEB 0 3 2010

10CFR50.73

LR-N10-0019

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington DC 20555-001

> LER 272/09-001 Salem Nuclear Generating Station Unit 1 Facility Operating License No. DPR-70 NRC Docket No. 50-272

Subject: Chillers Inoperability Exceeds TS Allowed Outage Time

This Licensee Event Report, "Chillers Inoperability Exceeds TS Allowed Outage Time" is being submitted pursuant to the requirements of the Code of Federal Regulations 10CFR50.73(a)(2)(i)(B).

The attached LER contains no commitments. Should you have any questions or comments regarding this submittal, please contact Mr. Howard Berrick at 856-339-1862.

Sincerety

Carl/Fricker Site Vice President - Salem

Attachments (1)

Document Control Desk Page 2 LR-N10-0019

СС

Mr. S. Collins, Administrator - Region I Mr. R. Ennis, Licensing Project Manager - Salem USNRC Senior Resident Inspector - Salem (X24) Mr. P. Mulligan, Manager IV Mr. H. Berrick, Salem Commitment Tracking Coordinator Mr. L. Marabella, orporate Commitment Tracking Coordinator

NRC FOI (19-2007)	RM 366	,		U.S. N	NUCL	EAR RE	GULATOR	A COWNIS	SSION	4PPROV	VED BY OMB:	NO. 3150-0	0104	1 ML 41	EXPIRES:	08/31/2010
LICENSEE EVENT REPORT (LER)										Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs. NEOB-10202, (3150-0104). Office of Management and Budget. Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to. the						
										informat	ion collection.			·		
1. FACII	. FACILITY NAME										2. DOCKET NUMBER 3. PAGE					
Salem Generating Station - Unit 1									(05000272 1 of 4						
4. TITLE	: Chiller	rs Inope	erability	Exce	eds	TS All	owed Oı	utage Til	me							
5. EVENT DATE		6. LER NUMBER			7. REPORT DATE		ATE	8. OTHER I		OTHER F	ACILITIES INVOLVED					
MONTH	DAY	YEAR	YEAR	SEQUE NUM	ENTIAI IBER	L REV NO.	MONTH	DAY	YEAR	FACIL	ITY NAME				DOCKET	IUMBER
12	05	2009	2009	0 0	D 1	0	02	03	2010)				· .	DOCKET	IUMBER
9. OPEF	RATING	NODE	11	. THIS	REPO	ORTIS	SUBMITT	ED PURS	UANT T	D THE	REQUIREME	NTS OF	10 CF	R§: (Che	ck all that a	pply)
1 10. power level 100			20.2201(b) 20.2203(a)(3) 20.2201(d) 20.2203(a)(3) 20.2203(a)(1) 20.2203(a)(4) 20.2203(a)(2)(i) 50.36(c)(1)(i)) 20.2203(a)(2)(ii) 50.36(c)(1)(i)) 20.2203(a)(2)(ii) 50.36(c)(2) 20.2203(a)(2)(iv) 50.46(a)(3)(ii) 20.2203(a)(2)(v) 50.73(a)(2)(i) 20.2203(a)(2)(v) 50.73(a)(2)(i))(3)(i))(3)(ii))(4))(i)(A))(ii)(A))(ii)))(ii) 2)(i)(A) 2)(i)(B)	$ \begin{bmatrix} 50.73(a)(2)(i)(C) & 50.73(a)(2)(vii) \\ 50.73(a)(2)(ii)(A) & 50.73(a)(2)(viii)(A) \\ 50.73(a)(2)(ii)(B) & 50.73(a)(2)(viii)(B) \\ 50.73(a)(2)(iii) & 50.73(a)(2)(vii)(A) \\ 50.73(a)(2)(iv)(A) & 50.73(a)(2)(x) \\ 50.73(a)(2)(v)(A) & 73.71(a)(4) \\ 50.73(a)(2)(v)(B) & 73.71(a)(5) \\ 50.73(a)(2)(v)(C) & OTHER \\ 50.73(a)(2)(v)(D) & Specify in Abstract t b \\ \end{bmatrix} $)(A))(B) (A)				
			I			1	2. LICEN	SEE CON	TACT F	OR THI	SLER			or in	NRC Form	366A
FACILITY NAME TELEPHONE NUMBER (Include Area Code) Howard Berrick, Senior Engineer, Salem Regulatory Assurance (856) 339 -1862																
			13. COM	IPLET	E ON	E LINE	FOR EAC	н сомро	DNENT I	AILUR	E DESCRIBE	D IN THI	S RE	PORT		
CAUSE SYSTE		SYSTEM	COMPONENT MANU- FACTURER		REPORTABLE TO EPIX		c	AUSE	SYSTEM	SYSTEM COMPONENT		MANU- FACTURE	REP R T	REPORTABLE TO EPIX		
Х КМ			T	S	Ρ	129		N								
14			4. SUPPLEMENTAL REPORT EXPECTED						15. EXPECTED SUBMISSION)	MONTH	DAY	YEAR		
	=S (If yes	s, complet	te 15. EXPECTED SUBMISSION DATE)					Ľ	DATE				•			
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) On 11/30/09 at 1509 hours, the 12 Chiller was removed from service for maintenance and design change installation. With one Chiller inoperable, a 14-day Limiting Condition for Operation (LCO) was entered. On 12/02/09 at 1713 hours the 13 Chiller was found out of service and declared inoperable. With two inoperable Chillers, a 72-hour LCO was entered. On 12/04/09 at 2017 hours, the 12 Chiller was declared operable following completion of maintenance and testing of the design change installation. The 72-hour LCO was exited. However, the original 14-day LCO window remained active because of the inoperability of 13 Chiller.																
On 12/07/09, during the operability retest of 13 Chiller, the 12 Chiller tripped on low temperature freeze protection and a 72-hour LCO was re-entered. A detailed troubleshooting of the 12 Chiller identified that the low temperature trip switch was set 7 degrees F above its required setpoint. The 12 Chiller low temperature trip switch was promptly reset to the correct setpoint. However, because the low temperature trip switch setting that made the 12 Chiller inoperable existed during the period 12/02/09 through 12/07/09 while 13 Chiller was inoperable, two Chillers were inoperable for longer than the 72 hours allowed by TS 3.7.10 Action b.3.																
This report is being made in accordance with 10CFR50.73 (a)(2)(i)(B), "any operation prohibited by the plant's Technical Specification."																
. L						•		· .								

NRC FORM 366A (5-2007) U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET		3. PAGE				
Salem Generating Station Unit 1	05000272	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		2009	-001-	00-	2	of	4

NARRATIVE

PLANT AND SYSTEM IDENTIFICATION

Westinghouse - Pressurized Water Reactor (PWR/4)

Chilled Water System {KM/TS}

* Energy Industry Identification System {EIIS} codes and component function identifier codes appear as {SS/CCC}

IDENTIFICATION OF OCCURRENCE

Event Date: December 5, 2009

Discovery Date: December 7, 2009

CONDITIONS PRIOR TO OCCURRENCE

Salem Unit 1 was in Operational Mode 1 at 100% reactor power

DESCRIPTION OF OCCURRENCE

On 11/30/09 at 1509 hours, 12 Chiller was removed from service (a 14-day Limiting Condition for Operation (LCO) entered) for maintenance and design change installation. All appropriate non-essential heat loads were removed from the chilled water system {KM/-} as required by Technical Specifications (TS) 3.7.10 "Chilled Water System – Auxiliary Building Subsystem." The 12 Chiller had been operating properly prior to its removal from service.

On 12/02/09 at 1713 hours the 13 Chiller was found out of service and declared inoperable. With two (2) Chillers (i.e., 12 and 13) inoperable, a 72-hour LCO was entered in accordance with TS 3.7.10 Action b.3, expiring on 12/05/09 at 1713 hours.

On 12/04/09 the 12 Chiller tripped on freeze protection shortly after being placed in service for testing. The trip was due to the low temperature cutout. The trip was reset, and the 12 Chiller re-started, but tripped again after a short run. The recently performed Chiller work scope was reviewed; the only work items that could have affected Chiller operation were the liquid line solenoid valve (LLSV) addition and the Chiller internal inspection (unloader adjustment). The LLSV was verified to be operating correctly by temperature measurements across the valve. The unloader was adjusted and the 12 Chiller was declared Operable at 2017 hours and the 72-hour LCO exited. However, the original 14-day LCO window remained active because of the inoperability of 13 Chiller.

NRC FORM-366A (9-2007)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET		3. PAGE		
Salem Generating Station Unit 1	05000272	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
		2009	-001-	00	3 of 4

NARRATIVE

DESCRIPTION OF OCCURRENCE (cont'd)

On 12/07/09, during the operability retest of 13 Chiller, 12 Chiller tripped on low temperature freeze protection. The 72-hour LCO was re-entered at 0907 hours, with an expiration date of 12/10/09 at 0907 hours. A detailed troubleshooting of the 12 Chiller was performed which included a calibration check of the low temperature trip switch. This switch was found to be out of calibration, tripping 7 degrees F above its setpoint. The setpoint for the freeze trip from this device is 35 +/- 1.5 degrees F. The 12 Chiller low temperature trip switch was promptly reset to correct the setpoint. However, the 12 Chiller was not declared Operable due to other equipment issues.

On 12/07/09 at 1126 hours, 13 Chiller was declared Operable and the 72-hour LCO exited.

However, because the low temperature trip switch setting that made the 12 Chiller inoperable existed during the period 12/02/09 through 12/07/09 while 13 Chiller was inoperable, two Chillers were inoperable for longer than the 72 hours allowed by TS 3.7.10 Action b.3.

This report is being made in accordance with 10CFR50.73 (a)(2)(i)(B), "any operation ... prohibited by the plant's Technical Specification."

CAUSE OF OCCURRENCE

The cause of the 12 Chiller tripping on freeze protection was the low temperature trip switch being set 7 degrees F high. The low temperature trip switch was found out of position from where it was left following calibration in June 2009. The cause for the mispositioned setpoint knob is unknown but most likely occurred during the 11/30/09 maintenance and design change installation window.

PREVIOUS OCCURRENCES

A review of LERs for Salem Station back to 2006 identified one previous similar occurrence, LER 311/07-001-00, "Inoperability of the Chilled Water System - 21 and 22 Chillers Inoperable. The cause of this LER was a loose key switch barrel in its mounting hole that allowed the body of the switch to rotate and provide a false indication of Chiller operating status. The corrective actions associated with LER were specific to that event and would not have prevented this LER.

SAFETY CONSEQUENCES AND IMPLICATIONS

There was no actual safety consequences associated with this event.

Although the opposite unit Control Room Emergency Air Conditioning System (CREACS) was not placed in single train filtration in accordance with TS for having two inoperable Chillers, the ability of the system to perform its safety function was not compromised. Placing the opposite units' CREACS in single train filtration means that the airflow through the affected unit is being circulated with the opposite units' fans to minimize the heat load in the affected unit. NRC FORM 366A (9-2007) U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER	3. PAGE
Salem Generating Station Unit 1	05000272	YEAR NUMBER NUMBER	
	•	2009 - 0 0 1 - 00	4 of 4

NARRATIVE

SAFETY CONSEQUENCES AND IMPLICATIONS (cont'd)

At the time of the event, appropriate non-essential heat loads had been removed from service because the original inoperability of the 12 Chiller on 11/30/09. Furthermore, the environmental condition (river water temperature was 55 degrees F) at the beginning of December was not near the 90 degrees F assumed in the accident analysis. Therefore, the significance of not having placed the CREACS in single train filtration was minimal.

A review of this event determined that a Safety System Functional Failure (SSFF) as defined in NEI 99-02, Regulatory Assessment Performance Indicator Guidelines, did not occur. There was no condition that alone, could have prevented the fulfillment of a safety function of a system needed to remove residual heat.

CORRECTIVE ACTIONS

- 1. The trip setpoint for the low temperature cutout (freeze) trip on 12 Chiller was re-adjusted to the correct setpoint of 35 +/- 1.5 degrees F.
- 2. Review of work orders and notifications written between May and December 2009 was completed and did not identify any activities that may have required work in the 12 Chiller control panel.
- 3. A cause evaluation is in progress, any additional corrective actions associated with this event will be tracked in the PSEG Corrective Action Program.

COMMITMENTS

No commitments are made in this LER.