Stephen E. Quinn Vice President

Consolidated Edison Company of New York, Inc. Indian Point Station Broadway & Bleakley Avenue Buchanan, NY 10511 Telephone (914) 734-5340

December 2, 1996

Re:

Indian Point Unit No. 2 Docket No. 50-247 LER 96-22-00

Document Control Desk US Nuclear Regulatory Commission Mail Station PI-137 Washington, DC 20555

The attached Licensee Event Report 96-22-00 is hereby submitted in accordance with the requirements of 10 CFR 50.73.

Very truly yours,

Aupha P. Qui

Attachment

cc: Mr. Hubert J. Miller Regional Administrator - Region I US Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

> Mr. Jefferey Harold, Project Manager Project Directorate I-1 Division of Reactor Projects I/II US Nuclear Regulatory Commission Mail Stop 14B-2 Washington, DC 20555

Senior Resident Inspector US Nuclear Regulatory Commission PO Box 38 Buchanan, NY 10511

9612160147 961202 PDR ADOCK 05000247 S PDR

Y1 1 e22



NRC FC	RM 366										_		U.S. M		850		V COM	Seint	-	D -										
(6-89)													J.a. NI	JULEAN	пEG	ULATOP	T COMM	1551ON	1			APPR	OVEC	OMB	NO.	. 3150 0/92	0-01 04			
7					LIC	;EN	VSE	EE I	EVI	ENT	R	EP	ORT	LER)					ES IN CC AN RE TH	TIMATEI FORMAT MMENT ID REPO GULATO IE PAPE	D BUI TION REG RTS I DRY (RWOF	RDEN COLL IARDI MANA COMM	PER ECTIONG BI AGEMI ISSIO EDUC	RESP N RE JRDE ENT B N, WA TION	PONS EQUE IN ES BRAN SRAN SRAN PRO	SE TO EST: STIM/ NCH (NGTO DJECT	O COI 50.0 ATE T (P-530 DN, DI T (315	MPLY HRS. O THE), U.S. C 2055	WTH FOR E REC NUC 55, AI	THIS WARD ORDS LEAR ND TO FFICE
FACILIT		(1)													-						OCKE		MBER	(2)		3111			PAGE	. (3)
	ndia	an i	PO:	in	E 1	Ün	it	N	o.	2										0	5	0	10	0	1 ²	4	17	1	OF	0 4
T	urb:	ine	Rı	unl	ba	ck	D	ur	in	g	Ju	mp	er F	Remo	va	.1														
EVENT DATE (5) LER NUMBER (6)			6) TableT	REPORT DATE (7) OTHE								THER F.	FACILITIES INVOLVED (8)																	
MONTH DAY YEAR			YEAR			MBER			BER	R MONTH CAT TEAR					FACILITY NAMES															
1 1	0	19	6	9	6	-	0	2	2	—	D	0	1 2	0 2	9	16							_		5		. <u>.</u> .	<u> </u>		
OPI		 }		THIS	REF	20R1	r is s	BUBM	ITTE	D PUF	SUA	NT 1	O THE R		MEN.	TS OF 10	CFR §:	(Check	one o	more of	the fo	llowi	ngj (1'	U 11	-					<u> </u>
· M	ODE (9)				20.4	102(t	,)						20.405	(c)			X	50	.73(a)(2)(iv)					73	.71(b)			
POWE LEVE					20.4	105(a 405(a	a)(1)(i 	i) 					50.36(c	()(1)			_	- 50	.73(a)(;	2)(v)				73.71(c)						
		.10			20.405(e)(1)(ii) 20.405(e)(1)(iii)						50.36(c)(2)(i)			-	50	.73(a)(; 73(a)(;	2) (vii) 2) (viii) (A)	ii} :::\/∧\				0T be/	HER	(Spec nd in	ify in Text, i	Abstr NRC	act Form		
					20.4	405 (s	a)(1)(iv)			ł		50.73(a)(2)(ii)			- H	50	.73(a)(2)(viii)(8)					300	04/				
					20.4	405 (a)(1)(v)					50.73(a)(2)(iii)				50.	.73(a)(2)(x)		_								
NAME												L	ICENSEE	CONTAC	T FC	OR THIS	LER (12)													
in Anic																					AR	EAC	ODE	TELE	РНО	NE N		ER		
Jai	mee	.т	Ma	- - 7	lat	⊦h		20	ni	٥r	កា	na	inoc	r							0	11	1.4	71	21			51	21	51 6
			LAC	<u>. y</u> .		-	, cc	MPL	ETE		INE I	FOR	EACH C	OMPONE	NT F	AILURE	DESCRIB	ED IN	THIS	REPORT	(13)	1 -	14		5	4	1_1	<u> </u>	<u> </u>	5 0
CAUSE	SYSTE	и с(Омро	NEN'	r	M		JFAC- IER		REPO TO	RTA	BLE DS				CAUSE	SYSTEM	- co	OMPON	IENT	MA	NUF	AC. R	RET	POR O NI	TABI	LE			
																						1	ł							
			1 1	<u>م</u>			I												╘╼╌╶┻╴		Å			╞						
				L			S		EME	NTAL	REPO	ORT	EXPECTI	ED (14)	-					-!			1			мог	<u>ы:</u> NTH	DAY	<u></u>	YEAR
YE!	S (If yes,	comple	nte EX	PECT	TED S	SUBA	AISSI	ON D	ATE)	1			L X	NO NO								SUBI	TE (1	D DN 5)			,	1		1
ABSTRAC	CT (Limi	to 140	0 spec	ces, i.	e., ep	prox	imet	ly fif	teen i	ingle-s	pece	type	written lin	es/ (16)						I							LL	ł.		
		()))))))))))))))))))	On runl that oista orev corr unit Fina	No bac bac t is able ven rect t wa al S pine	ver k c k, a des e o t su ro as afe e ru	mb xcci a ju sign uch t res ty unb	er urr nec out oos tor An pacl	1, 1 red, per l to cir ccu itio ed f aly k ar	990 rec wa in cui rre n v to 1 sis nd	6, w duc as b itiat t w nce vas 1009 Rej with	ith ing ein æ a s ir ver % p por hou	th 3 point ina ina ina th ina th ina ina ina ina ina ina ina ina ina ina	e unit ower remov rbine dvert dvert ed, th ver. T. nalyz rurbin	t oper approved fro runb ently ure. Fo e cau his ev es the e run	ati om acl int ollo se ven e di bao	ing at matel a ro k. Du terruj owin of the it had roppe ck. Bo	100% y 20 M d bott ring th oted g term e runb no ac ed cor oth an	o por MWa com he ju Acti nina back dver ntrol alys	wer, e. A bist unp ons tion was rse in rse in roc ses a	, an a t the able c er rer are b of th s dete mpac l occu re acc	uto: tim outp nov ein; e ru rrm t to rre cep	mate of out val, g ta inece saf nce tab.	tic t f the circ the ker ack d an iety e wi le.	urb e cuit n to nd t . Th th	the	e				

NRC.FORM 366A	U.S. NUCLEAR REGULATORY COMMISSION	APPROVED OMB NO. 315 EXPIRES: 4/30/92	50-0104
LICENSEE EVENT F TEXT CONTINU	REPORT (LER) JATION	ESTIMATED BURDEN PER RESPONSE INFORMATION COLLECTION REQUEST COMMENTS REGARDING BURDEN ESTIN AND REPORTS MANAGEMENT BRANCH REGULATORY COMMISSION, WASHINGT THE PAPERWORK REDUCTION PROJEC OF MANAGEMENT AND BUDGET, WASHI	TO COMPLY WTH THIS : 50.0 HRS. FORWARD AATE TO THE RECORDS (P-530), U.S. NUCLEAR :ON. DC 20555, AND TO TO (3150-0104), OFFICE NGTON, DC 20503.
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
Indian Point Unit No. 2	0 5 0 0 2 4 7	YEAR SEQUENTIAL NUMBER REVISION NUMBER 916 0 2 2 0 0	02 OF 0 4
TEXT (If more space is required, use additional NRC Form 366A's) (17)		· · · · · · · · · · · · · · · · · · ·	

PLANT AND SYSTEM IDENTIFICATION:

Westinghouse 4-Loop Pressurized Water Reactor

IDENTIFICATION OF OCCURRENCE:

Turbine Runback During Jumper Removal

EVENT DATE:

November 1, 1996

REPORT DUE DATE:

December 2, 1996

REFERENCES:

Condition Identification and Tracking System (CITRS) No. 96-E02451

PAST SIMILAR OCCURRENCE:

LER 96-009

DESCRIPTION OF OCCURRENCE:

On November 1, 1996 at 1458 hours, with the unit operating at 100% power, an automatic turbine runback occurred. Power was automatically reduced approximately 20 MWe with the runback. The "ROD BOTTOM ROD STOP" alarm was actuated. No automatic rod insertion occurred, and there was no observable change in indicated rod position for any control rod. Correct rod position was verified following termination of the runback, and the unit was restored to 100% power in accordance with operating procedures.

NRC,FORM 366A (6.89)	U.S. NUCLEAR REGULATORY COMMISSION	APPROVED OMB NO. 3150-0104
LICENSEE EVEN TEXT CONT	T REPORT (LER) NUATION	EXTINCT 4150/32 EXTINCT 4150/32 EXTINCT 4150/32 EXTINCT 4150 EXTINCT
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6) PAGE (3)
Indian Point Unit No. 2	0 5 0 0 0 2 4 7	YEAR SEGUENTIAL REVISION 9 6 - 0 2 2 - 0 0 0 3 0F 0 4
TEXT (If more space is required, use additional NRC Form 366A's) (1)	┷╌╍┶╾╌┶╴╴┶╶╴┶╴╴┶╴╴┶╌╸┙╴╸┻╴╶╸┷╸

ANALYSIS OF OCCURRENCE:

This report is being made because the turbine runback actuation constitutes a Reactor Protection System (RPS) actuation. This actuation is reportable under 10 CFR 50.73(a)(2)(iv).

Turbine runback can be initiated by any one of the 53 (one per control rod) rod bottom bistables or by any one of the four power range channels of the Nuclear Instrumentation System. The runback function was originally designed to compensate for reactor power and core distribution changes due to a dropped control rod. The automatic runback is designed to terminate at turbine power of no less than 85%. The dropped control rod occurrence is analyzed both with turbine runback and without turbine runback in the Final Safety Analysis Report for Indian Point 2. There were no dropped rods and no observable change in rod position for any control rod. Therefore, this occurrence did not have any impact on safety. There were no injuries to personnel or damage to equipment as a result of this event.

CAUSE OF OCCURRENCE:

The automatic turbine runback was caused by inadequate planning for removal of a jumper associated with the rod bottom bistable for Control Rod L-3. This resulted in a momentary interruption in the rod bottom bistable output circuit when the jumper was being removed from the rod bottom bistable output terminal points. A normally open contact from each rod bottom bistable output in a bank of control rods is connected in series with the coil of a control relay. If a control rod goes below the bistable setpoint, the output contact will open, and the control relay will de-energize. Normally closed contacts from each control relay are connected in parallel. This parallel combination is connected in series with a "Turbine Runback Defeat" switch in the turbine runback circuit. If any control relay de-energizes, the associated contact in the runback circuit will close. This will initiate a turbine runback if turbine power is above 85% power and the "Turbine Runback Defeat" switch is not engaged.

During removal of the jumper for Control Rod L-3, a technician inadvertently interrupted the rod bottom bistable circuit. The "Turbine Runback Defeat" switch was not engaged at that time (if this switch had been engaged, the runback would not have occurred). The automatic turbine runback circuit was actuated reducing power by 20 MWe. Following this momentary circuit interruption, the control relay was re-energized resulting in termination of the runback. The "Turbine Runback Defeat" switch was not engaged during the

нс Г ОRM 366A -89)		U.S. NUCLEAR REGULATORY COMMISSI	APPROVED OMB NO. 3150-0104
	LICENSEE EVENT RE	PORT (LER)	EXPIRES: 4/30/92 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS DECRMATION COLLECTION RECUEST, EAG. HER. SORWARD
	TEXT CONTINUA	TION	COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P.530), U.S. NUCLEAR
. . .			REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE
CILITY NAME (1)	DOCKET NUMBER (2)	OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.
			LER NUMBER (6) PAGE (3)
Indian	Point Unit No. 2	0 5 0 0 2 4 1	7 9 6 -0 2 2 -0 0 0 4 OF 0
XT (If more space)	is required, use additional NRC Form 366A's) (17)		
	in more an even and he are set the		1
	drawings) did not address the	Jumper Jumper Log Entry Fo	orm and associated
	appropriate procedures indi	cated that additional control of	switch. A review of
	removal phases of jumpers is	s required to preclude recurre	on the instantion and
		require to preclade recuire	
	CORRECTIVE ACTION:		
,			
	Correct rod position was ver	ified following termination of	f the runback, and the
	unit was restored to 100% pc	ower in accordance with opera-	ating procedures.
	Potential impacts to the plan	t that can occur during the inc	stallation and
	removal phases of a jumper	as well as how these impacts	can be precluded
	must be considered during it	imper evaluation (Jumper Lo	g Entry Form and
	associated drawings). These	considerations must be deline	eated and reinforced
	with personnel who prepare,	, install and remove the jump	ers. Station
	Administrative Order (SAO)	206 will be evaluated and rev	vised to provide
	additional controls. This ever	nt and any significant changes	s to SAO 206 shall be
	provided in continuing traini	ing programs as appropriate.	
	Following ravision of $SAO 2$) = ==================================	
	assure that there are no note	otial impacts to the plant who	s will be reviewed to
	removed. Also, reuse of prev	iously installed jumpers will l	he reviewed and
	documented in accordance w	with the newly revised SAO 20)6.
		, , , , , , , , , , , , , , , , , , ,	
	· · · · · · · · · · · · · · · · · · ·		
•			