

1

Consolidated Edison Company of New York, Inc. Indian Point Station Broadway & Bleakley Avenue Buchanan, NY 10511 Telephone (914) 734-5340 Fax: (914) 734-5718 blinda@coned.com

April 16, 1999

Re: Indian Point Unit No. 2 Docket No. 50-247 LER 99-05-00

Document Control Desk US Nuclear Regulatory Commission Mail Station PI-137 Washington, DC 20555

The attached Licensee Event Report 99-05 is hereby submitted in accordance with the requirements of 10 CFR 50.73.

Very truly yours,

A- alen Blin

Je72

Attachment

cc: N

Mr. Hubert J. Miller Regional Administrator - Region I US Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

> Mr. Jefferey Harold, Project Manager Project Directorate I-1 Division of Reactor Projects I/II US Nuclear Regulatory Commission Mail Stop 14B-2 Washington, DC 20555

Senior Resident Inspector US Nuclear Regulatory Commission PO Box 38 Buchanan, NY 10511

9904290026 990416 PDR ADDCK 05000247 PDR PDR

NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION (6-1998)					APPROVED BY OMB NO. 3150-0104 EXPIRES 06/30/2001 Estimated burden per response to comply with this mandatory information										
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block) (See reverse for required number of digits/characters for each block)									corporated into the mments regarding F33), U.S. Nuclear 1 to the Paperwork ent and Budget, oes not display a uct or sponsor, and ection.						
FACILITY NAME (1)							DOCKET NUMBER (2)					PAGE (3)			
Indian Point Unit No. 2									50-247 1 O 4						O 4 F 4
TITLE (4)															
Failure to Declare Automatic Containment Isolation Valve Inoperable															
EVENT DATE (5) LER NUMBER (6) REPORT DATE (7)						OTHER FACILITIES INVOLVED (8)									
MONTH	DAY	YEAR	YEAR	SEQUENTIA REVIS		MONTH	DAY YEAR						DOCKET NUMBER		
3	17	99	99 -	- <u>0</u> 00)	4	16	99		FACILITY NAME				DOCKET NUMBER	
OPERATI	ING	N	THIS	REPORT IS SUB	μTT	ED PURS		O THE I	REQ	VIR	MENTS	6 OF 10 CFR §:	(Check	one or mo	re) (11)
MODE ((9)		20.2201(b)			20.2203(a)(2)(v)				\mathbf{v}	50.73(a	.)(2)(i)	50.73(a)(2)(v		(a)(2)(viii)
LEVEL (1	п 10)	99	20.2203(a)(1) 20.2203(a)(2)(i)		20.2203(a)(3)(i) 20.2203(a)(3)(ii)				50.73(a	.)(2)(iii)		50.73(a)(2)(x)			
			20.2203(a)(2)(ii)		20.2203(a)(4)				50.73(a)(2)(iv)		OTHER			
			20.2203(a)(2)(iii)		50.36(c)(1)				50.73(a)(2)(v)		Specify in Abstract below or			
			20.2203(a)(2)(IV)		50.36(c)(2)				50.73(a)(2)(vii)		III NHC FU	1111 300A
LICENSEE CONTACT FOR THIS I							TELEPHONE NUMBER (Include Area Code)								
Philip Griffith, Sr. Licensing Engineer						(914)734-5190									
		······································	COMPLET	ONE LINE FOR E	ACH	H COMPO	NENT F	AILURE	DE	ŞCR	IBED IN	THIS REPORT	[(13)		
CAUSE SYSTEM		SYSTEM	COMPONENT	MANUFACTURER	RI	EPORTABL TO EPIX	ORTABLE CAUS		SE	SYSTEM COMPONENT		MANUFACTURER		REPORTABLE TO EPIX	
													-		
SI			UPPLEMENTAL REPORT EXPECTED (14)								MONTH	DAY	YEAR		
YES (If yes, complete EXP			ECTED SUBM	ISSION DATE).			X NO				SUBMISSION DATE (15)				
ABSTRAC	CT (L	imit to 1400	spaces, i.e., a	oproximately 15 sin	gle-s	spaced typ	ewritter	i lines) ((16)						·
On March 17, 1999, with the unit operating at 99% power, the switches for Solenoid Operated Valves (SOV) EW-1 and EW-2, "WCP Air Supply To Cont. Isolation Valves," in the Weld Channel (WCCPPS) for the Post Accident Containment Ventilation System were found in the closed position contrary to the requirements of Check Off List 10.9.1, Post Accident Hydrogen Removal System. Valves EW-1 and EW-2 are maintained open to pressurize Weld Channel Zone 4 to 47 PSI. At 1150 A.M., upon discovery of the mispositioning of EW-1 and EW-2 switches, the seven day action statement was entered per Technical Specification 3.3.D.1.a for a portion of Zone 4 WCCPPS being inoperable. On March 17, 1999, at 1235 P.M. the switches for EW-1 and EW-2 were placed in the open position and Technical Specification 3.3.D.1.a action statement was exited. The design basis of the system is to prevent containment out-leakage, during a design basis Loss of Coolant Accident, by maintaining a higher external pressure on the liner welds and penetrations than containment pressure. This system is not required to meet the 10 CFR 100 offsite dose limits. Public health and safety were not affected by this event.															

NRC FORM 366A	· · · ·	U.S.	NUCLEAR	REGULATOR	Y COMMI	SSION
	ENT REPORT (I	LER)				
TEXT CC	ONTINUATION					
FACILITY NAME (1)	DOCKET (2)	<u> </u>	ER NUMBEI	3 (6)	PAG	E (3)
Indian Point Unit No. 2	05000-247	YEAR	SEQUENTIA L NUMBER NUMBEI		2 05	4
	03000-247	99	0 5	00		4
TEXT (If more space is required, use additional copies of NRC Form 366A) (17)	<u></u>		····		
PLANT AND SYSTEM IDENTIFICATION:						
Westinghouse 4-Loop Pressurized Water Reactor						
IDENTIFICATION OF OCCURRENCE:	· .			• • •	·	
Weld Channel Solenoid Valve Switches mispositioned			·			
EVENT DATE:						
March 17, 1999						
REPORT DUE DATE:						
April 16, 1999						
REFERENCES:						
Indian Point 2 Condition Reporting System (CRS)No. 19990	2207	·				
PAST SIMILAR OCCURRENCES:						
LER 82-008/03L Three Lines in Zone 2 Weld Channel Isolat 199801925 Residual Heat Removal Pump Heat Exchanger	ed, CRS No. 1997 Stops, SAO-132 R	00963 22 eport 98-0	Hydrogen 7, Tagout	Recombine issues	er, CRS	S No.
DESCRIPTION OF OCCURRENCE:						
On March 17, 1999, with the unit operating at 99% power, an solenoid operated valves (SOV) EW-1 and EW-2, "WCP Air out of position. This condition was noted while performing a	n operator in license Supply To Cont. Is Job Performance I	e training r olation Val Measure (J	eported th ves," in th IPM) as re	at the switc e Weld Cha quired for c	hes for annel we operator	re

license training. These valves supply Weld Channel (WCCPPS) air to the Post Accident Containment Ventilation System (PACVS) and are required to be open. As of 1150 A.M., a seven day action statement per Technical Specification (TS) 3.3.D.1.a was entered for an inoperable section of zone 4 of the WCCPPS. At 1235 P.M., the switches for SOVs EW-1 and EW-2 were placed in the open position, the valve positions verified open and TS 3.3.D.1.a action statement exited.

On March 17, 1999 at 1250 P.M., as a result of not meeting the design basis for the weld channel, a one-hour nonemergency notification per 10 CFR 50.72(b)(1)(ii)(B) and the requirements of station procedure SAO-124 item 7, Station Administrative Order "Oral Reporting of Non-Emergency Events and Items of Interest and Significant Occurrence Reporting" was made.

NRC FORM 366A (6-1998)			U.S. NUCLEAR REGULATORY	Y COMMISSION					
(5,1555)	LICENSEE EVEN	T REPORT (I	LER)						
TEXT CONTINUATION									
FACILI	Y NAME (1)	DOCKET (2)	LER NUMBER (6)	PAGE (3)					
• · · ·	•		YEAR SEQUENTIA REVISION						
Indian Point Unit No. 2		05000-247		3 OF 4					
			99 5 00						
TEXT (If more space is required, use	ə additional copies of NRC Form 366A)(17)							
ANALYSIS OF OCCURREN	CE:	•							
The sequence of events asso	ociated with this event are as follo	ws:	•						
January 1998	- EW-1 and EW-2 last worked	don							
January 6, 1999 - performance test PT-Q13, Inservice Valve Test for both EW-1 and EW-2 was performe									
March 17, 1999 1150 A M	and subsequently an Indeper	dent Verification	of valve position was performed	di : Torrocco of					
Watch 17, 1999 1100 A.W.	JPM. reported to watch super	vision, entered 7	day action statement per TS 3	3 D 2 a					
March 17, 1999 1235 P.M.	- switches for SOV EW-1 and	EW-2 were repo	ositioned to the open position, th	ne Weld					
	Channel was reestablished as	s operable and th	ne TS 3.3.D.1.a action statemen	it was exited					
March 17, 1999 1250 P.M.	- determination made that this event placed the plant outside the design basis for the								
	Penetration and Weld Channel	Satety Analysis F	Report, section 6.6.1, Containme	ent					
	notification was made per the requirements of 10 CER 50 72(b)(1)(ii)(R) and the								
	requirements of station procedure SAO-124 item 7, Station Administrative Order "Oral								
	Reporting of Non-Emergency	Events and Item	is of Interest and Significant Oco	currence					
March 47, 4000 and	Reporting"			-					
March 17, 1999 and March 18, 1999	all appagaible WCCPRS vol								
March 10, 1999	- all accessible wCCPPS val	es checked to v	erity proper alignment						
The design basis for positive pressure zon requirements of the d determination of cont and provides assurar no credit taken for sy not affected as a resu	the Weld Channel states that the les incorporated into the containn lesign basis could not be met. Th ainment leaktightness during pow nee that the containment leak rate stem operation in the calculation ult of this valve mispositioning.	system provides nent penetrations ne WCCPPS is d ver operation, it is is lower than as of the offsite acc	a means for continuously press s, with SOVs EW-1 and EW-2 cl lesigned to provide a means for s designed as an Engineered Sa sumed in the accident analysis, ident dose. The public health an	surizing the osed the the afety Feature but there is nd safety was					
ROOT CAUSE SUMMARY:									
During the review of t switches could not be switches between Jar	his event the specific time and ca determined. A review of all know nuary 1988 and March 17, 1999 v	use of the mispo wn operations as was performed:	ositioning of the SOV EW-1 and sociated with the SOV EW-1 an	EW-2 Id EW-2					
Although a specific ro the procedural guidar Standards and Expec Adherence and Use, be made as each ster	oot cause could not be determined ince associated with the plant conf tations for Operations Personnel states sign-offs will be signed off p is completed, not at the comple	d, an apparent ca iguration control , Revision 1, Dec prior to proceedi tion of the test or	ause of this event appears to be system. The operations depart cember 29, 1998, section 3.13, F ng to the next step These sign procedure.	weakness ir ment ² rocedure 1-offs are to					

During discussions with the Nuclear Plant Operators (NPO) that performed the January 6, 1999 PT-Q13 valve restoration they indicated that the independent verification was signed off after all valves had been aligned to prevent making numerous trips to the valve room. The NPO that performed the independent verification step did not accompany the NPO who performed the initial verification. However, the NPO who performed the initial verification was in the same room at the time the independent verification was performed. This potential loss of independence does represent a potential weakness in the independent verification process.

		. ·							
NRC F	DRM 366A	U.S. NUCLEAR REGULATORY COMMISSION							
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION									
	FACILITY NAME (1)		R NUMBER (PAGE (3)					
Indian	Point Unit No. 2	05000-247	YEAR	SEQUENTIA L NUMBER	REVISION NUMBER				
			99	0	00				
TEXT	(If more space is required, use additional copies of NRC	C Form 366A) (17	")						
ROOT	CAUSE SUMMARY(cont):	•			·				
The lack of some human factor considerations may have contributed to this mispositioning event. The indication lights for EW-1 and EW-2 do not work. The station event analysis report stated that the lights were a possible contributor and "lights that operated correctly would better cue the operator of incorrect valve position." The test procedure PT-Q13, Inservice Valve Test has the sign-offs for the independent verifier located on the same sheet as the initial verifier, it does not follow the same philosophy as the Operations Administrative Direction (OAD procedure for independent verification. The station event analysis report stated that; consistent application of the guidance indicated in the OAD for independent verification "would help clarify verification expectations."									
Previous corrective actions, for maintaining configuration control, have not been fully effective, and may have contributed to the Weld Channel EW-1 and EW-2 valve mispositioning. From a 1998 root cause analysis report SAO-132 98-07, Tagout Issues seven corrective actions associated with mispositioning events associated with tagouts were completed, however, the Switches for SOVs EW-1 and EW-2 were subsequently mispositioned.									
CORR	ECTIVE ACTIONS:								
1.	A vertical sampling of WCCPPS valve positions was conducted resulting in the verification of the correct alignment of all accessible valves.								
2.	A horizontal sampling of the valves addressed in PT-Q13, Inservice Valve Test, stroked on January 6, 1999 were verified to be properly aligned.								
3.	All valves and breakers in the same room with SOV EW-1 and EW-2 were verified properly aligned.								
4.	Security review was performed to verify that tampering was not an issue in this mispositioning event.								
5.	An evaluation to determine if repair or modification of the position indicating light circuits for EW-1 and EW-2 is scheduled for completion by July 30, 1999.								
6.	Operations procedures are scheduled to be revised to ensure consistency with the "Standards and Expectations for Operations Personnel" by August 31, 1999.								
7.	The philosophy for independent verification directed in the Operations OAD for independent verification is scheduled to be incorporated into performance test PT-Q13, Inservice Valve Test, by June 30, 1999.								
B.	The operations management is scheduled to re-empha verifications with all watch sections by July 30, 1999.	size the standard	is and exp	ectations fo	r indepen	ident			
9.	Operations training is scheduled to retrain all watch see August 31, 1999.	ctions on the upda	ated indep	endent verif	ication te	chniques by			
	· · ·								

•