

Consolidated Edison Company of New York, Inc. Indian Point Station Broadway & Bleakley Avenue Buchanan, NY 10511 Telephone (914) 734-5340 Fax: (914) 734-5718 blinda@coned.com

May 28, 1999

Re:

Indian Point Unit No. 2

Docket No. 50-247 LER 99-008-00

Document Control Desk
US Nuclear Regulatory Commission
Mail Station PI-137
Washington, DC 20555-0001

The attached Licensee Event Report 99-008-00 is hereby submitted in accordance with the requirements of 10 CFR 50.73.

Very truly yours,

A alan Bline

Attachment

C: Mr. Hubert J. Miller
Regional Administrator - Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Jefferey Harold, Project Manager Project Directorate I-1 Division of Reactor Projects I/II US Nuclear Regulatory Commission Mail Stop 14B-2 Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511

JE32/1

NRC FORM 366 (6-1998)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB NO. 3150-0104

Estimated burden per response to comply with this mandatory information collection request: 50 hrs. Reported lessons learned are incorporated into the licensing process and fed back to industry. Forward comments regarding burden estimate to the Records Management Branch (T-6 F33), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, and to the Paperwork Reduction Project (3150-0104), Office of Management and Budget, Washington, DC 20503. If an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection

LICENSEE	EVENT	REPORT	(LER
----------	-------	--------	------

(See reverse for required number of digits/characters for each block)

DOCKET NUMBER (2)

PAGE (3)

4

Indian Point No. 2

05000-247

OF

TITLE (4)

FACILITY NAME (1)

Deficiency in Respirator Qualification

EVE	NT DA	TE (5)	LE	R NUMBER (6)	REPORT DATE (7) OTHER I			П	OTHER FACILITIE	S INVOLVED (8)				
MONTH	DAY	YEAR -	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME		FACILITY NAME		DOCKET NUMBER 05000		
4	28	1999	1999	008	00	5	28	1999	FACILITY NAME		FACILITY NAME		FACILITY NAME		DOCKET NUMBER 05000
OPERATING THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)															
MODE		N ·	20.22	01 (b)		20.2203	3(a)(2)(v	<i>(</i>)		50.73(a)(2)(I)	50.73(a)(2)(viii)				
POW	ER	000	20.22	20.2203(a)(1)		20.2203(a)(3)(l)		20.2203(a)(3)(l)		X	50.73(a)(2)(ii)	50.73(a)(2)(x)			
LEVEL	(10)	099	20.22	20.2203(a)(2)(l)		20.2203(a)(3)(ii)		20.2203(a)(3)(ii)		50.73(a)(2)(iii)	73.71				
			20.22	.2203(a)(2)(ii)		20.2203(a)(4)		20.2203(a)(4)		50.73(a)(2)(iv)	OTHER				
		20.220	03(a)(2)(iii)		50.36(c	50.36(c)(1)		50.73(a)(2)(v) Sr		Specify in Abstract below					
		20.2203(a)(2)(iv)		50.36(c)(2)		50.73(a)(2)(vii)		or in NRC Form 366A							

LICENSEE CONTACT FOR THIS LER (12)

NAME

TELEPHONE NUMBER (Include Area Code)

Robert T. Allen, Manager, Regulatory Affairs

914-734-5129

		COMPLETE	ONE LINE FOR E	ACH COMPONE	NT F	AILURE DES	CRIBED IN	THIS REPORT	(13)		
CAUSE	SYSTEM .	COMPONENT	MANUFACTURER REPORTABLE TO EPIX			CAUSE	SYSTEM	COMPONENT	MANUFA	CTURER	REPORTABLE TO EPIX
								<u>-</u>			
	SUPPLEMENTAL REPORT EXPECTED (14)						EXPECTED		MONTH	DAY	YEAR
YES (If yes,	complete EX	PECTED SUBM	ISSION DATE).	J X	NO		SUB	MISSION TE (15)			

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

While conducting Self Contained Breathing Apparatus (SCBA) training with nuclear plant operators (NPO), it was brought to the trainer's attention that some individuals may not be presently qualified to wear respirators. The trainer then asked the Respiratory Protection Section to provide a list of individuals in Operations and their current respirator qualification status. The list was provided on the morning of April 28, 1999.

The list indicated that eighteen (18) Central Control Room (CCR) operators lacked respirator qualifications (16 due to respirator fits, 2 due to respirator medicals). Under certain emergency conditions CCR operators might be required to wear respirators.

This report is being made per 10CFR50.73(a)(2)(ii)(C), because the expired operator respirator qualifications is a condition not covered by the plant's operating and emergency procedures.

The health and safety of the public was not affected by this event.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2)	LE	PAGE (3)			
Indian Daint No. 0	05000-247	YEAR	SEQUENTIAL Number	REVISION NUMBER		-
Indian Point No. 2		1999	008	00	2 0	- 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

PLANT AND SYSTEM IDENTIFICATION:

Westinghouse 4-Loop Pressurized Water Reactor

IDENTIFICATION OF OCCURRENCE:

Deficiency in Respirator Qualification

EVENT DATE:

April 28, 1999

REFERENCES:

Condition Reporting System (CRS) Nos: 199903428, 199903431, and 199903460.

PAST SIMILAR OCCURRENCES:

None

DESCRIPTION OF OCCURRENCE:

While conducting Self Contained Breathing Apparatus (SCBA) training with Nuclear Plant Operators (NPO), it was brought to the trainer's attention that some individuals may not be presently qualified to wear respirators. The trainer then asked the Respiratory Protection Section to provide a list of the current respirator qualification status of Operations Section personnel. The list was provided on the morning of April 28, 1999.

The list indicated that eighteen (18) Central Control Room (CCR) operators lacked respirator qualifications (16 due to respirator fits, 2 due to respirator medicals). Under certain emergency conditions CCR operators might be required to wear respirators.

The trainer notified Operations management and began scheduling individuals that were in training for physical exams and respirator fits. At the time of the discovery of this condition all CCR operators on shift were respirator qualified. All CCR operators whose respirator qualification had lapsed were re-qualified prior to their assuming the watch. Since all operators with expired respirator qualifications were successfully re-qualified, the health and safety of the public was not affected by this event.

LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2)	LE	PAGE (3)			
Indian Daint No. 0	05000 047	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		NF 4
Indian Point No. 2	05000-247	1999	008	00	3 0)F 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

ANALYSIS OF OCCURRENCE:

Operators must be able to safety operate the plant and perform their CCR duties while wearing SCBAs in the event that a toxic gas release infiltrates the CCR. Operators who have current qualifications to wear SCBAs provide assurance that they are still capable of using SCBAs. Operators whose respirator qualifications have lapsed, may become incapacitated or impaired in their functioning upon donning the SCBAs for a postulated toxic gas event. This event places the plant in a condition that is not covered by the plant's operating and emergency procedures and therefore is reportable under 10 CFR 50.73(a)(2)(ii)(C).

CAUSE OF OCCURRENCE:

The cause of this occurrence is attributed to the lack of a formal process for tracking the status of individual respirator qualifications, with the exception of those individuals required to wear respirators per radiation work permits (RWP). Such a program would provide assurance that respirator qualifications remained current for personnel who are CCR operators.

(6-1998)

LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2)	LE	R NUMBER (PAGE (3)		
Indian Point No. 2	05000-247	YEAR	SEQUENTIAL Number	REVISION NUMBER	4 05	
indian Foint No. 2		1999	008	00	4 OF	4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

CORRECTIVE ACTION:

The immediate corrective action taken was to verify that the current on-shift personnel were respirator qualified. A subsequent corrective action was to provide the required re-qualification to all affected CCR personnel. All CCR operators whose respirator qualification had lapsed were re-qualified prior to assuming the watch.

In order to prevent the re-occurrence of this type of event, a program to track the respirator qualification of Operations section personnel will be implemented by August 1, 1999.