19-83)	n 366	1										. U.S. I	APP	AR REGUL	ATORY	2160-01	ISEION
	•					LIC	ENSE	E EVE	NT RE	PORT	(LER)		EXP	IRES: 8/31	/86	a 100-01	
	•										••		• . •				
FACILITY	NAME (1	)	•									DOCKET NUMBE	R (2)			PAG	E (3)
· Ti	ndian	Poir	1 <b>+</b>	Unit		· · · ·		1			• • •	0 15 10 10	0   0	12 1.8	16 🗖	OF	015
TITLE (4)	Man	1.011										<u> </u>		1-1	<u>- 1</u>		
So	ource	Rang	ge R	eact	or Trip	Due To	Pers	onnel	L Erro	r							
EVE	NT DATE	(5)		<u> </u>	ER NUMBER (	6)	RE	PORT DAT	re (7)	· .	OTHER	R FACILITIES INV	OLVE	D (8)			
MONTH	DAY	YEAR	YEA	R Side	NUMBER	NUMBE R	MONTH	DAY	YEAR.		FACILITY	AMES		CKET NUN	BER(S)		
					·						<u></u>	······································		15 0		<b>)</b>	
		مام		_   -								•					
<u>u</u> 2	0 4	89	8	<u>9</u>			1013 1015 B		18   9   ENTE OF 1	0.CER & (	Check and as mar	a of the following!	<u>. 1 v</u>	0		<u> </u>	<b>_</b>
OPE MC	RATING DE (9)			20 402/1		PORIDARI	20 405		ENTS OF T		50 73(a)(2)(iv)	or the ronowing,	<u> </u>	73 71 16	1		
POWE	R			20.405(	•}{1}(i)		50.36(c	)(1)		Ê	50.73(a)(2)(v)			73.71(c	)		
LEVE (10)		010	$\square$	20,405(a	1)(1)(ii)		50.38(c	)(2)	•	.	50.73(a)(2)(vii)			OTHER	(Specify	in Abs	tract
				20.405(s	•)(1)(iii)	· · [	50.73(a	)(2)(i)			50.73(a)(2)(viii)	)(A)		- Delow a 366A)	nd in Te	xt, NHC	· Form
				20.405(a	s)(1)(iv)	. ·	50.73(s	)(2)(ii)	•••	·	50.73(a)(2)(viii)	)(B)				÷	· .
				20.405(	i)(1)(v)		50.73(a	)(2)(iii)			50.73(a)(2)(x)	<u> </u>					
NAME			· · · ·			L	ICENSEE	CONTACT	FOR THIS	LER (12)	·	<u> </u>	TEI			,	
Vir	agont	р с	·~··1	chon					,			AREA COD	ÈŢ				
· • • • •	icent	к. с	our	enan								011 1/	. 7	1316	1 10	101	/ <b>F</b>
	· · · · · ·				COMPLETE	ONE LINE FOR	EACH CO	OMPONEN	TFAILURE	DESCRIB	ED IN THIS REPO	<u> </u>	17	12 1 0	<u> </u>		4 I/
						REPORTABLE						MANUFAC	6	EPORTAB	LE		
CAUSE	SYSTEM	COMP	ONENT	ŀ	TURER	TO NPRDS			CAUSE	SYSTEM	COMPONENT	TURER		TO NPRD	s		
Х	ЪG		E	T W	1120	N ·				<u></u>							
			ΗI	<u> </u>		1			<u></u>						<u>р</u> мты I		VEAR
					SUPPLEME	NIAL REPORT	EXPECT	ED (14)				EXPEC	TED				
YE	5 (If yes, c	omplete E	XPECT	ED SUB	MISSION DATE	7	<u> </u>	X NO				DATE	(15)		, I.	1	1
ABSTRAC	CT (Limit 1	to 1400 sp	aces, i.e	., eppro:	ximetely fifteen	single-space type	ewritten lir	nes) (16)						•	4		
											•	•				•	
						·						e de la composición d					
			· .		•					÷							
								•									
															•		
		'	_			- · ·		•				·					
	. 0	n Fe	bru	lary	4, 19	89 wit	th th	ie Ur	nit 3	read	ctor sul	bcritica	al	at l	ess		i
	د. 1	nan niti	iate	lu a ad h	umps In Wan T	L une 1 L C tác	hnter	rmear	Late	range	e, a rea	actor t	rip	was			
	r	ange	.ucc	All	plant	svste	ms f	Funct	-ione	d pro	nerly	number	32	sou	rce		
		<b>J</b> -			·						Sperry.						
	Į.	t wa	s d	lete	rmined	that	an I	E&C t	echn	ician	n remove	ed inst	rum	ent			
	f	uses	fc	pr t	he sou	rce ra	inge	rest	iltin	g in	a loss	of volt	tag	e to	the	e	
ł	h	igh	flu	ix t	rip bi	stable	е. Т	he s	sourc	e ran	nge has	been re	∋pā	ired	and	ž.	
	p	lace	d b	back	in se	rvice.											
					4								•		. •		l
		•									•				·		
							•								<u> </u>	_	
1														Ĵ	F	$\sum$	2
																,	
					· · · · ·				1. State 1.						1	1	

. . . 4. . .

NRC Form 366 (9-83) 8903150504 890306 PDR ADOCK 05000286 S PDC

.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104

		EXPIRES: 8/31/	'88
ILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
		YEAR SEQUENTIAL REVISION NUMBER NUMBER	· .
Indian Point, Unit 3			

0 |5 |0 |0 |2 |8 |6 |8 |9 - 0 |0 |4 - 0 |0 |0 |2 |0F 0 |5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

NRC Form 366A

FACILITY NAME (1)

#### DESCRIPTION OF THE EVENT

On February 4, 1989 at 0040 hours a plant shutdown was in progress. As power was reduced to below E-10 amps in the intermediate range, the logic that reenergizes the two nuclear instrumentation source range channels was made up. 31 source range energized normally, but 32 source range failed to energize. An Instrument and Controls (I&C) technician performing troubleshooting on the Westinghouse (W120) Source Range Nuclear Instrumentation N-32 Detector (IG) (DET) (Model 6051D50G01) removed the fuses from number 32 source range detector, which deenergized the high flux bistable, resulting in a reactor trip. Control room operators immediately commenced Emergency Operating Procedures (EOP) E-0, "Reactor Trip or Safety Injection" and ES-0.1, "Reactor Trip Response". The plant was stabilized with all rods on bottom. Number 32 source range detector was subsequently reenergized and functioned normally.

### INVESTIGATION OF THE EVENT

To address this event a meeting was held on February 9, 1989 with all personnel involved. The focus of this meeting was to include the responsible individuals in the process of determining the root causes of this event and also in providing an input in developing corrective actions. The following is a summary of factors leading to the trip as identified by this group.

- The I&C technician was not aware that the reactor trip 1. breakers were not open.
- The I&C technician interpreted the announcement on the 2. paging system (unit 3 off-line) to mean the reactor was shut down (in his words, "in a safe condition").
- The I&C technician did not have a clear understanding 3. of the difference between the plant being shut down and the trip breakers being open. This particular technician also did not know that it was unacceptable to activate the reactor protection system while the plant was shut down.

					-
LICENCEE	EVENIT	DEDADT	HED) TE	YT CONTINUES	TION
LICENSEE	CVCINI	neruni	(LEN) 16	CONTINUA	

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104 EXPIRES: 8/31/88

ACILITY. N	JAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	PAGE (3)
-4			YEAR	SEQUENTIAL REVISION NUMBER NUMBER	
India	Indian Point, Unit 3	· · · · · ·			
		0 5 0 0 0	2 8 6 8 9	-00 4 -0 0	03 05 0 15

4. When the I&C technician came into the control room he interpreted the environment (the general high level of activity) to mean that there was an urgency associated with restoring the SR channel to service.

5. The RO and the SRO both assumed the I&C technician would only "look" to determine the cause of the problem and would not take any action. They did not specifically tell the I&C technician not to touch anything and neither did they tell him to do other than investigate the problem.

It has been determined by this discussion as well as by an independent investigation that the Source Range Trip was initiated by a loss of voltage to the Source Range High Flux Trip Bistable resulting from the removal of instrument fuses for the source range drawer. The event occurred because:

- 1. The I&C technician acted on his own without consulting the control room operators.
- 2. The senior reactor operator had acknowledged the presence of the I&C technician but assumed, based on standard practices, that the technician would discuss corrective measures before implementing them.

### CAUSE OF THE EVENT

The following is a summary of the causal factors leading to the trip signal, as well as the root cause of this event.

Prior to being called to the control room, the I&C technician heard the page "Unit 3 is off line". This was interpreted by the technician that the reactor was shut down. Upon entering the control room, the technician thought all the control rods were fully inserted. He did not see that shutdown bank A was still partially withdrawn. The technician thought it was safe to work on the source range monitor including deenergizing the same. The Senior Reactor Operator had acknowledged the presence of the technician but assumed, based on standard practices, that the technician would discuss corrective measures before implementing them.

NRC Form 3664

LIACHIACE			1	AND DO NOT THE OWNER.	~ ~ * · = · * · · * = · ~ * ·
	LVENT	DEDMDI			C'ANTINILI A TIMRI
	EVENI	neruni	VEEN/		GUNTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OM8 NO. 3150-0104 EXPIRES: 8/31/88

FACILITY NAME (1)				DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
Indian Point, U	Unit 3		•		YEAR SEQUENTIAL REVISION NUMBER NUMBER	
	•	•	•	 0 5 0 0 0 2 8 6	8 9 - 0 0 4 - 0 0	0 4 0F 0 5

The generation of the reactor trip signal by the source range lies with the following:

Inadequate communication between the control room operators and the I&C technician. The root cause is cognitive personnel error.

## CORRECTIVE ACTIONS

The following corrective actions have been implemented as a result of this event:

- 1. A revision has been incorporated in the I&C Troubleshooting Procedure directing that technicians take no corrective actions until they discuss in detail the proposed corrective actions and possible consequences with the senior reactor operator on watch and get his approval to proceed.
- 2. The I&C technician involved has been counseled concerning unwarranted challenges to the plant's protection systems.
- 3. All personnel involved, Senior Reactor Operator, Reactor Operator, and I&C Technician, have been counseled as to the importance of effective communication.
- 4. Source Range number 32 has been repaired.

### ANALYSIS OF THE EVENT

This event is reportable under 10CFR50.73.a.iv.

The Source Range Hi Flux Trip is not utilized in any safety analysis in the plant's FSAR. Therefore, this event did not effect plant safety.

NRC Form 366A

LICENSEE	EVENT	REDORT	(  ER)	TEYT	CONTINUATION
LIOCHOLL			(EEII)		CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED	омв	NO.	3150-0104
EXPIRES: 8/	31/88		

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6) PAGE (3)			
		YEAR SEQUENTIAL REVISION	·		
Indian Point, Unit 3					
	0 5 0 0 2 8 6	8 9 - 0 0 4 - 0 0	0 5 OF 0 5		

# SECURING FROM THE EVENT

Plant personnel reenergized source range 32. The control room operators continued to place the plant in a cold shutdown condition.

NRC Form 366A (9-83) Indian Point 3 Nuclear Power Plant P.O. Box 215 Buchanan, New York 10511 914 739.8200



March 6, 1989 IP3-89-020

Docket No. 50-286 License No. DPR-64

Document Control Desk Main Station PI-137 U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Dear Sir:

The attached Licensee Event Report LER 89-004-00 is hereby submitted in accordance with the requirements of 10CFR50.73. This event is of the type defined in the requirements per 10CFR50.73(a)(2)(iv).

Very truly yours,

William A. Josiger Besident/Manager Indian Point Three Nuclear Power Plant

VG/rj Attachment

cc: Mr. William Russell Regional Administrator Region 1 U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, Pennsylvania 19406

> INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339