Indian Point 3 Nuclear Power Plant P.O. Box 215 Buchanan, New York 10511

914 736.8001



L. M. Hill Resident Manager

April 26, 1995 IPN-95-052

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

SUBJECT:

Indian Point 3 Nuclear Power Plant Docket No. 50-286 License No. DPR-64 Licensee Event Report # 95-007-00 Loss of Motor Control Center 36B Because Of Personnel

Loss of Motor Control Center 36B Because Of Personnel Error Caused Emergency Diesel Generator 32 to Become Inoperable: A Condition Prohibited By Technical Specifications

Dear Sir:

The attached Licensee Event Report (LER) 95-007-00 is hereby submitted as required by 10CFR50.73. This event is the type defined in 10CFR50.73 (a)(2)(i)(B). Also attached is the commitment made by the Authority in this LER.

Very truly yours,

¥. M. Hill Resident Manager Indian Point 3 Nuclear Power Plant

LMH/vjw

Attachment

cc: See next page



W23

Docket No. 50-286 IPN-95-052 Page 2 of 2

Mr. Thomas T. Martin Regional Administrator Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, Pennsylvania 19406-1415

INPO Record Center 700 Galleria Parkway Atlanta, Georgia 30339-5957

U.S. Nuclear Regulatory Commission Resident Inspectors' Office Indian Point 3 Nuclear Power Plant

cc:

Docket No. 50-286 IPN-95-052 Attachment I Page 1 of 1

List of Commitments

Number	Commitment	Due
IPN-95-052-01	Revise procedure MCC-001- ELC by incorporating permanent TPC No. 95-0499 dated 3/27/95 in accordance with the requirements of AP-3.	September 22, 1995.

NRC FOR	M 366		i i i i i i i i i i i i i i i i i i i			PEGIN	ATORY	COMM	ISSION	1			ONP NO	715	0.010	0/
(5-92)	11 300			-0.5	. NUCLEAR I	LOOL	LATURT	COMM	1351UN			EXPI	RES 5/31	315 /95	0-010	U4 ·
	LICENSEE EVENT REPORT (LER) (See provided outbook of divided of d								COMPLY WITH 50.0 HRS. ESTIMATE TO MENT BRANCH COMMISSION.							
(See	(See reverse for required number of digits/characters for each block)						:k)	WASH REDU MANA	IING JCTI GEM	TON, DC 20555 ON PROJECT ENT AND BUDGE	-0001, A (3150-0 T, WASHIN	ND T (104) (GTON	О ТН 1, <u>DC</u>	E PAPERWORK OFFICE OF 20503.		
FACILITY NAME (1)DOCKET NUMBER (2)PIndian Point Unit 3050002861 OF							PAGE (3))F 7									
TITLE (TITLE (4) Loss of Motor Control Center 36B Because Of Personnel Error Caused Emergency Diesel Generator 32 to Become Inoperable: A Condition Prohibited By Technical Specifications															
EVEN	EVENT DATE (5) LER NUMBER (6) REPORT DATE (7) OTHER FACILITIES INVOLVED (8)															
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	мо	NTH	DAY	YEAR	FACII	LITI	NAME		DOC	кет 05	NUMBER 5000
03	27	95	95	007	00	0)4	26	95	FACII	LITY	NAME		DOC	KET 05	NUMBER 5000
OPERA	TING	N	THIS RE	PORT IS SUBMITTE	D PURSUANT	TO	THE RE		MENTS	OF 10	CFF	₹§: (Check o	one or mo	re)	(11)	
MODE	(9)	IN	20.4	02(b)		20.	405(c))	·····			50.73(a)(2)(i	v)		73.7	'1(b)
POW	ER	000	20.4	05(a)(1)(i)		50.	36(c)	(1)				50.73(a)(2)(v	()	Π	73.7	'1(c)
LEVEL	(10)	000	20.4	05(a)(1)(ii)		50.	36(c)	(2)				50.73(a)(2)(v	(ii)		OTHE	R
			20.4	05(a)(1)(iii)	\checkmark	50.	73(a)((2)(i))			50.73(a)(2)(v	(iii)(A)	(Sp	ecif	y in
			20.4	05(a)(1)(iv)		50.	73(a)((2)(i)			50.73(a)(2)(v	(iii)(B)		trac	τ below Text.
			20.4	05(a)(1)(v)	·	50.	73(a)((2)(ii	i)			50.73(a)(2)(x	:)	NRC	For	m 366A)
				· · · · · · · · · · · · · · · · · · ·	LICENSEE (CONTA	ACT FO	R THI	S LER ((12)						
Nate	Heub	erge	r, Ma	intenance	Manage	er				•		TELEPHONE NUM (914) 7	18ER (Inc 736-86	lude 501	Area	a Code)
			COMF	LETE ONE LINE FO	R EACH CON	IPONE	ENT FA	ILURE	DESCR	BED I	N T	HIS REPORT (1	3)			
CAUSE	SYSTE	м	MPONENT	MANUFACTURER	REPORTABL TO NPRDS	LE S		С	AUSE	SYST	EM	COMPONENT	MANUFAC	CTURE	R	REPORTABLE TO NPRDS
			SUPPLEME	NTAL REPORT EXPE	CTED (14)	<u> </u>					<u>۴</u> ۰		MONTH	.	DAY	YEAR
YES (If	yes, com	iplete E	XPECTED	SUBMISSION DATE).	,	/ NO			SUBMISSION DATE (15)						
ABSTRACT	T (Limi	t to 14	00 space	s i.e. approxi	mately 15	sinc	le-sp	aced	tvpewri	tten	Lin	es) (16)				
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16) On March 27, 1995, a Control Room annunciator indicated a loss of Motor Control Center (MCC) 36B. Loss of MCC-36B resulted in the loss of, among other components, auxiliary components for Emergency Diesel Generator (EDG) 32 rendering that EDG potentially inoperable. A one hour non-emergency notification conservatively reported the plant outside design basis. Operations concluded, since EDG 33 was inoperable because of preventive maintenance, that caused two out of three EDGs to be inoperable therefore, the plant was in a condition prohibited by Technical Specifications. The cause of the event was a personnel error while conducting preventive maintenance on a circuit breaker cubicle of MCC-36B which resulted in the shorting of the feed (line) side terminals. The electrical short injured the worker and caused the MCC-36B feeder breaker on 480 VAC Safety Bus 6A to trip. MCC-36B is the power supply for the auxiliary components for EDG 32. The non-contaminated injured man was transported via ambulance to a local hospital, where he was treated and subsequently released. After various electrical verification checks were satisfactorily completed on MCC-36B and its feeder breaker, MCC-36B was re-energized and EDG 32 declared operable. Corrective actions include revision of the maintenance procedure to provide additional clarifications, purchase of additional insulated tools, conduct of a Performance Enhancement Review Committee meeting and maintenance staff meetings to discuss the event and identify lessons learned																

NRC FORM 366A .S. NUCLEAR (5-92)	S.S. NUCLEAR REGULATORY COMMISSION						
LICENSEE EVENT REPORT () TEXT CONTINUATION	ESTIMATED BURDEN PER RESPONSE TO COMPLY WIT THIS INFORMATION COLLECTION REQUEST: 50.0 HRS FORWARD COMMENTS REGARDING BURDEN ESTIMATE T THE INFORMATION AND RECORDS MANAGEMENT BRANC (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON, DC 20555-0001, AND TO THE PAPERWOR REDUCTION PROJECT (3150-0104), OFFICE C MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.						
FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6) .	PAGE (3)		
Indian Point Unit 3	05000000	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
	05000286	95	007	00	2 OF 7		
TEXT (If more space is required, use additional copies of NRC Form 366A) (17)							

DESCRIPTION OF EVENT

On March 27, 1995, at approximately 1425 hours, with the plant in cold shutdown, reactor power level at 3 CPS, average coolant temperature at 178 degrees F and coolant pressure at approximately 360 psig, an annunciator alarm was received in the Control Room indicating that the 480 VAC Motor Control Center (ED) (MCC) 36B had been lost. The loss of MCC-36B resulted in loss of power to, among other components, Emergency Diesel Generator (EDG) (EK) 32 auxiliary components; thereby, rendering the EDG 32 potentially inoperable. One of the affected MCC Cubicles 5RM, powers the EDG 32 Fuel Oil Transfer Pump (DE), the EDG Engine Crankcase Exhauster 32, EDG Building Sump Pump (WK) 33, and one of the redundant Exhaust Fans (VJ) (Nos. 315, 317, and 319) for each EDG Room. In addition, the Fire Display Control Panel (IB) was also de-energized as a result of tripping MCC-36B. However, hourly roving fire watches for ongoing fire protection (10CFR50, Appendix R) work remained in effect throughout the event. Fire fighting capability was available since the main fire pumps remained operable.

Operations concluded that two EDGs were inoperable because of the power loss to EDG 32 auxiliary components with EDG 33 out of service for preventive maintenance. At 1524 hours, a one hour non-emergency notification reported the plant outside design basis. After further assessment operations concluded that with two out of three EDGs inoperable the event was a violation of Technical Specifications. Operations documented this event in Deviation Event Report (DER) 95-0660, as a violation of Technical Specification 3.7.F.4, which requires at least two operable EDGs in cold shutdown. Coincident to this event, at 1428 hours, the Control Room received a report of an injured man in the vicinity of MCC-36B. Emergency medical personnel and Operations staff were dispatched to the scene.

The injured man had received flash burns while performing preventive maintenance on Auxiliary Component Cooling Water Pump 32 Cubicle 5RK in MCC-36B. He was not radiologically contaminated. At 1453 hours, the injured worker was transported to an offsite medical facility (Hudson Valley Medical Center, Peekskill, NY).

The one hour notification report identified the EDG 32 as "potentially inoperable" because the auxiliary support equipment, normally powered from MCC-36B, would not have prevented EDG 32 from starting and loading. However, the EDG 32 was considered inoperable because after starting, the diesel engine crankcase would pressurize without the crankcase exhauster and result in unreliable EDG operation.

NRC FORM 366A J.S. NUCLEAR RE (5-92)	GULATORY COMMISSION		APPROVED BY O	MB NO. 3150 S 5/31/95	0-0104
LICENSEE EVENT REPORT (LE TEXT CONTINUATION	ESTIMAT THIS II FORWARD THE IN (MNBB 7 WASHING REDUCTI MANAGEM	ED BURDEN PER NFORMATION COLLE COMMENTS REGAR FORMATION AND R 714), U.S. NUCLE ITON, DC 20555-00 ON PROJECT (IENT AND BUDGET,	RESPONSE CTION REQU RDING BURD ECORDS MAN AR REGULAT JO1, AND TI (3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. EN ESTIMATE TO VAGEMENT BRANCH ORY COMMISSION, O THE PAPERWORK O THE PAPERWORK O THE COF OF LCE OF DE 20503.	
FACILITY NAME (1)		LER NUMBER (6)	, <u> </u>	PAGE (3)	
Indian Point Unit 3		VEAD	SEQUENTIAL	REVISION	
	05000286	95	NUMBER 007	NUMBER O O	3 OF 7
TEXI (If more space is required, use additional copies of	NRC Form 3664) (17	<u> </u>			
A preliminary inspection of t that the DE-ION disconnect sw been removed as required for However, this leaves a small energized (line side) unless energization of an entire MCC Westinghouse Type "W" 480 VAC the Primary Auxiliary Building to the energized components is although it is possible to in screwdriver) such that they con Inspection of the MCC cubicle the time, indicated that the energized equipment causing a supply feeder breaker. The as under an emergency work reques the cubicle was inspected with and raceways were also inspect breaker was racked out and vis noted. The MCC was meggered the feeder breaker and the bre 1995, at 1705 hours MCC-36B wa EDG 32 was declared operable. at 1727 hours.	NRC Form 366A) (17 he affected) itch was open work on the area above to the entire M is usually Motor Contro g (PAB) (NF) s physically sert small d ould contact and the scre shank of the short circu ffected cubic st (WR 95-01) h no damage of ted with no of satisfactori eaker was the as re-energing A follow-up	<pre>MCC-3 n and load he DE impra ol Ce impra ol Ce iameri ewdri ewdri ite w 505-0 odamag cted ly vi en ra p rep</pre>	6B cubicle the load side of the ION disco de-energe ctical. N nter (W123 vation 55 ricted by er objects gized comp ver which wdriver hat ich trippe as removed 1). The h ved. Adjo e noted. again with a the load cked in: nd at 1713 ort was ma	<pre>> indic side f ne cubi onnect ized. 4CC-36E 3) loca foot. a cove s (e.g. oonents was ir ad cont of from ous wor oining The MC n no da i side On Man 3 hours ade to</pre>	cated fuses had icle. switch The de- B is a ated in Access er, ., b use at cacted MCC-36B the MCC ck behind cubicles CC feeder amage stabs of cch 27, 5, the the NRC

The injured worker who was transported to an offsite medical facility was treated for first degree burns to the right hand and face, and first and second degree burns of the left hand. There was no radiological contamination of the injured worker. The worker was later released and returned to work the next day, Tuesday, March 28, 1995. The injured person is an electrician contracted to the Maintenance department for outage support. He is an experienced electrician who had previously completed preventive maintenance successfully on similar MCC cubicles.

NRC FORM 366A	EGULATORY COMMISSION	APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95					
LICENSEE EVENT REPORT (L TEXT CONTINUATION	ER)	ESTIMATED BURDEN PER RESPONSE TO COMPLY WIT THIS INFORMATION COLLECTION REQUEST: 50.0 HRS FORWARD COMMENTS REGARDING BURDEN ESTIMATE THE INFORMATION AND RECORDS MANAGEMENT BRANG (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON, DC 20555-0001, AND TO THE PAPERWOR REDUCTION PROJECT (3150-0104), OFFICE (MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.					
FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6))	PAGE (3)		
Indian Point Unit 3	05000000	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
	95	007	00	4 OF 7			

The event was a potential human performance problem; therefore, a Performance Enhancement Review Committee (PERC) meeting was convened on April 6, 1995 to review the event to provide management support and involvement in the identification and correction of the underlying causes of human performance problems. At that meeting, the worker stated that while tightening the screw for the locking latch of the MCC-36B bucket for Auxiliary Component Cooling Water Pump 32, the screwdriver slipped and contacted an energized lug on the line side behind the latch. PERC also noted that checking the tightness of the locking latch was not a required procedural step. PERC concluded that the human performance problem was a personnel cognitive error where momentary carelessness allowed the screwdriver to slip off the screw.

CAUSE OF EVENT

The cause of the event was personnel error which resulted in an inadvertent insertion of a screwdriver into energized components. While access to energized MCC components is restricted with its disconnect switch (DE-ION) open, it is possible to insert small diameter objects such as screwdrivers into the area above the DE-ION disconnect switch and make contact with energized components.

Contributing to this event were the following:

- Inattention to detail in which the worker was not paying attention to precautions contained in procedure MCC-001-ELC and a complacent mindset that the task was a routine activity.
- Inadequate procedural guidance for warnings being placed immediately before a potentially hazardous step when working with an energized line side. The procedure also was not precise in defining when insulated tools and electrical protective equipment needed to be used.
- Failure to have only insulated tools available when performing work near energized equipment.

NRC FORM 366A	EAR REGULATORY COMMISSION	APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95					
LICENSEE EVENT REPORT TEXT CONTINUATION	ESTIMATED BURDEN PER RESPONSE TO COMPLY WIT THIS INFORMATION COLLECTION REQUEST: 50.0 HRS FORWARD COMMENTS REGARDING BURDEN ESTIMATE T THE INFORMATION AND RECORDS MANAGEMENT BRANC (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON, DC 20555-0001, AND TO THE PAPERWOR REDUCTION PROJECT (3150-0104), OFFICE O MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.						
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)			
Indian Point Unit 3	YEAR SEQUENTIAL NUMBER	REVISION NUMBER					
		95 007	00	5 OF 7			

(17 more space is required, use additional copies of NRC Form SODA) (17

CORRECTIVE ACTION

The following corrective actions have been or will be performed to prevent recurrence of this event:

- Appropriate electrical inspections and tests were conducted and MCC-36B was re-energized and declared operable on March 27, 1995 at 1705 hours, which restored EDG 32 to operability and at 1713 hours, EDG 32 was declared operable.
- A meeting was convened with on-site electricians on March 27, 1995, at 1700 hours, to discuss the event and review proper precautions for working on electrical components, particularly MCC cubicles. At that meeting the Safety Program Administrator stated and reinforced that the recently revised and re-issued Indian Point 3 Electrical Work Practices and Procedures Work Rules define the minimum required standards acceptable for work on electrical equipment. The PERC meeting also referenced the Electrical Work Practices and Procedures Work Rules and discussed lessons learned. All other departments were informed of the event and lessons learned through safety tailgate meetings on the following Friday, March 31, 1995. Managers and supervisors were specifically informed of the lessons learned at the next two Plan-of-the-Day (POD) meetings and the Plant Leadership Team (PLT) meetings.
- A Term Procedure Change (TPC) 95-0499 was issued for Maintenance Procedure MCC-001-ELC to clarify the precautions by stating that only insulated tools are used while working within this procedure, to ensure that a meter is used to check that equipment is de-energized, to specifically define when electrical protective equipment must be worn, and to provide caution statements warning of the energized line side immediately before a step. Other electrical safety statements in the procedure were also clarified including verification that load side wiring connections are tight instead of all wiring connections are tight. TPC 95-0499 is a permanent TPC which will be incorporated into procedure MCC-001-ELC in accordance with the requirements of Administrative Procedure AP-3, "IP3 Procedure Preparation, Review and Approval."
- 4. Additional insulated tools were purchased and stocked in the tool room to ensure their availability when personnel work near energized circuits.

NRC FORM 366A U.S. NUCLEAR (5-92)	J.S. NUCLEAR REGULATORY COMMISSION					
LICENSEE EVENT REPORT (TEXT CONTINUATION	ESTIMATED BURDEN PER RESPONSE TO COMPLY THIS INFORMATION COLLECTION REQUEST: 50.0 FORWARD COMMENTS REGARDING BURDEN ESTIMAT THE INFORMATION AND RECORDS MANAGEMENT BI (MNBB 7714), U.S. NUCLEAR REGULATORY COMMIS: WASHINGTON, DC 20555-0001, AND TO THE PAPE! REDUCTION PROJECT (3150-0104), OFFICE MANAGEMENT AND BUDGET, WASHINGTON, DC 20503					
FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	PAGE (3)	
Indian Point Unit 3	n Point Unit 3			REVISION NUMBER		
	05000286	95	007	00	6 OF 7	

ANALYSIS OF EVENT

This event was conservatively reported as a one hour non-emergency report under 10 CFR 50.72(b)(1)(ii)(B); a condition that was outside the design basis of the plant. During the event, EDG 31 could have supplied emergency power to 480 VAC Electrical Distribution System Buses 2A and 3A, which includes RHR Pump 31, to maintain a safe plant condition during cold shutdown. Therefore, this event is being reported under 10 CFR 50.73(a)(2)(i)(B). The licensee shall report any operation or condition prohibited by the plant's Technical Specifications. Emergency Diesel Generator (EDG) 32 was determined inoperable as a result of the loss of 480 VAC Motor Control Center (MCC) 36B, when EDG 33 was out of service for preventive maintenance, causing two of three EDGs to be inoperable, which is a violation of Technical Specification 3.7.F.4.

Similar events have been reported in previous Licensee Event Reports. Events related to EDG support systems affecting the operability of the EDGs have been reported in LERs; 94-010, 93-053, 93-050, and 93-042. Events related to improper maintenance or testing of EDG support systems which affected the operability of the EDGs have been reported in LERs; 93-020, 93-024, 93-032, and 93-033.

NRC FORM 366A S.S. NUCLEAR RE (5-92)	APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95				
LICENSEE EVENT REPORT (LE TEXT CONTINUATION	ESTIMAT THIS IN FORWARD THE IN (MNBB 7 WASHING REDUCTI MANAGEM	ED BURDEN PER NFORMATION COLLE COMMENTS REGAI FORMATION AND R 7714), U.S. NUCLE ITON, DC 20555-01 ON PROJECT (IENT AND BUDGET,	RESPONSE CTION REQU RDING BURD ECORDS MA EAR REGULAT 001, AND T (3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. EN ESTIMATE TO NAGEMENT BRANCH FORY COMMISSION, 0 THE PAPERWORK 0, OFFICE OF 1, DC 20503.	
FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6))	PAGE (3)
Indian Point Unit 3	0500000	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
	-	95	007	00	7 OF 7

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

SAFETY SIGNIFICANCE

This event had no significant effect on the health and safety of the public.

The basis for this conclusion is that the loss of EDG 32 was due to a random, unintended human error. During the event there was no loss of the normal power sources used to maintain cold shutdown (offsite power), nor was there any plant evolution or transient which would have presented a challenge requiring the use of the EDGs. Also, EDG 31 could supply emergency power to 480 VAC Electrical Distribution System Buses 2A and 3A, which includes RHR Pump 31, to maintain a safe plant condition. The loss of the EDG due to random human error can be considered similar to a single failure. Therefore, with one EDG operable, adequate EDG capacity was available during this event to maintain a safe plant condition. If this event had occurred when operating, three EDGs are required per Technical Specification 3.7. Any two emergency diesel generator units, as a backup to the normal AC power supply are capable of sequentially starting and supplying the power requirement of one minimum required set of safeguards equipment. Any two diesels have adequate capacity to supply the engineered safety features for the hypothetical accident concurrent with loss of outside power. In addition, although the Appendix "R" Diesel Generator was not available during this event, it normally represents an alternate onsite source of power for safe shutdown loads since it is required to be available above cold shutdown to feed the 6.9kV buses that supplies the 480 VAC Electrical Distribution System (EDS).

The loss of power to the EDG 32 engine crankcase exhauster would not have prevented EDG 32 from starting and loading. However, without the crankcase exhauster, the crankcase would pressurize and be relieved by blowout units resulting in unreliable (degraded) EDG operation.