		_					•								
NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION (5-92)									APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95						
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each bloc							block)	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.						
FACILITY NAME (1) Indian Point 3							DOCKET NUMBER (2) 05000286			PAGE 1 OF	(3) 4				
TITLE (4) Automatic Reactor Trip due to a High Resistance Contact on a Reactor Protection Relay While Testing An Analog Channel															
EVEN	T DATE	(5)			LER NUMBER (6)		REPOR	T DATE	(7)	OTHER FACILITIES INVOLVED (8)				
MONTH	DAY	YEA	R	YEAR	SEQUENTIAL NUMBER	REVIS	ion Er	MONTH	DAY	YEAR	FACILITY NAME			DOCKET NUMBER	
09	15	97		97	-025-	00		10	15	97	FACILITY NAME			DOCKET NUMBER 05000	
OPERATING THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)							(11)								
MODE (9) NA				20.402(b)			20.405(c)			50.73(a)(2)(iv)			73.71(b)		
POVER				20,405(a)(1)(j)			50.360	50.36(c)(1)			50.73(a)(2)(y)		73.71(c)		
LEVEL (10)		030		20.405(a)(1)(ii)		50.36(c)(2)				50.73(a)(2)(vii) 0			HER		
				20.405(a)(1)(iii)				50.73(a)(2)(i)				50.75(a)(2)(V111)(A)			city in ract below
				20.405(a)(1)(iv)				50.73(a)(2)(ii)			50.75(a)(2)(V111)(B)			and	in Text,
				20.405(a)(1)(v)				50.73(a)(2)(iii)			50.73(a)(2)(X)			NRC	Form 366A)
						LICENSEE	CON	ITACT FOR	THIS	LER (12)	· · · · ·			
NAME Steve Manzione, I&C Engineering Supervisor (914)736-8783															
				COMPLE	TE ONE LINE FO	R EACH CO	OMPO	DNENT FA	LURE	ESCRI	BED IN	THIS REPORT	(13)		
CAUSE	CAUSE SYSTEM		COM	OMPONENT MANUFACTURER		REPORTAB	ILE IS		CAUS	E S	YSTEM	COMPONENT	MANUFACTU	JRER	REPORTABLE TO NPRDS
x	J	2	I	RLY	W120	Y	;		· × in-						. · ·
						. <u></u>									
SUPPLEMENTAL REPORT EXPECTED (14)								EXPECTED		MONTH	· DAY	YEAR			
YES (If	yes, c	:omple	te E	XPECTED \$	SUBMISSION DATE			V NO			SUBMISSION DATE (15)				
ABSTRACT (limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)															
On September 15, 1997 the plant was operating at approximately thirty															
percent reactor power. At 1623 hours, the plant experienced an inadvertent															

On September 15, 1997 the plant was operating at approximately thirty percent reactor power. At 1623 hours, the plant experienced an inadvertent automatic reactor trip when the logic for two out of four channels for low pressurizer pressure was completed. One channel was placed in trip as per procedure in order perform instrument channel testing in accordance with Technical Specifications. At that time, the logic relay for another channel was already effectively tripped due to a high resistance contact causing an insufficient voltage being applied to the corresponding reactor trip relay. After the trip, the relay with the high resistance contact was replaced. Voltage drops across contacts on reactor protection relays were measured, relay contacts were cleaned and found to be acceptable. Review of the plant trip identified that other protective equipment responded as designed after the trip. Corrective action to preclude future similar events will be developed by engineering to include a preventative maintenance program for reactor protective relays. The event had no affect on the health and safety of the public.

NRC FORM 366 (5-92) 9710240041 971015 9DR ADDCK 05000286 9DR ADDCK 9DR

NRC FORM 366A (5-92)	U.S. NUCLEAR REGULATORY COMMISS	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95							
	LICENSEE EVENT REPORT (TEXT CONTINUATION	LER)	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.						
	FACILITY NAME (1) DOCKET NUMBER				LER NUMBER (6) PAGE (3)				
	Indian Point 3		YEAR	SEQUENTIAL	REVISION				
		05000286	97	-025-	00	2 OF 4			

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Note: The Energy Industry Identification System Codes are identified within the brackets { }.

DESCRIPTION OF EVENT

On September 15, 1997 the plant was operating at approximately thirty percent reactor power, at 200 MWe and at normal reactor coolant {AB} pressure and temperature. At 1619 hours, Instrumentation and Control (I&C) Technicians commenced a surveillance test, 3PT-Q95, "Pressurizer Pressure Analog Functional Test." In order to test each pressurizer low pressure analog channel the test requires placing the channel in trip. This places a channel in a trip condition for each of the two reactor protection logic trains {JC}. At 1623 hours, when an analog channel was placed in trip, the plant experienced an inadvertent automatic reactor trip. Operators responded to the trip using emergency operating procedure E-0, "Reactor Trip or Safety Injection."

The plant protective equipment responded to the trip as expected. Rods {AA} inserted fully and auxiliary feed water pumps {BA} started. No safety injection actuation {JE} occurred nor was one required. At 1700 hours, when RCS average temperature reached approximately 540 degree F, operators closed main steam isolation valves {SB} and RCS temperature stabilized at a normal temperature of 547 degree F. Offsite power {EB} remained available during the event. The plant was maintained stable in the hot shutdown condition.

At 1747 hours, a non-emergency four-hour report (Incident Log No. 32930) for the reactor trip was made to the NRC Operations Center in accordance with 10CFR50.72(b)(2)(ii). At that time, the cause of the reactor trip was unknown. As a follow-up, on September 18, 1997, at 1503 hours, NYPA made a supplemental report for Incident Log No. 32930 to the Operations Center for this event to provide the cause of the trip.

NRC FORM 366A (5-92)	U.S. NUCLEAR REGULATORY COMMISSIO	APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95						
, ,	LICENSEE EVENT REPORT (L TEXT CONTINUATION	ER)	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.					
	FACILITY NAME (1) DOCKET NUMBER				LER NUMBER (6) PAGE (3			
			YEAR	SEQUENTIAL	REVISION			
	Indian Point 3	05000286	97	-025-	00	3 OF 4		

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

CAUSE OF EVENT

An investigation of the reactor protection circuitry disclosed that there was a reactor protection logic relay contact with high contact resistance. When the channel being tested was placed in trip for testing it opened select contacts in the train B trip matrix. These opened contacts in combination with the high resistance contact caused insufficient voltage to the corresponding reactor trip relay. Therefore, the two of four logic matrix was completed for train B causing reactor trip breaker B to open resulting in a reactor trip from train B. Only one contact had high resistance, therefore there was no indication to the operator or I&C technicians of the high resistance condition prior to the trip.

A contributing cause to the event was that cleaning reactor protection relay contacts was not a preventative maintenance activity.

CORRECTIVE ACTIONS

I&C replaced the relay that had the high resistance contact.

I&C functionally checked reactor protection relays in both logic trains by energizing and de-energizing their relay coil. Voltage across the reactor trip relay coils was monitored as relays were cycled. This provided indication of any voltage drop across the remaining closed contacts in the logic circuit. The results of this testing showed that the voltage drop across the contacts was up to one volt (2 cases), which was within the acceptance criteria. This was determined to be satisfactory when compared to the drop out voltage for the reactor trip relay. This testing effectively verified that approximately 400 relay contacts from approximately 200 relays were satisfactory. The relay contacts were cleaned using an electronic spray cleaner. The relays and associated contacts were found to function satisfactorily. The relay contacts were determined to be clean based on the voltage drop measurements.

	NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION (5-92)	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95								
	LICENSEE EVENT REPORT (LEE TEXT CONTINUATION	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET. WASHINGTON. DC 20503.								
Ī	FACILITY NAME (1)		PAGE (3)							
	Indian Point 3	05000286	year 97	SEQUENTIAL	revisio 00	4 OF 4				
ſ	TEXT (If more space is required, use additional copies of NRC Form 366A) (17)									
	CORRECTIVE ACTIONS, Continued I&C performed an inspection of the safety injection logic relays (approximately 120). This inspection found these relays to be satisfactory. I&C reviewed the failure history of these type of relays and found no indication that there is a set failure pattern associated with previous relay failures. Failures were found to be due to contact degradation or coil failure and were random in nature. I&C Engineering will develop a preventative maintenance program for reactor protection relays. This will be completed by May 15, 1998, in time for implementation during the next refueling outage (RO-10). This outage is planned for 1999. I&C will implement the reactor protection preventative maintenance program during the next refueling outage (RO-10). This outage is planned for the									
	ANALYSIS OF EVENT									
	The event is reportable under 10CFR50.73(a)(2)(iv) for an automatic reactor trip. A review of the past two years for similar reactor trips where protective electrical equipment contributed to the event identified LER 97- 005-00, Manual Reactor Trip Initiated due to Overpower Delta T Channel Signal and Turbine Runback caused by a Foxboro bistable failure.									
	SAFETY SIGNIFICANCE									
	This event had no effect on the health and safety of the public. The reactor trip occurred as designed and no safety injection actuation occurred. If the plant was operating at full power, it is expected that the systems would respond as designed and safe shutdown of the plant would occur as it did in this event.									
Ì										