Docket No. 50-286 IPN-97-004 Enclosure I Page 1 of 1

SERVICE WATER IMPROVEMENT PLAN



IDSE-SIP-96-005, Rev. 1 ACTS #19245 November 20, 1996...

PURPOSE:

The purpose of this plan is to identify actions being taken by the New York Power Authority to improve the reliability of the plant service water system. The Individual Plant Examination (IPE) study found that improvements to the service water system would reduce risk of core damage by over 5%, the seventh highest percentage of all plant systems. In addition, the effect of doubling the unavailability of this system would increase the risk of core damage by almost 5%, the sixth highest system in the station. Therefore, the development of a plan to properly upkeep and improve upon this system would be most beneficial to the safe operation of the plant.

This revision will also be a consolidation of the various action plans that were developed separately to deal with Maintenance Rule concerns and issues raised by Generic Letter 89-13 and subsequent meetings on improving the overall condition of the service water system. In this way, one unified action plan can be followed by anyone interested in the status of all of the ongoing efforts and improvements to the service water system.

Note that this action plan will **not** be tracking normal corrective maintenance activities for the service water system, nor its preventive maintenance cycles. It will **not** track those work packages that will require a minimal amount of engineering, such as a DC package to replace an obsolete or unavailable model valve.

REFERENCES:

- 1. IDSE-APL-96-015, Revision 1 (ACTS 18446)
- 2. IDSE-APL-96-022, Revision 0 (ACTS 19246)
- 3. IDSE-SIP-96-005, Revision 0
- 4. Generic Letter 89-13, dated July 18, 1989
- 5. NRC Letter TAC M74003, dated July 18, 1989
- 6. Letter IPN-90-004, dated February 6, 1990
- 7. Supplement 1 to Generic Letter 89-13, dated April 4, 1990
- 8. Letter IPN-92-040, dated September 9, 1992
- 9. NRC Letter TAC M74016, dated September 30, 1992
- 10. IP3 Design Basis Licensing Database: Log items 90-013A through L, 92-052, and 92-061-A, B, &C
- 11. Enercon Services, Inc., "Assessment of IP3 Service Water System Procedures and Training NYP1-PR-01 Final Report", dated March 15, 1991
- 12. Administrative Procedure AP-58, Revision 1
- 13. System Engineering Procedure TSP-048, Revision 1
- 14. System Engineering Procedure TSP-043, Revision 3

IDSE-SIP-96-005, Rev. 1 ACTS #19245 November 20, 1996

- 15. Specification 9321-05-248-35, up to and including Addendum H
- 16. Operations Procedure SOP-RW-5, Revision 18
- 17. SOR 93-332
- 18. SOR 93-573
- 19. Deficiency Event Report DER 94-0385
- 20. Deficiency Event Report DER 95-1889
- 21. IP3-RPT-SWS-01927, Rev. 0, "Maintenance Rule Basis Document for System F44-0151 Service Water System"
- 22. Memo IP-DSE-96-190, with attached notes of meeting, dated October 21, 1996
- 23. Memo from J. Lafferty to J. Deroy, subject Service Water Repair Team, undated
- 24. IP3 SWS: Experience & Prognosis & Plans

STATUS:

A. System Condition Strengths

Biofouling and Tube Plugging Prevention

- 1. NYPA inspects the service water pump intake bay during refueling outages.
- 2. NYPA monitors heat exchanger condition through aggressive cleaning of its cooling tubes through its Preventive Maintenance program, as well as examine tubing condition through its eddy current testing program.
- 3. NYPA continuously chlorinates its service water system to prevent biofouling.
- 4. NYPA performs weekly flow tests on its Emergency Diesel Generator (EDG) coolers (3PT-W1) to ensure that no plugging has occurred in these tubes.
- 5. NYPA has developed an equipment layup program for its heat exchangers to minimize corrosion (OD-14).

Test Program to Assess Heat Exchanger Capability

- 1. Aggressive cleaning of heat exchangers with provision to increase and decrease frequency based on findings (multiple maintenance procedures).
- 2. Pilot test program showing that under worst case conditions (i.e., just prior to semi-annual cleaning), EDG lube oil and jacket water coolers are still capable of handling their design heat loads (ENG-487F).
- 3. Pilot test program showing that under worst case condition (i.e., fifteen years of operation without tube side cleaning), containment recirculation fan (CRF) is still capable of removing its design heat load (ENG-486F).

Establishment of a Routine Inspection and Maintenance Program to Ensure SWS Reliability

1. Revised of TSP-048 to incorporate field experiences with areas most susceptible to silting and corrosion and targeting areas for investigation and trending.

IDSE-SIP-96-005, Rev. 1 ACTS #1°?45 November 20, 1996

- Bio-boxes installed in conventional chemistry (SWAP) lab and in control room air conditioning (CRAC) room to monitor presence of zebra mussels in SWS.
 Biofouling plates installed in front of plant intake are monitored monthly.
- 3. Availability of Zebra Mussel Task Force to respond to imminent threat of zebra mussels to service water system at Indian Point 3.

Confirm that SWS is Operating in Accordance with Design and Licensing Bases

- 1. Design Basis Document has been established. Revision 1 was approved May 19, 1995.
- 2. A hydraulic model has been developed to compute the flows of service water through various parts of the system.

Confirm that Training, Maintenance, Operating and Emergency Procedures are Adequate

- 1. The Service Water System is considered a Risk Significant system and is included in the plant Maintenance Rule program.
- 2. Operating procedures have been established for the service water system and are constantly updated by plant staff in response to feedback from operating crews.
- 3. Operations staff are qualified on operations and emergency procedures on an ongoing basis.
- B. System Condition Problem Areas
- 1. Small bore piping and valves are in poor condition, as borne out by recent inspections.
- 2. Coating and insulation of the service water piping is poor and haphazard (e.g., the use of fiberglass on outdoor installations).
- 3. Replacements of system hardware difficult due to increasing obsolescence.
- 4. Increasing need for more corrosion/biofouling monitoring.
- C. Maintenance Rule Status vs. Performance Criteria
- 1. Maintenance Preventable Functional Failures (MPFFs) ≤ 2 per cycle: As of the third quarter, 1996 reporting period the service water system has 3 MPFFs for the cycle, which causes the service water system to be in (a)(1) status.
- 2. No Repeat MPFFs. The service water system is currently in (a)(1) status due to recurring failures of the auto strainer backwash valves.
- 3. 3.0% max. unavailability of each of the six main service water pumps. As of the third quarter, 1996, all six main service water pumps have met this goal.

IDSE-SIP-96-005, Rev. 1 ACTS #19245 November 20, 1996

ACTIONS:

A. Improvement of System Condition

1.	Identify valves which should be replaced to maximize service water system reliability.					
	Responsible Person:	P. Zellmer	Due Date:	Completed		
	Completion Docume	nt: Printout of modi	fications w. affe	cted valves (see A.19)		
2.	Protect the service water system pipe installed by completion of outstanding work requests for this problem.					
	Responsible Person:	A. Bortz	Due Date:	12/31/96		
	Tracking Items: -47, -55	WR 96-00003-05 (c	completed), WRs	s 96-00006-44, -45, -46,		
3.	Provide written report to docket SWS replacement plan to NRC.					
	Responsible Person:	J. Lafferty	Due Date:	12/31/96		
	Tracking Item:	IDSE-SIP-96-005				
4.	Provide engineering package for replacement of seal oil cooler service water					
	piping.					
	Responsible Person:	T. Schaefer	. Due Date:	1/4/97 (both)		
	Tracking Items:	WRs 96-03539-00,	96-03539-01			
5.	Provide engineering package for replacement of CRAC service water pipe.					
	Responsible Person:	M. Pactong	- Due Date:	1/16/97		
	Tracking Item:	WR 95-01994-00				
6.	Provide engineering package for replacement of CRAC unit condensers.					
	Responsible Person:	J. Bubniak	Due Date:	1/16/97		
	Tracking Item:	WR 95-03752-00				
7.	Provide engineering package for replacement of exciter cooler isolation valves.					
	Responsible Person:	T. Czerniewski	Due Date:	1/20/96		
	Tracking Items:	WR 96-03461-49 (A	ACTS 18751), W	/R 96-03005-00 (work)		
8.	Prepare a report consolidating and summarizing results of failure studies and					
	present recommendations for service water improvements.					
	Responsible Person: D. Werder (MPR), w. W. Spataro consulting					
	Due Date: 2/1/97	Tracking It	tem: IDSE	-SIP-96-005		

IDSE-SIP-96-005, Rev. 1 ACTS #19245 November 20, 1996

9.	Provide engineering	package for replaceme	age for replacement of service water header to SWAP			
	lab, including header isotation valve SWT-73.					
	Responsible Person :	M. Pactong	Due Date:	2/3/97		
	Tracking Item:	WR 96-05068-01				
10.	Provide engineering	package for replaceme	nt of Fan Coole	er Unit (FCU) motor		
	cooler return pipe.					
	Responsible Person:	R. Lee	Due Date:	2/15/97		
	Tracking Item:	WR 95-04997-00				
11.	Provide engineering	backage for replaceme	nt of FCU cool	ing coil inlet flanges.		
	Responsible Person:	M. Pactong	Due Date:	2/15/97		
	Tracking Item:	WR 95-00278-18				
12.	Install MMP 95-3-24	1 SWS, CRAC piping	replacement.			
	Responsible Person:	N. Nilsen	Due Date:	End of R09		
	Tracking Item:	WR 95-01994-01				
13.	Install DC 95-3-129 S	SWS, CRAC condense	er replacement.			
	Responsible Person:	N. Nilsen	Due Date:	End of R09		
	Tracking Item:	WR 95-03752-xx				
14.	Install DC 95-3-303 S	SWS, FCU motor cool	er return piping	replacement.		
	Responsible Person:	N. Nilsen	Due Date:	End of R09		
	Tracking Item:	WR 95-04997-01				
15.	Install MMP 96-3-212 SWS, FCU flanged connections replacement.					
	Responsible Person:	N. Nilsen	Due Date:	End of R09		
	Tracking Item:	WR 95-00278-21				
16.	Install DC 96-3-190 S	SWS, DC 96-3-191 SV	WS, seal oil coo	lers SW valve & pipe		
	replacement.					
	Responsible Person:	N. Nilsen	Due Date:	End of R09		
	Tracking Items:	WR 96-03539-05. 96	5-03539-04			
17.	Install DC 96-3-179 S	SWS, exciter cooler va	lve replacement			
	Responsible Person:	N. Nilsen	Due Date:	End of R09		
	Tracking Items:	WRs 96-03493-00 (S	SWT-25-1), 96-	03499-01 (SWT-25-2),		
	96-03005-01 (SWT-25-3), 96-03503-00 (SWT-25-4), 96-03005-04 thru -08					
	inclusive (SWT-26-1	thru -4)				
18.	Install DC 96-3-339 S	SWS, SWAP lab head	er and SWT-73	replacements.		
	Responsible Person	N. Nilsen	Due Date:	End of KU9		
	Tracking Items:	WR 95-05068-02 (p	ping), 95-0506	8-05 (SW1-73)		

IDSE-SIP-96-005, Rev. 1 ACTS #19245 November 20, 1996

- 19. Provide engineering to replace following portions of service water system during R09 or shortly after R09:
 - Main service water pump backwash piping (WR 96-07499-00)
 - * IACC supply/return piping (WR 96-07500-00)
 - * Circulating Water Pump seal/lube water piping/valves (WR 96-07504-00)
 - * R16 A/B piping/valve replacement (PID 59646)
 - Backup service water pump backwash piping (WR 96-07659-00)
 - * Replacement of drain lines 470 & 471 (WR 96-08018-00)

Responsible Person: J. Bubniak, w. F. Gilbert (Yankee Atomic)

Due Date: Prior to start of R09 **Tracking Item:** IDSE-SIP-96-005

- 20. Install the following portions of the service water system during R09:
 - DC 96-3-507 SWS: Main service water pump backwash piping (WR 96-07499-01)
 - * DC 96-3-504 SWS: IACC supply/return piping (WR 96-07500-01)
 - * R16 A/B piping/valve replacement (PID 59646)
 - * Replacement of drain lines 470 & 471 (WR 96-08018-01)

Responsible Person: N. Nilsen, w. H. Safar (NPS)

Due Date:End of R09Tracking Item:IDSE-SIP-96-00521.Provide engineering to replace following portions of service water system during R10:

- * Isophase bus duct coolers supply/return piping (WR 96-07501-00)
- * Exciter cooler piping/valves (WR 96-07502-00)
- * Main Boiler Feed Pump lube oil cooler piping/valves (WR 96-07503-00)
- * TCV-1104/TCV-1105 pipe replacement (WR 96-07505-00)

Responsible Person: J. Bubniak, w. F. Gilbert (Yankee Atomic)

Due Date: Prior to start of R10 Tracking Item: IDSE-SIP-96-005
22. Install the following portions of the service water system by the start of refueling outage R10:

* Backup service water pump backwash piping (WR 96-07659-01)

Responsible Person: N. Nilsen, w. H. Safar (NPS)

Due Date: Prior to start of R10 **Tracking Item:** IDSE-SIP-96-005

IDSE-SIP-96-005, Rev. 1 ACTS #19245 November 20, 1996

- 23. Install or complete the installation of the following portions of the service water system during R10:
 - DC 96-3-508 SWS: Isophase bus duct coolers supply/return piping (WR 96-07501-01)
 - * DC 96-3-506 SWS: Exciter cooler piping/valves (WR 96-07502-01)
 - DC 96-3-509 SWS: Main Boiler Feed Pump lube oil cooler piping/valves (WR 96-07503-01)
 - * DC 96-3-510 SWS: Circulating Water Pump seal/lube water piping/valves (WR 96-07504-01)
 - * DC 96-3-505 SWS: TCV-1104/TCV-1105 pipe replacement (WR 96-07505-01)

Responsible Person: N. Nilsen, w. H. Safar (NPS)

Due Date:End of R10Tracking Item:IDSE-SIP-96-00524.Service Water Project Manager to coordinate replacement of service water piping
over next two to three outages, including materials procurement, engineering, and
installation.

Responsible Person:T. ColeDue Date:R10+Tracking Item:IDSE-SIP-96-005IDSE-SIP-96-005IDSE-SIP-96-005

B. Installation of Upgrades to Service Water System

1. Provide engineering package for reduction of instrument air (IA) failures to the FCU temperature control valves (TCVs). **Responsible Person:** M. Pactong **Due Date:** 2/15/97 **Tracking Item:** WR 95-03321-00 2. Provide engineering package for changeout and upgrade of the hydrogen coolers in the main turbine generator. **Responsible Person:** R. Lee **Due Date:** 2/17/97 Tracking Item: WR 96-00186-00 3. Install DC 96-3-177 SWS, flexible IA connections to TCV actuators. Responsible Person: A. Vitale **Due Date:** 3/15/97 **Tracking Item:** WR 95-03321-01 4. Install MMP 96-3-178 SWS, hydrogen cooler upgrade. **Responsible Person:** G. Kazakias **Due Date:** End of R09 **Tracking Item:** WR 96-00186-01

IDSE-SIP-96-005, Rev. 1 ACTS #19245 November 20, 1996

C. Continue/Improve Corrosion/Biofouling Monitoring of Service Water System

1.	Determine method of ensuring that Chemistry department personnel are contacted					
	wab sample can be					
	taken to check for microbes.	-				
	Responsible Person: J. Kristensen Due	Date:	Completed			
-	Completion Document: Memo IP-CHM-96-122, dated November 6, 1990					
2.	Evaluate internal inspection points and the need to	o install n	nanways.			
	Responsible Persons: T. Moran/J. Bubniak Due	Date:	1/3/97			
-	Tracking Item: IDSE-SIP-96-005					
3.	Investigate industry experience with coupon testin	ng for cor	rosion monitoring.			
	Responsible Person: T. Moran Due	Date:	1/3/97			
	Tracking Item: IDSE-SIP-96-005	·				
4.	4. Begin tracking of river water salinity and track frequency of SWS leaks in re					
	to salinity levels.					
	Responsible Persons: T.Moran/J. KristensenDue	Date:	12/20/96			
	Tracking Item: IDSE-SIP-96-005					
5.	Choose additional inspection points on large bore	pipe prio	or to and during R09.			
Locations to include 10" headers to FCUs, supply headers to Closed Cool						
	Water (CCW) heat exchangers, and supply and return headers to EDG coolers.					
	Responsible Person: D. Pennino Due	Date:	1/15/97			
	Tracking Item: IDSE-SIP-96-005	• • • •	(D , C) · · · ·			
6.	Complete qualification of comparitive density rad	lograph (RI) examination			
	technique for inspection of welds.					
	Responsible Person: P. Peloquin Due	Date:	1/31/97			
_	CIS 17839)					
7.	Identify contingency repair plans based on inspect	tions loca	itions.			
	Responsible Persons: J.Bubniak/J.1.Ownby Due	Date:	2/5/97			
-	Tracking Item: IDSE-SIP-96-005	• 11	·			
8.	Create contract for analysis of microfouling organ	Create contract for analysis of microfouling organisms collected from swab				
	samples of service water system.	D ()	2/1/07			
	Responsible Person: H. Hartjen Due	Date:	3/1/97			
	Tracking Item: IDSE-SIP-96-005		•			
9.	Develop a microbiologically-influenced corrosion	n (MIC) r	nonitoring program.			
	Responsible Person: H. Hartjen Due	Date:	3/13/97			
	Tracking Item: IDSE-SIP-96-005					



IDSE-SIP-96-005, Rev. 1 ACTS #19245 November 20, 1996

10. Review layup procedure OPS-SD-5 for extended outages and develop recommendations for improvements to service water equipment. **Responsible Persons:**D. Lyon/T. Moran **Due Date:** 3/15/97 **Tracking Item:** IDSE-SIP-96-005 11. NYPA to inspect the SWS Intake Bay during refueling outage R09. Responsible Persons: C. Bristol/D. Pennino Due Date: End of R09 Tracking Item: ACTS 10709 12. NYPA to inspect a minimum of 25 locations using NDE for service water piping during R09. Responsible Person: D. Pennino **Due Date:** End of R09 Tracking Item: ACTS 10190/WR 96-03461-82 13. NYPA to check six small bore valves which had less than 15% margin using ultrasonic examination (UT) methods. Responsible Person: D. Pennino **Due Date:** End of R09 **Tracking Item:** ACTS 14376 NYPA to check four welds on service water pump discharge lines for evidence of 14. further degradation. Responsible Person: D. Pennino **Due Date:** End of R09 **Tracking Item:** ACTS 21055 & 10190 Use boroscope and/or robotic crawler to examine interior of 24" SWS mains 408 15. and 409 upstream and downstream of valves SWN-98 and SWN-99. Responsible Person: D. Pennino **Due Date:** End of R09 Tracking Item: **ACTS 1122** 16. Coordinate boroscope or robotic crawler examination of SWS supply pipe to EDG coolers upstream of SWN-29 and SWN-30. Responsible Person: D. Pennino **Due Date:** End of R09 **Tracking Item: IDSE-SIP-96-005** 17. NYPA to check one weld on service water pump discharge lines for evidence of further degradation. Responsible Person: D. Pennino End of R10 **Due Date: Tracking Item: ACTS 21056**

D. Completed and Continuing Testing Program Efforts

 Complete testing of an EDG oil-to-water heat exchanger and water-to-water heat exchanger under ENG-487F under Pilot Testing Program for safety-related service water heat exchangers.
 Responsible Person: T. Moran Due Date: Completed Completion Document: ENG-487F, ACTS 6748 closed

IDSE-SIP-96-005, Rev. 1 ACTS #19245 November 20, 1996

2. Complete testing of an FCU air-to-water heat exchanger under ENG-486F under Pilot Testing Program for safety-related service water heat exchangers. Responsible Person: T. Moran **Due Date:** Completed **Completion Document:** ENG-486F, ACTS 1490 closed 3. Summarize results of Pilot Testing Program, showing how results do or do not justify using aggressive cleaning in place of regular testing to demonstrate heat exchanger capability. **Responsible Person:** T. Moran **Due Date:** 1/15/97 **Tracking Item: IDSE-SIP-96-005** 4. Update flow test for service water system to determine actual velocities in various regions of the SWS to better assist in allocation of corrosion monitoring resources. Responsible Person: D. Pennino 3/1/97 **Due Date: Tracking Item:** IDSE-SIP-96-005 5. Perform flow test for service water system to capture flow data. Responsible Person: D. Pennino **Due Date:** 6/1/97 **Tracking Item:** IDSE-SIP-96-005 Ε. Procedural/Design Basis Action Items Evaluate service water system operation in modes of little or no load. Determine 1. a method of operating the system without cross-tieing the two headers. Responsible Person: T. Moran **Due Date:** 12/24/96 **Tracking Item:** WR 95-06345-00 2. Review and approve latest version (8.9) of the Service Water System flow model. **Responsible Person:** J. Gullick Due Date: 12/31/96 **Tracking Item:** ACTS 10042 Update SOP-RW-5 upon completion of work associated with WR 95-06345-00. 3. **Due Date:** 1/6/97 **Responsible Person:** M. Levitan **Tracking Item:** IDSE-SIP-96-005 Update service water system piping specification, including use of AL6XN and 4. 254SMo materials. 1/10/97 **Due Date:** Responsible Person: D. Pennino IDSE-SIP-96-005 **Tracking Item:** Update piping specification to ensure that foamglas or equivalent material is used 5. in outdoor applications to prevent moisture from being trapped in insulation adjacent to pipe. Due Date: 1/10/97 Responsible Person: D. Pennino IDSE-SIP-96-005 **Tracking Item:**

IDSE-SIP-96-005, Rev. 1 ACTS #1°245 November 20, 1996

6. Develop welding procedure using 6% Mo stainless steel.
 Responsible Persons: W. Spataro, w. assistance from N. Chapman (JAF)
 Due Date: 1/10/97 Tracking Item: IDSE-SIP-96-005

F. Maintenance Rule Action Items

- 1.Review industry experience with this type of failure for lessons learned.Responsible Person:T. MoranDue Date:12/31/96Tracking Item:IDSE-SIP-96-005
- 2. Analyze chronic operating problems with the backwash mode of the Zurn strainers.

Responsible Person:T. MoranDue Date:1/31/97Tracking Item:IDSE-SIP-96-0051/31/97

- Make recommendations for modifications and/or changes to plant PM program.
 Responsible Person: T. Moran Due Date: 1/31/97
 Tracking Item: IDSE-SIP-96-005
- 4. Monitor and trend failure-to-start DERs for Service Water Pumps for remainder of Cycle 9.

Responsible Person:T. MoranDue Date:7/31/97Tracking Item:IDSE-SIP-96-005