



FirstEnergy Nuclear Operating Company

Perry Nuclear Power Station  
10 Center Road  
Perry, Ohio 44081

Mark B. Bezilla  
Vice President

440-280-5382  
Fax: 440-280-8029

March 25, 2010  
L-10-069

10 CFR 50.73(a)(2)(v)(B)

ATTN: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

SUBJECT:  
Perry Nuclear Power Plant  
Docket No. 50-440, License No. NPF-58  
Licensee Event Report Submittal

Enclosed is Licensee Event Report (LER) 2010-001, "Invalid Isolation Signal Results in Shutdown Cooling Interruption." There are no regulatory commitments contained in this submittal.

If there are any questions or if additional information is required, please contact Mr. Robert Coad, Manager – Regulatory Compliance, at (440) 280-5328.

Sincerely,

Mark B. Bezilla

Enclosure:  
LER 2010-001

cc: NRC Project Manager  
NRC Resident Inspector  
NRC Region III

IE22  
NRR

# LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hrs. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to [infocollects@nrc.gov](mailto:infocollects@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

<b>1. FACILITY NAME</b> Perry Nuclear Power Plant	<b>2. DOCKET NUMBER</b> 05000440	<b>3. PAGE</b> 1 OF 5
------------------------------------------------------	-------------------------------------	--------------------------

**4. TITLE**  
Invalid Isolation Signal Results in Shutdown Cooling Interruption

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
04	27	2009	2010	001	00	03	25	2010	FACILITY NAME	DOCKET NUMBER

<b>9. OPERATING MODE</b>  5	<b>11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §:</b> <i>(Check all that apply)</i>																																				
<b>10. POWER LEVEL</b>  0	<table style="width:100%; border: none;"> <tr> <td><input type="checkbox"/> 20.2201(b)</td> <td><input type="checkbox"/> 20.2203(a)(3)(i)</td> <td><input type="checkbox"/> 50.73(a)(2)(i)(C)</td> <td><input type="checkbox"/> 50.73(a)(2)(vii)</td> </tr> <tr> <td><input type="checkbox"/> 20.2201(d)</td> <td><input type="checkbox"/> 20.2203(a)(3)(ii)</td> <td><input type="checkbox"/> 50.73(a)(2)(ii)(a)</td> <td><input type="checkbox"/> 50.73(a)(2)(viii)(A)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(1)</td> <td><input type="checkbox"/> 20.2203(a)(4)</td> <td><input type="checkbox"/> 50.73(a)(2)(ii)(B)</td> <td><input type="checkbox"/> 50.73(a)(2)(viii)(B)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(i)</td> <td><input type="checkbox"/> 50.36(c)(1)(i)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(iii)</td> <td><input type="checkbox"/> 50.73(a)(2)(ix)(A)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(ii)</td> <td><input type="checkbox"/> 50.36(c)(1)(ii)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(iv)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(x)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(iii)</td> <td><input type="checkbox"/> 50.36(c)(2)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(A)</td> <td><input type="checkbox"/> 73.71(a)(4)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(iv)</td> <td><input type="checkbox"/> 50.46(a)(3)(ii)</td> <td><input checked="" type="checkbox"/> 50.73(a)(2)(v)(B)</td> <td><input type="checkbox"/> 73.71(a)(5)</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(v)</td> <td><input type="checkbox"/> 50.73(a)(2)(i)(A)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(C)</td> <td><input type="checkbox"/> OTHER</td> </tr> <tr> <td><input type="checkbox"/> 20.2203(a)(2)(vi)</td> <td><input type="checkbox"/> 50.73(a)(2)(i)(B)</td> <td><input type="checkbox"/> 50.73(a)(2)(v)(D)</td> <td style="font-size: small;">Specify in Abstract below or in NRC Form 366A</td> </tr> </table>	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(a)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input checked="" type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A
<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)																																		
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(a)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)																																		
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)																																		
<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)																																		
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)																																		
<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)																																		
<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input checked="" type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)																																		
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER																																		
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A																																		

**12. LICENSEE CONTACT FOR THIS LER**

FACILITY NAME Perry Nuclear Power Plant, John Pelcic, Compliance Engineer	TELEPHONE NUMBER <i>(Include Area Code)</i> (440) 280-5824
------------------------------------------------------------------------------	---------------------------------------------------------------

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX

<b>14. SUPPLEMENTAL REPORT EXPECTED</b> <input type="checkbox"/> YES <i>(If yes, complete EXPECTED SUBMISSION DATE).</i> <input checked="" type="checkbox"/> NO	<b>15. EXPECTED SUBMISSION DATE</b> MONTH:      DAY:      YEAR:
--------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------

**ABSTRACT** (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On April 27, 2009, the shutdown cooling mode of operation for the Residual Heat Removal (RHR) system was interrupted for one hour and four minutes. At the time of the event, the plant was in MODE 5 (Refueling). Plant operators verified the designated alternate methods for decay heat removal were available. Reactor coolant temperature increased three degrees F.

The event initiated as Instrumentation and Control technicians were installing an electrical jumper for a surveillance test. During the installation process, the jumper slipped off the terminal connector and created a short circuit to ground which blew the circuit's protective fuse. The blown fuse caused an RHR common suction valve to close (i.e., invalid signal) and trip the operating RHR A subsystem. Loss of the common suction flow path also prevented the RHR B subsystem from being operated.

The fuse was replaced and logic reset to open the suction valve and establish RHR B shutdown cooling operation. The individual human performance deficiencies were addressed in accordance with the company's performance management process. Procedure and program changes were made to address weaknesses in risk perception, use of jumpers and lifted leads, and work on protected equipment.

The safety significance of this event is considered to be low. This event is reported in accordance with 10 CFR 50.73 (a)(2)(v)(B) as a condition that could have prevented the fulfillment of the safety function of a system needed to remove residual heat.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Perry Nuclear Power Plant	05000440	YEAR	SEQUENTIAL NUMBER	REV NO.	2 OF 5
		2010	-- 001 --	0	

**NARRATIVE**

Energy Industry Identification System Codes are identified in the text as [XX].

**INTRODUCTION**

On April 27, 2009, at 1730 hours, the Residual Heat Removal (RHR) [BO] shutdown cooling outboard common suction isolation valve 1E12-F008 [ISV] received an invalid isolation signal resulting in the operating RHR A pump [P] tripping while the system was in the shutdown cooling mode of operation. When valve 1E12-F008 isolated, both the A and B RHR subsystems became inoperable and shutdown cooling flow to the reactor from the RHR system was interrupted for approximately one hour and four minutes. At the time of the event, the plant was in MODE 5 (Refueling) with the RHR B subsystem in standby. On April 28, 2009, at 0055 hours, notification was made to the NRC Operations Center (ENF No. 45025) in accordance with 10 CFR 50.72(b)(3)(v)(B), as an event or condition that could have prevented fulfillment of the safety function of a system needed to remove residual heat.

The event notification was retracted on June 25, 2009, based on further evaluation which determined that interrupted operation of the RHR system in the shutdown cooling mode was not reportable in accordance with 10 CFR 50.72 or 50.73 because (1) there was not a reasonable expectation of the loss of the safety function of a system needed for residual heat removal, and; (2) there was no operation or condition prohibited by the plant's Technical Specifications.

The event was later re-evaluated for reportability using additional guidance and enforcement history related to safety system functional failure reporting. The evaluation determined that the April 27, 2009, loss of shutdown cooling event is reportable as a Licensee Event Report (LER) under 10 CFR 50.73(a)(2)(v)(B), "Any event or condition that could have prevented the fulfillment of the safety function of structures, or systems that are needed to remove residual heat." On March 10, 2010 at 1515 hours, the NRC Operations Center was notified that the event documented in ENF No. 45025 is reportable in accordance with 10 CFR 50.73(a)(2)(v)(B).

**EVENT DESCRIPTION**

On April 27, 2009, at 1730 hours, with the plant in MODE 5 during refueling outage 12 and water level less than 22 feet 9 inches above the top of the reactor pressure vessel (RPV) flange, the RHR shutdown cooling outboard common suction isolation valve 1E12-F008 received an invalid isolation signal. This caused the RHR A pump to trip while operating in the shutdown cooling mode of operation. RHR A was the primary (operating) RHR subsystem. RHR B was the backup subsystem as required by Technical Specification (TS) Limiting Condition for Operation (LCO) 3.9.9 "Residual Heat Removal (RHR) – Low Water Level." When valve 1E12-F008 isolated, both the A and B RHR subsystems became inoperable. The capability for shutdown cooling subsystem operation was lost with this configuration. The operators entered Off-Normal Instruction (ONI) E12-2, "Loss of Decay Heat Removal" and TS LCO 3.9.9, Conditions A and C due to closure of valve 1E12-F008. The operators took the appropriate required actions to comply with the LCO requirements including Required Action A.1, to verify that an alternate method of decay heat removal was available for each inoperable RHR shutdown cooling subsystem; Required Action C.1, to verify reactor coolant circulation by an alternate method; and Required Action C.2, to monitor reactor coolant temperature.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Perry Nuclear Power Plant	05000440	YEAR	SEQUENTIAL NUMBER	REV NO.	3 OF 5
		2010	-- 001 --	0	

**NARRATIVE**

At 1735 hours, a blown fuse was discovered in control room panel 1H13-P691. The fuse services the circuit that provides 24 vdc electrical power to Trip Unit Card File & Calibration Unit Z1A. When the fuse blew, the 24 vdc electrical power was lost to Trip Unit 1B21-N679A "Reactor Pressure High." Relay 1B21-K124A de-energized, which caused automatic closure of valve 1E12-F008 and the subsequent automatic tripping of the RHR A pump, as designed.

Plant operators pursued parallel paths (both local and remote) to manually realign the valve for RHR B subsystem operation. At 1816 hours, the fuse was replaced. The isolation logic initiated by the blown fuse was reset. Valve 1E12-F008 was aligned manually to the open position from the control room to support RHR B subsystem operation. At 1834 hours, the RHR B pump was started to restore shutdown cooling operation in compliance with TS LCO 3.9.9. The amount of time that RHR shutdown cooling was interrupted was one hour and four minutes. During that time, reactor coolant temperature increased three degrees F from 94 to 97 degrees F.

On April 28, 2009, after performing fill and vent activities on the RHR A subsystem, at 0430 hours, the RHR A subsystem was declared operable and TS LCO 3.9.9, Condition A was exited. At 0458 hours, the RHR A subsystem was started in the normal shutdown cooling lineup and at 0513 hours, the RHR B subsystem was placed in standby.

**CAUSE OF EVENT**

The interruption of RHR shutdown cooling system operation was caused by a blown fuse which sent an isolation signal to valve 1E12-F008. Closure of this valve sent an automatic trip signal to the operating RHR A subsystem and, with the valve now closed, prevented immediate startup of the RHR B pump to restore shutdown cooling.

The fuse blew while Instrumentation and Control (I&C) technicians were installing a jumper in control room panel 1H13-P691 as part of prerequisites for performing the containment integrated leak test (ILRT). While the I&C technicians attempted to attach the jumper wire, the mini-grabber on the jumper slipped off the terminal connector, made contact with the ground bus, created a short circuit to ground and blew the fuse. This represented a human performance error by the I&C technicians.

A root cause evaluation performed for this event identified the following causes which established the conditions leading to the improper jumper installation:

- Organizational and individual weaknesses exist with risk perception and mitigation. The pre-job briefing for the ILRT prerequisite task did not include a specific discussion of risk and risk mitigation. The inherent risk of using jumpers, specifically in the installed location, was not recognized and mitigated. Planning/review/scheduling of outage work activities did not include adequate risk determination/risk management.
- There was continued tolerance and use of less than adequate tools (i.e., procedures, labeling, jumpers, etc) needed for successful task performance. Difficult installation of jumpers and lifted leads had become a routine and accepted practice due to the frequency of use in past work activities and procedures.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Perry Nuclear Power Plant	05000440	YEAR	SEQUENTIAL NUMBER	REV NO.	4 OF 5
		2010	-- 001 --	0	

**NARRATIVE**

- Work permitted on or near protected equipment is outside industry norms. Control Room panel 1H13-P691 was posted as protected equipment.
- Use of jumpers, lifted leads, and difficult measuring and test equipment (M&TE) connections had not been rigorously challenged and corrected.

**EVENT ANALYSIS**

The purpose of the RHR system in MODE 5 is to remove decay heat and sensible heat from the reactor coolant. There are two redundant, manually controlled shutdown cooling subsystems (RHR A/B) available to perform the shutdown cooling function. Each subsystem loop consists of one motor driven pump, two heat exchangers in series, and associated piping and valves. Both subsystems share a common suction from the same recirculation loop. Motor operated valves 1E12-F008 and 1E12-F009 are located in this line to provide inboard and outboard containment isolation. Each pump discharges coolant to the reactor after it has been cooled by circulation through the respective heat exchangers. The RHR heat exchangers transfer heat to the Emergency Service Water System.

In MODE 5, decay heat removal by the RHR system in the shutdown cooling mode is not required for mitigation of any events or accidents evaluated in the safety analyses.

For this event, shutdown cooling was lost for one hour and four minutes in MODE 5. During that time, reactor coolant temperature rose from 94 to 97 degrees F. The reactor coolant time-to-boil was approximately nine hours due to low decay heat level in the core.

The operators promptly verified the alternate methods of decay heat removal were available for the inoperable RHR A/B shutdown cooling subsystems in accordance with TS 3.9.9, Required Action A.1.

A qualitative probabilistic risk assessment (PRA) was performed for the duration that shutdown cooling was interrupted. Based on the availability of the Shutdown Cooling function, the timeframe involved before boiling of the reactor vessel inventory was expected, and the other mitigating alignments available to preclude reaching the boiling point had they been required, this event is considered as having a low safety significance. The conclusion of Shutdown Cooling availability is in alignment with the guidance/definition provided in NRC Inspection Manual 0609, Significance Determination Process, Appendix G, Shutdown Operations.

**CORRECTIVE ACTIONS**

The remaining refueling outage activities were reviewed jointly by Operations and Maintenance to drive improved execution of risk-significant work. The risks were defined and appropriate measures were developed to manage those risks. Among the actions taken were:

- Sessions were conducted with Maintenance and Operations personnel, reinforcing expectations to consistently use Human Performance tools and behaviors;
- Identifying and reviewing maintenance activities that could affect shutdown cooling, reactor water level or pressure control, or reactivity management control and developing mitigation strategies for maintenance items identified as risk-significant; and

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Perry Nuclear Power Plant	05000440	YEAR	SEQUENTIAL NUMBER	REV NO.	5 OF 5
		2010	-- 001 --	0	

**NARRATIVE**

- Flagging work packages with yellow, orange, or red elevated work authorization forms.

A Human Performance Strategic Plan was developed to establish actions to improve:

- Organizational and individual risk perception and mitigation;
- The rigor and intrusiveness for risk assessment of daily work activities; and
- Site culture with respect to continued tolerance and use of less than adequate tools (procedures/work packages, jumpers, and labels) needed for successful task performance.

The protected equipment process established in Nuclear Operating Instruction (NOP)-OP-1007, "Risk Management," was revised to strengthen the controls, access requirements and limitations for work on protected equipment.

A project plan was created to establish the necessary strategies to identify, prioritize, and implement engineered solutions in order to eliminate the use of difficult jumpers, lifted leads, and M&TE connections. Potential solutions include the use of alternate locations or use of other solutions such as test lugs, test switches, sliding links, test boxes, or use of a robust barrier.

**PREVIOUS SIMILAR EVENTS**

A review of Perry LERs and the corrective action program database for the past three years found one instance of a loss of shutdown cooling event. On July 11, 2007, with the plant in MODE 4 (Cold Shutdown), the RHR B pump tripped off while operating in shutdown cooling. The pump trip occurred when an I&C technician performing a Reactor Core Isolation Cooling (RCIC) test unnecessarily loosened a wire connection from an electrical terminal, inducing a current from the RCIC circuitry into the electrically independent RHR B trip system. Plant modifications to separate the wiring and install noise suppression diodes were initiated. This event was reported under LER 2007-002.

Corrective actions for the July 11, 2007, loss of shutdown cooling event were directed toward fixing a latent vendor design deficiency and would not have prevented the April 27, 2009, loss of shutdown cooling event. A common factor in both events, however, is that they were initiated by an I&C human performance error. The individual human performance shortfalls were addressed in accordance with the company's performance management process.

**COMMITMENTS**

There are no regulatory commitments contained in this report. Actions described in this document represent intended or planned actions, are described for the NRC's information, and are not regulatory commitments.