



**SAFETY INSPECTION REPORT  
AND COMPLIANCE INSPECTION**

1. LICENSEE <b>Premier Cardiovascular Specialists</b>		2. NRC/REGIONAL OFFICE <b>Region III</b> 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
REPORT NUMBER(S) <b>2010-01</b>			
3. DOCKET NUMBER(S) <b>030-38009</b>	4. LICENSE NUMBER(S) <b>21-32740-01</b>	5. DATE(S) OF INSPECTION <b>March 31, 2010</b>	
6. INSPECTION PROCEDURES <b>87130</b>	7. INSPECTION FOCUS AREAS <b>03.01-03.07</b>		

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM <b>2201</b>	2. PRIORITY <b>G5</b>	3. LICENSEE CONTACT <b>M. Hashem, M.D., RSO</b>	4. TELEPHONE NUMBER <b>313-624-8417</b>
<input checked="" type="checkbox"/> Main Office Inspection	Next Inspection Date: <u>March 2015</u>		
<input type="checkbox"/> Field Office	_____		
<input type="checkbox"/> Temporary Job Site Inspection	_____		

**PROGRAM SCOPE**

One part-time technologist performs about 55 procedures per month Monday through Thursday, 8:30 am-5:00pm at the Dearborn, MI location utilizing Tc99m and Th-201. The licensee obtains unit doses from an area nuclear pharmacy. An outside consultant performs quarterly program audits which appears to adequately maintain program compliance.

Amendment No. 03, dated 02/12/10, authorized a second location in Canton, MI, however, according to licensee representatives, no licensed material had been received and was therefore not reviewed at this time. The licensee indicated that the new facility is planned to be operational on April 14, 2010. The licensee indicated that currently, procedures will be performed on Wednesday and Saturday only at the Canton, MI location.

**Performance Observations**

Licensed material was observed adequately secured during the review and was not readily accessible to members of the general public. According to the available technologist, the hot-lab area is locked when not under surveillance.

Interviews conducted with the technologist revealed an adequate level of understanding of emergency and material handling procedures and techniques. Daily surveys, injection techniques, dose calibrator checks, waste handling and disposal, and package receipt procedures, were successfully demonstrated or observed.

Independent measurements taken during the review did not indicate readings in excess of expected in restricted or unrestricted areas. Personal dosimetry records reviewed did not indicate readings approaching regulatory limits.

Available survey instrumentation was calibrated and operational during the review and compared well with the NRC instrument. Licensee's sealed source inventory was visually verified during the review.